

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

03 DEC 2018

Estimate No. : **b1 49316**
Date Estimated : **03/12/2018**
Prepared By : **Kevin Leong Wai Kit**

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Chan Chi Ping
6 Sunrise Avenue

Singapore 806668

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKK8117G	J209695	30/08/2013	116iA/5	0

DESCRIPTIONVALUE

To replace rear right side panel, rear bumper & all
attachments cause by accident.

5,950.00

Painting on rear right side panel, rear bumper & rear RH
trunk floor.

2,454.00

To remove and install fuel tank to facilitate repairs
including extract fuel and conduct leak tests.

531.00

To remove and install rear hat-tray, rear seat, carpet
and roof top lining to facilitate repairs.

873.00

To check steering geometry and conduct wheel alignment
according to BMW specification (1x)

531.00

To replace tyre and wheel rim including balancing. (1x).

94.00

To check electrical wiring systems at the rear section
for proper function.

177.00

To carry out body cavity preservation.
(For cut panel).

531.00

Sundries.

150.00

Total Labour 1: **11,291.00**

DESCRIPTIONQTYPRICVALUE

RR RH FENDER

1

1,328.35

1,328.35

REINFORCEMENT PLATE C-PILLAR RH

1

50.45

50.45

REINFORCEMENT PLATE ROCKER PLATE RH

1

50.45

50.45

REINFORCEMENT PLATE UNIVERSAL

1

28.45

28.45

RR BUMPER RH SIDE GUIDE

1

49.05

49.05

REAR BUMPER PRIMED (LINES)

1

924.75

924.75

REAR RH WHEEL HOUSING COVER

1

131.10

131.10

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X**E S T I M A T E**Estimate No. : **b1 49316**Page No. : **2 of 5**Date Estimated : **03/12/2018**Prepared By : **Kevin Leong Wai Kit**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKK8117G	J209695	30/08/2013	116iA/5	0

DESCRIPTION	QTY	PRIC	VALUE
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
BLIND RIVET AVIBVLB	7	0.55	3.85
SCREW (SF PLUS M5X15)	3	0.55	1.65
(DG/SL) BODY ADHESIVE K5B (195ML)	1	326.80	326.80
(DG) BODYWORK ADHESIVE K5A (50ML)	1	112.70	112.70
(DG) CLEANER R1 (100ML)	1	26.15	26.15
PUNCH RIVET N4	32	0.55	17.60
(S/L) SEAM SEAL 300ML	1	33.80	33.80
Total Parts :			3,105.35

Labour 1	:	11,291.00
Parts	:	3,105.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,007.74
Grand Total	:	15,404.09

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

	23 Jul 1992	23 Jul 1992
s 2B	Motorcycles =< 200 cc	
s 3	Motor cars with unladen weight =< 3000kg with =< 7 passengers, exclusive of driver; and other motor vehicles with unladen weight =< 2500kg	

Licence No. 250468



28A

