



Reporting Centre 5 Soon Lee Street, #01-60 Pioneer Point, Singapore 627607
 Workshop 5 Soon Lee Street, #01-62 Pioneer Point, Singapore 627607
 Spray-painting 1 Soon Lee Street, #06-41 Pioneer Centre, Singapore 627605
 Office: 6631 0707 Fax: 6316 2431 cab@chengauto.com Cheng Auto Bodyworks Singapore



DATE : 3/12/2018

REPAIR DETAILS	
REFERENCE	
Vehicle Reg No.	: SLV6802E
Make & Model	: MITSUBISHI ATTRAGE 1.2 CVT
Chassis No.	: MMB5TA13AJH001106
Engine No.	: 3A92UGP5326
Manufactured Year	: 2017
Labour	: REPAIRER'S
TP Vehicle Reg No.	: SGK7720T
DOA & Location	: 23/11/2018 FILTER LANE AT JURONG TOWN HALL RD TO JURONG EAST AVE 1
Our Ref	: SLV6802E / CHAN SIEW GEOK

ESTIMATES OF PARTS

No.	Qty	Description	Part No.	Price
1	1	REAR BOOT		\$ 885.96 <i>bx</i>
2	1	BOOT HINGE RH		\$ 205.44 <i>Ry</i>
3	1	BOOT HINGE LH		\$ 205.44 <i>Ry</i>
4	1	EMBLEM ATTRAGE		\$ 40.66 <i>19</i>
5	1	EMBLEM LOGO STAR		\$ 43.87 <i>med</i>
6	1	CENTRE CHROME GANISH		\$ 340.26 <i>x</i>
7	1	BOOT LOCK ASSY		\$ 220.42 <i>P</i>
8	1	BOOT CATCH		\$ 21.40 <i>Ry</i>
9	1	BOOT RUBBER		\$ 158.36 <i>x</i>
10	1	TAILLAMP RH		\$ 295.32 <i>eng</i>
11	1	TAILLAMP LH		\$ 295.32 <i>eng</i>
12	1	ENDPANEL		\$ 430.14 <i>Ry</i>
13	1	END PANEL TOP GANISH		\$ 66.34 <i>K</i>
14	1	REAR BUMPER		\$ 757.56 <i>de</i>
15	1	BUMPER REFLECTOR RH		\$ 21.40 <i>x</i>
16	1	BUMPER REFLECTOR LH		\$ 21.40 <i>x</i>
17	1	BUMPER RETAINER RH		\$ 27.82 <i>na</i>
18	1	BUMPER RETAINER LH		\$ 27.82 <i>x</i>
Sub-Total (S\$)				\$ 4,064.93
SAAA List Item Discount 10% (S\$)				\$ 406.49
Sub-Total (S\$)				\$ 3,658.44

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Tanjin 9795749
wp
6/2/18 24:15pm
Resurvey after repair
5 days
surellkan to you.

LABOUR

No.	Description	Price
1	LABOUR	\$ 1,200.00 700
2	SPRAYPAINTING	\$ 1,200.00 1800
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	\$ 40.00 30
4	REMOVE AND REINSTALL UPHOLSTERY TO FACILITATE REPAIRS	\$ 200.00 60
5	ANTI-RUST COATING AND APPLY CORROSION PROTECTION	\$ 150.00 430
6	DISMANTLE AND INSTALL REAR BOOT SPOILER	\$ 200.00 60
7	CHECK PARKING SENSOR	\$ 100.00 30
Total Labour (\$\$)		\$ 3,090.00

MISCELLANEOUS ITEMS

No.	Description	Price
1	REAR PARKING SENSOR	\$ 200.00 1W
2	END PANEL SEALANT	\$ 100.00 X
3	BUMPER CLIPS 1 SET	\$ 100.00 30NR
4	BOOT CHROME CLIPS 1 SET	\$ 50.00 X
5	REAR FENDER INNER COVER RH CLIPS 1 SET	\$ 50.00 X
6	REAR FENDER INNER COVER LH CLIPS 1 SET	\$ 50.00 X
7	REAR NUMBER PLATE WITH COVER	\$ 35.00 X
Total Miscellaneous Items (\$\$)		\$ 550.00

Total Parts (\$\$)	\$ 3,658.44
Total Labour (\$\$)	\$ 3,090.00
Total Miscellaneous (\$\$)	\$ 550.00
Total (\$\$)	\$ 7,298.44
GST 7% (\$\$)	\$ 510.89
Grand Total (\$\$)	\$ 7,809.33