

REF:

CC3 / AU 18021882 / Asber

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop no's _____

of _____

Insured _____

Policy No _____

Claims No _____

Sum Insured _____

Excess: _____


\$0/-

(Client's Record)

Make of Veh _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

95K.

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

21 8 1/2 days

Res: Yes or No

Lump Sum: _____

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLS1885P' Yr Regn: 2017 Sept

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Audi A3

CS 999

Colour: _____

White

A/C: Insured / Std / NI / NA

Sp. Reading: _____

26858

Ti/Radio: Insured / Std / NI / NA

Engl No: _____

WAU2228V2J1013309.

C/no: _____

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt /Brake: ☒ Inorder / Jammed / Leaked / Burnt /

Modi: Nil / S/Rim / STD A/Rim / or

Tyre Size: _____

F: _____

205/55R16.

R: _____

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: _____

06

mm

R/Bal: _____

06

mm

L/Bal: _____

06

mm

L/Bal: _____

06

mm

D.O.A: _____

D.O.I: _____

04/12/18.

Survey held at _____

Premium.

Des. of Damages: ☒ Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD Allg.

New Car Price: 136K.

05/12/18 @ 17:39 revised IA to A3G via merimer.

06/12/18 @ 14:13 p.m. mandate requested authentic repair to A3G via merimer.

MV: 95K

RV: 54K

Nett: 41K

RECEIVED 17 APR 2019

07/12/18 @ 12:35 p.m. mandate approved by Victor Koh via merimer.

08/12/18 @ 13:20 p.m. revert authentic repair to James Gopuram via email.

Date/Time: File Para to?

17/04/19



: Prel. Report



: Final Report

11

Typical

Date/Time: For Return to?

Days Of Repair: _____

21

Resurvey No. of Trip: _____

2

Survey Fee

200

Transportation

1 Site Insp. (\$)

Add Fee: ☐

Site Insp. (\$)



Interview (\$)



Tech. Insp. (\$)



Weekend (\$)

Report Format

Lump Sum / I.B.I. 13

40,392.44

200

10

200

22/03/19

Confirmed v/p \$ 40,392.44 @ 21 days with
Adrian
(\$ 19,313.56 Red - 32%)

RETAIL PRICE LIST

Effective as of 15 Nov 2018



MODEL	Power (hp)	Torque (Nm)	Combined Fuel Consumption L/100km	VES (Band)	Retail Price	VES (rebate / surcharge)	Nett Price after VES
AUDI A3 Sportback							
A3 1.0 TFSI S tronic	116	200	4.8	C1	\$124,240	\$10,000	\$134,240
S3 2.0 TFSI qu S tronic	290	380	6.6	C2	\$219,580	\$20,000	\$239,580
RS 3 2.5 TFSI qu S tronic	400	480	8.4	C2	\$278,680	\$20,000	\$298,680
AUDI A3 Sedan							
A3 1.0 TFSI S tronic	116	200	4.7	C1	\$126,440	\$10,000	\$136,440
A3 1.4 TFSI S tronic	150	250	4.9	B	\$142,480	\$0	\$142,480
S3 2.0 TFSI qu S tronic	290	380	6.5	C2	\$221,780	\$20,000	\$241,780
RS 3 2.5 TFSI qu S tronic	400	480	8.4	C2	\$286,380	\$20,000	\$306,380
AUDI A3 Cabriolet							
A3 1.4 TFSI S tronic	150	250	5.1	B	\$178,719	\$0	\$178,719
AUDI A4 Sedan							
A4 2.0 TFSI S tronic	190	320	5.2	B	\$166,980	\$0	\$166,980
A4 2.0 TFSI qu S tronic (Design)	252	370	6.2	C2	\$223,080	\$20,000	\$243,080
S4 3.0 TFSI qu tiptronic	354	500	7.9	C1	\$284,680	\$10,000	\$294,680
AUDI A4 Avant							
A4 2.0 TFSI S tronic	190	320	5.4	B	\$176,480	\$0	\$176,480
A4 2.0 TFSI qu S tronic (Design)	252	370	6.5	C2	\$232,680	\$20,000	\$252,680
S4 3.0 TFSI qu tiptronic	354	500	8.0	C1	\$294,180	\$10,000	\$304,180
RS 4 2.9 TFSI qu tiptronic	450	600	8.9	C2	\$362,280	\$20,000	\$382,280
AUDI A5 Sportback							
A5 2.0 TFSI S tronic (Design)	190	320	5.6	B	\$191,980	\$0	\$191,980
A5 2.0 TFSI qu S tronic (Sport)	252	370	6.4	C2	\$236,930	\$20,000	\$256,930
S5 3.0 TFSI qu tiptronic	354	500	7.9	C1	\$289,580	\$10,000	\$299,580
AUDI A5 Coupe							
A5 2.0 TFSI S tronic (Design)	190	320	5.5	B	\$196,580	\$0	\$196,580
A5 2.0 TFSI qu S tronic (Sport)	252	370	6.4	C2	\$242,030	\$20,000	\$262,030
S5 3.0 TFSI qu tiptronic	354	500	7.8	C1	\$296,880	\$10,000	\$306,880
RS 5 2.9 TFSI qu tiptronic	450	600	8.8	C2	\$359,080	\$20,000	\$379,080
AUDI A5 Cabriolet							
A5 2.0 TFSI S tronic (Design)	190	320	5.9	B	\$235,701	\$0	\$235,701
A5 2.0 TFSI qu S tronic (Sport)	252	370	6.7	B	\$274,280	\$0	\$274,280
S5 3.0 TFSI qu tiptronic	354	500	8.1	C1	\$334,780	\$10,000	\$344,780
AUDI A7 Sportback							
A7 2.0 TFSI S tronic	252	370	5.9	C1	\$290,080	\$10,000	\$300,080
A7 3.0 TFSI qu S tronic (New)	340	500	7.3	C1	\$360,500	\$10,000	\$370,500
AUDI A8							
A8 L 3.0 TFSI qu tip	310	440	7.9	C1	\$402,580	\$10,000	\$412,580
A8 L 3.0 TFSI qu tip (New)	340	500	8.2	C2	\$417,479	\$20,000	\$437,479
AUDI Q2							
Q2 1.0 TFSI S tronic	116	200	5.2	C1	\$130,906	\$10,000	\$140,906
Q2 1.4 TFSI COD S tronic	150	250	5.3	B	\$150,406	\$0	\$150,406
Q2 1.4 TFSI COD S tronic (Sport)	150	250	5.3	B	\$160,380	\$0	\$160,380
AUDI Q5							
Q5 2.0 TFSI qu S tronic (Sport)	252	370	7.4	C1	\$219,080	\$10,000	\$229,080
SQ5 3.0 TFSI qu tiptronic	354	500	8.7	C2	\$286,080	\$20,000	\$306,080
AUDI Q7							
Q7 2.0 TFSI qu tip	252	370	7.4	C1	\$281,780	\$10,000	\$291,780
Q7 3.0 TFSI qu tip	333	440	7.9	C2	\$343,402	\$20,000	\$363,402
AUDI Q8							
Q8 3.0 TFSI qu tip	340	500	8.9	C2	\$349,300	\$20,000	\$369,300
AUDI TT Roadster							
TT 1.8 TFSI S tronic	180	250	6.1	B	\$209,980	\$0	\$209,980
AUDI R8 Coupe							
R8 5.2 FSI qu S tronic	540	540	11.4	C2	\$763,380	\$20,000	\$783,380
AUDI R8 Spyder							
R8 5.2 FSI qu S tronic	540	540	11.7	C2	\$837,080	\$20,000	\$857,080

Terms and Conditions :

- ✓ Retail price is subject to in-house Financier and Insurance. Price includes 12-months road tax, registration fee and GST but without insurance.
- ✓ COE is non guaranteed and subject to B-bids, failing which new terms and conditions shall apply.
- ✓ Booking deposit for all models is \$520,000/-. Minimum booking deposit for indent order is \$525,000/-. with the exception of RS/RB is \$75,000/-.
- ✓ All deposits are non-refundable upon cancellation.
- ✓ In-House utilization of PARF/COE Rebates for new car registration is within Premium Automobile's discretion.

All prices and promotions are subject to change without any prior notice.



Audi Centre Singapore
281 Alexandra Road Singapore 159938

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Singapore NRIC
Owner ID:	8987C
Vehicle Details	
Vehicle No.:	SL51885P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Dec 2018
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED)
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	CHZ528864
Chassis No.:	WAUZZZ8V2J1013309
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,472.00
Original Registration Date:	12 Sep 2017
First Registration Date:	12 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$16,261.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Sep 2027
PARF Rebate Amount:	\$12,195.00
Intended COE Details	
COE Expiry Date:	11 Sep 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,001.00
COE Rebate Amount:	\$28,800.00
Total Rebate Amount:	\$40,995.00

The information contained herein is correct as at 04 Dec 2018

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 28 March 2019 10:42 AM
To: 'Boo seng yak'
Cc: Adrian Ling (LKKAuto); SUR; 'Carrine Leong'; jiayee.yap@premiumauto.com.sg;
'Chang Chee Sing'
Subject: RE: FINAL REVISION - SLS1885P - OD AIG - SURVEYED 4 DEC 18

Dear Mr Boo,

Confirmed final fig \$ 40,392.44 @ 21 days of repairs before excess \$0/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]
Sent: Saturday, 2 March 2019 6:07 PM
To: Adrian Ling <adrianling@lkkauto.com>; shirleyHiew@lkkauto.com; sur@lkkauto.com; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SLS1885P - OD AIG - SURVEYED 4 DEC 18

Hi Adrian and all,

Revised estimate is attached. Photographs is available from our Ubi office.

Please confirm repair cost of \$40,392.44 @ 21 days of repairs, exclude 3 Sundays 1 Public Holiday. with checked items replace. Vehicle was re-inspected by Rasul on 11 Dec 18

Your early closure is well appreciated.

Best regards - jb

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 7 December 2018 4:21 PM
To: 'Claims'
Cc: SUR
Subject: RE: OD claim for SLS 1885 P

Hi James,

According to Adrian, maximum repair limit based on new car price value for the vehicle is not exceeding S 90,000.00.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Friday, 7 December 2018 1:23 PM
To: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>
Cc: 'SUR' <sur@lkkauto.com>; Claims <claims@premiumauto.com.sg>
Subject: RE: OD claim for SLS 1885 P

Dear Shirley,

What is the maximum repair limit for the vehicle?

Best Regards,

James Tan

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 7 December 2018 1:20 PM
To: 'Claims'
Cc: SUR
Subject: RE: OD claim for SLS 1885 P
Attachments: ESTIMATE MARKED.pdf

Hi James,

As instructed by our client, please proceed to repair the insured vehicle **SLS 1885P** (Excess \$0/-). Based on our surveyor's estimate marking or whichever lower.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Please refer to the attachment above.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Wednesday, 5 December 2018 4:36 PM
To: 'Claims' <claims@premiumauto.com.sg>; 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>
Cc: 'SUR' <sur@lkkauto.com>; 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OD claim for SLS 1885 P

Dear Shirley,

We propose \$70,000 for repair.
Please advise.
Thanks.

Best Regards,
James Tan
Claims Advisor

Premium Automobiles Pte Ltd (Reg No: 09902271W)
55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims [<mailto:claims@premiumauto.com.sg>]

Sent: Wednesday, 5 December 2018 4:22 PM

To: 'Shirley Hiew (LKK Auto)'

Cc: 'SUR'; 'Claims'

Subject: RE: OD claim for SLS 1885 P

Dear Shirley,

We unable to accept your limit repair offer @ \$50,000.

Please advise.

Best Regards,

James Tan

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]
Sent: Wednesday, 5 December 2018 4:04 PM
To: 'Claims'
Cc: SUR
Subject: RE: OD claim for SLS 1885 P

Hi James,

The limit repair is based on market value not new car value.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [<mailto:claims@premiumauto.com.sg>]
Sent: Wednesday, 5 December 2018 3:35 PM
To: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>
Cc: 'SUR' <sur@lkkauto.com>; 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OD claim for SLS 1885 P

Dear Shirley,

How come the limit repair so long.
This car only 1 year plus.
You base on market value or new car value?
Please advise.
Thanks.

Best Regards,
James Tan
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]
Sent: Wednesday, 5 December 2018 3:30 PM
To: 'Claims'
Cc: SUR
Subject: RE: OD claim for SLS 1885 P

Dear James,

Enclosed estimate marked by Adrian.

Kindly check the repair cost limit whether you are able to repair the vehicle not exceeding \$ 50,000.00 on part by part basis?

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [<mailto:claims@premiumauto.com.sg>]
Sent: Wednesday, 5 December 2018 3:07 PM
To: 'Claims' <claims@premiumauto.com.sg>; 'SUR' <sur@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OD claim for SLS 1885 P

Dear All,

Kindly assist approval and excess for the above mentioned vehicle.
At the same time, kindly provide us repair value and marked estimate.
Thanks.

Best Regards,
James Tan
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 1100902271W)
55 Ubi Road | Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims [mailto:claims@premiumauto.com.sg]

Sent: Tuesday, 4 December 2018 6:04 PM

To: 'Claims Dept'; 'SUR'; 'Admin A'

Cc: 'Claims'

Subject: RE: OD claim for SLS 1885 P

Dear All,

Kindly assist approval and excess for the above mentioned vehicle.

Survey was done this morning.

At the same time, kindly provide us repair value and marked estimate.

Thanks.

Best Regards,

James Tan

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims Dept [mailto:claims@premiumauto.com.sg]
Sent: Tuesday, 4 December 2018 3:18 PM
To: 'SUR'; 'Admin A'
Cc: 'Claims'
Subject: RE : OD claim for SLS 1885 P

Good afternoon all ,

Here is the attachment of estimate and GIA for your kind reference .

Kindly return us a marked copy of estimate .

Thank you .

Best Regards,
Phua
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

View Received Message

This mail is associated with :

***SLS1885P (3216280155SG)**

OD

Dec 2 2018 4:00PM

[ZOU QIBIN]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 03/01/2019 10:24 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$42865.00) - SLS1885P - Claim Handler: Mohd Zawaye, Norsazani

Approved:42865.00:Supplementary ok.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SLS1885P**

OD

Dec 2 2018 4:00PM

[ZOU QIBIN]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 07/12/2018 12:35 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$41926.00) - SLS1885P - Claim Handler: Loo, Tong Shing

Approved:41926.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mohd Zawaye, Norsazani

Date: 02 Jan 2019

Preliminary Advice

Vehicle No	: SLS1885P	Accident Date	: 02/12/2018
Make	: AUDI A3	Policy No.	: 1700050003
Assignment Date	: 05/12/2018	Excess	: S\$0.00
Date of Inspection	: 04/12/2018	Est. Duration of Repair	: 15 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	59,706.00 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	42,865.00 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	8,626.00
Total	:S\$	51,491.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	136,000.00
Pre-Accident Value	:S\$	95,000.00
COE / PARF Rebate	:S\$	40,995.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	95,005.00
Margin for Repair		54,005.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : SUPPLEMENTARY AMOUNT IS \$ 939.00.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 06 Dec 2018

Preliminary Advice

Vehicle No	: SLS1885P	Accident Date	: 02/12/2018
Make	: AUDI A3	Policy No.	: 1700050003-01
Assignment Date	: 05/12/2018	Excess	: S\$0.00
Date of Inspection	: 04/12/2018	Est. Duration of Repair	: 15 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	58,767.00
Revised Amount	:S\$	41,926.00
Check Items (Estimated)	:S\$	8,626.00
Total	:S\$	50,552.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	136,000.00
Pre-Accident Value	:S\$	95,000.00
COE / PARF Rebate	:S\$	40,995.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	95,005.00
Margin for Repair	:S\$	54,005.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 05 Dec 2018

Preliminary Advice

Vehicle No	: SLS1885P	Accident Date	: 02/12/2018
Make	: AUDI A3	Policy No.	: 1700050003-01
Assignment Date	: 05/12/2018	Excess	: S\$0.00
Date of Inspection	: 04/12/2018	Est. Duration of Repair	: 15 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	58,767.00
Revised Amount	:S\$	41,926.00
Check Items (Estimated)	:S\$	8,626.00
Total	:S\$	50,552.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	136,000.00
Pre-Accident Value	:S\$	95,000.00
COE / PARF Rebate	:S\$	40,995.00
Salvage Value	:S\$	
Margin for Repair (New For Old Value)	:S\$	95,005.00
Margin for Repair		54,005.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : WE ARE PENDING REPAIR COST FROM REPAIRER.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/12/2018 15:43
Date Of Accident	02/12/2018 16:00
Exact Location Of Accident	MANDAI ROAD GOING TOWARDS YISHUN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS1885P
Insured/Policyholder	
Name Of Registered Owner	ZOU QIBIN
NRIC No	S2718987C
Email Address	MAXZOU.ERA@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81399558
Alternative Phone No	OTHERS-81399558

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SEDAN 1.0 TFSI 8V
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700050003-01
Cover Note Number	

Driver

Name of Driver	ZOU QIBIN
NRIC No	S2718987C
Date Of Birth	07/08/1964
Occupation	INDOOR
Date Of Driving Pass	20/10/2005
Driving Experience	13 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-81399558
Fax Number	
Contact Number	OTHERS-81399558
EMail Address	MAXZOU.ERA@GMAIL.COM

Address	158 CANBERRA DRIVE #07-38
Postcode	768083
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - OPENING DOOR OF VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	VG1616 (PRIVATE CAR)
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : SUKI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 . POSTCODE: 408865 . COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT T/20181203-2032

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	VG1616
Vehicle Make/Model/Colour	TOYOTA / ALPHARD / BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	DAVID
NRIC/Passport Number	
Contact Number	+6013-5232323

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLS1885P

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE

1. Please report **truthfully** the details of the accident to speed up the claims process.
2. This form must be completed by the **Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy benefits**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insured to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information submitted in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above purposes, and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agent(s) (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulatory, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Date & Time

Or-in's Signature
 (if there is not the policyholder)
 Date & Time


 Reporting Centre Person's Signature
 Name: 
 NRIC/IN No.

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT T/2018/203/2083

DECLARATION

I/We declare the foregoing particulars are true in every respect

[Signature]
 Driver's Signature
 If driver is not the policyholder
 Date & Time

[Signature]
 Driver's Signature
 If driver is not the policyholder
 Date & Time

[Signature]
 Reporting Officer's Signature
 Name: *James Tan*
 NRIC/ID No.:

Police Report



**SINGAPORE
POLICE FORCE**



T/201812032032

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20181203/2032

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/12/2018 11:30	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: ZOU QIBIN	Address: APT BLK 158 CANBERRA DRIVE #07-38 THE BROWNSTONE SINGAPORE 768063		
ID Type / ID No.: NRIC NO / S2718987C	Contact No.: Home/Office: Mobile: 81369558		
Nationality: SINGAPORE CITIZEN	Email:		
Sex: Male	Age: 54	Date of Birth: 07/08/1964	Type of Informant: Driver
Race: Chinese	Language:		Institution / School Name:
Occupation: MANAGER	Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 02/12/2018 16:00	Type of Location: T-Junction
Location: Along Road 1 MANDAI ROAD GOING TOWARDS YISHUN				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: FRONT LEFT SIDE				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLS1885P	Car	AUDI	A3 SEDAN 1.0 TFSI S TRONIC (LED)	White	Slightly Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLS1885P	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1700050003-01	12/09/2018	11/09/2019

Police Report



SINGAPORE
POLICE FORCE



T/20181203/2032

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408665
Tel No: 65470000

2 of 3

Report No. T/20181203/2032

CONTINUATION OF REPORT

Brief Details.

ON THE ABOVE MENTIONED DATE TIME AND LOCATION
I WAS TRAVELLING ALONG THE SAID LOCATION, WHILST TRAVELLING STRAIGHT TOWARDS
THE JUNCTION, THE MENTIONED VEHICLE WHOM WAS ON THE OPPOSITE LANE, MADE A
RIGHT TURN. AS HIS VEHICLE WAS ALREADY TOO CLOSE TO MY VEHICLE, I WASN'T ABLE TO
APPLY BRAKE ON TIME AND AS A RESULT, MY VEHICLE COLLIDED ONTO THE SIDE OF HIS
VEHICLE. TRAFFIC POLICE AND THE AMBULANCE ARRIVED AT THE SCENE. MY PASSENGER
WAS THEN CONVEYED TO THE HOSPITAL FOR FURTHER MEDICAL TREATMENT.

Police Report



SINGAPORE
POLICE FORCE



T/2018/203/2032

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408665
Tel No: 65470000

3 of 3

Report No. T/2018/203/2032

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
NG JIN SHENG

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
03/12/2018 11:30

Officer In Charge Of Case:
TP / GIT /
Sr Staff Sgt RAZIZ BIN TAHAR
Contact No.: 65476200

Classification Of Case:

Authentication Stamp
NP158

Accident Photo



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2718987C



Name:

ZOU QIBIN

邹其滨

Race:
CHINESE

Date of birth:

07-08-1964

Sex:

M

S2718987C

Country/Place of birth:
CHINA



REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S2718987C

Name:

ZOU QIBIN

Birth Date: 07 Aug 1964

Issue Date: 10 May 2014



S399188



NRIC No. S2718987C



Date of issue:
10-12-2014

158 CANBERRA DRIVE #07-38
SINGAPORE 768083

NRIC No: S2718987C

Date: 06/03/2018

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES):

EFFECTIVE

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg 20 Oct 2006



NP 426A



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : ZOU QIBIN
Period of Insurance : 12 Sep 2018 To 11 Sep 2019
Engine No. : CHZ528864
Chassis No. : WAUZZZ8V2J1013309

Vehicle No. : SLS1885P
Policy No. : 1700050003-01
Endorsement No. :
Issued Date : 24 Aug 2018

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC **Sum Insured** : Market Value **First Year of Registration** : 2017
Driver Restriction : NA **Off Peak Car** : No **Insuring with COE/PAF** : Yes
Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

ZOU QIBIN - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125268

PREMIUM LEASING -MPL
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Jonik

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

58PGLT

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours of the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours of the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours of the next working day of the accident.
- Submit Write/Summons/Correspondences from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc.)

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.



Audi

74862

SALES AGREEMENT

Particulars of Customer

Full name as in NRIC/PASSPORT (Underline Surname)

Name: ZOU QIBIN

Date: 27 Aug 2017

Address: BLK 513 WEST COAST ROAD #13-485

NRIC / Passport No.: S2718987C

Telephone No.: 81399558

Email: stevan6487@hotmail.com

Postal Code: 120513

Vehicle Details

Year Of Manufacture: 2017

Chassis No.: WAUZZZ8V2J1013309

Make / Model: A3 SEDAN 1.0 TFSI 6VMANG

Engine No.: CHZ 528864

Registration Type: Private

Vehicle Regn.

Colour: GLACIER WHITE METALLIC

Trim: BLACK

Purchase Details

Basic Price with Std specifications, Imp Duty, ARF, Regn, COE and 1 year Road Tax

\$ 145,400.00

Accessories: CEVS Rebate/Surcharge

\$ -10,000.00

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

Remarks / For Office Use

5 years warranty

FOC Solar film (Classic)

FOC T5 RECORDING CAMERA (FRONT & REAR)

FOC 3 yrs/45k km service whichever comes first

VEHICLE TO BE REGISTERED ON SAME COE MONTH

COE Rebate \$ 35,000.00

Number of bids: 4

☐ Guaranteed COE

☒ Non-guaranteed COE

☐ Immediate Registration

Finance Details

Finance Company:

For _____ mths at _____ % loan 5

Discount Price:

\$ 15,401.00

Insurance Subsidy:

\$

Total Purchase Price:

\$ 119,999.00

Deposit paid

\$

(Non-Refundable)

☐ Visa:

☐ Cash:

☐ Cheque No.:

Receipt No./ Date:

Important:

- The above prices and specifications are subject to change without notice.
- Full car booking deposit must be made on the date of this Sales Agreement, failing which this Sales Agreement shall be deemed cancelled by both parties and any deposit received by the Company shall be forfeited by the Company henceforth.
- The purchaser must register the vehicle if available within the month of obtaining the COE and full payment must be made before registration.
- The company's Official Receipt will acknowledge and evidence any payment made by the purchaser for the vehicle.
- Cheques must be crossed and made payable to the company.
- The Company is not responsible for any payments made for the purchase of motor accessories unless the purchases are stated in this Agreement and substantiated by the Company's Official Receipt.
- This Agreement is not transferable and not assignable and only the name stated herein is recognised for registration of the vehicle. The Company reserves the right to refuse to register the vehicle in any name other than that given in this Agreement.
- In the event the purchaser does not proceed with the purchase of the motor vehicle, the deposit paid by the purchaser to the Company, any advance payment and any other payment shall not be refunded to the purchaser.
- In the event the purchase of the motor vehicle is not completed, by reason of the failure of the Company to obtain a COE the deposit paid by the purchaser to the Company, any advance payment and any other payment shall be refunded to the purchaser.
- This Agreement is subject to the Conditions of Sale overleaf.
- Car performance data eg. fuel consumption figures, power and torque, acceleration, etc can only be treated as indicative figures provided by test bodies under test conditions which cannot be interpreted as a guarantee to the performance during actual usage.
- Engine oil consumption up to 1 litre per 1,000km is an accepted characteristics depending on the type of engine Oil used.
- The contract will be void if full documentations for COE bidding and deposit is not submitted prior to the COE Bidding Exercise.

I hereby accept the abovementioned terms and conditions detailed above and on the overleaf, and confirm there is no other oral and unwritten warranty in this agreement

Purchaser's Signature

Date 27 Aug 2017

Witnessed by

Sales Executive Michael Poh

Date

27 Aug 2017

Signature

Agreed on behalf of Premium Automobiles Pte Ltd

Management

Signature

Date

27 Aug 2017

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1390/2018/PH
Date	:	4-Dec-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Zou QiBin
Address	:	158 Canberra Drive #07-38 Singapore 768083
Telephone	:	HP +65 81399558
Type of Claim	:	Own Damage Claim
Policy No.	:	1700050003-01
Vehicle No	:	SLS 1885 P
Model Code	:	Audi A3 Sedan 1.0 TFSI
Model / Year	:	Sep-17
Engine No	:	CHZ528864
Chassis No	:	WAUZZZ8V2J1013309
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	2-Dec-18
Place of Accident	:	Mandai Road going towards Yishun

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 1885 P.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To remove and renew air-con condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,000.00 ✓	
3	To remove centre console, instrument panels and clusters. Renew dashboard, both frontal airbags, slip ring. Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining, both curtain air bags and knee airbag.	S/N \$ 3,600.00 ✓	
4	To dismantle and renew front bumper, bonnet, lhs front fender and lhs headlight. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	3000 \$ 4,500.00 1750 (without lock carrier) 3000 (with lock carrier).	
5	To respray front bumper, lhs front fender, bonnet and hinges. ✓	\$ 2,700.00 1650.	
6	To renew lhs front rim and carry out wheel alignment. Inspect front suspension assy for further damages.	S/N \$ 280.00 X	
7	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		\$ 12,632.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1885 P.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	\$ 1,739.00 ✓	1391.20
2	FIXING PARTS FOR FRONT BUMPER <i>new</i>	\$ 161.00 X	
3	GUIDE SECTION - LH <i>new</i>	\$ 33.00 ✓	27.52
4	LOWER CENTRE GRILLE - CENTRE <i>crushed</i>	\$ 140.00 ✓	112.00
5	CLOSING ELEMENT - LOWER CENTRE <i>crushed</i>	\$ 460.00 ✓	368.00
6	CLOSING ELEMENT - LH <i>new</i>	\$ 254.00 ?	
7	COVER TRIM - LH <i>new</i>	\$ 140.00 ✓	118.40
8	ADAPTER WHEEL HOUSING LINER - LH <i>new</i>	\$ 32.00 ?	
9	RADIATOR GRILLE <i>crushed</i>	\$ 1,239.00 ✓	991.20
10	CLOSING ELEMENT <i>new</i>	\$ 167.00 ✓	133.20
11	AIR GUIDE GRILLE - LH <i>missing</i>	\$ 164.00 ✓	136.40
12	SIDE REINFORCEMENT <i>new</i>	\$ 633.00 ✓	506.00
13	FOAM FILLER PIECE <i>crushed</i>	\$ 162.00 ✓	137.60
14	COVER <i>new</i>	\$ 105.00 ✓	83.60
15	FRONT FENDER - LH <i>crushed</i>	\$ 746.00 ✓	596.80
16	ATTACHMENT PARTS FOR FENDER <i>new</i>	\$ 62.00 ?	
17	BRACKET FOR FENDER <i>new</i>	\$ 34.00 ✓	27.76
18	FRONT FENDER BRACE - LH <i>new</i>	\$ 84.00 ?	
19	WHEEL HOUSING LINER - LH <i>new</i>	\$ 151.00 ✓	126.20
20	ATTACHMENT PARTS FOR WHEEL HOUSING LINER <i>new</i>	\$ 77.00 ?	
SUB - TOTAL SPARE PARTS		\$ 6,583.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1885 P.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	BONNET <i>dented</i>	S	2,755.00 ✓ 2204
22	ATTACHMENT PARTS FOR BONNET <i>Not New</i>	S	141.00 ? X
23	LID HINGE - LH/RH <i>2</i>	2 S	106.00 X
24	FRONT BONNET STRUT <i>Not New</i>	S	105.00 X
25	CATCH HOOK	S	78.00 X
26	STRIKER - LH/RH	2 S	192.00 X
27	EDGE PROTECTOR <i>New</i>	S	24.00 ✓ 1992
28	CATCH HOOK <i>New</i>	S	55.00 X
29	BOWDEN CABLE - CENTRE <i>New</i>	S	50.00 X
30	LID LOCK CABLE <i>New</i>	S	64.00 X
31	HORN - HIGH TONE LH <i>Not New</i>	S	177.00 ? X
32	LED HEADLIGHT - LH <i>cracked</i>	S	4,888.00 ✓ 3910.40
33	POWER MODULE FOR MAIN LIGHT ELECTRONICS <i>Not New</i>	S	665.00 ? X
34	LED WITH HEAT SINK - LH <i>Not New</i>	S	625.00 ? X
35	CONTROL UNIT FOR LIGHT CONTROL SYSTEM <i>Not New</i>	S	486.00 ? X
36	WASHER TANK RESERVOIR <i>Not New</i>	S	177.00 ? X
37	HEADLIGHT LIFT CYLINDER - LH <i>Not New</i>	S	123.00 ? X
38	HOSE <i>New</i>	S	57.00 X X
39	FRONT LOCK CARRIER FOR RADIATOR <i>cracked</i>	S	638.00 ? ✓ 510.00
40	AIR GUIDE - LH/RH <i>RH Defunct</i>	2 S	40.00 ? ✓ 17.12
SUB TOTAL SPARE PARTS		:	<u>\$ 11,446.00</u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1885 P.

S/N	Parts Description	Damage Parts & Prices		REMARKS
		S/NETT		
41	RADIATOR FAN WITH FAN RING <i>Not new</i>	S	1,425.00	X
42	INTERCOOLER <i>Not new</i>	S	828.00	X
43	ADDITIONAL COOLER FOR COOLANT <i>Not new</i>	S	797.00	X
44	COOLANT <i>Not new</i>	4 S	133.00	✓ 67.20
45	A/C CONDENSER <i>Bent.</i>	S	468.00	✓ 374.00
46	FRONT RIM - LH <i>Not new</i>	S	659.00	X
47	RUBBER VALVE <i>Not new</i>	4 S	12.00	X
48	FRONT NUMBER PLATE <i>Dented.</i>	S/N S	25.00	✓
SUB TOTAL SPARE PARTS		:	\$	4,347.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1885 P.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
50	STEERING AIRBAG	\$	3,111.00 ✓ 2488.80
51	FRONT DASHBOARD AIRBAG - LH	\$	4,060.00 ✓ 3248.00
52	HEAD AIRBAG - LH/RH	2 \$	3,384.00 ✓ 2707.20
53	C' PILLAR AIR BAG GUIDE - LH/RH	2 \$	44.00 ? X
54	KNEE AIR BAG	\$	1,692.00 ✓ 1353.60
55	KNEE AIRBAG TRAY COVER PANEL	\$	397.00 ? X
56	CONTROL UNIT FOR AIRBAG	\$	1,538.00 ✓ 1230.40
57	CRASH SENSOR FOR AIRBAG	3 \$	716.00 ✓ 572.40
58	DASHBOARD WITH AIR DUCT	\$	3,729.00 ✓ 2983.20
59	ROOF LINER	\$	1,551.00 ✓ 1240.80
60	THREE POINT SEAT BELT WITH TENSIONER - LH/RH	2 \$	1,912.00 ✓ 1529.60
61	SEAT BELT HEIGHT ADJUSTER	2 \$	343.00 X ✓ 274.40
62	A PILLAR TRIM - LH - ROCK GREY	\$	141.00 ? ✓ 112.40
63	A PILLAR TRIM - RH UPPER - ROCK GREY	\$	141.00 ? ✓ 112.40
64	SUNDRIES	\$	1,000.00 ✓ 23.20
TOTAL SPARE PARTS		:	\$ 46,135.00
TOTAL LABOUR CHARGES		:	\$ 12,632.00
GRAND TOTAL		:	\$ 58,767.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

59206

59497.72

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name
Surveyed Date
Authorised Date
Excess Cost
Liability
Remarks

: Adrian Li
: 04/12/18

:
: *Not Authorised, 18 Days - (with Lock Carrier)*
: *15 Days (without Lock Carrier)*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1390/2018/PH 11-Dec-18 Kee Siang 1 of 1 SLS 1885 P Audi A3 Sedan 1.0 TFSI
Quantity	Description	Unit Price	Amount
Parts			
1	Noise insulation <i>CR</i>	\$ 226.00	226.00 130.80
2	Air cond Sticker <i>CR</i>	\$ 7.00	5.12
3	"Caution Sticker" <i>CR</i>	\$ 12.00	9.26
4	Headlight vent hose <i>MS</i>	\$ 35.00	28.32
5	Lock Carrier Air Guide <i>CR</i>	\$ 10.00	8.32
TOTAL		\$ 290.00	

For Premium Automobiles Pte Ltd



[Handwritten Signature]

Authorised Signature

11/12/18
LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1390/2018/PH 19-Dec-18 Kee Siang 1 of 1 SLS 1885 P Audi A3 Sedan 1.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Grab Handle <i>damaged</i>	2 \$ 249.00	✓ 198.40
<u>Labour</u> 1	To supply and reinstall solar film.	\$ 400.00	✓ 400.00
TOTAL		\$ 649.00	

For Premium Automobiles Pte Ltd

Adrian Ling



Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

As acknowledged by Repairer

(Signature)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1390/2018/PH
Date : 4-Dec-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

We took 21 days exclude 3 Sundays

1 PH with checked items replaced

jb 2 Mar 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Zou QiBin
Address : 158 Canberra Drive
#07-38
Singapore 768083
Telephone : HP +65 81399558
Type of Claim : Own Damage Claim
Policy No. : 1700050003-01
Vehicle No : **SLS 1885 P**
Model Code : Audi A3 Sedan 1.0 TFSI
Model / Year : Sep-17
Engine No : CHZ528864
Chassis No : WAUZZZ8V2J1013309
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 2-Dec-18
Place of Accident : Mandai Road going towards Yishun

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 1885 P.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove,check and reinstall front wire harness for headlights,horns,outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$ 360.00
2	To remove and renew air-con condenser,additional radiator and radiator.Check electrical fans and control unit.Pressurise cooling system.To carry out vacuum and regas.	S/N	\$ 1,000.00	\$ 1,000.00
3	To remove centre console,instrument panels and clusters.Renew dashboard,both frontal airbags,slip ring.Transfer old fittings.Renew seat belts and control unit,pillar trims,roof lining ,both curtain air bags andknee airbag.	S/N	\$ 3,600.00	\$ 3,600.00
4	To dismantle and renew front bumper,bonnet,lhs front fender and lhs headlight.Renew frpnt lock carrier and align to position.Re-organise front crash management components.Reinstall all parts removed.		\$ 4,500.00	\$ 3,000.00
5	To respray front bumper,lhs front fender,bonnet and hinges.		\$ 2,700.00	\$ 1,650.00
6	To renew lhs front rim and carry out wheel alignment.Inspect front suspension assy for further damages.	S/N	\$ 280.00	
7	<i>Added labour - see attached 19 Dec 18</i>		\$ 400.00	\$ 400.00
8	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
	TOTAL LABOUR CHARGES	:	\$ 13,032.00	\$ 10,202.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1885 P .

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,739.00	\$ 1,391.20
2	FIXING PARTS FOR FRONT BUMPER	\$ 161.00	
3	GUIDE SECTION - LH	\$ 33.00	\$ 27.52
4	LOWER CENTRE GRILLE - CENTRE	\$ 140.00	\$ 112.00
5	CLOSING ELEMENT - LOWER CENTRE	\$ 460.00	\$ 368.00
6	CLOSING ELEMENT- LH	\$ 254.00	
7	COVER TRIM - LH	\$ 140.00	\$ 118.40
8	ADAPTER WHEEL HOUSING LINER - LH	\$ 32.00	
9	RADIATOR GRILLE	\$ 1,239.00	\$ 991.20
10	CLOSING ELEMENT	\$ 167.00	\$ 133.20
11	AIR GUIDE GRILLE -LH	\$ 164.00	\$ 136.40
12	SIDE REINFORCEMENT	\$ 633.00	\$ 506.00
13	FOAM FILLER PIECE	\$ 162.00	\$ 137.60
14	COVER	\$ 105.00	\$ 83.60
15	FRONT FENDER - LH	\$ 746.00	\$ 596.80
16	ATTACHMENT PARTS FOR FENDER	\$ 62.00	
17	BRACKET FOR FENDER	\$ 34.00	\$ 27.76
18	FRONT FENDER BRACE - LH	\$ 84.00	
19	WHEEL HOUSING LINER - LH	\$ 151.00	\$ 126.00
20	ATTACHMENT PARTS FOR WHEEL HOUSING LINER	\$ 77.00	
SUB - TOTAL SPARE PARTS		\$ 6,583.00	\$ 4,755.68

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1885 P .

S/N	Parts Description		Damage Parts & Prices		REMARKS
			S/NETT		
		c/f		\$	4,755.68
21	BONNET		\$ 2,755.00	\$	2,204.00
22	ATTACHMENT PARTS FOR BONNET		\$ 141.00		
23	LID HINGE - LH/RH	2	\$ 106.00		
24	FRONT BONNET STRUT		\$ 105.00		
25	CATCH HOOK		\$ 78.00		
26	STRIKER - LH/RH	2	\$ 192.00		
27	EDGE PROTECTOR		\$ 24.00	\$	19.92
28	CATCH HOOK		\$ 55.00		
29	BOWDEN CABLE - CENTRE		\$ 50.00		
30	LID LOCK CABLE		\$ 64.00		
31	HORN - HIGH TONE LH		\$ 177.00		
32	LED HEADLIGHT - LH		\$ 4,888.00	\$	3,910.40
33	POWER MODULE FOR MAIN LIGHT ELECTRONICS		\$ 665.00		
34	LED WITH HEAT SINK - LH		\$ 625.00		
35	CONTROL UNIT FOR LIGHT CONTROL SYSTEM		\$ 486.00		
36	WASHER TANK RESERVOIR		\$ 177.00		
37	HEADLIGHT LIFT CYLINDER - LH		\$ 123.00		
38	HOSE		\$ 57.00		
39	FRONT LOCK CARRIER FOR RADIATOR		\$ 638.00	\$	510.00
40	AIR GUIDE - LH/RH	2	\$ 40.00	\$	17.12
SUB TOTAL SPARE PARTS			\$ 11,446.00	\$	11,417.12

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1885 P .

S/N	Parts Description	Damage Parts & Prices		
		S/NETT	REMARKS	
			\$	11,417.12
41	RADIATOR FAN WITH FAN RING	\$ 1,425.00		
42	INTERCOOLER	\$ 828.00		
43	ADDITIONAL COOLER FOR COOLANT	\$ 797.00		
44	COOLANT	4 \$ 133.00	\$	67.20
45	A/C CONDENSER	\$ 468.00	\$	374.00
46	FRONT RIM - LH	\$ 659.00		
47	RUBBER VALVE	4 \$ 12.00		
48	FRONT NUMBER PLATE	S/N \$ 25.00	\$	25.00
SUB TOTAL SPARE PARTS		\$ 4,347.00	\$	11,883.32

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1885 P .

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
				\$ 11,883.32
50	STEERING AIRBAG		\$ 3,111.00	\$ 2,488.80
51	FRONT DASHBOARD AIRBAG - LH		\$ 4,060.00	\$ 3,248.00
52	HEAD AIRBAG - LH/RH	2	\$ 3,384.00	\$ 2,707.20
53	C' PILLAR AIR BAG GUIDE - LH/RH	2	\$ 44.00	
54	KNEE AIR BAG		\$ 1,692.00	\$ 1,353.60
55	KNEE AIRBAG TRAY COVER PANEL		\$ 397.00	
56	CONTROL UNIT FOR AIRBAG		\$ 1,538.00	\$ 1,230.40
57	CRASH SENSOR FOR AIRBAG	3	\$ 716.00	\$ 572.40
58	DASHBOARD WITH AIR DUCT		\$ 3,729.00	\$ 2,983.20
59	ROOF LINER		\$ 1,551.00	\$ 1,240.80
60	THREE POINT SEAT BELT WITH TENSIONER - LH/RH	2	\$ 1,912.00	\$ 1,529.60
61	SEAT BELT HEIGHT ADJUSTER	2	\$ 343.00	\$ 274.40
62	A PILLAR TRIM - LH - ROCK GREY		\$ 141.00	\$ 112.40
63	A PILLAR TRIM - RH UPPER - ROCK GREY		\$ 141.00	\$ 112.40
64	Added parts 11 Dec 19		\$ 249.00	\$ 198.40
65	Added parts 19 Dec 19		\$ 290.00	\$ 232.32
66	SUNDRIES		\$ 1,000.00	\$ 23.20
	TOTAL SPARE PARTS	:	\$ 46,674.00	\$ 30,190.44
	TOTAL LABOUR CHARGES	:	\$ 13,032.00	\$ 10,202.00
	GRAND TOTAL	:	\$ 59,706.00	\$ 40,392.44

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1390/2018/PH 11-Dec-18 Kee Siang 1 of 1 SLS 1885 P Audi A3 Sedan 1.0 TFSI
Quantity	Description	Unit Price	Amount
Parts			
1	Noise insulation	\$ 226.00	\$ 180.80
2	Air cond Sticker	\$ 7.00	\$ 5.12
3	"Caution Sticker"	\$ 12.00	\$ 9.76
4	Headlight vent hose	\$ 35.00	\$ 28.32
5	Lock Carrier Air Guide	\$ 10.00	\$ 8.32
TOTAL		\$ 290.00	\$ 232.32

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1390/2018/PH 19-Dec-18 Kee Siang 1 of 1 SLS 1885 P Audi A3 Sedan 1.0 TFSI	
Quantity	Description		Unit Price	Amount
<u>Parts</u> 1	Grab Handle	2	\$ 249.00	\$ 198.40 \$ 198.40
<u>Labour</u> 1	To supply and reinstall solar film.		\$ 400.00	\$ 400.00 \$ 400.00
TOTAL			\$ 649.00	\$ 598.40

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLS 1885 P

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1390/2018/MAS

16 April 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SLS 1885 P, Audi A3 Sedan 1.0 TFSI

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SLS 1885 P**, claimant, **Mr. Zou Qibin**, please find the related document per attached.

1. A copy of the Original invoice no. 85013683 – S\$43,219.91
2. A copy of the Discharge Voucher duly signed by client.
3. Medical bill – S\$120.00

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLS 1885 P



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159958
Main Telephone: 6388 2223
Main Telefax: 6471 3333

Alexandra Service Centre
281 Alexandra Road
Singapore 159958
Telephone: 6388 2223
Telefax: 6471 3333

Ubi Service Centre
55 Ubi Road 1
Singapore 408722

Customer Service
Service Appointment:
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6388 2323
6628 1233

Page 1 17:34

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013683 Date : 09/04/2019 Order : SLS1885P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLS1885P (V 35192)	Regn Dates: 12/09/2017	Mileage: 31053	WIP No.: 34426
Model: A3 SEDAN 1.0 TFSI 8VMANG	Chassis: WAUZZZ8V2J1013309	Engine: CHZ 528864	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
S	SUBLET	M: INSTALL FRONT WINDSCREEN SOLAR FILM.	400.00	1.00	400.00
S	BODYWORK	M: TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	360.00	1.00	360.00
S	BODYWORK	M: TO REMOVE AND RENEW AIR CON CONDENSER. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	1000.00	1.00	1,000.00
S	BODYWORK	M: TO REMOVE CENTRE CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS, CONTROL UNIT, PILLAR TRIMS, ROOF LINING, BOTH CURTAIN AIR BAGS	3600.00	1.00	3,600.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 158008
Main Telephone: 6346 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 158008
Telephone: 6388 2223
Telefax: 6475 1021

Ubi Service Centre
55 Ubi Road 1
Singapore 408080
Telephone: 6388 2223

Customer Service
Service Appointment
Hour Breakdown Service
2788
customer.care@premiumauto.com.sg

6346 2223
6475 1021

INS TAX INVOICE

Company-Reg. No: 199902271W

GST Reg. No. 199902271W

Page 2 17:34

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoices: 85013683
Date : 09/04/2019
Order : SLS1885P
Term : 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLS1885P (U 35192)

Regn Date: 12/09/2017

Mileage: 31053

WIP No.: 34426

Model: A3 SEDAN 1.0 TFSI 8VMANG

Chassis: WAUZZZ8V2J1013309

Engine: CHZ 528864

Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee

(33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	AND KNEE AIRBAG M: TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT, RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	3000.00	1.00	3,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET	1650.00	1.00	1,650.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8V0880201DNGPS	(A) (GER) AIRBAG (10/12)	1.00	3111.00	2,468.80
X	A8V5880741D	(A) (GER) AIRBAG (10/12)	1.00	1692.00	1,353.60
X	A8V5880742D	(A) (GER) AIRBAG (10/12)	1.00	1692.00	1,353.60
X	A8V2880041D	(A) (SK) AIRBAG (10/12/	1.00	1692.00	1,353.60
X	A500959655BJ	(A) (SK) MODULE (10/12/	1.00	1538.00	1,238.40
X	A8V58675055 YX7	(A) (GER) ROOFLINING (1	1.00	1551.00	1,240.80
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6386 2223
Main Telefax: 6471 2733

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6386 2223
Telefax: 6471 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408701
Telephone: 6386 3023

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6386 2223
6428 1233

Page 3 17:34

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013683 Date : 09/04/2019 Order : SLS1885P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLS1885P (V 35192) Regn Date: 12/09/2017 Mileage: 31053 WIP No.: 34426

Model: A3 SEDAN 1.0 TFSI 8VWANG Chassis: WAUZZZ8V2J1013309 Engine: CHZ 528864 Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	ABV5867233A VUG	(A) (GER)LINING(10/12	Less 020%	1.00	140.50	112.40
X	ABV5867234A VUG	(A) (GER)LINING(10/12	Less 020%	1.00	140.50	112.40
X	ABV0941717B	(V) (Ger)HOSE(11/12/1	Less 020%	1.00	35.40	28.32
X	ABV3853651AA3FZ	GRILLE	Less 020%	1.00	1239.00	991.20
X	ABV0880204B	(A) (SK)AIRBAG(10/12/	Less 020%	1.00	4068.00	3,248.00
X	ABV0941773D	(A) (GER)HEADLIGHT(10	Less 020%	1.00	4088.00	3,910.40
X	ABV5821105A	FENDER	Less 020%	1.00	746.00	596.80
X	ASD0825236Q	BAFFLE	Less 020%	1.00	226.00	180.80
X	ABV5821171G	WHEEL HOUS	Less 020%	1.00	157.50	126.00
X	ASD0816411AS	CONDENSER	Less 020%	1.00	467.50	374.00
X	ABV5807233B	PLATE	Less 020%	1.00	460.00	368.00
X	ABV0805588A	(V) (SK)CARRIER(11/12	Less 020%	1.00	637.50	510.00
X	ABV0807550A	FORM INSER	Less 020%	1.00	172.00	137.60
X	ABV4807109E	BEAM	Less 020%	1.00	632.50	506.00
X	AG A13040M2	PREMIX-COOLANT	Less 020%	4.00	21.00	67.20
X	ABV5823829A	(SK)HOOD	Less 020%	1.00	2755.00	2,204.00
X	ABV5807065R GRU	COVER	Less 020%	1.00	1739.00	1,391.20
X	ABV2857001J 24R	(A) (GER)DASHBOARD(10	Less 020%	1.00	3729.00	2,983.20
Sub-Total						
7% GST						
Grand Total						



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159928
Main Telephone: 6386 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159928
Telephone: 6386 2223
Telefax: 6471 1023

Uli Service Centre
55 Uli Road 1
Singapore 159928
Telephone: 6386 2223

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6386 1523
6386 1233

INS TAX INVOICE

Company Reg. No: 199902271W

GST Reg. No. 199902271W

Page 4 17:34

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013683 Date : 09/04/2019 Order : SLS1885P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLS1885P (V 35192)	Regn Date: 12/09/2017	Mileage: 31053	WIP No.: 34426
Model: A3 SEDAN 1.0 TFSI 8VWANG	Chassis: WAUZZZ8V2J1013309	Engine: CHZ 528864	Dept: U
USB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details		Qty	Unit Price	Amount
X	ZC-801Y4910J-ERP2	ERP LABEL/STICKER 2G	Less 020%	1.00	4.00	3.20
X	ABV0121285A	AIR DUCT	Less 020%	1.00	10.40	8.32
X	ABV0023126B	(SK)EDGING	Less 020%	1.00	24.90	19.92
X	ABV0007217A	COVER	Less 020%	1.00	104.50	83.60
X	ABV5007183	GUIDE	Less 020%	1.00	34.40	27.52
X	ABV5007533A	COVERSTRIP	Less 020%	1.00	148.00	118.40
X	ABV5021467B	BRACKET	Less 020%	1.00	34.70	27.76
X	ABV00857819	ADJUSTER	Less 020%	2.00	171.50	274.40
X	ABV5007681AA9B9	GRILL	Less 020%	1.00	170.50	136.40
X	AAD0260749B	WASHER	Less 020%	1.00	3.00	2.40
X	A3D0260749C	WASHER	Less 020%	1.00	4.00	3.20
X	ABV5057705E V04	(A) (SK)SEAT BELT(10/	Less 020%	1.00	956.00	764.80
X	ABV5057706E V04	(A) (SK)SEAT BELT(10/	Less 020%	1.00	956.00	764.80
X	ABV00857607 M66	(V) (Ger)HANDLE(17/12	Less 020%	2.00	124.00	198.40
X	ABV5007647B 989	GRILLE	Less 020%	1.00	140.00	112.00
X	A5D0959651B	(A) (SK)SENSOR(10/12/	Less 020%	3.00	238.50	572.40
X	ABK0010520A	PLATE	Less 020%	1.00	12.20	9.76
X	ABV0010515A	STICKER	Less 020%	1.00	6.40	5.12

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6366 2222
Fax: 6475 1734

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6366 2222
Telefax: 6475 1022

Ubi Service Centre
55 Ubi Avenue 1
Singapore 408899
Telephone: 6366 2222
GST Reg No. 199902271W

Customer Service
24 Hour Appointment
24 Hour Breakdown Service
6366 2222
6328 1233
customer.zare@premiumauto.com.sg

Page 5 17:34

INS TAX INVOICE

Company Reg No. 199902271W
GST Reg No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013683 Date : 09/04/2019 Order : SLS1885P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLS1885P (V 35192) Regn Date: 12/09/2017 Mileage: 31053 WIP No.: 34426
Model: A3 SEDAN 1.0 TFSI 8VMQNG Chassis: WAUZZZ8V2J1013309 Engine: CHZ 528864 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
X	ABV0121283K	AIR DUCT	1.00	21.40	17.12
X	ABV3853949	PLATE	1.00	166.50	133.20
X	AN 0161857	POP-RIVET	5.00	3.00	12.00
X	AN 91022001	NUT	2.00	1.50	2.40

Parts 30,165.44
Labour 0.00
Sublet 10,227.00
Menus 0.00
Lubricant 0.00

Sub-Total 40,392.44
7% GST 2,827.47
Grand Total 43,219.91



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLS 1885 P

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1390/2018/KS
4TH January 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 SEDAN 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8V2J1013309
Vehicle Regn No. : **SLS 1885 P**
Vehicle Mileage : 31053 KM
Vehicle Owner : Mr. Zou QiBin
Certificate No : 1700050003-01
Own Damage Excess : **WAIVER**
Accident Date : 2/12/2018
Place : Mandai Road going Towards Yishun
Repair Cost : \$ 43,219.91
WIP No. : 34426
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733


Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :


04 Jan 19

TO: MR. ZOU QIBIN
BLK 158 #07-38
CANBERRA DRIVE
THE BROWNSTONE
SINGAPORE - 768083

Tax Invoice GST REG NO M90370246G

VISIT DATE : 02.12.2018 17:59
LOCATION : KCANEP3

This Tax Invoice is for charges incurred at **Khoo Teck Puat Hospital (UEN 200717564H)**

Case/Invoice No	Invoice Date	Outstanding Amount
5718597136Z-00001	02.12.2018	Nil

Patient Name: ZOU QIBIN

Patient ID: S2718987C

Services

	Amount(\$)
A&E Facility/Service Fee	240.00
Less Government Subsidy	-120.00
	<u>120.00</u>

Total Amount Payable

120.00

Total amount payable after GST is \$128.40 .

GST at 7% is absorbed by the Singapore Government: \$8.40

Payer	Adjustment	Payment	Amount Due
ZOU QIBIN	0.00	120.00	0.00

(VISA - 02.12.2018 , RECEIPT #: K003254882)

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2718987C



Name

ZOU QIBIN

郭其滨

Race

CHINESE

Date of birth

07-08-1964

Country/Place of birth

CHINA

Sex
M

S2718987C



REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S2718987C

Name

ZOU QIBIN

Birth Date: 07 Aug 1964

Issue Date: 10 May 2014



002294644C

5399188



NRIC No. S2718987C



Date of issue

10-12-2014

158 CANBERRA DRIVE #07-38
SINGAPORE 788083

NRIC No: S2718987C

Date: 06/03/2018

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)
EFFECTIVE

Class 2 Motor Cars $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of the driver; and other motor vehicles $\leq 2500\text{kg}$ 20 Oct 2005

NP 428A



Licence No: S2718987C



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : ZOU QIBIN
Period of Insurance : 12 Sep 2018 To 11 Sep 2019
Engine No. : CHZ528864
Chassis No. : WAUZZZ8V2J1013309

Vehicle No. : SLS1885P
Policy No. : 1700050003-01
Endorsement No. :
Issued Date : 24 Aug 2018

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PARF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

ZOU QIBIN - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 8200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG S/G Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

3504125268

PREMIUM LEASING -MPL

81 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. J. J. J.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

58PSLT

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Dec 2018		05 Dec 2018 11:46 Edit Adj Rpt	\$40,392.44 Edit Estimates	\$40,392.44 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured: ZOU QIBIN , ID: S2718987C, Tel: +6581399558, Email: MAXZOU.ERA@GMAIL.COM									
Vehicle Reg. No.: SLS1885P		Date of Loss: 02/12/2018 16:00 - :59 [14 Months and 20 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 3216280155SG		Policy/Cover Note No.: 1700050003 (Comprehensive)							
		Excess: \$50.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 14/12/2018]									
Driver/Custodian: ZOU QIBIN (54 / Male) , NRIC: S2718987C, Tel: +6581399558 Email: MAXZOU.ERA@GMAIL.COM									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (03/01/2019): Alert - Adj Mandate Approved (\$42865.00) - SLS1885P - Claim Handler: Mohd Zaway... - AIG_SG (07/12/2018): Alert - Adj Mandate Approved (\$41926.00) - SLS1885P - Claim Handler: Loo, Tong ... - AIG_SG (06/12/2018): SLS1885P / OD / 02/12/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS1885P (3216280155SG)
OD
Dec 2 2018 4:00PM
[ZOU QIBIN]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page			☒		
No	Finalized On		Premium Automobiles Pte Ltd (UBI)												Thumbnail			Print		
1	03/12/18 16:13		Video - Accident [Linked Accident Report Documents]												1			Load MP4		
Assessment Reports															1 per page			☒		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	05/12/18 17:24		Adjuster Immediate Advice												1			Load HTM		
2	05/12/18 17:39		Adjuster Immediate Advice												1			Load HTM		
3	06/12/18 14:12		Adjuster Immediate Advice												1			Load HTM		
4	02/01/19 14:49		Adjuster Immediate Advice												1			Load HTM		
Photos/Images															3 per page			☒		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	05/12/18 15:26		General View												1			Load JPG		
2	05/12/18 15:26		Chassis Number												1			Load JPG		
3	05/12/18 15:26		General View												1			Load JPG		
4	05/12/18 15:26		General View												1			Load JPG		
5	05/12/18 15:26		General View												1			Load JPG		
6	05/12/18 15:26		General View												1			Load JPG		
7	05/12/18 15:26		General View												1			Load JPG		
8	05/12/18 15:26		General View												1			Load JPG		
9	05/12/18 15:26		General View												1			Load JPG		
10	05/12/18 15:26		General View												1			Load JPG		
11	05/12/18 15:26		General View												1			Load JPG		
12	05/12/18 15:26		General View												1			Load JPG		
13	05/12/18 15:26		General View												1			Load JPG		
14	05/12/18 15:26		General View												1			Load JPG		
15	05/12/18 15:26		General View												1			Load JPG		
16	05/12/18 15:26		General View												1			Load JPG		
17	05/12/18 15:26		General View												1			Load JPG		
18	05/12/18 15:26		General View												1			Load JPG		
19	05/12/18 15:26		General View												1			Load JPG		
20	05/12/18 15:26		General View												1			Load JPG		
21	05/12/18 15:26		General View												1			Load JPG		
22	05/12/18 15:26		General View												1			Load JPG		
23	05/12/18 15:26		General View												1			Load JPG		
24	05/12/18 15:26		General View												1			Load JPG		
25	05/12/18 15:26		General View												1			Load JPG		
26	05/12/18 15:26		General View												1			Load JPG		
27	05/12/18 15:26		General View												1			Load JPG		
28	05/12/18 15:26		General View												1			Load JPG		
29	05/12/18 15:26		General View												1			Load JPG		

Video			1 per page	☒
No.	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
30	05/12/18 15:26	General View	 Load JPG	☒
31	05/12/18 15:26	General View	 Load JPG	☒
32	05/12/18 15:26	General View	 Load JPG	☒
33	05/12/18 15:26	General View	 Load JPG	☒
34	05/12/18 15:26	General View	 Load JPG	☒
35	05/12/18 15:26	General View	 Load JPG	☒
36	05/12/18 15:26	General View	 Load JPG	☒
37	05/12/18 15:26	General View	 Load JPG	☒
38	05/12/18 15:26	General View	 Load JPG	☒
39	05/12/18 15:26	General View	 Load JPG	☒
40	05/12/18 15:26	General View	 Load JPG	☒
41	05/12/18 15:26	General View	 Load JPG	☒
42	05/12/18 15:26	General View	 Load JPG	☒
43	05/12/18 15:26	General View	 Load JPG	☒
44	05/12/18 15:26	General View	 Load JPG	☒
45	05/12/18 15:26	General View	 Load JPG	☒
46	05/12/18 15:26	General View	 Load JPG	☒
47	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
48	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
49	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
50	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
51	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
52	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
53	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
54	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
55	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
56	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
57	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
58	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
59	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
60	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
61	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
62	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
63	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
64	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
65	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
66	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
67	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
68	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
69	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
70	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
71	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
72	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
73	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
74	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
75	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
76	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
77	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
78	02/01/19 14:52	Reinspection Photo	 Load JPG	☒
79	02/01/19 14:52	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
80	02/01/19 14:52	Reinspection Photo	Load JPG	☒
81	02/01/19 14:52	Reinspection Photo	Load JPG	☒
82	02/01/19 14:52	Reinspection Photo	Load JPG	☒
83	02/01/19 14:52	Reinspection Photo	Load JPG	☒
84	02/01/19 14:52	Reinspection Photo	Load JPG	☒
85	02/01/19 14:52	Reinspection Photo	Load JPG	☒
86	02/01/19 14:52	Reinspection Photo	Load JPG	☒
87	02/01/19 14:52	Reinspection Photo	Load JPG	☒
88	02/01/19 14:52	Reinspection Photo	Load JPG	☒
89	02/01/19 14:52	Reinspection Photo	Load JPG	☒
90	02/01/19 14:52	Reinspection Photo	Load JPG	☒
91	02/01/19 14:52	Reinspection Photo	Load JPG	☒
92	02/01/19 14:52	Reinspection Photo	Load JPG	☒
93	02/01/19 14:52	Reinspection Photo	Load JPG	☒
94	02/01/19 14:52	Reinspection Photo	Load JPG	☒
95	02/01/19 14:52	Reinspection Photo	Load JPG	☒
96	02/01/19 14:52	Reinspection Photo	Load JPG	☒
97	02/01/19 14:52	Reinspection Photo	Load JPG	☒
98	02/01/19 14:52	Reinspection Photo	Load JPG	☒
99	02/01/19 14:52	Reinspection Photo	Load JPG	☒
100	02/01/19 14:52	Reinspection Photo	Load JPG	☒
101	02/01/19 14:52	Reinspection Photo	Load JPG	☒
102	02/01/19 14:52	Reinspection Photo	Load JPG	☒
103	02/01/19 14:52	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/12/18 15:25	ESTIMATE.pdf	Load PDF	
2	05/12/18 15:25	DRIVING & INS CERT DOC.pdf	Load PDF	
3	05/12/18 17:39	Audi NEW CAR PRICE LIST.pdf	Load PDF	
4	02/01/19 14:50	SUPPLEMENTARY 1.pdf	Load PDF	
5	02/01/19 14:50	SALES AGREEMENT.pdf	Load PDF	
6	28/03/19 10:14	ESTIMATE & SUPPLEMENTARY MARKED.pdf	Load PDF	
7	30/04/19 17:54	Workshop Invoice	Load PDF	
8	30/04/19 17:54	Discharge Voucher	Load PDF	

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	03/12/18 16:13	Video - Accident	Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	03/12/18 16:58	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	03/12/18 16:08	Police Report	Load JPG	☒
2	03/12/18 16:08	Police Report	Load JPG	☒
3	03/12/18 16:08	Police Report	Load JPG	☒
4	03/12/18 16:10	Accident Photo	Load JPG	☒

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
5	03/12/18 16:10	Accident Photo	 Load JPG	☒
6	03/12/18 16:10	Accident Photo	 Load JPG	☒
7	03/12/18 16:10	Accident Photo	 Load JPG	☒
8	03/12/18 16:10	Accident Photo	 Load JPG	☒
9	03/12/18 16:10	Accident Photo	 Load JPG	☒
10	03/12/18 16:10	Accident Photo	 Load JPG	☒
11	03/12/18 16:10	Accident Photo	 Load JPG	☒
12	03/12/18 16:10	Accident Photo	 Load JPG	☒
13	03/12/18 16:10	Accident Photo	 Load JPG	☒
14	03/12/18 16:10	Accident Photo	 Load JPG	☒
15	03/12/18 16:10	Accident Photo	 Load JPG	☒
16	03/12/18 16:10	Accident Photo	 Load JPG	☒
17	03/12/18 16:10	Accident Photo	 Load JPG	☒
18	03/12/18 16:10	Accident Photo	 Load JPG	☒
19	03/12/18 16:10	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	03/12/18 16:53	Sketch Plan	 Load JPG	☒
2	03/12/18 16:53	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sun@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18021882/ASBE2

Date: 02/05/2019

REFERENCE

Insured/Claimant: ZOU QIBIN Policy No: 1700050003
Date of Loss: 02/12/2018 Nature of Claim: OD Claim No: 3216280155SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS1885P**
Make & Model: AUDI A3, 999cc TFSI (A) Engine No: CHZ528864
Reg. Date: 12/09/2017 (Man. Year: 2017) Chassis No: WAUZZZ8V2J1013309
Colour: White Odometer: 26858 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$95,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	46,565.72	30,190.44	16,375.28	35.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,032.00	10,202.00	2,830.00	21.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	59,597.72	40,392.44	19,205.28	32.22
+ GST 7.00/7.00% (S\$)	4,171.84	2,827.47	1,344.37	32.22
Nett Amount (S\$)	63,769.56	43,219.91	20,549.65	32.22

INSPECTION

Date of Assignment: 05/12/2018
Date Inspected: 04/12/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 21.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Distorted	1,739.00 FS	*1,391.20 FS
2	1	*FIXING PARTS FOR FRONT BUMPER	Not Necessary	161.00 FS	*- FS
3	1	*GUIDE SECTION - LH	Damaged	33.00 FS	*27.52 FS
4	1	*LOWER CENTRE GRILLE - CENTRE	Cracked	140.00 FS	*112.00 FS
5	1	*CLOSING ELEMENT - LOWER CENTRE	Cracked	460.00 FS	*368.00 FS
6	1	*CLOSING ELEMENT - LH	Not Necessary	254.00 FS	*- FS
7	1	*COVER TRIM - LH	Deformed	140.00 FS	*118.40 FS
8	1	*ADAPTER WHEEL HOUSING LINER - LH	Not Necessary	32.00 FS	*- FS
9	1	*RADIATOR GRILLE	Cracked	1,239.00 FS	*991.20 FS
10	1	*CLOSING ELEMENT	Torn	167.00 FS	*133.20 FS
11	1	*AIR GUIDE GRILLE - LH	Missing	164.00 FS	*136.40 FS
12	1	*SIDE REINFORCEMENT	Bent	633.00 FS	*506.00 FS
13	1	*FOAM FILLER PIECE	Cracked	162.00 FS	*137.60 FS
14	1	*COVER	Torn	105.00 FS	*83.60 FS
15	1	*FRONT FENDER - LH	Buckled	746.00 FS	*596.80 FS
16	1	*ATTACHMENT PARTS FOR FENDER	Not Necessary	62.00 FS	*- FS
17	1	*BRACKET FOR FENDER	Bent	34.00 FS	*27.76 FS
18	1	*FRONT FENDER BRACE - LH	Not Necessary	84.00 FS	*- FS
19	1	*WHEEL HOUSING LINER - LH	Torn	151.00 FS	*126.00 FS
20	1	*ATTACHMENT PARTS FOR WHEEL HOUSING LINER	Not Necessary	77.00 FS	*- FS
21	1	*BONNET	Dented	2,755.00 FS	*2,204.00 FS
22	1	*ATTACHMENT PARTS FOR BONNET	Not Necessary	141.00 FS	*- FS
23	2	*LID HINGE - LH/RH	Not Necessary	106.00 FS	*- FS
24	1	*FRONT BONNET STRUT	Not Necessary	105.00 FS	*- FS
25	1	*CATCH HOOK	Not Necessary	78.00 FS	*- FS
26	2	*STRIKER - LH/RH	Not Necessary	192.00 FS	*- FS
27	1	*EDGE PROTECTOR	Necessary	24.00 FS	*19.92 FS
28	1	*CATCH HOOK	Not Necessary	55.00 FS	*- FS
29	1	*BOWDEN CABLE - CENTRE	Not Necessary	50.00 FS	*- FS
30	1	*LID LOCK CABLE	Not Necessary	64.00 FS	*- FS
31	1	*HORN - HIGH TONE LH	Not Necessary	177.00 FS	*- FS
32	1	*LED HEADLIGHT - LH	Cracked	4,888.00 FS	*3,910.40 FS
33	1	*POWER MODULE FOR MAIN LIGHT ELECTRONICS	Not Necessary	665.00 FS	*- FS
34	1	*LED WITH HEAT SINK - LH	Not Necessary	625.00 FS	*- FS
35	1	*CONTROL UNIT FOR LIGHT CONTROL SYSTEM	Not Necessary	486.00 FS	*- FS
36	1	*WASHER TANK RESERVOIR	Not Necessary	177.00 FS	*- FS
37	1	*HEADLIGHT LIFT CYLINDER - LH	Not Necessary	123.00 FS	*- FS
38	1	*HOSE	Not Necessary	57.00 FS	*- FS
39	1	*FRONT LOCK CARRIER FOR RADIATOR	Cracked	638.00 FS	*510.00 FS
40	1	*AIR GUIDE - LH/RH	O/S Deformed	40.00 FS	*17.12 FS
41	1	*RADIATOR FAN WITH FAN RING	Not Necessary	1,425.00 FS	*- FS
42	1	*INTERCOOLER	Not Necessary	828.00 FS	*- FS
43	1	*ADDITIONAL COOLER FOR COOLANT	Not Necessary	797.00 FS	*- FS
44	4	*COOLANT	Necessary	133.00 FS	*67.20 FS
45	1	*A/C CONDENSER	Bent	468.00 FS	*374.00 FS
46	1	*FRONT RIM - LH	Not Necessary	659.00 FS	*- FS
47	4	*RUBBER VALVE	Not Necessary	12.00 FS	*- FS
48	1	*FRONT NUMBER PLATE	Dented	25.00 FS	*25.00 FS
49	1	*STEERING AIRBAG	Activated	3,111.00 FS	*2,488.80 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
50	1	*FRONT DASHBOARD AIRBAG - LH	Activated	4,060.00 FS	*3,248.00 FS
51	2	*HEAD AIRBAG - LH/RH	Activated	3,384.00 FS	*2,707.20 FS
52	2	*C PILLAR AIR BAG GUIDE - LH/RH	Not Necessary	44.00 FS	*- FS
53	1	*KNEE AIR BAG	Activated	1,692.00 FS	*1,353.60 FS
54	1	*KNEE AIRBAG TRAY COVER PANEL	Not Necessary	397.00 FS	*- FS
55	1	*CONTROL UNIT FOR AIRBAG	Activated	1,538.00 FS	*1,230.40 FS
56	3	*CRASH SENSOR FOR AIRBAG	Activated	716.00 FS	*572.40 FS
57	1	*DASHBOARD WITH AIR DUCT	Torn	3,729.00 FS	*2,983.20 FS
58	1	*ROOF LINER	Crumpled	1,551.00 FS	*1,240.80 FS
59	2	*THREE POINT SEAT BELT WITH TENSIONER - LH/RH	Activated	1,912.00 FS	*1,529.60 FS
60	2	*SEAT BELT HEIGHT ADJUSTER	Damaged	343.00 FS	*274.40 FS
61	1	*A PILLAR TRIM - LH - ROCK GREY	Cut	141.00 FS	*112.40 FS
62	1	*A PILLAR TRIM - RH UPPER - ROCK GREY	Cut	141.00 FS	*112.40 FS
63	1	*SUNDRIES	Necessary	1,000.00 FS	*23.20 FS
64	1	*NOISE INSULATION	Cracked	180.80 FS	*180.80 FS
65	1	*AIR COND STICKER	Necessary	5.12 FS	*5.12 FS
66	1	*CAUTION STICKER	Necessary	9.76 FS	*9.76 FS
67	1	*HEADLIGHT VENT HOSE	Missing	28.32 FS	*28.32 FS
68	1	*LOCK CARRIER AIR GUIDE	Cracked	8.32 FS	*8.32 FS
69	2	*GRAB HANDLE	Damaged	198.40 FS	*198.40 FS
F=Franchise part. S=SpcNett.					
Total Parts (S\$)				46,565.72	30,190.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND RENEW AIR-CON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,000.00	1,000.00
3	TO REMOVE CENTRE CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING, BOTH CURTAIN AIR BAGS AND KNEE AIRBAG	New	3,600.00	3,600.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,500.00	3,000.00
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND HINGES	New	2,700.00	1,650.00
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT. INSPECT FRONT SUSPENSION ASSY FOR FURTHER DAMAGES	New	280.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO SUPPLY AND REINSTALL SOLAR FILM	New	400.00	400.00
Gross Labour Cost (S\$)			13,032.00	10,202.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >