

ASS. REC. BY:

REF:

CS/FCL18021901/Usbnz

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

CWS Karen Tan

of

FCL

Date/Time:

05122018 506pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 8237B

Insured:

SHC 1906U

at Workshop m/s

Focus Auto

Tel:

6886 9097

of

Blk 1 Kaki Bukit Ave 6 #02-50

Policy No:

Claim No:

D18008605MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

04122018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

05122018 512pm

Person Contacted:

Sim

Vehicle (IN) OUT

Date/Time

Action/Instruction (✓) Estimate

GBF 8237B x

SHC 1906U - CS/FCL18017261/Ttd3

DATA: 18092018

06/12/18

@ 17:39 p.m. revised PA to Karen Tan via email.

(08/11/13) wef

ASS. REQ. BY: Marcus

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

G/A PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

3500

RECEIVED 7 DEC 2018

Date/Time, File Pass to?

07/12/13

1)

Typist

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 3,500/- HS)

150

50

50

75

325

7/12/13 confirmed H/S & 3500 with MR way.

07/12/13 confirmed HS & 3,500/- @ 5 days with Marcus
(3,592.91 Red - 51%)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008605MFSH

Date: 06 December 2018

Our Ref: CS/FCI18021909/Usb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GBF 8237B .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 05/12/2018 at the premises of M/s Focus Auto Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 7,092.91 .
Revised Estimate Amount	: S\$ 4,421.52 .
"Check" Items Amount	: S\$.
Market Value	: S\$.
LTA Reimbursement Value	: S\$.
Nett Value	: S\$.

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 5 Days

Yours faithfully,
Marcus Chua
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	05-12-2018	Our Ref No. D18008605MFSH
Accident Date	04-12-2018	Claim Type. Third Party
Insured Vehicle	SHC1906U	Third Party Vehicle. GBF8237B
Survey Location	NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-50	
Contact Person.	SIN	
Contact No.	68869097/0	Fax No. 64819095
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	FOCUS AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Foru

- Stop comparing Spore cars to other countries
- Comments on Mazda CX5
- The continuing GLOBAL stressful thread! Part II

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad


Advertiser Login

Ways of Selling

Excellent Condition Honda Civic 2.0 A



Done Only 118,000 Km, Great Running Condition, Well Maintained Thru Out, Direct Owner StarAd



Browse by Category ▼

Sort by Date Posted

16 vehicles

Toyota Hiace

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh
Search Selection	Toyota Hiace		Any	Any	2017	Any	Any	
	Toyota Hiace		\$57,800	\$6,860 /yr	08-May-2017	2,982 cc	-	
	Fuel Type: Diesel							
	Posted: 04-Dec-2018 Tags: 2017 Toyota Hiace, 2017 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota							
	Toyota Hiace		\$59,800	\$6,950 /yr	13-Jul-2017	2,982 cc	-	
	Fuel Type: Diesel							
	Used For Only A Year, Well Kept And Maintained By Owner! No Repairs Needed. Under Warranty. Monthly Cheaper Than Rental, High Loan Call Now To View!							
	ABWIN (1994) Pte Ltd							
	Posted: 03-Dec-2018 Tags: 2017 Toyota Hiace, 2017 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota							
	Toyota Hiace Commuter		\$111,900	\$13,330 /yr	27-Apr-2017	2,982 cc	10,100 km	
	Fuel Type: Diesel							
	Look No Further, Superbly Low Mileage. Best Value For Your Money. Beautiful Hiace Commuter GL 3.0 Auto With Brown-Black Leather Uphc Owned By 1 Private Owner. Selling Due To Upgrading To New Car...							
	Posted: 03-Dec-2018 Tags: 2017 Toyota Hiace, 2017 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota							
	Toyota Hiace		\$58,800	\$6,900 /yr	13-Jun-2017	2,982 cc	-	
	Fuel Type: Diesel							
	\$1 Driveaway Available! Cheaper Than Rental! Renowned For Durability And Reliability! Engine And Gearbox In Excellent Condition! High Tr Your Vehicle! Call Our Friendly Sales Exec For A No O...							
	Posted: 28-Nov-2018 Tags: 2017 Toyota Hiace, 2017 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota							
	Hanip Automobiles Pte Ltd - Repair & Servicing							
	Hanip Automobiles is one of the few workshops in Singapore which is owned, run and operated by a former diagnostic specialist and master							
	More info about this shop							
	Toyota Hiace		\$57,800	\$6,830 /yr	23-May-2017	2,982 cc	38,000 km	
	Fuel Type: Diesel							
	***!! ***!!-tained! Engine And Gearbox In Superb Condition. Agent Unit Vehicle.Warranty Still Valid With 2 Free Servicing From Borneo Motor							
	High Loan And Trade In Welcomed! Call Now ...							
	e Ltd							

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 6 December 2018 5:39 PM
To: 'Karen Tan'; 'CWS Motor Claims'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: SURVEY ASSESSMENT - D18008605MFSH/1
Attachments: GBF 8237B - Preli Advise.pdf

Dear Karen,

Enclosed preliminary revised of vehicle GBF 8237B.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 5 December 2018 5:11 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008605MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 5 December, 2018 5:06 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008605MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Business

Owner ID:

3674D

Vehicle Details

Vehicle No.:

GBF8237B

Vehicle to be Exported:

No

Intended Deregistration Date:

04 Dec 2018

Vehicle Make:

TOYOTA

Vehicle Model:

HIACE 3.0 DX AT

Primary Colour:

Silver

Manufacturing Year:

2016

Engine No.:

1KD2667219

Chassis No.:

KDH2010210885

Maximum Power Output:

-

Open Market Value:

\$32,536.00

Original Registration Date:

20 Mar 2017

First Registration Date:

20 Mar 2017

Transfer Count:

0

Actual ARF Paid:

\$1,627.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

19 Mar 2027

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

PQP Paid:

\$46,575.00

COE Rebate Amount:

\$38,612.00

Total Rebate Amount:

\$38,612.00

The information contained herein is correct as at 04 Dec 2018

OK

not Authorized LPR 4/5 3500 5/12/18 take photo of the car FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6841 9095 Email: focusautopte@vahoo.com.sg

GST:201004495R RCB NO:201004495R

M/S: FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

TEL: 6507 3848

FAX: 6507 3849

ATTN: Motor Claim Department

Your Ref No: GBF8237B

Claim Type: Third Party

Accident Date: 04-12-2018

TP Veh Reg No: SHC1906U

Estimate No:

EST0000762

Date:

05 Dec 2018

Policy No:

DMCVSN1806991800

Veh Reg No:

GBF8237B

Make/Model:

TOYOTA HIACE 3.0 DX
AT

Chassis No:

KDH2010210885

Engine No:

1KD2667219

Reg. Date:

20-03-2017

Estimate Repair Cost to Vehicle No :GBF8237B

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
TOYOTA HIACE 3.0 DX AT				
List Price				
1 Rear Boot	2,250.0000	1 PC	2,250.00	X
2 Rear Boot Lock	275.0000	1 PC	275.00	✓
3 Rear Boot Lock Catch	48.5000	1 PC	48.50	X
4 Rear Boot Lock Cover	40.2000	1 PC	40.20	✓
5 Rear Boot Emblem (HIACE)	65.0000	1 PC	65.00	✓
6 Rear Boot Centre Logo	75.0000	1 PC	75.00	✓
7 Rear End Panel Inner	890.0000	1 PC	890.00	✓
8 Rear End Panel Outer	544.5000	1 PC	544.50	✓
9 Rear Boot Rubber	395.0000	1 PC	395.00	✓
10 Rear Bumper	445.0000	1 PC	445.00	✓
11 Rear Bumper Inner Centre Step Bracket	242.0000	1 PC	242.00	✓
12 Rear Bumper Lower Bracket	46.0000	4 PC	184.00	✓
13 Rear Bumper Lower Clipse	5.5000	6 PC	33.00	✓
14 Rear Bumper Side Retainer	55.0000	2 PC	110.00	X
			5,597.20	3188.7
			Less 25%	2391.52
			1,399.30	4,197.91
Special Net				
15 Rear Boot Sticker 70km/h	15.0000	1 PC	15.00	10
16 Rear Bumper Sensor	300.0000	1 SET	300.00	200
17 Rear Windscreen Gum	80.0000	1 PC	80.00	X
			395.00	395.00
Labour				
18 Panel Beating	1,200.0000	1 PC	1,200.00	1000
19 Check Wiring	80.0000	1 PC	80.00	20
20 Rust Proofing	80.0000	1 PC	80.00	50
21 To Remove & Refit Rear Windscreen	160.0000	1 PC	160.00	X
22 To Remove & Replace Bumper Sensor	80.0000	1 PC	80.00	50
23 To Spray Painting	900.0000	1 PC	900.00	700
			2,500.00	2,500.00
			Total	SS 7,092.91

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND NINETY TWO AND CENTS NINETY ONE ONLY

For FOCUS AUTO PTE LTD

Focus Auto Pte Ltd

No 1 Kaki Bukit Ave 6 Auto Bay

#02-50 Singapore 417883

AUTHORISED SIGNATURE

tel: 68869095



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18021909/Usbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 10-12-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1906U	Veh. Inspected	GBF 8237B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008605MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	05/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE DX (A)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KDH2010210885	Colour	SILVER	
Odometer	65904	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	GREMAX	6 mm	
L/H Front Tyre	195 R15	GREMAX	6 mm	
R/H Rear Tyre	195 R15	GREMAX	6 mm	
L/H Rear Tyre	195 R15	GREMAX	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/12/2018	Inspection Date	05/12/2018	
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 8237B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT	TO REPAIR SEE LABOUR	2,250.00	-
1	REAR BOOT LOCK	TWISTED / JAMMED	275.00	275.00
1	REAR BOOT LOCK CATCH	NOT NECESSARY	48.50	-
1	REAR BOOT LOCK COVER	DEFORMED / TORN	40.20	40.20
1	REAR BOOT EMBLEM (HIACE)	NECESSARY	65.00	65.00
1	REAR BOOT CENTRE LOGO	NECESSARY	75.00	75.00
1	REAR END PANEL INNER	BADLY DENTED	890.00	890.00
1	REAR END PANEL OUTER	BADLY DENTED	544.50	544.50
1	REAR BOOT RUBBER	TWISTED	395.00	395.00
1	REAR BUMPER	DENTED	445.00	445.00
1	REAR BUMPER INNER CENTRE STEP BRACKET	BENT	242.00	242.00
4	REAR BUMPER LOWER BRACKET @\$46.00	BENT	184.00	184.00
6	REAR BUMPER LOWER CLIPSE @\$5.50	NECESSARY	33.00	33.00
2	REAR BUMPER SIDE RETAINER @\$55.00	NOT NECESSARY	110.00	-
	LESS 25% DISCOUNT		-1,399.30	-797.18
			4,197.90	2,391.52
SPECIAL NETT ITEMS				
1	REAR BOOT STICKER 70KM/H (SN)	NECESSARY	15.00	10.00
1	SET REAR BUMPER SENSOR (SN)	SHORTED	300.00	200.00
1	REAR WINDSCREEN GUM (SN)	NOT NECESSARY	80.00	-
			395.00	210.00
LABOUR				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BOOT.		1,200.00	1,000.00
	CHECK WIRING.		80.00	20.00
	RUST PROOFING.		80.00	50.00
	TO REMOVE & REFIT REAR WINDSCREEN.	NOT NECESSARY	160.00	-
	TO REMOVE & REPLACE BUMPER SENSOR.		80.00	50.00

Report Ref No. CS/FCI18021909/Usbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINTING.		900.00	700.00
			2,500.00	1,820.00
GRAND TOTAL			7,092.90	4,421.52
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,500.00

Report Ref No. CS/FCI18021909/Usbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.