

INS. CASE OWNER:

CC 6, ALA 180

LKK:
IDAC:

Surveyor:

MRE

DOI:

ASSIGNMENT

304118

Date / Time:

30-11-18

Registered in Merimen:

5/12/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLN 6449J

Claim No.:

Name of Insured:

Tay Jio Joo Jeremy

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :S\$

D.O.A.:

24/11/18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SLN 6449J

SJN 17427

SJES7765



INSRS:

WSP:

Tel:

Liability:

RMKS:

07



INSRS:

WSP:

Tel:

Liability:

RMKS:

78



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

11/12/18
Jog

SJN 17427 - X, SLN 6449J - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

14-1-19 @ 256 PM W/ OI MR TAN
CONFIRMED, AGREED
& AWARE NCD ISSUE.

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

5,136.xx

Loss of Rental (LOR):

S\$

500

(550 x 10 days)

Loss of Use (LOU):

S\$

500

(550 x 10 days)

Loss of Income (LOI):

S\$

-

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

5,636

Global Sum S\$:

5,635

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$

5,635.xx

Name 1:

TAN LIM MOTOR PTE LTD

Payee 2: (Strike if N.A.)

S\$

X

Name 2:

X

Payee 3: (Strike if N.A.)

S\$

X

Name 3:

X

GRT 1/19/18

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 4053H

Vehicle Details

Vehicle No.: SJN1742T
Vehicle to be Exported: No
Intended Deregistration Date: 30 Nov 2018
Vehicle Make: NISSAN
Vehicle Model: LATIO SPORT BASE 1.5L AT ABS D/AB 2WD 5D
Primary Colour: Grey
Manufacturing Year: 2008
Engine No.: HR15080948B
Chassis No.: JN1FAAC11Z0010456
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$18,906.00
Original Registration Date: 06 Feb 2009
First Registration Date: 06 Feb 2009
Transfer Count: 0
Actual ARF Paid: \$18,906.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 05 Feb 2019
PARF Rebate Amount: \$9,453.00

Intended COE Rebate Details

COE Expiry Date: 05 Feb 2019
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$3,200.00
COE Rebate Amount: \$48.00
Total Rebate Amount: \$9,501.00

The information contained herein is correct as at 30 Nov 2018

OK



陳林峰有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLN6449J
Date of Accident : 24 November 2018

Mr Nayagam Anthony

Date : 30 November 2018

Estimate To Repair SJN1742T - NISSAN LATIO 1.5 4AT SPORT BASE ABS
Chassis No : JN1FAAC11Z0010456

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	tailgate lid <i>TH</i> ✓	\$ 1,314.70
02	1 pc	tailgate lid outer handle <i>repair</i>	\$ 88.90
03	1 pc	tailgate lid inner trimboard bottom <i>X nn</i>	\$ 256.00
04	1 pc	rear end panel <i>TH</i> ✓	\$ 442.60
05	1 pc	rear bumper <i>DE</i> ✓	\$ 651.00
06	2 ps	rear bumper side retainer @ \$25.00 <i>nn</i> ✓	\$ 50.00
07	1 pc	rear bumper inner sponge <i>DE</i> ✓	\$ 38.60
08	1 pc	rear licence plate bracket <i>TH</i> ✓	\$ 55.00
09	1 pc	rear licence plate lamp <i>X nn</i>	\$ 54.00
10	1 pc	tailgate lid rubber <i>nn</i> ✓	\$ 98.30
11	1 pc	rear exhaust box <i>X nn</i>	\$ 513.10
12	1 pc	rear exhaust box heat shield <i>X nn</i>	\$ 95.00
13	2 ps	rear exhaust box mounting @ \$65.00 <i>X nn</i>	\$ 130.00
14	1 pc	front bumper <i>DE</i> ✓	\$ 456.30
15	2 ps	front bumper side retainers @ \$33.00 <i>nn</i> ✓	\$ 66.00
16	1 pc	right headlamp assy <i>X nn</i>	\$ 486.30
17	1 pc	front bumper fog lamp right <i>X nn</i>	\$ 320.70
18	16 ps	front and rear bumper clips @ \$4.50 <i>nn</i> ✓	\$ 72.00
19	1 pc	radiator grille garnish <i>X nn</i>	\$ 48.30
20	6 ps	radiator grille garnish clips @ \$4.50 <i>X nn</i>	\$ 27.00
			\$ 5,263.80
Less 30 %			\$ 1,579.14
			\$ 3,684.66
<u>NETT ITEMS</u>			
21	2 ps	rear lamps @ \$319.40 <i>CR</i> ✓	\$ 638.80
22	1 pc	tailgate lid wiper cover <i>X nn</i>	\$ 55.00
23	1 pc	tailgate lid Latio badge <i>nn</i> ✓	\$ 56.20
24	1 pc	tailgate lid centre emblem badge <i>nn</i> ✓	\$ 45.60
25	1 pc	tailgate lid inner lock <i>TH</i> ✓	\$ 143.10
26	1 pc	tailgate lid inner lock motor <i>X nn</i>	\$ 253.70
27	1 pc	tailgate lid windscreen glass moulding <i>nn</i> ✓	\$ 128.70
28	1 pc	rear end panel inner trimboard <i>DE</i> ✓	\$ 73.10
29	1 pc	front radiator grille <i>X nn</i>	\$ 395.30
			\$ 1,789.50
Less 10 %			\$ 178.95
			\$ 1,610.55
<u>SPECIAL NETT ITEMS</u>			
30	1 pc	tailgate lid windscreen inner sponge seal <i>nn</i> ✓	\$ 40 50.00
31	1 pc	tailgate lid windscreen sealant <i>nn</i> ✓	\$ 60 100.00



陳林坤摩私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLN6449J
Date of Accident : 24 November 2018

Mr Nayagam Anthony

Date : 30 November 2018

Estimate To Repair SJN1742T - NISSAN LATIO 1.5 4AT SPORT BASE ABS
Chassis No : JN1FAAC11Z0010456

S/No	Quantity	Description	Amount
		SPECIAL NETT ITEMS	
32	1 pc	rear licence plate <i>PK</i>	\$ 35 80.00
33	1 pc	rear bumper parking sensor <i>nu</i>	\$ 200 450.00
			\$ 690.00
		LABOUR & MISC. CHARGES	
01		To check electrical lighting concerned.	\$ 60.00 30
02		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 200.00 100
03		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 150.00 80
04		To remove and refit rear windscreen glass.	\$ 150.00 120
05		To reinstall of rear bumper parking sensor.	\$ 100.00 60
06		To drop rear exhaust box and renew the same.	\$ 200.00
07		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,600.00 1000
08		Putty and spray painting of the affected portion.	\$ 1,200.00 1000
			\$ 3,660.00
		Total	\$ 9,645.21

Resue
Hp 90010068
9 days / L/S
30/11/18 @ 1225
Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting.
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Ownership Details	
Owner ID Type:	Singapore NRIC
Owner ID:	4053H
Vehicle Details	
Vehicle No.:	SJN1742T
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Dec 2018
Vehicle Make:	NISSAN
Vehicle Model:	LATIO SPORT BASE 1.5L AT ABS D/AB 2WD 5D
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	HR15080948B
Chassis No.:	JN1FAAC11Z0010456
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$18,906.00
Original Registration Date:	06 Feb 2009
First Registration Date:	06 Feb 2009
Transfer Count:	0
Actual ARF Paid:	\$18,906.00
Intended PARF/COE Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Feb 2019
PARF Rebate Amount:	\$9,453.00
Intended COE Rebate Details	
COE Expiry Date:	05 Feb 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$3,200.00
COE Rebate Amount:	\$45.00
Total Rebate Amount:	\$9,498.00

The information contained herein is correct as at 04 Dec 2018

OK

10,000
9498
502



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Address: 51 Defu Lane 10 Singapore 539216

Tel: 6858 5151 Fax: 6858 0877

Our Ref : TP038112018

Date : 09/01/2019

Your Ref : CC6/AIG18021957/R1ja3

WITHOUT PREJUDICE

AIG Asia Pacific Insurance Pte Ltd

Attn: Ms Joy Irene

Dear Sir/Madam,

ACCIDENT INVOLVING SJN1742T & SLN6449J ON 24.11.2018

We refer to the above accident.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

☐ Original survey report/_____ copies of photographs

☒ Original Tax-Invoice number

☐ Original rental invoice number

☒ SAS / AS & IS / police report

☐ police result

☐ Certificate Of Insurance

☐ Vehicle search result

☒ Authorisation To Act

☐ _____

*Survey under insurance instruction –

a)	Cost of repair (inclusive GST)	\$	5,136.00
b)	Survey fees / Photographs as per request	\$	
c)	Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$	
d)	Loss of hire / use / rental / earnings / rental fees <i>[R100 x 10 days]</i>	\$	1,000.00
e)	Scene photographs	\$	
f)	Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$	
g)	Admin fee	\$	300.00
Total		\$	<u>6,436.00</u>

* Driver's injury and other losses exclude in this claim.

Please acknowledge receipt of this letter within 14 days.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Tan Lim Motor Pte Ltd" within 28 days.

Yours faithfully,

Johnson Chua

Email: johnson.chua@tlmotor.com.sg

Joy Irene (LKKAUTO)

From: Joy Irene (LKKAUTO)
Sent: Monday, 14 January 2019 3:35 PM
To: 'dash.jt29@gmail.com'
Cc: Admin A
Subject: ACCIDENT INVOLVING SLN 6449J / SJN 1742T / OTHERS ON 24/11/18

OUR REF: CC6/AIG18021957/R1ja3

TAY JIA JUN JEREMY

Policy Holder

Dear Sir,

ACCIDENT INVOLVING SLN 6449J / SJN 1742T / OTHERS ON 24/11/18

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Best Regards,

Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Nayagam Anthony ("the third party claimant")
of Block 42 Chai Chee Street #12-58 (S) 461042 (address),
owner of SJN 17427 (vehicle no.) hereby authorize
Tan Lim Motor Pte Ltd

("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SJN 17427 that was
damaged pursuant to the accident which occurred on 24/11/2018 (date) along
Braddell Road (location)
involving vehicle no/s SLN 6449 J ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 30 day of Nov (month) 20 18 (year)



Signed by "the third party claimant"



Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, TAN LIM MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$5,635.00 (Global Sum) for vehicle no. SJN 1742T that was damaged pursuant to the accident which occurred on 24/11/2018 (date) along BRADELL ROAD/FLYOVER (location) involving vehicle no/s SLN 6449J. This is pursuant to the inspection conducted on 30/11/2018 (date) at "the workshop".


We/I confirm that we/I are/am authorized by the owner NAYAGAM ANTHONY ("the third party claimant") of vehicle no. SJN 1742T make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJN 1742T (vehicle no.) as a result of the accident.



We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 15th (day) of January (month) 2019 (year)

 MPB

Signed by appointed surveyor

Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Nov 2018 Edit Reg		30 Nov 2018 00:00 Edit Adj Rpt	S\$4,800.00 Edit Estimates	S\$4,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: TAY JIA JUN JEREMY , ID: S9436349G									
Main Claimant: NAYAGAM ANTHONY , ID: S0194053H									
Vehicle Reg. No.: SJN1742T		Date of Loss: 24/11/2018 14:00 - :59 [117 Months and 18 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 8162730831SG		Policy/Cover Note No.: 1800098910 (Comprehensive) Coverage: 15/08/2018 - 14/08/2019							
Vehicle Reg. No. (Insured): SLN64493		Policy No. (Claimant): P10034989R00							
		Excess:							
Repairer: Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com									
Claimant's Insurer: Auto & General Insurance (Singapore) Pte. Limited. (HQ) - Tel: 6540 2180									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 14/12/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents


















































***SJN1742T (8162730831SG)
[SLN6449J]**



























**TP
NAYAGAM ANTHONY
Nov 24 2018 2:00PM
[TAY JIA JUN JEREMY]
Tan Lim Motor Pte Ltd**

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser ▼
----------------------------------	--	-------------------------------	------------------------------------	------------------------------	------------------------------	--

Letters/Correspondences				1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit	

Photos/Images				3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
32	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	15/01/19 10:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	15/01/19 10:58	General View	1	Load JPG	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
36	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
37	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
38	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
39	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
40	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
41	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
42	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
43	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
44	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
45	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
46	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
47	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
48	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
49	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
50	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
51	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
52	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
53	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
54	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
55	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
56	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
57	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
58	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
59	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
60	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
61	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
62	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
63	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
64	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
65	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
66	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
67	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
68	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
69	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
70	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
71	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
72	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
73	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
74	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
75	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
76	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
77	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
78	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
79	15/01/19 10:58	General View		<input checked="" type="checkbox"/>
80	15/01/19 10:59	Reinspection Photo		<input checked="" type="checkbox"/>
81	15/01/19 10:59	Reinspection Photo		<input checked="" type="checkbox"/>
82	15/01/19 10:59	Reinspection Photo		<input checked="" type="checkbox"/>
83	15/01/19 10:59	Reinspection Photo		<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	15/01/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/12/18 20:33	TP ESTIMATE - MARKED	 Load PDF	
2	05/12/18 20:33	TP GIA REPORT	 Load PDF	
3	18/01/19 10:54	WORKSHOP INVOICE	 Load PDF	
4	18/01/19 10:54	AUTHORISATION TO ACT FORM	 Load PDF	
5	18/01/19 10:54	Release Voucher	 Load PDF	
6	18/01/19 10:54	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	06/12/18 09:16	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLN6449J (Insd veh)	Model:	NISSAN LATIO 1.5 SPORTS (A)
	SJN1742T (TP veh)		
Date of Accident:	24/11/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [X] Yes	<input type="checkbox"/> [] No	
Repair Estimate	:	\$		10,320.37
Final Repair Cost	:	\$		5,635.00
Loss of Use	:	\$		10.00 days at \$50.00 per day
Rental (if any)	:	\$		days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$		5,635.00

Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ 100 _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Tan Lim Motor Pte Ltd	:	\$ 5,635.00
2)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

18 Jan
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18021957/R1JA3Q2

Date: 18/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800098910

Claimant Vehicle No : SJN1742T Insured Vehicle No : SLN6449J

Date of Loss: 24/11/2018 Nature of Claim: TP Claim No: 8162730831SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJN1742T**
 Make & Model: NISSAN LATIO, 1.5 Sports (A) Engine No: HR15080948B
 Reg. Date: 06/02/2009 (Man. Year: 2008) Chassis No: JN1FAAC11Z0010456
 Colour: Brown Odometer: 128154 km
 Engine Capacity: 1498 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm
 Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,985.21	3,583.10	2,402.11	40.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,660.00	2,390.00	1,270.00	34.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,645.21	5,973.10	3,672.11	38.07
Approved Total (Overridden) (S\$)		4,800.00		
(S\$)	9,645.21	4,800.00	4,845.21	50.23
+ GST 7.00/7.00% (S\$)	675.16	336.00	339.16	50.23
Nett Amount (S\$)	10,320.37	5,136.00	5,184.37	50.23
+ Loss of Use (10.0 x S\$50.00/day) (S\$)		500.00		
Nett Liability (S\$)		5,636.00		
Global Sum Settlement (S\$)		5,635.00		

INSPECTION

Date of Assignment: 30/11/2018
 Date Inspected: 30/11/2018 Inspected At:

Tan Lim Motor Pte Ltd (Defu)
51 Defu Lane 10
Singapore 539216

Estimated Period of Repair: 9.0 days

Adjuster: MOHD RASUL

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LID	Bent	1,314.70 FL	*1,314.70 FL
2	1		*TAILGATE LID OUTER HANDLE	Repair	88.90 FL	*- FL
3	1		*TAILGATE LID INNER TRIMBOARD BOTTOM	Not Necessary	256.00 FL	*- FL
4	1		*REAR END PANEL	Bent	442.60 FL	*442.60 FL
5	1		*REAR BUMPER	Deformed	651.00 FL	*651.00 FL
6	2		*REAR BUMPER SIDE RETAINER	Necessary	50.00 FL	*50.00 FL
7	1		*REAR BUMPER INNER SPONGE	Deformed	38.60 FL	*38.60 FL
8	1		*REAR LICENCE PLATE BRACKET	Bent	55.00 FL	*55.00 FL
9	1		*REAR LICENCE PLATE LAMP	Not Necessary	54.00 FL	*- FL
10	1		*TAILGATE LID RUBBER	Necessary	98.30 FL	*98.30 FL
11	1		*REAR EXHAUST BOX	Not Necessary	513.10 FL	*- FL
12	1		*REAR EXHAUST BOX HEAT SHIELD	Not Necessary	95.00 FL	*- FL
13	2		*REAR EXHAUST BOX MOUNTING	Not Necessary	130.00 FL	*- FL
14	1		*FRONT BUMPER	Deformed	456.30 FL	*456.30 FL
15	2		*FRONT BUMPER SIDE RETAINERS	Necessary	66.00 FL	*66.00 FL
16	1		*RIGHT HEADLAMP ASSY	Not Necessary	486.30 FL	*- FL
17	1		*FRONT BUMPER FOG LAMP RIGHT	Not Necessary	320.70 FL	*- FL
18	16		*FRONT AND REAR BUMPER CLIPS	Necessary	72.00 FL	*72.00 FL
19	1		*RADIATOR GRILLE GARNISH	Not Necessary	48.30 FL	*- FL
20	6		*RADIATOR GRILLE GARNISH CLIPS	Not Necessary	27.00 FL	*- FL
21	2		*REAR LAMPS	Cracked	638.80 FN	*638.80 FN
22	1		*TAILGATE LID WIPER COVER	Not Necessary	55.00 FN	*- FN
23	1		*TAILGATE LID LATIO BADGE	Necessary	56.20 FN	*56.20 FN
24	1		*TAILGATE LID CENTRE EMBLEM BADGE	Necessary	45.60 FN	*45.60 FN
25	1		*TAILGATE LID INNER LOCK	Bent	143.10 FN	*143.10 FN
26	1		*TAILGATE LID INNER LOCK MOTOR	Not Necessary	253.70 FN	*- FN
27	1		*TAILGATE LID WINDSCREEN GLASS MOULDING	Necessary	128.70 FN	*128.70 FN
28	1		*REAR END PANEL INNER TRIMBOARD	Deformed	73.10 FN	*73.10 FN
29	1		*FROTN RADIATOR GRILLE	Not Necessary	395.30 FN	*- FN
30	1		*TAILGATE LID WINDSCREEN INNER SPONGE SEAL	Necessary	60.00 FS	*40.00 FS
31	1		*TAILGATE LID WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
32	1		*REAR LICENCE PLATE	Bent	80.00 FS	*35.00 FS
33	1		*REAR BUMPER PARKING SENSOR	Not Working	450.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	7,743.30	4,665.00
- List Item Discount on L Items 30.00/30.00% (\$\$)	1,579.14	973.35
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	178.95	108.55

Total Parts (\$\$)	5,985.21	3,583.10
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	30.00
2	TO TRANSFER OF TAILGATE FITTINGS, FIXTURE AND PERFORM WATERSEEPAGE TEST	New	200.00	100.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	New	150.00	80.00
4	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
5	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	100.00	60.00
6	TO DROP REAR EXHAUST BOX AND RENEW THE SAME	New	200.00	-
7	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	1,600.00	1,000.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	1,000.00
Gross Labour Cost (S\$)			3,660.00	2,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >