

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
CHIN	A TAIPING INSUI	RANCE (S) PTE LTD	Ref : CC3/CTI18021974/T1ha3s2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Date: 04-05-2020 Code: CTI		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJT 8467K	Veh. Inspected	SHB 1621X	
	Policy No.	DMPCSN3038911800	Coverage (\$)	0.00	
	Claim No.	SNM18D05644/C02/tkl	Excess (\$)	0.00	
	Assign From		Assign Date	05/12/2018	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA PRIUS	c.c	1798	
	Engine No.	HIDDEN	Year of Reg.	2013	
	Chassis No.	JTDKN36U705707962	Colour	MAROON	
	Odometer	777155	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	FALKEN	6 mm	
	L/H Front Tyre	195/65 R15	FALKEN	6 mm	
	R/H Rear Tyre	195/65 R15	FALKEN	6 mm	
	L/H Rear Tyre	195/65 R15	FALKEN	6 mm	
4.	· · · · · · · · · · · · · · · · · · ·				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.					
	Accident Date	04/12/2018	Inspection Date	05/12/2018	
	Survey held at	SMRT AUTOMOTIVE SERVICES	S PTE LTD		
	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				