


<<

Service Request Details

Claim

S8M015I4

Reference

CC4/ASM18022012/Kea3 

Loss Date

December 4, 2018

Report Date

Feb 25, 2019 4:40:00 PM

Request Date

January 16, 2020

Due Date

December 5, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

PAST DUE: Report that your work is blocked, and modify the Expected Completion Date.

Complete Work

More ▾

Vehicle Information

Incident Vehicle

SGB5588U

Registration #

Make

TPVD BMW

Model

520I se atuo

Service Address

, , ,

Primary Contact/Insured

NG POH SOON

169 BUKIT BATOK WEST AVENUE 8, #11-377, 650169, Singapore

MOTOR@TONGHIN.COM.SG

Claim Handler













TEO Kitty

6568804602

kitty.teo@axa.com.sg

Additional Instructions

4

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
<div>New Message</div>						
TYPE	SENT	FROM	SUBJECT	BODY		
	8/11/20 1:39 PM	TEO Kitty	Re:RE: Re:RE: Re:<TP - Mandate IA> - S8M015I4 [ACCIDENT INVOLVING SLD 68S(OI) / SGB 5588U(TP) / OTHERS ON 04/12/2018]	Hi Hsiao Tong, Pls offer LOR \$1348.20 (\$180 X 7DA...		
	8/4/20 3:32 PM	LKK AUTO CONSULTANTS PTE LTD (TP)	RE: Re:RE: Re:<TP - Mandate IA> - S8M015I4 [ACCIDENT INVOLVING SLD 68S(OI) / SGB 5588U(TP) / OTHERS ON 04/12/2018]	Hi, We have offered up to \$20,639.52(all-in). Howe...		
	4/24/20 9:27 AM	TEO Kitty	Re:RE: Re:<TP - Mandate IA> - S8M015I4 [ACCIDENT INVOLVING SLD 68S(OI) / SGB 5588U(TP) / OTHERS ON 04/12/2018]	Hi Hsiao Tong Pls proceed at \$20,639.52.		
	4/23/20 11:00 AM	LKK AUTO CONSULTANTS PTE LTD (TP)	RE: Re:<TP - Mandate IA> - S8M015I4 [ACCIDENT INVOLVING SLD 68S(OI) / SGB 5588U(TP) / OTHERS ON 04/12/2018]	Hi, kindly refer to my TP-Mandate IA dd 230420. We...		
	4/21/20 1:47 PM	TEO Kitty	Re:<TP - Mandate IA> - S8M015I4 [ACCIDENT INVOLVING SLD 68S(OI) / SGB 5588U(TP) / OTHERS ON 04/12/2018]	Hi Hsiao Tong, The bonnet actuator should be \$386...		
	4/20/20 12:41 PM	LKK AUTO CONSULTANTS	<TP - Mandate IA> - S8M015I4 [ACCIDENT INVOLVING SLD 68S(OI) / SGB 5588U(TP) / OTHERS ON 04/12/2018]	Liability: 100%(BOLA S28). 4 vehicles chain		

TYPE	SENT	PTE LTD (TP) FROM	SUBJECT	collis... BODY	
?	8/22/19 5:20 PM	TEO Kitty	PLEASE LET US HAVE YOUR MANDATE IA	*	↩
?	1/23/19 3:33 PM	WANG Peter	Pls proceed DS with quantum to be reviewed	amended GIA linked to you. Pls provide an update.	↩
?	12/6/18 7:36 PM	LKK AUTO CONSULTANTS PTE LTD (TP)	RE: Liability clear - pls ask insured to do addendum to amend car plate number indicated in report	NOTED	↩
?	12/6/18 9:28 AM	WANG Peter	Liability clear - pls ask insured to do addendum to amend car plate number indicated in report	.	↩