

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref : CC4/ASM18022012/Kpa3s2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KITTY TEO			Date: 19-08-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLD 68S	Veh. Inspected	SGB 5588U	
	Policy No.	GA365282/1	Coverage (\$)	0.00	
	Claim No.	S8M015I4	Excess (\$)	0.00	
	Assign From	KITTY TEO	Assign Date	05/12/2018	
2. Vehicle Particulars & Condition					
	Make & Model	B.M.W. 520I (A)	c.c	1998	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	WBAJA12020BJ19965	Colour	METALLIC GREY	
	Odometer	06570	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	245/40 R19	GOODYEAR	9 mm	
	L/H Front Tyre	245/40 R19	GOODYEAR	9 mm	
	R/H Rear Tyre	275/35 R19	GOODYEAR	9 mm	
	L/H Rear Tyre	275/35 R19	GOODYEAR	9 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	04/12/2018	Inspection Date	06/12/2018	
	Survey held at	160 SIN MING DRIVE #06-02 SINGAPORE 575721			
	Repairer	Repairer MBM WHEELPOWER PTE LTD			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days			