

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT  
SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD  
59 SENOKO ROAD  
SINGAPORE 758123

Attention : Motor Claim Department  
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002685

Date : 05/12/2018  
Vehicle Num. : YP2246P  
Make/Model : MITSUBISHI FK 62  
Chassis/Eng# : FK62FMA30069  
Accident Date : 29/11/2018  
Claim No. :  
Reference : SJG8447L  
Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
		NETT ITEMS :		
1.	2	SIDE GUARD, LHS	750.00	1,500.00 <i>bt</i>
2.	<del>3</del> 2	SIDE GUARD BRACKET	180.00	540.00 <i>bt</i>
3.	1	STEP, LHS		350.00 <i>bt</i>
4.	1	SLIDING DOOR PANEL, LH		850.00 <i>Rp</i>
5.	1	STICKER		150.00 <i>net</i>
		Nett Total S\$ :		3,390.00
		10.00% Discount S\$ :		339.00
				3,051.00
		LABOUR :		
		TO PANEL BEAT/REPAIR LH BODY		650.00 <i>550.</i>
		TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS		
		SPRAY PAINTING		650.00 <i>500</i>
		LOSS OF USE : 5 DAYS @ \$ 180/DAY		
		Labour Total S\$ :		1,300.00

Total S\$ : 4,351.00

SIN SHENG ENGINEERING SERVICES

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Taniffin 97495746*  
*wp'*  
*6/2/18 1715*  
*Resurvey after repair.*  
*4 days*  
*sure lkk auto.com*