

ASS. REC. BY:

REF:

CS / EGI 1802030 / And3

n2

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Yee Pei Li 6829 9194

EGI

Date/Time:

7/12/18 @ 12.04pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS :

To Inspect Vehicle No:

GBF 387D

Insured:

GBB 7195R

at Workshop m/s:

New Hock Teck

Tel:

6747 9241

of

11 Kaki Bukit Ave 6 # 01-43 Autobay

Policy No:

Claim No:

GBB 7195R / SL / PI

Sum Insured:

Excess:

6

Make of Veh:

(Client's Record)

D.O.A.

5/12/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

1242pm @ 7/12/18

Person Contacted:

Deen

Vehicle (IN) OUT

Date/Time

Action/Instruction (✓) Estimate

GBF 387D - X

GBB 7195R - CS3 / AXA13010792 / Ggbk3-1 DOA: 13/6/13

10/12/18

Informed Pei Li pending workshop est by email

4/1/19

Adrian confirmed LS \$ 3200 (Red 11,550.10, 78%)

4/1/19

Email preli revised to Pei Li

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of:

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / -24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBF387D.

Yr Regn:

2016 May

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Nissan NV200

C.C.

1587

Colour:

Grey.

A/C

Insured / Std / NI / NA

Sp. Reading

78405.

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VM20088220.

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

185/70R14.

R:

185/70R14.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Habilead.

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

07/12/18.

Survey held at

NHT.

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

Front o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Engp

10/1/19 @ 246pm Check with: Steve DON : 6/12/18

RECEIVED 10 JAN 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

10/1 - typist

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format :

TP

Lump Sum / I.B.I: (\$

3200/-

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

350



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: GBB 7195R/SL/pl

Our ref: CS/EGII8022030/Avd3

Date : 4/1/2019

The Motor Claims Department
M/s: ERGO INSURANCE PTE LTD

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. GBF 387D


We thank you for your instruction on 7/12/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 7/12/2018 at the premises of M/s NEW HOCK TECK MOTOR PTE LTD

Workshop Estimate Amount	: S\$14,750.10
Revised Estimate Amount	: S\$3,200.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front o/s portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 4 January 2019 11:48 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: GBB7195R / TP : GBF387D/LKK / DOA : 05/12/2018
Attachments: GBF 387D PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle GBF 387D
Date of survey: 7/12/2018
Number of days : 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Monday, 10 December 2018 9:50 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GBB7195R / TP : GBF387D/LKK / DOA : 05/12/2018

Dear Pei Li,

Please be informed that we have inspected the vehicle GBF 387D on 7/12/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 7 December 2018 12:46 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GBB7195R / TP : GBF387D/LKK / DOA : 05/12/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]

Sent: Friday, 7 December 2018 12:04 PM

To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>

Cc: SUR (sur@lkkauto.com) <sur@lkkauto.com>

Subject: OI : GBB7195R / TP : GBF387D/LKK / DOA : 05/12/2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **NEW HOCK TECK MOTOR PTE LTD,**

ADDRESS : 1 KAKI BUKIT AVE 6
#01-43 BLK C AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : REENA / SUKYL @ 6747 9241

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9194
Tel.: +65 6829 9199
Fax : +65 6829 9247

www.ergo.com.sg

ERGO

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 10 December 2018 9:50 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: GBB7195R / TP : GBF387D/LKK / DOA : 05/12/2018

Dear Pei Li,

Please be informed that we have inspected the vehicle GBF 387D on 7/12/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 7 December 2018 12:46 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GBB7195R / TP : GBF387D/LKK / DOA : 05/12/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Friday, 7 December 2018 12:04 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: SUR (sur@lkkauto.com) <sur@lkkauto.com>
Subject: OI : GBB7195R / TP : GBF387D/LKK / DOA : 05/12/2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **NEW HOCK TECK MOTOR PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVE 6
#01-43 BLK C AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : REENA / SUKYI @ 6747 9241

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID: +65 6829 9194
Tel: +65 6829 9199
Fax: +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Friday, 7 December 2018 12:04 PM
To: 'admin-d@lkkauto.com'
Cc: SUR (sur@lkkauto.com)
Subject: OI : GBB7195R / TP : GBF387D/LKK / DOA : 05/12/2018
Attachments: GBF387D - PRS FORM.pdf

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **NEW HOCK TECK MOTOR PTE LTD**,

ADDRESS : 1 KAKI BUKIT AVE 6
#01-43 BLK C AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : REENA / SUKYI @ 6747 9241

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9194
Tel.: +65 6829 9199
Fax: +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

ERGO

Date: 07.12.2018

Our Reference: GBB 7195R/SL/pl

Your Reference: GBF 387D

Sent via Fax

6741 7276

or

Email

To: NEW HOCK TECK MOTOR PTE LTD

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: GBF 387D

Insured's Vehicle: GBB 7195R

Date Of Accident: 05.12.2018


We acknowledge receipt of your request for PRS on: 06.12.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPk	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- ☒ Your request for inspection does not have your client's GIA report, kindly forward a copy.
- ☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
- ☒ Our Insured's driver has not reported the accident to us to date.
- ☒ Others: OFFICER-IN-CHARGE - STEVE

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____

Assignment Time: _____

Remarks:

Workshop use only:Assessor attended workshop on:

Date: _____

Time: _____

Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

ERGO

Date: 07.12.2018
Our Reference: GBB 7195R/SL/pl
Your Reference: GBF 387D

Sent via Fax

6741 7276

or

Email

To:

NEW HOCK TECK MOTOR PTE LTD**Pre-Repair Survey (PRS) Acknowledgement**

Vehicle For Inspection: GBF 387D
Insured's Vehicle: GBB 7195R
Date Of Accident: 05.12.2018


We acknowledge receipt of your request for PRS on: 06.12.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- ☒ Your request for inspection does not have your client's GIA report, kindly forward a copy.
- ☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
- ☒ Our Insured's driver has not reported the accident to us to date.
- ☒ Others: OFFICER-IN-CHARGE - STEVE

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:**Assessor attended workshop on:**

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 3345M

Vehicle Details

Vehicle No.: GBF387D

Vehicle to be Exported: No

Intended Deregistration Date: 06 Dec 2018

Vehicle Make: NISSAN

Vehicle Model: NV200 1.6 A

Primary Colour: Grey

Manufacturing Year: 2015

Engine No.: HR16055887D

Chassis No.: VM20088220

Maximum Power Output: -

Open Market Value: \$16,683.00

Original Registration Date: 26 May 2016

First Registration Date: 26 May 2016

Transfer Count: 1

Actual ARF Paid: \$835.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 25 May 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$5,378.00

COE Rebate Amount: \$4,016.00

Total Rebate Amount: \$4,016.00

The information contained herein is correct as at 06 Dec 2018

OK

REPUBLIC OF SINGAPORE **DRIVING LICENCE**

Licence Number: **G 0343311 R**


Name: **LI TIANJUN**

Birth Date: **06 May 1951**

Issue Date: **18 Sep 2017**

Valid Till **17/09/2022**

002724732J



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	EFFECTIVE DATE
Class 3C Motor cars with unladen weight \leq 3000kg with \leq 7 passengers, exclusive of driver	18 Sep 2017

NP 428A



00/14 2010 THU 10:00 FAX

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MNO Complex Singapore 069110
tel 65 6223 9433 | fax 65 6224 3903 | www.eqinsurance.com.sg
reg no. 1878-00490-N

**CERTIFICATE OF INSURANCE**

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

COMMERCIAL VEHICLE PRIVATE (SCH I)
Comprehensive

Certificate No.: DMCPhQ18-003162

Form: LCVP1

Excess:

Section 1

SGD500.00

YEID-AC

Additional SGD3,000.00

1. Index Mark and Registration Number of Vehicles
GBF387D

2. Name of Policyholder
H2 HUB PTE LTD

3. Effective Date of the Commencement of Insurance for the purpose of the Act
26/05/2018

4. Date of Expiry of Insurance
25/05/2019

5. Person or Classes of Persons entitled to drive*

Goods carrying - (MZ300) Authorised Driver. Any of the following :-

1. The Policyholder
2. Any person on the order or with the permission of the Policyholder

*Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle, has been permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act has not been cancelled at the time of accident loss or damage.

6. Limitations as to use*

1) Use in connection with the Insured's business. 2) Use for the carriage of passengers (other than for hire or reward) in connection with the Insured's business. 3) Use for social, domestic and pleasure purposes.

THE POLICY DOES NOT COVER

- 1) Use for hire or reward or for racing pace-making reliability trial or speed testing.
- 2) Use whilst drawing a greater number of trailers in all than is permitted by Law.
- 3) Use for the carriage of passengers for hire or reward.
- 4) Liability arising from or in connection with the carriage of hazardous materials, high explosives, inflammable liquid or gases including LPG in cylinders.

*Limitations rendered inoperative by Section 8 of the Motor vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or and Amendment, Act or Acts passed in substitution thereof.

unwsbh/HO/A000283/Intrade Management

A Member of Citystate

Authorised Signatory
EQ Insurance Company Limited



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

06/12/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Ergo.

Veran

Accident date: 06/12/2018

Estimated repair cost for vehicle no: GBF387D NISSAN NV200 1.6 A '16

CHASSIS: VM20088220

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet <i>Repair</i>		\$782.00+
2	1	Front Bonnet Lock <i>new</i>		\$74.00+
3	1	Front R/H Fender <i>distorted</i>		\$544.80
4	1	Front R/H Fender Inner Panel <i>Repair</i>		\$237.00+
5	1	Front R/H Fender Cowling <i>distorted</i>		\$207.10
6	10	Front R/H Fender Cowling Clip <i>new</i>	\$6.50	\$65.00 30
7	1	Front R/H Head Lamp <i>cracked</i>		\$618.00
9	1	Front R/H Head Lamp Lower Cover <i>distorted</i>		\$329.60
11	1	Front Bumper <i>distorted</i>		\$548.60
12	8	Front Bumper Clip <i>new</i>	\$6.50	\$52.00 30
13	2	Front Bumper Side Retainer <i>RH and</i>	\$34.00	\$68.00 34
14	1	Front Bumper Inner Sponge <i>cracked</i>		\$291.00
15	1	Front Bumper Reinforcement <i>best</i>		\$559.00
16	1	Front Grille <i>new</i>		\$383.00+
17	8	Front Grille Clip <i>new</i>	\$6.50	\$52.00+
18	1	Front Support Panel <i>new</i>		\$362.00+
19	1	Front R/H Hub Cap		\$186.00+
20	1	Front R/H Rim		\$650.00+
21	1	Front R/H Tyre <i>NP new</i>		\$380.00+
22	1	Front R/H Lower Arm		\$242.00+
23	1	Front R/H Knuckle Arm		\$357.00+
24	1	Front R/H Knuckle Arm Bearing		\$329.00+
25	1	Front R/H Shock Absorber		\$292.00+
26	1	Front R/H Drive Shaft		\$961.00+
27	1	Front Steering Rack		\$1,670.00+

Subtotal :- \$10,240.10

3192.10

2872.89

Labour charges

To remove & refit air-condenser, radiator, fan motor & top up gas		\$380.00 +
To remove & refit drive shaft & steering rack		\$450.00 +
To remove & refit front R/H undercarriage		\$380.00 +
To check wheel alignment		\$150.00 +
To check wiring	1130	\$100.00 30
Towing fee		\$100.00 +
Tuff kote		\$150.00 +
Panel beating		\$1,400.00 600
Spray painting		\$1,400.00 500

Subtotal :- \$4,510.00

Total:- \$14,750.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 400289

i/s: 3.2K

05 Days

3.2K

05 Days




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18022030/Avd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 14-01-2019		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 7195R	Veh. Inspected	GBF 387D	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBB7195R/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	07/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	VM20088220	Colour	GREY	
Odometer	78405	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/70 R14	HABILEAD	6 mm	
L/H Front Tyre	185/70 R14	HABILEAD	6 mm	
R/H Rear Tyre	185/70 R14	HABILEAD	6 mm	
L/H Rear Tyre	185/70 R14	HABILEAD	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/12/2018	Inspection Date	07/12/2018	
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 387D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET	TO REPAIR SEE LABOUR	782.00	-
1	FRONT BONNET LOCK	NOT NECESSARY	74.00	-
1	FRONT R/H FENDER	DISTORTED	544.80	544.80
1	FRONT R/H FENDER INNER PANEL	TO REPAIR SEE LABOUR	237.00	-
1	FRONT R/H FENDER COWLING	DEFORMED	207.10	207.10
10	FRONT R/H FENDER COWLING CLIP @\$6.50	NECESSARY	65.00	30.00
1	FRONT R/H HEAD LAMP	CRACKED	618.00	618.00
1	FRONT R/H HEAD LAMP LOWER COVER	DEFORMED	329.60	329.60
1	FRONT BUMPER	DEFORMED	548.60	548.60
8	FRONT BUMPER CLIP @\$6.50	NECESSARY	52.00	30.00
2	FRONT BUMPER SIDE RETAINER @\$34.00	O/S DAMAGED	68.00	34.00
1	FRONT BUMPER INNER SPONGE	CRACKED	291.00	291.00
1	FRONT BUMPER REINFORCEMENT	BENT	559.00	559.00
1	FRONT GRILLE	NOT NECESSARY	383.00	-
8	FRONT GRILLE CLIP @\$6.50	NOT NECESSARY	52.00	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	362.00	-
1	FRONT R/H HUB CAP	NOT NECESSARY	186.00	-
1	FRONT R/H RIM	NOT NECESSARY	650.00	-
1	FRONT R/H TYRE	NOT NECESSARY	380.00	-
1	FRONT R/H LOWER ARM	NOT NECESSARY	242.00	-
1	FRONT R/H KNUCKLE ARM	NOT NECESSARY	357.00	-
1	FRONT R/H KNUCKLE ARM BEARING	NOT NECESSARY	329.00	-
1	FRONT R/H SHOCK ABSORBER	NOT NECESSARY	292.00	-
1	FRONT R/H DRIVE SHAFT	NOT NECESSARY	961.00	-
1	FRONT STEERING RACK	NOT NECESSARY	1,670.00	-
	LESS 10% DISCOUNT		-	-319.21
			10,240.10	2,872.89

Report Ref No. CS/EGI18022030/Avd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE & REFIT AIR-CONDENSER,RADIATOR,FAN MOTOR & TOP UP GAS.	NOT NECESSARY	380.00	-
	TO REMOVE & REFIT DRIVE SHAFT & STEERING RACK.	NOT NECESSARY	450.00	-
	TO REMOVE & REFIT FRONT R/H UNDERCARRIAGE.	NOT NECESSARY	380.00	-
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
	TO CHECK WIRING.		100.00	30.00
	TOWING FEE.	NOT NECESSARY	100.00	-
	TUFF KOTE.	NOT NECESSARY	150.00	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BONNET,FRONT R/H FENDER INNER PANEL AND FRONT SUPPORT PANEL.		1,400.00	600.00
	SPRAY PAINTING.		1,400.00	500.00
			4,510.00	1,130.00
	GRAND TOTAL		14,750.10	4,002.89
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,200.00

Report Ref No. CS/EGI18022030/Avd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.