

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

07 DEC 2018

E S T I M A T EEstimate No. : b1 49365
Date Estimated : 06/12/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Advanced Coretrades Pte Ltd
51 Bukit Batok Crescent
#06-22 Unity Centre

Singapore 658077

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLF1969A	G390289	25/07/2016	528ia	0

DESCRIPTIONVALUETo replace right wing mirror assy including to knock out
dented area caused by the accident

2125 3,400.00

To respray front bumper, front right fender, front right door
and right wing mirror cover

2594 2,882.00

To check steering geometry and conduct wheel alignment
according to BMW specification (1x)

451 531.00

To replace tyre and wheel rim including balancing. (RHF)

80 94.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

150 177.00

Sundries.

/ 150.00

Total Labour 1: **7,234.00**DESCRIPTIONQTYPRICVALUE

ALLOY RIM 8.5X19 STY 610

1 1,374.00 1,374.00

HUB CAP WITH CHROME EDGE (BMW)

1 28.35 28.35

FINISHER SIDE PANEL FRT RH

1 75.15 75.15

EMBLEM GROMMET

2 0.80 1.60

BMW EMBLEM

1 71.25 71.25

RIVET

10 0.45 4.50

RH MIRROR GLASS HEATED WIDE-ANGLE

1 776.70 776.70

RH OUTSIDE MIRROR W/O GLASS

1 1,011.25 1,011.25

FRT RH DOOR EXTERIOR CHANNEL COVER

1 139.15 139.15

Total Parts : **3,481.95**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49365

Page No. : 2 of 5

Date Estimated : 06/12/2018

Prepared By : Han Kwan Yong

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLF1969A	G390289	25/07/2016	528iA	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time _____ Excess S\$ _____

Surveyor's Name Quo Qiao Sign _____Surveyor's Tel 82880282 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail quoqiao@lkkauto.comNo. of Working Days Recommend 6

before print photos.

Labour 1	:	7,234.00
Parts	:	3,481.95
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	750.12
Grand Total	:	<u>11,466.07</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **