

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

ROC:53360061L

GST:53360061L

QT18/PH2846G/TPC-370

Lonpac Insurance Bhd

100 Beach Road

#19-00 Shaw Tower

Singapore 189702

QUOTATION

Dear Sir,

Cost of Repair to Vehicle PH2846G

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Rear bumper DD	1	3,550.00	3,550.00 1,900
2.	Rear bumper inner structure DD	1	1,600.00	1,600.00
3.	Rear bumper LH & RH bracket	2	350.00	700.00
4.	Labour charges	1	1,000.00	4,504,000.00
5.	Spray painting	1	500.00	250 500.00
SUB-TOTAL				S\$7,350.00

- Price before 7% gst

Thank you.

Yours faithfully,



Winnie Chai
HP: 9850-9666



Auto Company to notify
the Repairer

- To resurvey before starting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal repairs are allowed
- Supplemental repairs must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



Hwee Jie (LKK)

12/12/18

L/S 3 days

