LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

> 3 Anson Road #16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

> Paya Ubi Industrial Park Singapore 408933

Date: 12 Dec 2018 Attn: Elaine Cheong

Preliminary Advice

Vehicle No : GBH5608Z **Accident Date** : 29/11/2018

Make : NISSAN NV200 Policy No.

DMCVSN1820691800

Assignment Date : 11/12/2018 **Excess** : S\$3,350.00

Date of Inspection : 11/12/2018 Est. Duration of Repair : 9.00

Inspection At : ASM AUTOMOTIVE SERVICES KWONG MIN RD (HQ)

NO. 2 KWONG MIN ROAD SINGAPORE 628705

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,600.00
Revised Amount	:S\$	10,857.00
Check Items (Estimated)	:S\$	1,955.75
Total	:S\$	12,812.75

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 63,000.00 COE / PARF Rebate :S\$ 27,690.00

Salvage Value :S\$

Margin for Repair :S\$ 35,310.00

Remarks

X	()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :