

HS140 7024

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/JHI/152/2018
DATE : 10-DEC-2018

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :
MOTOR CLAIM DEPT

OWNER'S NAME : TAN ZHE WEI, LEON
ADDRESS : APT BLK 906 JURONG WEST STREET 91
#06-187
S(640906)
TELEPHONE NO : 9675 4071

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : -
VEHICLE NO : SLN1469J
MODEL CODE : GT3AK2C
MODEL/YEAR : IMPREZA 5D 1.6I-S AWD CVT
ENGINE NO : FB16Y606213
CHASSIS NO : JF1GT3KC5HG004617
MILEAGE : 1 KM
DATE IN : 10/12/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 10/12/2018

Print Date : 10/12/2018
Print Time : 19:32:51

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLN1469J

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	BUMPER FACE R 5D FHI <i>DE</i>	57704FL230	414.00			
2	BRKT SD R 5D RH <i>NE</i>	57707FL360	23.40			
3	BRKT SD R 5D LH <i>NE</i>	57707FL370	23.40			
4	BRKT CORNER R 5D RH <i>NE</i>	57707FL460	21.60			
5	BRKT CORNER R 5D LH <i>(SUPP) X SU</i>	57707FL470	21.60			
6	BEAM COMPL R EU <i>pt</i> USE FL0409P	57711FL0419P	203.00			
7	COVER HOOK R 5D FHI <i>X ny</i>	57731FL550NN	9.00			
8	LENS & BODY COMPLRH <i>? X ny</i>	84912FL040	378.00			
SUB TOTAL			1094.00	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			218.80	0.00	0.00	0.00
GRAND TOTAL			875.20	0.00	0.00	0.00
OVERALL TOTAL			875.20			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLN1469J

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	REPLACE REAR BUMPER,BUMPER BEAM,RHS TAILAMP	1680.00	560 ✓
2	ZZ/002	RESPRAY REAR BUMPER,BUMPER BEAM AND R.RHS FENDER	1440.00	660 ✓
3	ZZ/003	TO CONDUCT REAR LIGHTING TEST	150.00	✓
4	ZZ/004	REMOVE AND REFIX REVERSE SENSOR	80.00	X n ✓
5	ZZ/005	SUNDRIES	100.00	20 ✓
TOTAL LABOUR CHARGES			3450.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLN1469J

TOTAL LABOUR CHARGES	3450.00
TOTAL SPARE PARTS CHARGES	875.20
GRAND TOTAL	4325.20 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	: Rasul - Hf 90010068
SURVEYED DATE	: 14/12/16 @ 1225
AUTHORIZED DATE	:
EXCESS CLAUSE	: 0.00 3 days
LIABILITY	: 0.00
REMARKS	: Reming 64 paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey ~~before~~ after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/JHI/152/2018
DATE : 10-DEC-2018

AIG ASIA PACIFIC INSURANCE PTE LTD
7B SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :
MOTOR CLAIM DEPT

OWNER'S NAME : TAN ZHE WEI, LEON
ADDRESS : APT BLK 906 JURONG WEST STREET 91
#06-187
S(640906)
TELEPHONE NO : 9675 4071

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : -
VEHICLE NO : SLN1469J
MODEL CODE : GT3AK2C
MODEL/YEAR : IMPREZA 5D 1.6I-S AWD CVT
ENGINE NO : FB16Y606213
CHASSIS NO : JF1GT3KC5HG004617
MILEAGE : 1 KM
DATE IN : 10/12/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 10/12/2018

Print Date : 25/07/2019
Print Time : 11:25:23

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLN1469J

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	REPLACE REAR BUMPER,BUMPER BEAM,RHS TAILAMP	1680.00	560.00 ✓
2 ZZ/002	RESPRAY REAR BUMPER,BUMPER BEAM AND R.RHS FENDER	1440.00	660.00 ✓
3 ZZ/003	TO CONDUCT REAR LIGHTING TEST	150.00	150.00 ✓
4 ZZ/004	REMOVE AND REFIX REVERSE SENSOR	80.00	.00 X
5 ZZ/005	SUNDRIES	100.00	20.00 ✓
6 ZZ/006	SUPPLEMENTARY JOB - REPAIR END PANEL	560.00	560.00
7 ZZ/007	SUPPLEMENTARY JOB - RESPRAY END PANEL	440.00	440.00
8 ZZ/008	SUPPLEMENTARY JOB - TO REPLACE REVERSE SENSOR	300.00	300.00
TOTAL LABOUR CHARGES		4750.00	2690.00

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLN1469J

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 BUMPER FACE R 5D FHI	57704FL230	414.00 ✓			OK
2 BRKT SD R 5D RH	57707FL360	23.40 ✓			OK
3 BRKT SD R 5D LH	57707FL370	23.40 ✓			OK
4 BRKT CORNER R 5D RH	57707FL460	21.60 ✓			OK
5 BRKT CORNER R 5D LH (SUPP)	57707FL470	21.60 X			X
6 BRKT LWR R	(SUPP) 57707FL510	25.20 (S)			OK
7 BEAM COMPL R EU	USE FL0409P 57711FL0419P	203.00 ✓			OK
8 COVER HOOK R 5D FHI	57731FL550NN	9.00 X			X
9 LENS & BODY COMPLRH	84912FL040	378.00 X			X
SUB TOTAL		710.60	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		142.12	0.00	0.00	0.00
GRAND TOTAL		568.48	0.00	0.00	0.00
OVERALL TOTAL		568.48			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLN1469J

NETT ITEM	710.60
LESS 20 %	-142.12
NETT AMOUNT	568.48

LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00

SPECIAL NETT AMOUNT	0.00
---------------------	------

S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00

TOTAL LABOUR CHARGES	2690.00
TOTAL SPARE PARTS CHARGES	568.48

TOTAL CHARGES	3258.48
ADD 7 % GST	228.09

GRAND TOTAL	3486.57
-------------	---------
