

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD
 8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288 FAX: 68804739
 ATTN: Motor Claim Department

WS Ref: TP/AXA/AMK
 Claim Type: Third Party
 Accident Date: 09/12/2018
 TP Veh Reg No: SKA4885B

Estimate No: ES1891400/AMK
Date: 13 Dec 2018
Policy No: 10739866
Veh Reg No: SGU6295H
Make/Model: TOYOTA COROLLA
 ALTIS 1.6 AUTO
Chassis No: MR053ZEC107144062
Engine No: 3ZZ4639116
Reg. Date: 21/05/2007

Not Authorized
1/1 Part & ?
Resurvey After Paint 4 days

Estimate Repair Cost to Vehicle No :SGU6295H

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT RH FENDER	182.53	1 PC	182.53	✓
2 FRT RH FENDER INNER SHIELD	26.90	1 PC	26.90	✓
3 FRONT RH FENDER INNER SHIELD CLIP	3.50	6 PC	21.00	✓
4 FRONT RH DOOR PROTECTOR	37.90	1 PC	37.90	✓
5 FRONT RH DOOR MOULDING	14.30	1 PC	14.30	✓
6 FRONT RH RIM	350.00	1 PC	350.00	✓
7 FRONT RH SIDE MIRROR ASSY	387.22	1 PC	387.22	✓
			1,019.85	
		Less 25%	254.96	764.89
Labour				
8 REMOVE & REFIX FRT BUMPER,GRILLE,HEADLAMP,FRT RH FENDER; KNOCKING & REPAIR FRT RH DOOR & REALIGN THE SAME	500.00	1 LA	500.00	450
9 PUTTY & RESPRAY FRT BUMPER,FRT RH FENDER,FRT RH DOOR,RH SIDE MIRROR & ALL AFFECTED AREAS	600.00	1 LA	600.00	500
10 REMOVE & REFIX FRT RH DOOR WINDOW GLASS & RESET CENTRAL LOCKING	60.00	1 LA	60.00	✓
11 REMOVE & REFIX FRT RH RIM,TYRE,BALANCE & REALIGN THE SAME	40.00	1 LA	40.00	20
12 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
13 RUSTPROOFING	60.00	1 LA	60.00	30
			1,320.00	1,320.00
		Total		S\$ 2,084.89
		Add GST @ 7%		145.94
		Total Amount Payable		S\$ 2,230.83

SURVEY VEHICLE AT ANGI MO KIO WORKSHOP

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE