

10/10/18

INS. CASE OWNER

Daniel Poon

CC 4/III1802 2298, E 16 3/4

LKK:
IDAC

Surveyor:

Steve

DOI:

17/11/18

Date / Time:

11/12/18

Registered in Merimen:

11/12/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SH 8525H

Name of Insured : LPU

Insured Tel No. : HP: 812/10

Excess Sec II :SS D.O.A. : 8/12/18

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : Huan Shun Siang 50y PREB man

Driver Tel No. : (V/L: YES/ NO)

Claim No. : 11000015

Policy No. : 10000015

Make / Model : Toyota

Place of Accident : Victoria St 100y 7th

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SUM 44592



INSRS:
WSP:
Tel :
Liability :
RMKS:

W/L



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time

11/12/18
Police

SUM 44592 ->
SH 8525H - 100% LIA
BOLA 27 approve ✓
Personal Liability clear ✓
Pending LOD ✓
All pass to Steve to revert Mr Meka email

2-11-19 FILE PASS TO TYPIST TO PREPARE REPORT.

2-11-19 08:40pm LOD with 111

STAGE	DATE / PIC
Non-Reporting 1st (1st)	
Non-Reporting 1st (2nd)	
Non-Reporting 1st (Final)	
Notification 1st (if non-pickup)	
Call OI	
After call 1st to OI	
Documentation Check List: Handler	Typist
Notification 1st (if non-pickup)	
After call 1st to OI	
Authorisation To Act	
Release Voucher	
Final Repair Bill	
Car Rental Invoice	
Towing Invoice	
LTA / GIA	
Medical Bill	
PIR	
Mandate/Reject Instruction	
LOD	
Payment Breakdown Form	
Post-Repair Photos	
Others	

PRELIMINARY ADVICE Date/Time: 11/12/18 Sent By: LPK		Confirm by: CTY	
FINALIZATION Date/Time: 11/12/18 Confirm with: 04/11/18		Email ☒ Call ☐	
Repair Cost: 45	\$53,950.00	(3 days) Reduction:	45 %
FINAL SETTLEMENT Date/Time: 10-12-19 Confirm with: 04/11/18		Email ☒ Call ☐	
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No. : 27	If NO or B 28, Ass. Lia:	
Repair Cost:	\$53,263.50	Front to rear collision	
Loss of Rental (LOR):	\$5 200.85 (3 days) = \$66.95	COMPLAINT	
Loss of Use (LOU):	\$5 - (5 x days)		
Loss of Income (LOI):	\$5 - (5 x days)		
LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LO ☐ (Tick only one)		1) Claim status: ☒ Normal/Reject/Private Settle	
GIA/LTA Search	\$57.45	2) Report Format: TP	
Medical:	\$5 -	3) Survey fee: \$350	
Disbursement:	\$5 - (e.g. Tow/ Independent)		
Legal Cost	\$5 -		
Total:	\$5 3,471.80	Global Sum \$5:	
FINAL PAYMENT Date/Time: 10-12-19 Confirm with: 04/11/18		Email ☒ Call ☐	
Payee 1:	\$53,911.80	Name 1:	H-Si Automotive Pte Ltd
Payee 2: (Strike if N.A.)	\$5	Name 2:	
Payee 3: (Strike if N.A.)	\$5	Name 3:	

f

Figure 10.10



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref : CC4/III18022298/fb3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Date : 11-12-2018	
			Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 8525H	Veh. Inspected	SLM 4459Z	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	11/12/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/12/2018	Inspection Date		
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Attn: Mr Neo

Contact : 66550005 82607851

ESTIMATE

Repair Code : CLM14939

Date in : 08/12/2018

Vehicle Num. : SLM4459Z

Model : NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR

Chassis/Eng# : SJNFJAJ11U1766779/HRA2331779A

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>DD</i>	1	717.00	717.00 ✓
REAR BUMPER CENTER HOLDER CLIPS <i>NEC</i>	3	18.50 <i>10</i>	30 55.50 ✓
REAR BUMPER INNER SPONGE <i>TN</i>	1	126.40 <i>779</i>	979 126.40 ✓
REAR BUMPER REINFORCEMENT <i>DD</i>	1	619.20	619.20 ✓
REAR BUMPER REINFORCEMENT BRACKET RH <i>DT</i>	1	126.00	126.00 ✓
REAR BUMPER RH REFLECTOR <i>BR</i>	1	55.00	55.00 ✓
REAR BUMPER SIDE RETAINER L/R <i>BT (RH) NN (LH)</i>	2	36.90	36.90 73.80 ✓
REAR BUMPER TOW HOOK COVER <i>CUT</i>	1	16.80	16.80 ✓
REAR END PANEL	1	482.60	R 482.60 X
REAR END PANEL INNER TOP GARNISH <i>CRA</i>	1	63.50	63.50 ✓
REAR RH FENDER ARCH GARNISH <i>BR</i>	1	483.00	483.00 ✓
REAR RH TAILLAMP <i>BR</i>	1	323.70	323.70 ✓
REAR TAILGATE 'QASHQAI' EMBLEM <i>NN</i>	1	87.00	87.00 X
Subtotal before discount		2569	3,229.50
Percentage discount 10%		-10%	322.95
Sub-total 1		2312.10	2,906.55
REAR BUMPER REVERSE SENSOR <i>BR</i>	1	450.00	300 450.00 ✓
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>NEC</i>	1	20.00	15 20.00 ✓

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005 82607851

ESTIMATE

Repair Code : CLM14939

Date in : 08/12/2018

Vehicle Num. : SLM4459Z

Model : NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR

Chassis/Eng# : SJNFEAJ11U1766779/HRA2331779A

REAR FENDER ARCH GARNISH CLIPS L/R - SET	NEC	2/1	40.00	30	30/40.00
REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R - SET	NN	2	50.00		100.00 X
REAR RH TAILLAMP CLIPS - SET	NEC	1	30.00		30/30.00
Subtotal before discount			365		680.00
Percentage discount 0%					0.00
Sub-total 2					680.00
Parts-total					3,586.55

LABOUR

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	100.00 X
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,000.00 55
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	800.00 55
To apply anti-rust chemical on repaired and replaced panel.	50.00 38
Labour Total	1,950.00
Parts & Labour Total	5,536.55

1130

*** This is a computer-generated document which requires no signature.***

page 2

from : Steve L/S
 Mary 27/12/18
 6256 3561

3 day repair

P - 2,312.10
 Net - 365
 2,677.10
 L - 1,130.00
 3,807.10

Printed
 28/12/18

L/S - 3,045.68 = 3050 ✓

[➤ Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7200G
Vehicle Details	
Vehicle No.:	SLM4459Z
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Dec 2018
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	HRA2331779A
Chassis No.:	SJNFEAJ11U1766779
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$18,725.00
Original Registration Date:	30 Mar 2017
First Registration Date:	30 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$13,725.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Mar 2027
PARF Rebate Amount:	\$10,293.00
Intended COE Rebate Details	
COE Expiry Date:	29 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,101.00
COE Rebate Amount:	\$41,481.00
Total Rebate Amount:	\$51,774.00

The information contained herein is correct as at 18 Dec 2018

OK

Used Nissan



Nissan Qashqai 2.0A Premium **\$104,000** **\$10,220 /yr** **21-Dec-2017** **1,997 cc** **16,500 km** **SUV** **Available**

Enjoy Loan Interest Rate At 2.28%! Single Owner Unit, Comes With Agent Warranty Of 5 Years, Extremely Well Maintained And Comes With Panoramic Glass Roof! This Beast Does Not Just Look Beautiful, It's...

Posted: 11-Dec-2018 Tags: 2017 Nissan Qashqai, 2017 nissan qashqai, Nissan Qashqai, nissan qashqai, Nissan, Qashqai, qashqai, Used Nissan



Nissan Qashqai 1.2A DIG-T Premium **\$79,800** **\$9,040 /yr** **12-Jan-2017** **1,197 cc** **24,000 km** **SUV** **Available**

1 Owner! Agent Warranty With Full Service Records At Tan Chong! Excellent Condition, Well Taken Care Of By Previous Owner, Trade In/Flexible Loan Available! Hurry Call Or Visit Us Now For Further Deta...

Posted: 11-Dec-2018 Tags: 2017 Nissan Qashqai, 2017 nissan qashqai, Nissan Qashqai, nissan qashqai, Nissan, Qashqai, qashqai, Used Nissan



Nissan Qashqai 1.2A DIG-T Premium **\$117,000** **\$13,200 /yr** **24-Apr-2017** **1,197 cc** **19,000 km** **SUV** **Available**

\$3960 Driveaway! \$1480/month! Low Mileage Unit With 2 Free Servicing! Agent Warranty Included! Trade In Available! Call Now For Custom Loan Plans! Designed For Urban Driving, This 1.2L Turbo Variant L...

Don Motoring

Posted: 09-Dec-2018 Tags: 2017 Nissan Qashqai, 2017 nissan qashqai, Nissan Qashqai, nissan qashqai, Nissan, Qashqai, qashqai, Used Nissan



Nissan Qashqai 1.2A DIG-T Premium **\$88,800** **\$9,180 /yr** **28-Oct-2017** **1,197 cc** **20,765 km** **SUV** **Available**

\$2,000 Republic Auto Warranty Workshop Credits.3 Years Factory Warranty By Tan Chong Motor, Fully Serviced And Maintained By Tan Chong Motor, Low Mileage, Authorized 70% Bank Interest Rate At 2.28%, C...

Republic Auto

Posted: 04-Dec-2018 Tags: 2017 Nissan Qashqai, 2017 nissan qashqai, Nissan Qashqai, nissan qashqai, Nissan, Qashqai, qashqai, Used Nissan



Sell your Car for \$3,000 More

With over 15K cars sold via Auction and a 500+ Dealer Network, cars on sgCarMart Quotz typically receive up to \$3000 above market value. Quotz Guarantees the Highest Selling Price in Singapore - if we fail, you get \$100 cash from us. Get your Car Listed Today.

Find out more!



Nissan Qashqai 1.2A DIG-T Premium **\$82,000** **\$8,800 /yr** **30-Jun-2017** **1,197 cc** **-** **SUV** **Available**

Single Owner, Full Serviced And Maintained By Tan Chong, No Repairs Needed! Not Abused! Great Fuel Economy! Spacious For The Family With Easy Comfort Driving! Low Maintenance Needed, High Trade In And...

Audax Auto Pte Ltd

Posted: 04-Dec-2018 Tags: 2017 Nissan Qashqai, 2017 nissan qashqai, Nissan Qashqai, nissan qashqai, Nissan, Qashqai, qashqai, Used Nissan



Nissan Qashqai 2.0A Premium **\$99,800** **\$9,900 /yr** **08-Nov-2017** **1,997 cc** **20,000 km** **SUV** **Available**

Latest Addition! Like New, Fully Agent Serviced, Just Serviced Only, 5 Years Agent Warranty, Value For Money With The Latest Model! Owner Relocation, Lowest Depreciation, Down Payment From 10%, In- Ho...

Posted: 03-Dec-2018 Tags: 2017 Nissan Qashqai, 2017 nissan qashqai, Nissan Qashqai, nissan qashqai, Nissan, Qashqai, qashqai, Used Nissan



Nissan Qashqai 1.2A DIG-T Premium **\$81,800** **\$8,790 /yr** **30-Jun-2017** **1,197 cc** **-** **SUV** **Available**

New Arrival! Surely Brand New Condition! 5 Years Warranty By TC. Ultra Racing Bars Added! Upgraded Sound System. Fully Agent Service, Definite Worthwhile Buy Excellent Interior Condition. High Loan An...

Car Search

Posted: 01-Dec-2018 Tags: 2017 Nissan Qashqai, 2017 nissan qashqai, Nissan Qashqai, nissan qashqai, Nissan, Qashqai, qashqai, Used Nissan



Nissan Qashqai 1.2A DIG-T Premium **\$82,000** **\$9,080 /yr** **31-Mar-2017** **1,197 cc** **39,000 km** **SUV** **Available**

1 Owner, Pristine Condition, Factory Fitted Interior. Accident Free. Schedule A Test Drive Today, Viewing Is Strictly By Appointment Only.

Carro

Posted: 01-Dec-2018 Tags: 2017 Nissan Qashqai, 2017 nissan qashqai, Nissan Qashqai, nissan qashqai, Nissan, Qashqai, qashqai, Used Nissan



Nissan Qashqai 1.2A DIG-T Premium **\$80,888** **\$8,790 /yr** **24-May-2017** **1,197 cc** **-** **SUV** **Available**

5 Years Agent Warranty, Fully Serviced By Tan Chong, 100% Accident Free, Exterior And Interior In Pristine Condition, Almost Like New, Free Polishing, Interior And Exterior Grooming Will Be Done Befor...

Monster Motors Pte Ltd

Condition Legend
 (1) Bent (2) Dented (3) Disoriented (4) Cracked (5) Cut (6) Scratched
 (7) Deformed (8) Dislodged (9) Ductile (10) Broken (11) Necessary
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

AC110211AC)
 (1) Replace (✓) (2) Repair (X) (3) Check (E)
 (4) Not Consistent (NC)

Aug 2003

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	00	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover	CUT	✓	
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket RH		?	
1148	993068	Rear Bumper Side Retainer LH	BR	✓	
1149	993045	Rear Bumper Reinforcement		?	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge		?	
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector RH	CUT	✓	
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	BR	✓	
1159	993327	Rear End Panel		R	
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp		?	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

Vehicle No:

SLM 4459Z

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993429	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector	Arch	00	✓
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield		?	
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 11 December 2018 9:44 AM
To: Chin Hui Xin; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Manivel Priyadarshini
Subject: RE: SLM4459Z & SH8525H - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS
Attachments: 10122018174012-0001.pdf

9:57am @ 11/12/18
VNI
person @ Melody

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLM4459Z and let us have your report urgently.

This claim will be handled by Ms Priya.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street, #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Chin Hui Xin [mailto:huixin@n51.com.sg]
Sent: 11 December, 2018 9:32 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: SLM4459Z & SH8525H - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

We appoint your surveyor company Lkk Auto Consultants Pte Ltd.

Please see attached.

Thank you

Regards,
Melody Chin
N-51 Automotive Pte Ltd
Office : 6842 0051
Fax : 6741 0510
www.n51.com.sg



On Tue, Dec 11, 2018 at 9:02 AM Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



Singapore 049711

Tel: 6347 6100, Ext – 248

From: Chin Hui Xin [mailto:huixin@n51.com.sg]

Sent: 10 December, 2018 5:43 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: SLM4459Z & SH8525H - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

As per above subject,

Please refer attachment and:-

Kindly propose / provide your 10 surveyors.

Thank you...

Regards,

Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

or any modification.

- Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

From: Poh Kin (LKKAUTO)
Sent: Tuesday, 18 December 2018 3:54 PM
To: 'huixin@n51.com.sg'
Cc: 'Sabrina (N-51)'; Admin A; assignments
Subject: ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SH 8525H AND SLM 4459Z
ALONG VICTORIA STREET ON 08/12/2018

Importance: High

WITHOUT PREJUDICE

Our Ref: CC4/III18022298/fb3
Your Ref: SLM 4459Z

Dear Hui Xin,

**ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SH 8525H AND SLM 4459Z ALONG VICTORIA STREET
ON 08/12/2018**

We refer to above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

In the meantime, kindly arrange TP survey ASAP.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



View Received Message

This mail is associated with :

***SLM4459Z
[SH8525H]**

TP

GRAB RENTALS PTE LTD

Dec 8 2018 8:00PM

[COMFORT TRANSPORTATION PTE LTD]

N-S1 Automotive Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 18/12/2018 14:37 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SLM4459Z - Claim Handler: Pool Chin Han Daniel

Approved:0.00.

DOCUMENTS SUMMARY

There are no documents.

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	11 Dec 2018 16:34	CIm Veh Model Changed	(204861) NISSAN QASHQAI 1.2 (A).	[A] Lau Shu Pei
2	11 Dec 2018 16:34	CIm Created	Reg No: SLM4459Z, Acct Date: 2018/12/08, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ), Workshop: N-51 Automotive Pte Ltd (HQ)	[A] Lau Shu Pei
3	11 Dec 2018 16:34	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	11 Dec 2018 16:34	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/12/20	[A] Lau Shu Pei
5	11 Dec 2018 16:34	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
6	11 Dec 2018 16:34	Label Added	(30651):Vehicle Not In,(30653):Direct Settlement.	[A] Lau Shu Pei
7	11 Dec 2018 16:34	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] Lau Shu Pei
8	14 Dec 2018 08:56	CIm Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
9	14 Dec 2018 08:56	CIm Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
10	18 Dec 2018 14:31	Adj Mandate Request	Cur.Reg:0.00:PODS Liability; 100% Remarks: BOLA 27, OID rear ended TP vehicle.	[A] Chong Poh Kin
11	18 Dec 2018 14:37	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/12/20	[I] Lalitha Krishnan
12	18 Dec 2018 14:37	Adj Mandate Set	Approved:0.00.	[I] Lalitha Krishnan
13	18 Dec 2018 14:45	Label Removed	(30651):Vehicle Not In.	[A] Lau Shu Pei
14	18 Dec 2018 14:45	Adj Adjuster Assigned	ADRIAN LING -> CHEN TSUE YEE	[A] Lau Shu Pei

Date From Date To Audit Type None Go

ACTIVITY
No record

Merimen Billing for this case - Transaction History							
Bill Ref No.	Bill Date	Acc. Type	Acc. Name	Co Name (Branch)	Ref 1	Ref 2	Amount
No billing items							

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Thursday, 4 April 2019 9:31 AM
To: Steve Chen (LKK Auto)
Subject: FW: Our ref : MCT18120223
Attachments: SLM4459Z MCT18120223.PDF; MCT18120223.pdf

Importance: High

forward

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Shu Pei (LKKAuto)
Sent: Tuesday, 2 April 2019 7:19 PM
To: Mekavathanan Sarangapani <mekavathanan@iil.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Poh Kin (LKKAuto) <pohkin@lkkauto.com>
Subject: FW: Our ref : MCT18120223

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Please note that: -

LKK ref	Officer in charge
CC4/III18022298/EFB3	Poh Kin

To check availability of the case handler, you may contact the undersigned

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Poh Kin (LKKAUTO)

From: Shu Pei (LKKAUTO)
Sent: Tuesday, 2 April 2019 7:19 PM
To: Mekavathanan Sarangapani
Cc: Admin A; Poh Kin (LKKAUTO)
Subject: FW: Our ref : MCT18120223
Attachments: SLM4459Z MCT18120223.PDF; MCT18120223.pdf

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Please note that: -

LKK ref	Officer in charge
CC4/III18022298/EFB3	Poh Kin

To check availability of the case handler, you may contact the undersigned

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Olivia Lau (LKKAUTO)
Sent: Tuesday, 2 April 2019 1:09 PM
To: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; assignments <assignments@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: FW: Our ref : MCT18120223

From: Mekavathanan Sarangapani
Sent: Tuesday, 2 April 2019 1:09:09 PM (UTC+08:00) Kuala Lumpur, Singapore
To: Hsiao Tong (LKKAUTO); Olivia Lau (LKKAUTO); KKLau
Cc: Manivel Priyadarshini; Stanley Lai
Subject: Our ref : MCT18120223

Dear LLK team,

Recd LOD from N 51 for this accident . Are damages consistent for such a low impact collision, undercarriage damaged ?

Scratches and torn appears to be old damages ?

Claiming costs of repairs S\$ 3K odd ?

Meka





2 [SH8525H] - Submitted by: LKK Auto Consultants Pte Ltd (HQ)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	11 Dec 2018 16:34	Clim Veh Model Changed	(204861) NISSAN QASHQAI 1.2 (A).	[A] Lau Shu Pei
2	11 Dec 2018 16:34	Clim Created	Reg No: SLM4459Z. Acct Date: 2018/12/08. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Workshop: N-51 Automotive Pte Ltd (HQ)	[A] Lau Shu Pei
3	11 Dec 2018 16:34	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	11 Dec 2018 16:34	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/12/20	[A] Lau Shu Pei
5	11 Dec 2018 16:34	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.	[A] Lau Shu Pei
6	11 Dec 2018 16:34	Label Added	(30651):Vehicle Not In,(30653):Direct Settlement.	[A] Lau Shu Pei
7	11 Dec 2018 16:34	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] Lau Shu Pei
8	14 Dec 2018 08:56	Clim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
9	14 Dec 2018 08:56	Clim Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
10	18 Dec 2018 14:31	Adj Mandate Request	Cur.Req:0.00:PODS Liability; 100% Remarks: BOLA 27, OID rear ended TP vehicle.	[A] Chong Poh Kin
11	18 Dec 2018 14:37	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/12/20	[I] Lalitha Krishnan
12	18 Dec 2018 14:37	Adj Mandate Set	Approved:0.00.	[I] Lalitha Krishnan
13	18 Dec 2018 14:45	Label Removed	(30651):Vehicle Not In.	[A] Lau Shu Pei
14	18 Dec 2018 14:45	Adj Adjuster Assigned	ADRIAN LING -> CHEN TSUE YEE	[A] Lau Shu Pei
15	06 Dec 2019 13:48	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
16	06 Dec 2019 13:48	Clim Dtl Modified	Insured ID: -> -.	[A] JOANNE LEE KHANG MIN
17	06 Dec 2019 13:48	Clim Dtl Modified	JPJ Reg. Date: -> 2017/03/30.	[A] JOANNE LEE KHANG MIN
18	06 Dec 2019 13:48	Clim Details Notified		[A] JOANNE LEE KHANG MIN
19	07 Dec 2019 16:35	Adj Mandate Request	Cur.Req:3471.80:PODS: LIABILITY: 100% QUANTUM: (a) COR w/GST: \$3,263.50 + (b) LOR : \$200.85 (3days x \$66.95) + LTA : \$7.45 Total: a+b+c = \$3,471.80 VEH MODEL: NISSAN QASHQAI 1197cc PLEASE REVERT WITH YOUR APPROVAL / MANDATE / INSTR UCTIONS, IF AN	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc. Type	Acc. Name	Cr Name (Branch)	Ref 1	Ref 2	Amount
2369639	06 Dec 2019 13:48:44	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLM4459Z	SH8525H	11.77

Print Received Message

This mail is associated with :

***SLM4459Z (MCT18120223)
[SH8525H]**

TP
GRAB RENTALS PTE LTD
Dec 8 2018 8:00PM
[COMFORT TRANSPORTATION PTE LTD]
N-51 Automotive Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 09/12/2019 10:39 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3471.80) - SLM4459Z - Claim Handler: Priya

Approved:3471.80:Request TP WS to issue Tax invoice for Repairs in III's favour

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Apr 2019 Edit Reg		11 Dec 2018 00:00 Edit Adj Rpt	S\$3,050.00 Edit Estimates	S\$3,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -								
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Vehicle Reg. No.:	SLM4459Z	Date of Loss:	08/12/2018 20:00 - :59 [20 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18120223	Policy/Cover Note No.:	MCOMD015						
Vehicle Reg. No. (Insured):	SH8525H	Policy No. (Claimant):	A29069766MKF						
		Excess:							
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 20/12/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (09/12/2019): Alert - Adj Mandate Approved (S\$3471.80) - SLM4459Z - Claim Handler: Priya - III_SG (24/04/2019): LOD FROM N-51 AUTOMOTIVE PTE LTD - III_SG (18/12/2018): Alert - Adj Mandate Approved (S\$0.00) - SLM4459Z - Claim Handler: Pool Chin Han ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLM4459Z (MCT18120223)
[SH8525H]
TP
GRAB RENTALS PTE LTD
Dec 8 2018 8:00PM
[COMFORT TRANSPORTATION PTE LTD]
N-51 Automotive Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	27/12/18 10:58	Accident Photo						Load JPG	☒	
2	27/12/18 10:58	Accident Photo						Load JPG	☒	
3	27/12/18 10:58	Accident Photo						Load JPG	☒	
4	27/12/18 10:58	Accident Photo						Load JPG	☒	
5	27/12/18 10:59	Accident Photo						Load JPG	☒	
6	27/12/18 10:59	Accident Photo						Load JPG	☒	
7	27/12/18 10:59	Accident Photo						Load JPG	☒	
8	27/12/18 10:59	Accident Photo						Load JPG	☒	
9	27/12/18 10:59	Accident Photo						Load JPG	☒	
10	27/12/18 10:59	Accident Photo						Load JPG	☒	
11	27/12/18 10:59	Accident Photo						Load JPG	☒	
12	27/12/18 10:59	Accident Photo						Load JPG	☒	
13	27/12/18 10:59	Accident Photo						Load JPG	☒	
14	27/12/18 10:59	Accident Photo						Load JPG	☒	
15	27/12/18 10:59	Accident Photo						Load JPG	☒	
16	27/12/18 10:59	Accident Photo						Load JPG	☒	
17	27/12/18 10:59	Accident Photo						Load JPG	☒	
18	27/12/18 10:59	Accident Photo						Load JPG	☒	
19	27/12/18 10:59	Accident Photo						Load JPG	☒	
20	27/12/18 10:59	Accident Photo						Load JPG	☒	
21	27/12/18 10:59	Accident Photo						Load JPG	☒	
22	27/12/18 10:59	Accident Photo						Load JPG	☒	
23	27/12/18 10:59	Accident Photo						Load JPG	☒	
24	27/12/18 10:59	Accident Photo						Load JPG	☒	
25	27/12/18 10:59	Accident Photo						Load JPG	☒	
26	27/12/18 10:59	Accident Photo						Load JPG	☒	
27	27/12/18 10:59	Accident Photo						Load JPG	☒	
28	27/12/18 10:59	Accident Photo						Load JPG	☒	
29	27/12/18 10:59	Accident Photo						Load JPG	☒	
30	27/12/18 10:59	Accident Photo						Load JPG	☒	
31	27/12/18 10:59	Accident Photo						Load JPG	☒	
32	27/12/18 10:59	Accident Photo						Load JPG	☒	
33	27/12/18 10:59	Accident Photo						Load JPG	☒	
34	27/12/18 10:59	Accident Photo						Load JPG	☒	
35	27/12/18 10:59	Accident Photo						Load JPG	☒	
36	27/12/18 10:59	Accident Photo						Load JPG	☒	
37	27/12/18 11:01	Dismantled Parts						Load JPG	☒	
38	27/12/18 11:01	Dismantled Parts						Load JPG	☒	
39	27/12/18 11:01	Dismantled Parts						Load JPG	☒	
40	27/12/18 11:01	Dismantled Parts						Load JPG	☒	
41	27/12/18 11:01	Dismantled Parts						Load JPG	☒	
42	27/12/18 11:01	Dismantled Parts						Load JPG	☒	
43	27/12/18 11:01	Dismantled Parts						Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
45	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
46	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
47	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
48	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
49	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
50	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
51	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
52	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
53	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
54	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
55	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
56	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
57	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
58	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
59	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
60	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
61	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
62	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
63	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
64	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
65	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
66	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
67	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
68	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
69	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
70	27/12/18 11:01	Dismantled Parts	 Load JPG	☒
71	27/12/18 11:03	Photo After Spray	 Load JPG	☒
72	27/12/18 11:03	Photo After Spray	 Load JPG	☒
73	27/12/18 11:03	Photo After Spray	 Load JPG	☒
74	27/12/18 11:03	Photo After Spray	 Load JPG	☒
75	27/12/18 11:03	Photo After Spray	 Load JPG	☒
76	27/12/18 11:03	Photo After Spray	 Load JPG	☒
77	27/12/18 11:03	Photo After Spray	 Load JPG	☒
78	27/12/18 11:03	Photo After Spray	 Load JPG	☒
79	27/12/18 11:03	Photo After Spray	 Load JPG	☒
80	27/12/18 11:03	Photo After Spray	 Load JPG	☒
81	27/12/18 11:03	Photo After Spray	 Load JPG	☒
82	27/12/18 11:03	Photo After Spray	 Load JPG	☒
83	27/12/18 11:03	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/12/18 16:35	EMAIL FROM III DD 11122018	 Load PDF	
2	11/12/18 16:35	NOTICE & GIA REPORT	 Load PDF	
3	12/01/19 16:04	TP Estimate-Marked	 Load PDF	
4	06/12/19 13:57	WORKSHOP INVOICE	 Load PDF	
5	06/12/19 13:57	RENTAL RECEIPT	 Load PDF	
6	06/12/19 13:57	LTA SEARCH	 Load PDF	
7	06/12/19 13:57	LOD	 Load PDF	
8	20/12/19 14:37	AUTHORISATION TO ACT FORM	 Load PDF	
9	20/12/19 14:37	DISCHARGE VOUCHER	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	12/12/18 09:14	Singapore Accident Statement	 Load PDF	
2	26/03/19 15:43	LOD FROM N-51	 Load PDF	
3	17/04/19 16:12	Letter of Demand from Third Party TPD LOD FROM NS1 AUTOMOTIVE [SLM4459Z]	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18022298/EEB3Q2

Date: 20/12/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No: SLM4459Z Insured Vehicle No: SH8525H
 Date of Loss: 08/12/2018 Nature of Claim: TP Claim No: MCT18120223

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLM4459Z
 Make & Model: NISSAN QASHQAI, 1.2 (A) Engine No: HRA2331779A
 Reg. Date: 30/03/2017 (Man. Year: 2016) Chassis No: SJNFEAJ11U1766779
 Colour: White Odometer: 132272 km
 Engine Capacity: 1197 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
 Front Left Side: Habilead 6 mm Rear Left Side: Habilead 6 mm
 Front Right Side: Habilead 6 mm Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,586.55	2,677.10	909.45	25.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	1,130.00	820.00	42.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,536.55	3,807.10	1,729.45	31.24
Approved Total (Overridden) (S\$)		3,050.00		
(S\$)	5,536.55	3,050.00	2,486.55	44.91
+ GST 7.00/7.00% (S\$)	387.56	213.50	174.06	44.91
Nett Amount (S\$)	5,924.11	3,263.50	2,660.61	44.91
+ Car Rental (3.0 x S\$66.95/day) (S\$)		200.85		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,471.80		

INSPECTION

Date of Assignment: 11/12/2018
 Date Inspected: 17/12/2018 Inspected At: N-51 Automotive Pte Ltd (HQ)
 BLK 2 KAKI BUKIT, #01-17/18 KAKI
 BUKIT AUTOHUB
 Singapore 417921
 Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Dec 2019)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM4459Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	717.00 FL	*717.00 FL
2	3		*REAR BUMPER CENTER HOLDER CLIPS	Necessary	55.50 FL	*30.00 FL
3	1		*REAR BUMPER INNER SPONGE	Torn	126.40 FL	*97.90 FL
4	1		*REAR BUMPER REINFORCEMENT	Dented	619.20 FL	*619.20 FL
5	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Bent	126.00 FL	*126.00 FL
6	1		*REAR BUMPER RH REFLECTOR	Broken	55.00 FL	*55.00 FL
7	1		*REAR BUMPER SIDE RETAINER L/R	O/S Bent / N/S Not Necessary	73.80 FL	*36.90 FL
8	1		*REAR BUMPER TOW HOOK COVER	Cut	16.80 FL	*16.80 FL
9	1		*REAR END PANEL	Repair	482.60 FL	*- FL
10	1		*REAR END PANEL INNER TOP GARNISH	Cracked	63.50 FL	*63.50 FL
11	1		*REAR RH FENDER ARCH GARNISH	Broken	483.00 FL	*483.00 FL
12	1		*REAR RH TAILLAMP	Broken	323.70 FL	*323.70 FL
13	1		*REAR TAILGATE QASHQAI EMBLEM	Not Necessary	87.00 FL	*- FL
14	1		*REAR BUMPER REVERSE SENSOR	Broken	450.00 FS	*300.00 FS
15	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	20.00 FS	*15.00 FS
16	2		*SET REAR FENDER ARCH GARNISH CLIPS L/R	Necessary (1 PCS ONLY)	80.00 FS	*30.00 FS
17	2		*SET REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R	Not Necessary	100.00 FS	*- FS
18	1		*SET REAR RH TAILLAMP CLIPS	Necessary	30.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,909.50	2,934.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	322.95	256.90
Total Parts (\$\$)	3,586.55	2,677.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT, TRIM GARNISH ,TRIN LINER CARPET (TO FR)	New	100.00	0.00
2	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR ,PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	550.00
3	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE- CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	800.00	550.00
4	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	50.00	30.00
Gross Labour Cost (S\$)			1,950.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >