

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

VGS Singapore, 247, 159934 Singapore

ANDREW GAN JIAN WEN
216A COMPASSVALE DRIVE
#11-534
Singapore, 541216
Singapore

Acknowledged by Repairer
Signature:
Date:

VGS Singapore
247
Alexandra Road
159934 Singapore

Phone No. +65 6305 7299
Fax No. +65 6474 3643
E-Mail service@vw.com.sg

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV035447
Quote No. SER/QUO/1802126
QuoteDate 11/12/18
Salesperson JAMES PENG
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.4 CL 92 (DSG)	26,979	Tang Shu Shi
License No.	VIN	Initial Registration	Sales Advisor
SLH8813J	WVWZZZAUZGW209852	31/10/16	JAMES PENG
Engine Code	Labor Type	Engine No.	Model Code
	1T	CZC 431390	5G13HZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P MACP LABOUR	LABOUR	2	5 UNIT		1680 4,200.00
P B&P MACP LABOUR	TFR DOOR MECH	1	UNIT		420 840.00
P B&P MACP PAINT	SPRAY PAINT	2	4 Labor		1600 3,200.00
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		480.00
	COMPULSORY TO DO AFTER AC				
P B&P MECH	CHECK WIRE HARNESS, ECU, S	1	Time Un		280.00
	Nett				
P B&P MECH	RIM & BALANCE	1	Time Un		50.00
	Nett				
P B&P WHEEL ALIGNMENT	B&P WHEEL ALIGNMENT NETT	1	Time Un		360.00
	Sum Labor				4870 9,410.00
P 5G0073147B FZZ	ALLOY WHEELS 17" MADRID	1	Pieces		1,993.36
	With Tyre 225/45 R17 Pirelli				
P 5G0805912J	RHF WHEEL HOUSE LOWER	1	Pieces		43.25
	Use Predecessor 5G0805912H				
P 5G0805970N	RHF WHEEL HOUSE UPPER	1	Pieces		130.59
P 5G0821106A	RHF FENDER	1	Pieces		626.54
	Use Predecessor 5G0821106				
P 5G0821136B	RHF FENDER BRACKET	1	Pieces		33.54
	Use Predecessor 5G0821136A				
P 5G4831056AQ	RHF DOOR	1	Pieces		1,942.49
P 5G4837652B	RHF DOOR SEAL	1	Pieces		109.43
	Use Predecessor 5G4837652A				
P D 378500A2	RHF DOOR INSULATOR	1	Pieces		46.22
Sum carried forward					14,335.42

Payments to: - BBN: - Acc.-No.:

VGS Singapore
247
Alexandra Road
159934 Singapore

Phone No. +65 6305 7299
Fax No. +65 6474 3643
E-Mail service@vw.com.sg

VGS Singapore, 247, 159934 Singapore

ANDREW GAN JIAN WEN
216A COMPASSVALE DRIVE
#11-534
Singapore, 541216
Singapore

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV035447
Quote No. SER/QUO/1802126
QuoteDate 11/12/18
Salesperson JAMES PENG
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description
Volkswagen Passeng	GOLF A7 1.4 CL 92 (DSG)
License No.	VIN
SLH8813J	WVWZZZAUZGW209852
Engine Code	Labor Type
	1T

Mileage	Initial Registration
26,979	31/10/16
Engine No.	
CZC 431390	

Service Advisor	Sales Advisor
Tang Shu Shi	JAMES PENG
Model Code	
5G13HZ	

Continued	14,335.42
-----------	-----------

Sum Item

9752.17

4,925.42

Sum Labor	9,410.00
Sum Item	4,925.42

Total SGD	14,335.42
7% GST	14,335.42
Total SGD Incl. GST	15,338.90

Explanations

P = Proportionately Charged

Payment Terms No Credit

Payments to: - BBN: - Acc.-No.: