REPAIR ESTIMATE*

VEHICLE NO: SHC 8210Y (Supplementary)

: HYUNDAI SONATA

DATE: 19.12.2018

TEL: 6542 5119

FAX: 6542 6039

DEL	: HYUNDAI SONATA		: 0542 0039	
Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Crossmember 184			\$ 1,140.40
				\$ 1,140.40
	SUB TOT			
	LESS 2			\$ 228.08
	DISCOUNTED TO	TAL		\$ 912.32
	19/12/2	n 8	ş	
				_
	J KC/C ANAD			
	FICE TIWA			
	-			
		-		
		1.76		
	7.7		2	
		2		
	2. 4.			- 1
	1,			
		1	3	
		. ,		
			-	
			,	
	This is an initial estimate based on a visual inspecti	on of the above	vehicle. The final ren	air quantum will
	This is an initial estimate based on a visual inspection be prepared after the vehicle is surveyed by a moto	r Surveyor appo	inted by the insurance	company.
	be prepared after the vehicle is surveyed by a moto	A	me of me meeters	