

AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 Shenton Way #07-16
Singapore 079120

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. : **SKK7408Z**

CHASSIS NO : WBAKB42020CY82629

ENGINE NO : 06247157N54B30A

MAKE / MODEL : BMW 740LI 3.0L A/T ABS D/AB 2WD 4DR HID SR

DATE OF ACCIDENT : 08.12.2018 @ 16:30HRS

YOUR INSURED VEHICLE NUMBER : SJQ963M

Resume
Hp 90010068
5 days
48
12/12/18 @ 1355
Revey after repair

<u>PARTS DISCRIPTION</u>	<u>QTY</u>	<u>List Price</u>	<u>Total List Price</u>
FRONT BUMPER ASSY <i>sch</i>	1	\$ 1,350.00	\$ 1,350.00
FRONT LH BUMPER CHROME MOULDING <i>sch</i>	1	\$ 150.00	\$ 150.00
FRONT LH HEADLAMP ASSY <i>glo</i>	1	\$ 950.00	\$ 950.00
FRONT LH FOG LAMP ASSY <i>?</i>	1	\$ 250.00	\$ 250.00
FRONT LH FENDER <i>st</i>	1	\$ 600.00	\$ 600.00
FRONT LH TYRE <i>x</i>	1	\$ 350.00	\$ 350.00
FRONT LH RIM <i>sch</i>	1	\$ 790.00	\$ 790.00

Total	\$ 4,440.00
ADD 10%	\$ 444.00
TOTAL PARTS	\$ 4,884.00

LABOUR CHARGES

TO REMOVE, REPLACE & REPAIR ALL DAMAGES PARTS DUE TO ACCIDENT	\$ 1,050.00 <i>600</i>
TO CHECK, REPAIR AND REPLACE ALL ELECTRICAL WIRE FOR HEADLAMP AND FOG LAMP	\$ 700.00 <i>40</i>
TO SPRAY PAINT ON THE AFFECTED AREAS DUE TO THE ACCIDENT	\$ 600.00 <i>500</i>
TO APPLY ANTI RUSTPROOFING	\$ 100.00 <i>40</i>
TOTAL LABOUR	\$ 2,450.00

SUB TOTAL \$ 7,334.00

LABOUR : \$350 per day
SPRAY PAINT : \$300 per panel

Prepared By : -

LYNN AHMAD

Motor Claims Manager

TEL: 6571 9635 FAX : 6278 5535

EMAIL: lynn@motorway.com.sg