

GUAN HIN MOTOR WORKSHOP

NO 10 ANG MO KIO INDUSTRIAL PARK 2A

#02-03 AMK AUTOPOINT 568047

Tel No. : 64837111 Fax No. : 64837221

E-Mail : guanhinmotor@yahoo.com

Buss. Reg. No. : 06035200X

ISMATH EUNOON

Attention : Motor Claim Department

Estimate : ES000844

Date : 11/12/2018

Vehicle Num. : SJC 1186 G

Make/Model : TOYOTA WISH 1.8-2007

Chassis/Eng# : ZNE100384038/1ZZ2978610

Accident Date : 11/12/2018

Claim No. :

Reference :

Policy No. : (31/01/2008)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR BOOT LID	80.00	80.00
2.	2	REAR BOOT LID HINGE	105.00	210.00
3.	2	REAR BOOT DAMPER		205.00
4.	1	REAR BOOT INNER TRIM BOARD TOP		350.00
5.	1	REAR BOOT INNER TRIM BOARD LOWER		57.00
6.	1	REAR BOOT LOCK		165.00
7.	1	REAR BOOT HANDLE		25.00
8.	1	REAR BOOT EMBLEM		170.00
9.	1	REAR WIPER MOTOR		140.00
10.	1	REAR WIPER ARM		45.00
11.	1	REAR WIPER BLADE		15.00
12.	1	REAR WIPER BLADE COVER		140.00
13.	2	REAR NO PLATE LAMP	70.00	140.00
14.	1	REAR LH FENDER		859.00
15.	1	REAR LH FENDER INNER TRIM BOARD		230.00
16.	1	REAR WEALTHSTRIP		311.30
17.	1	LH TAIL LAMP		605.00
18.	1	REAR END PANEL (INNER)		519.80
19.	1	REAR END PANEL REINFORCEMENT inner		230.00
20.	1	REAR END PANEL GARNISH		605.00
21.	1	REAR BUMPER		490.20
22.	1	REAR BUMPER SIDE RETAINER L/H		50.00
23.	1	REAR BUMPER REFLECTOR		56.50
24.	1	REAR FENDER SHIELD		95.00
25.	2	REAR BUMPER BRACKET	50.00	100.00
26.	1	REAR WINDSCREEN		913.50
27.	1	REAR WINDSCREEN MOULDING		60.00
List Total S\$:				8,080.60
SPECIAL NETT ITEMS :				
1.	1	REVERSER SENSOR		350.00

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

GUAN HIN MOTOR WORKSHOP

Page 2 / 2

NO 10 ANG MO KIO INDUSTRIAL PARK 2A

#02-03 AMK AUTOPOINT 568047

Tel No. : 64837111 Fax No. : 64837221

E-Mail : guanhinmotor@yahoo.com

Buss. Reg. No. : 06035200X

ISMATH EUNOON

Estimate : ES000844

Attention : Motor Claim Department

Date : 11/12/2018
Vehicle Num. : SJC 1186 G
Make/Model : TOYOTA WISH 1.8-2007
Chassis/Eng# : ZNE100384038/1ZZ2978610
Accident Date : 11/12/2018
Claim No. :
Reference :
Policy No. : (31/01/2008)

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1	REAR WINDSCREEN SEALANT		50.00
3.	1	VIEW CAMERA		250.00 ?
		Special Nett Total S\$:		650.00
		LABOUR :		
		LABOUR CHARGE FOR CUTTING & WELDING REAR END PANEL, STRAIGHTEN REAR CHASSIS ,FLOOR BOARD REPAIRING WHEEL-HOUSE AND REPLACEMENT OF PARTS		2,500.00
		REMOVE & FIX BACK CUSHION & UPHOLSTERY		150.00
		REMOVE & FIX BACK FENDER WINDSCREEN AND FIXING REAR BOOT WINDSCREEN		280.00
		TO SPRAY PAINTING		1,200.00
		TO CHECK REAR LIGHTING ,THIRD BRAKE LIGHT WIRING		80.00
		TO REMOVE & INSTALL REAR TAILGATE LOCK ANTI RUST PROOFING ACCIDENT AFFECTED AREA		60.00
		TO REMOVE AND REFIX REAR BOOT ACCESS		200.00
		TO REMOVE & INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR		100.00
		TO REMOVE & REFIT BOOT LID COMPONENT TO REPLACE BOOT LID,CHECK & RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE		180.00
		REMOVE & FIX BACK REAR REVERSE SENSOR		120.00
		Labour Total S\$:		5,050.00
		E. & O.E.	Total S\$:	13,780.60

for GUAN HIN MOTOR WORKSHOP