## Vic (LKKAuto)

From: Vic (LKKAuto)

Sent: Thursday, 14 March, 2019 7:44 PM

To: Janet Tan

Cc: Admin A; Vic (LKKAuto)

Subject: RE: Our Ref: DM18HO03430/JT: Direct Settlement - Accident Involving GBF2596D

(OI: EQI - TBA) AND SJK767U (TP: LKK REF - CC6/EQI18022368/Uhb3) on

12.12.2018

**Attachments:** LKK INSPECTION PHOTOS.pdf; LKK REINSPECTION PHOTOS.pdf; TP ESTIMATE -

MARKED.pdf; Preliminary Advice.pdf

## WITHOUT PREJUDICE

Dear Janet,

We refer further to our below email.

We have inspected TP vehicle SJK 767U at M/s Fastech Auto Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP estimate marked
- **Inspection Photos**
- **Re-inspection Photos**
- **Preliminary Advice**

## Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)





Save the Earth Print only when necessary

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Shu Pei (LKKAuto)

Sent: Thursday, 13 December, 2018 5:25 PM

To: Janet Tan

Cc: Admin A; Vic (LKKAuto)

Subject: Direct Settlement - Accident Involving GBF2596D (OI: EQI - TBA) AND SJK767U (TP: LKK REF -

CC6/EQI18022368/Uhb3) on 12.12.2018

## WITHOUT PREJUDICE

Dear Janet,

We refer to the above matter.

We have inspected TP vehicle SJK 767U at M/s Fastech Auto Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

TP's GIA report

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

Thank you.

Best Regards,

Shu Pei | Admin

**LKK Auto Consultants Pte Ltd** 

Phone: 6366-0055 | email: <u>shupei@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)