

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan

Date: 17 Dec 2018

Preliminary Advice

Insured Vehicle No	: SJB2265K		
TP Vehicle No	: SKU5157H	Accident Date	: 09/12/2018
Make	: VOLKSWAGEN JETTA TSI	Assignment Date	: 12/12/2018
Date of Inspection	: 14/12/2018	Est. Duration of Repair	: 3/Days
Inspection At	: VOLKSWAGEN CENTRE SINGAPORE		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...Rear O/S.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,777.51
Revised Amount	:S\$	4,285.05
Check Items (Estimated)	:S\$	830.18
Total	:S\$	5,115.23

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :We have not authorized repairs.