

VGS Singapore
 247
 Alexandra Road
 159934 Singapore

Phone No. +65 6305 7299
 Fax No. +65 6474 3643
 E-Mail service@vw.com.sg

VGS Singapore, 247, 159934 Singapore

CHAU KIM WA
 214 BISHAN STREET 23
 #03-215
 Singapore, 570214
 Singapore

VAT Registration No. M20098505-2
 Tax No. 199101494Z

Service Quote

Customer No. CV030496
 Quote No. SER/QUO/1802122
 QuoteDate 10/12/18
 Salesperson Trever Koh
 Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA TSI (DSG) TRENDLINE	40,833	Wong MeiY
License No.	VIN	Initial Registration	Sales Advisor
SKU5157H	WVWZZZ16ZFM047471	30/07/15	Trever Koh
Engine Code	Labor Type	Engine No.	Model Code
	M4	CAX F72046	1632G5

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	3	Labor		2,520.00 840
P B&P ALEX PAINT	SPRAY PAINT	2	Labor		1,600.00 800
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		280.00
P B&P MECH	CHECK WIRE HARNESS, ECU, S Nett	1	Time Un		480.00
	Sum Labor				4,880.00
P 5C6807251E	FOAM INSERT ?	1	Pieces		143.83
P 5C6807305	BUMPER REINFORCEMENT ?	1	Pieces		498.22
P 5C6807375	BUMPER BRACKET LEFT REAR X	1	Pieces		91.14
P 5C6807376	BUMPER BRACKET RIGHT REAR Rec	1	Pieces		91.14
P 5C6807393D	GUIDE LEFT REAR X	1	Pieces		91.14
P 5C6807394D	GUIDERIGHT REAR ?	1	Pieces		91.14
P 5C6807421H GRU	REAR BUMPER DE- Predecessor 5C6807417J GRU	1	Pieces		1,258.64
P 5C6807433J	SPOILER end	1	Pieces		535.27
P 5C6807863B	STRIP ?	1	Pieces		96.99
	Sum Item				2,897.51

Payments to: - BBN: - Acc.-No.:

VGS Singapore
247
Alexandra Road
159934 Singapore

Phone No. +65 6305 7299
Fax No. +65 6474 3643
E-Mail service@vw.com.sg

VGS Singapore, 247, 159934 Singapore

CHAU KIM WA
214 BISHAN STREET 23
#03-215
Singapore, 570214
Singapore

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV030496
Quote No. SER/QUO/1802122
QuoteDate 10/12/18
Salesperson Trever Koh
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA TSI (DSG) TRENDLINE	40,833	Wong Meiy
License No.	VIN	Initial Registration	Sales Advisor
SKU5157H	WVWZZZ16ZFM047471	30/07/15	Trever Koh
Engine Code	Labor Type	Engine No.	Model Code
	M4	CAX F72046	1632G5

Sum Labor	4,880.00
Sum Item	2,897.51
Total SGD	7,777.51
7% GST	544.43
Total SGD Incl. GST	8,321.94

Explanations

P = Proportionately Charged

Payment Terms No Credit

Resu
Hp 90010068
3 days
14/12/18 @ 1120
Resu b4 paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Payments to: - BBN: - Acc.-No.: