



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No: 121218

Date: 12.12.2018

Tarkus Interiors Pte Ltd

46 Defu Lane 9,
Singapore 539286.

Hino XZU710R 14FT Wide Cab. 5T

Estimated Repair Cost for Vehicle Reg. No: YP 9147 X

REPLACEMENT OF DAMAGED PANELS / PARTS

1 Pc. Head Lamp Assy. LH <i>ent / scratched</i>	1,490.00 ✓
1 Pc. Head Lamp Procter LH <i>HL</i>	145.00 X
1 Pc. Head Lamp Bracket <i>HL</i>	189.00 X
1 Pc. Grille ?	988.00 ?
1 Pc. Grille Logo ?	160.00 ?
1 Pc. Corner Fender ?	499.00 ?
1 Pc. Corner Fender Top Cover <i>HL</i>	95.00 X
1 Pc. Bumper <i>distorted / Dented</i>	1,380.00 ✓
1 Pc. Bumper Bracket LH <i>HL</i>	325.00 X
6 Pcs. Bumper Clips <i>HL</i> @ 6.00	36.00 ✓
1 Pc. Bumper Fog Lamp ?	399.00 ?
1 Pc. Bumper Fog Lamp Bracket <i>HL</i>	185.00 X
1 Pc. Step Panel <i>HL</i>	495.00 X
1 Pc. Company Logo Sticker & Words <i>HL</i>	330.00 (S.Nett) ✓
1 Pc. Company Tel. Sticker <i>HL</i>	105.00 (S.Nett) ✓
1 Pc. Itoki Group Sticker (Two Color) <i>HL</i>	200.00 (S.Nett) ✓
1 Pc. 616 Sticker <i>HL</i>	45.00 ✓
10 Pcs. Grille Clips <i>HL</i> ? @ 5.00	50.00 ?

Total (Panels / Parts): **7,116.00 (SGD)**

LABOR CHARGES

To check wiring	120.00 30/-
To repair & renew, straightening & knocking all accidents Affected area.	800.00 600/-



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



To respray painting on all accident affected area.

~~800.00~~ 600/-

To reseal all stickers.

~~120.00~~ NRI 80/-

Total (Labor Charges): 1,840.00 (SGD)

TOTAL COST SUMMARY

PANELS / PARTS 7,116.00

LABOR CHARGES 1,840.00

Grand Total: 8,956.00 (SGD)

13/12/2018 @ 1430 hrs

N/A Andrew

~~4~~ P/Part

Try 5 days

LKK Auto

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Check part price.

Photo is 4 part

Photo with damage parts.