

INS. CASE OWNER:

Bernard

CC 6, MG 180

2434, Ufa32

LKK:

IDAC:

Surveyor:

Marius

DOI:

ASSIGNMENT

13/12/2018

Date / Time:

13/12/18

Registered in Merimen:

13/12/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLX 439A

Name of Insured:

SEAH SHEAM MING

Insured Tel No.:

HP:

Excess Sec II : \$

D.O.A.: 30/11/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Maz. Outlander

Place of Accident:

LCP

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

V/L

FBJ 19705



INSRS:

WSP:

Tel:

Liability:

RMKS:

BHA



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time		STAGE	DATE / PIC
18/12/18	FBJ 19705, X: SLX 439 A, X	Non-Reporting ltr (1st):	
18/12/18		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
11/1/2019	Spoke to OI (Mr. Seah) confirmed accident details, intent there is some vehicle involve in accident, OI try to survive left to avoid collision with front vehicle however he still collided into front vehicle after OI change lane TP called into OI now portion due to OI change lane, OI agree to settle and own. Help libse send letter to OI. Seek instruction for BOLA 28 (I) Bernard said 28 (I) not apply as 28 (I) for OI loss control Bernard suggest 50% offer to 50% or wait PIR	After call ltr to OI: 11/1/2019	
25/3/2020	FILE PMS TO HMM TO CLOSE	Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	
		After call ltr to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.: 28 (I)

If NO or BOLA Ass. Lia

Repair Cost:

\$

Loss of Rental (LOR):

\$

(days)

Loss of Use (LOU):

\$

(\$ x days)

Loss of Income (LOI):

\$

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$

Medical:

\$

Disbursement:

\$

Legal Cost

\$

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

WP

3) Survey fee:

\$290

Total:

\$

Global Sum \$:

Email

Call

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

\$

Name 1:

Payee 2: (Strike if N.A.)

\$

Name 2:

Payee 3: (Strike if N.A.)

\$

Name 3:

(00/11/13) waf

ASS. REC. BY: MAR 16/15

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: F3J19705at Workshop m/s BHM

of _____

Insured: SLX439A

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

X	
N/S	O/S

Bal. or Market Value: 16k.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: 95247Date / Time Action / Instruction 20/1/155 yrs 27A1381L1 - \$5800 (Red \$3681 / 39%) - exclude check items \$1221

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format : _____

Lump Sum / I.B.I: (\$) _____

Veh No: F3J19705 Yr Regn: 1, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda CBR1000RR 999Colour: multi colour A/C: Insured / Std / NI / NASp. Reading: totally flat T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JH2SC59A6DK501047

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120-70ZR17R: 160-70ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 30/1/14 D.O.I. 13/12/14

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

full, old body

The U/C / Chassis frame / Body Structure affected due to collision.

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBJ1970S		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HONDA		
Vehicle Model :	CBR1000RR		
Chassis No. :	JH25C59A6DK501047		
Propellant :	Petrol		
Engine No. :	SC59E2410919		
Engine Capacity :	999 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	379 kg		
Unladen Weight :	200 kg		
Year Of Manufacture :	2013		
Original Registration Date :	24 Jan 2014		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$2,704.00		
COE Expiry Date :	23 Jan 2024		
Road Tax Expiry Date :	23 Jan 2019		
Inspection Due Date :	23 Jan 2019		
Intended Transfer Date :	13 Dec 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 23 Jan 2019. You may renew the road tax from 24 Oct 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 23 Jan 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 24 Jan 2019 to 23 Jul 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	126.00	-	126.00
Total Amount Payable :			151.00
Amount Payable (From 24 Jan 2019 to 23 Jan 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	252.00	-	252.00
Total Amount Payable :			277.00

You may print this page for reference.

OK

Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9529J
Vehicle Details	
Vehicle No.:	FBJ1970S
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Dec 2018
Vehicle Make:	HONDA
Vehicle Model:	CBR1000RR
Primary Colour:	Orange
Manufacturing Year:	2013
Engine No.:	SC59E2410919
Chassis No.:	JH2SC59A6DK501047
Maximum Power Output:	-
Open Market Value:	\$12,848.00
Original Registration Date:	24 Jan 2014
First Registration Date:	24 Jan 2014
Transfer Count:	1
Actual ARF Paid:	\$1,928.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Jan 2024
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$2,704.00
COE Rebate Amount:	\$1,381.00
Total Rebate Amount:	\$1,381.00

The information contained herein is correct as at 14 Dec 2018

OK



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 19700288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 33355

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

DATE : 12/12/2018
CLAIM NO. : 11219
POLICY NO. : MC/00512733
FROM : RAYMOND

VEHICLE NO. : FBJ1970S
MAKE/MODEL : HON / CBR1000RR

not Alford
13/12/18
21/12/18
Alford

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BOLT P/N: 50534	REPLACE	4.00	\$9.00	36.00 ?
2	CAP BOOST	REPLACE	1.00	\$0.00	0.00 ?
3	CAP CRANKCASE COVER 45MM	REPLACE	1.00	\$39.00	39.00 ?
4	CLIP NUT P/N: 50536	REPLACE	2.00	\$7.00	14.00 ?
5	COVER AIR DUCT LH	REPLACE	1.00	\$32.00	32.00 <i>one</i>
6	COVER AIR DUCT RH	REPLACE	1.00	\$32.00	32.00 <i>one</i>
7	COVER COWLING LAYER LH	REPLACE	1.00	\$95.00	95.00 <i>one</i>
8	COVER COWLING LAYER RH	REPLACE	1.00	\$95.00	95.00 <i>one</i>
9	COVER COWLING MIDDLE	REPLACE	1.00	\$52.00	52.00 <i>one</i>
10	COVER CRANKCASE COMP.	REPLACE	1.00	\$575.00	575.00 <i>one</i>
11	COVER INTAKE	REPLACE	1.00	\$52.00	52.00 <i>one</i>
12	COVER LAYER LH	REPLACE	1.00	\$18.00	18.00 <i>one</i>
13	COVER LAYER RH	REPLACE	1.00	\$18.00	18.00 <i>one</i>
14	COVER MIRROR INNER RH	REPLACE	1.00	\$213.00	213.00 <i>one</i>



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2003-1-2083
ISO 9001 : 2015

S/N	Description	Action	Qty	Unit Price	Amount
15	COVER MIRROR OUTER LH	REPLACE	1.00	\$48.00	48.00 ✓
16	COVER MIRROR OUTER RH	REPLACE	1.00	\$48.00	48.00 ✓
17	COVER SIDE RH	REPLACE	1.00	\$1,105.00	1,105.00 ✓
18	COWLING MIDDLE	REPLACE	1.00	\$892.00	892.00 ✓
19	COWLING MIDDLE INNER LH	REPLACE	1.00	\$52.00	52.00 ✓
20	COWLING MIDDLE LH	REPLACE	1.00	\$1,105.00	1,105.00 ✓
21	DAMPER MIRROR	REPLACE	2.00	\$9.00	18.00 ✓
22	DUCT AIR LH	REPLACE	1.00	\$145.00	145.00 ✓
23	DUCT AIR RH	REPLACE	1.00	\$145.00	145.00 ✓
24	HEADLAMP ASSY	REPLACE	1.00	\$1,445.00	1,445.00 ✓
25	HORN	REPLACE	1.00	\$182.00	182.00 ✓
26	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	16.00	\$35.00	560.00 ✓
27	MUDGUARD FRONT	REPLACE	1.00	\$405.00	405.00 ✓
28	NUT PLASTIC (WINDSHIELD) P/N: 30543	REPLACE	1.00	\$8.00	8.00 ✓
29	NUT PLASTIC (WINDSHIELD) P/N: 30543	REPLACE	8.00	\$8.00	64.00 ✓
30	NUT RUBBER	REPLACE	2.00	\$8.50	17.00 ✓
31	O-RING (48.1X3.6) P/N: 36668	REPLACE	1.00	\$12.00	12.00 ✓
32	PROTECTOR EXHAUST	REPLACE	1.00	\$488.00	488.00 ✓
33	RIVET P/N: 40901	REPLACE	11.00	\$9.00	99.00 ?
34	RUBBER COVER SEAL DUCT LHRUBBER COVER- SEAL DUCT	REPLACE	1.00	\$49.00	49.00 ?
35	RUBBER COVER SEAL DUCT RH	REPLACE	1.00	\$49.00	49.00 ?



Quotation Nos. : 33355

S/N	Description	Action	Qty	Unit Price	Amount
36	SCREW SMALL BOX P/N: 29943	REPLACE	6.00	\$7.50	45.00 ?
37	STAY COWLING P/N: 50539	REPLACE	2.00	\$18.00	36.00 ?
38	STAY HEADLAMP	REPLACE	1.00	\$383.00	383.00 ?
39	STAY VACUUM TANK	REPLACE	1.00	\$22.00	22.00 ?
40	TANK VACUUM COMP.	REPLACE	1.00	\$65.00	65.00 ?
41	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2 P/N: 45836 - FOR COLLECTION OF ACCIDENT BIKE.		1.00	\$55.00	35 55.00
42	WASHER	REPLACE	4.00	\$7.00	28.00 ?
43	WINDSCREEN SET	REPLACE	1.00	\$235.00	cm 235.00
44	WIRE HARNESS METER	REPLACE	1.00	\$405.00	405.00 ?

SUB TOTAL

\$9,481.00

GST @ 7 %

\$663.67

GRAND TOTAL

\$10,144.67

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

UKR Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is claimed
- Supplementary damage must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



CERT NO.: 2002-1-0383
ISO 9001 : 2015

Bike model
cbr1000

Type
Any

Price From
Any

Price To
Any

Class
Any

MORE SEARCH OPTIONS ▼

Q SEARCH

VIEW ALL (/LISTING/USEDBIKES/LISTING/)

Q SEARCH ▼

Honda CBR1000RA (/listing/usedbike/honda-honda-cbr1000ra/8492/)



(/listing/usedbike/honda-honda-cbr1000ra/8492/)

SGD\$38800

Reg : 27/02/2018

Type: Sport Bikes

1000cc

Pre-Reg Feb 2018 Honda CBR1000RA for Sale! Prices are negotiable. Trade in or Loan available. Viewing will be at Dynasty Motor Pte Ltd @ Kaki Bukit, Synergy @ KB, 25 Kaki Bukit Road 4 #01-82 ...

Posted on : 06/12/2018

★ PAID AD ★ DEALER AD

■ COMPARE

DETAILS > (/LISTING/USEDBIKE/HONDA-HONDA-CBR1000RA/8492/)

Honda CBR1000RR (/listing/usedbike/honda-honda-cbr1000rr/7844/)



(/listing/usedbike/honda-honda-cbr1000rr/7844/)

SGD\$9800

Reg : 19/05/2006

Type: Sport Bikes

998cc

Honda CBR1000RR for Sale. Interested parties are welcome to Neg. Trade/Loan available. Do visit us at Wing Fuat @ Sims Place! No Early Settlement Fee.

Posted on : 22/11/2018

★ PAID AD ★ DEALER AD

■ COMPARE DETAILS > (/LISTING/USEDBIKE/HONDA-HONDA-CBR1000RR/7844/)

Honda CBR1000RR (/listing/usedbike/honda-honda-cbr1000rr/10396/)



(/listing/usedbike/honda-honda-cbr1000rr/10396/)

SGD\$16000

Reg : 07/11/2008

Type: Sport Bikes

999cc

101000km

Selling bike due to upgrading. COE just renewed for 10 years. Bike well maintained. However may need some light touch ups cosmetic wise to enhance the looks. Looking for full cash or Reloan o...

Posted on : 19/11/2018

★ PAID AD ★ DIRECT SELLER

■ COMPARE DETAILS > (/LISTING/USEDBIKE/HONDA-HONDA-CBR1000RR/10396/)

Honda CBR1000RR (/listing/usedbike/honda-honda-cbr1000rr/10618/)

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Thursday, 31 January 2019 3:50 PM
To: 'Raymond'
Cc: CS A Team; Marcus Chua (LKKAUTO); Vivian Lau (LKKAUTO); Admin A
Subject: RE: Accident Involving FBJ1970S & SLX439A on 30/11/2018 *** LKK REF: CC6/AIG18022434/Ufa3

Importance: High

WITHOUT PREJUDICE

Our Ref: CC6/AIG18022434/Ufa3
Your Ref: FBJ 1970S

Dear Raymond,

We refer to the above matter and our tele conversation.

Apologies for late reply.

Please be informed that we have review the matter and we have instruction from **our Principal** propose 50/50 as Our Insured purposely change lane to avoid collision with front vehicle and your client collided into rear portion of our Insured vehicle when Our Insured already complete change lane. Our Insured had put red indicator to warn it is a long vehicle and had signal light before turning. We are view that your rider collided into rear of our Insured vehicle needed to be partially liable also.

As discuss, Please confirm Liability or furnish us a copy of Traffic Police Investigation Result.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



AUTO
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.


Poh Kin (LKKAuto)

From: Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>
Sent: Friday, 11 January 2019 4:57 PM
To: Poh Kin (LKKAuto)
Cc: Admin A
Subject: RE: Your Ref: 2078952405SG; Our Ref: CC6/AIG18022434/Ufa3
Attachments: image4.jpeg

Dear Poh Kin,

We would like to inform that the latest BOLA on scenario 28(j) mentioned that vehicle B lost control and collided into both A & C. (refer below)

28.	(j)	New	Vehicle B lost control and hit onto both A and C B is 100% liable to both A and C C is 100% liable to D D is 100% liable to E Reason: To avoid costly litigation for collision damages
-----	-----	-----	---



However, our insured vehicle did not lost control but he intentionally swerved to the left by making a lane change to avoid impact to the vehicle in front. Based on the scene photo provided, it also substantiate that our insured vehicle has completed the lane change and the damages to our insured vehicle is at the centre of the rear bumper.

Hence, BOLA 28(j) is not applicable for this accident and kindly advise TP to claim under OD to expedite the matter.

Thank you.

Best Regards,

Bernard Ler
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946

Bernard-JQ.Ler@aig.com | www.aig.com.sg

From: Poh Kin (LKKAuto) [mailto:pohkin@lkkauto.com]
Sent: 11 January 2019 3:45 PM
To: Ler, Bernard-JQ
Cc: Admin A
Subject: Your Ref: 2078952405SG; Our Ref: CC6/AIG18022434/Ufa3
Importance: High

WITHOUT PREJUDICE

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Friday, 11 January 2019 3:45 PM
To: 'Ler, Bernard-JQ'
Cc: Admin A
Subject: Your Ref: 2078952405SG; Our Ref: CC6/AIG18022434/Ufa3
Attachments: image4.jpeg; image11.jpeg

Importance: High

WITHOUT PREJUDICE

Your Ref: 2078952405SG
Our Ref: CC6/AIG18022434/Ufa3


Dear Benard,

ROAD TRAFFIC ACCIDENT INVOLVING NOS. SLX 439A (OI), FBJ 1970S (TP) AND OTHERS ALONG ECP ON 25/12/2018

We refer to the above matter and our tele conversation.

Nature of the accident: The said chain collision involved Four motor car and One Motorcycle. Our Insured is the last motorcar and alleged that is a prior collision for those front vehicle, our Insured try to swerve left to avoid the said collision, however he unable stop in time and collided into front vehicle rear left portion and causing the motorcycle who was driven along second lane from right unable to stop in time and collided into rear portion of OI vehicle.

Please be informed that we have offer 50% Liability to TP repairer as per your instruction, however TP reject 50% liability and furnish us a copy of the accident scene photo. They dispute their client already complete change lane as per scene photo and proposed settle this matter as per BOLA 28(j).

28.	(j)	New 	<p>B is 100% liable to both A and C C is 100% liable to D D is 100% liable to E</p> <p>Reason: To avoid costly litigation for collision damages</p>
-----	-----	---	--

We managed to spoke to OI (Mr Seah), confirmed accident details. OI changing lane for avoid the collision. We informed TP claim and NCD issue. OI agreed to settle, aware NCD will be affected.

For your comments/instruction on this matter.

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Jia Le (LKK Auto)

From: Raymond <raymond@bhh.com.sg>
Sent: Monday, 20 January 2020 3:07 PM
To: Jia Le (LKK Auto)
Subject: RE: Accident Involving FBJ1970S & SLX439A on 30/11/2018 *** LKK REF: CC6/AIG18022434/Ufa3

Dear Jia Le,

As informed by our client, he has engaged lawyer to proceed with the claims and is pending for the TPIR.

Thanks

Best Regards,

Raymond

Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>

Facebook: <http://www.facebook.com/bhhsg>



BAN HOCK HIN
Co., Pte Ltd

No. 6 Defu Lane 4, Singapore 539410

www.bhh.com.sg | [facebook.com/bhhsg](https://www.facebook.com/bhhsg)

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | L



From: Jia Le (LKK Auto) <JiaLe@lkkauto.com>

Sent: Monday, 20 January, 2020 3:03 PM

To: Raymond <raymond@bhh.com.sg>

Subject: RE: Accident Involving FBJ1970S & SLX439A on 30/11/2018 *** LKK REF: CC6/AIG18022434/Ufa3

WITHOUT PREJUDICE

Dear Raymond,

Kindly let us have a copy of Police Investigation Result.

Thank you.

Jia Le (LKK Auto)

From: Mei Kwan (LKKAuto)
Sent: Monday, 20 January 2020 2:20 PM
To: Ler, Bernard-JQ; Jia Le (LKK Auto)
Cc: Admin A
Subject: RE: Your Ref: 2078952405SG; Our Ref: CC6/AIG18022434/Uda3
Attachments: image4.jpeg

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and get back to you in due course.

Hi Jia Le,

Kindly assist.

To check availability of the case handler, you may contact the undersigned.

“Wishing you a Happy and Prosperous Lunar New Year”



Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>
Sent: Monday, 20 January, 2020 10:20 AM
To: Admin A <admin-a@lkkauto.com>
Subject: RE: Your Ref: 2078952405SG; Our Ref: CC6/AIG18022434/Ufa3

Dear LKK,

Please advise on who is the PIC.

Dear PIC,

Please advise whether there is any reply from TP. Please submit WP report for closure if there is no development.

Thanks.

Best Regards,

Bernard Ler
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Jia Le (LKK Auto)

From: Jia Le (LKK Auto)
Sent: Tuesday, 12 November 2019 9:34 AM
To: Raymond
Subject: RE: Accident Involving FBJ1970S & SLX439A on 30/11/2018 *** LKK REF: CC6/AIG18022434/Ufa3

WITHOUT PREJUDICE

Dear Raymond,

Kindly let us have a copy of Police Investigation Result.

Thank you.

Best Regards,

Chan Jia Le | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Raymond [mailto:raymond@bhh.com.sg]
Sent: Tuesday, 12 November 2019 9:22 AM
To: Jia Le (LKK Auto)
Subject: RE: Accident Involving FBJ1970S & SLX439A on 30/11/2018 *** LKK REF: CC6/AIG18022434/Ufa3

Dear Jia Le,

Our client do not accept the liability at 50/50.

Thanks

Best Regards,

Raymond

Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>

Facebook: <http://www.facebook.com/bhhsg>



BAN HOCK HIN
Co., Pte Ltd

No. 6 Detu Lane 4, Singapore 539410

www.bhh.com.sg | [facebook.com/bhhsg](https://www.facebook.com/bhhsg)

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | L



From: Jia Le (LKK Auto) <JiaLe@lkkauto.com>

Sent: Tuesday, 12 November, 2019 9:17 AM

To: Raymond <raymond@bhh.com.sg>

Subject: RE: Accident Involving FBJ1970S & SLX439A on 30/11/2018 *** LKK REF: CC6/AIG18022434/Ufa3

WITHOUT PREJUDICE

Dear Raymond,

Kindly advise if your client accept the liability.

Thank you.

Best Regards,

Chan Jia Le | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Raymond [<mailto:raymond@bhh.com.sg>]

Sent: Thursday, 5 September 2019 5:14 PM

To: Jia Le (LKK Auto)

Subject: RE: Accident Involving FBJ1970S & SLX439A on 30/11/2018 *** LKK REF: CC6/AIG18022434/Ufa3

Dear Jia Le,

Still pending to receive the confirmation from our client.

Reminder email sent.

Thanks

Best Regards,

Raymond

Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>

Facebook: <http://www.facebook.com/bhhsq>



BAN HOCK HIN
Co., Pte Ltd

No. 6 Defu Lane 4, Singapore 539410

www.bhh.com.sg | facebook.com/bhh

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | L



From: Jia Le (LKK Auto) <JiaLe@lkkauto.com>

Sent: Thursday, 5 September, 2019 5:06 PM

To: Raymond <raymond@bhh.com.sg>

Subject: RE: Accident Involving FBJ1970S & SLX439A on 30/11/2018 *** LKK REF: CC6/AIG18022434/Ufa3

WITHOUT PREJUDICE

Dear Raymond,

Kindly advise if your client accept our offer.

Thank you.

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Raymond [<mailto:raymond@bhh.com.sg>]

Sent: Thursday, 31 January, 2019 3:53 PM

To: Poh Kin (LKKAuto)

Cc: CS A Team; Marcus Chua (LKKAuto); Vivian Lau (LKKAuto); Admin A

Subject: RE: Accident Involving FBJ1970S & SLX439A on 30/11/2018 *** LKK REF: CC6/AIG18022434/Ufa3

Dear Poh Kin,

Thank you for your confirmation on your insured liability..

We will inform our client accordingly.

Thanks

Best Regards,
Raymond

Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>

Facebook: <http://www.facebook.com/bhhsg>



No. 6 Defu Lane 4, Singapore 539410

www.bhh.com.sg

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | L



From: Poh Kin (LKKAUTO) <pohkin@lkkauto.com>

Sent: Thursday, 31 January, 2019 3:50 PM

To: Raymond <raymond@bhh.com.sg>

Cc: CS A Team <cs-a@lkkauto.com>; Marcus Chua (LKKAUTO) <MarcusChua@lkkauto.com>; Vivian Lau (LKKAUTO) <vivianlau@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Accident Involving FBJ1970S & SLX439A on 30/11/2018 *** LKK REF: CC6/AIG18022434/Ufa3

Importance: High

WITHOUT PREJUDICE

Our Ref: CC6/AIG18022434/Ufa3

Your Ref: FBJ 1970S

Dear Raymond,

We refer to the above matter and our tele conversation.

Apologies for late reply.

Please be informed that we have review the matter and we have instruction from **our Principal** propose 50/50 as Our Insured purposely change lane to avoid collision with front vehicle and your client collided into rear portion of our Insured vehicle when Our Insured already complete change lane. Our Insured had put red indicator to warn it is a long vehicle and had signal light before turning. We are view that your rider collided into rear of our Insured vehicle needed to be partially liable also.

As discuss, Please confirm Liability or furnish us a copy of Traffic Police Investigation Result.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Raymond [<mailto:raymond@bhh.com.sg>]

Sent: Thursday, 31 January 2019 11:56 AM

To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; Poh Kin (LKKAuto) <pohkin@lkkauto.com>

Cc: CS A Team <cs-a@lkkauto.com>; Marcus Chua (LKKAuto) <MarcusChua@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Accident Involving FB1970S & SLX439A on 30/11/2018 *** LKK REF: CC6/AIG18022434/Ufa3

Dear Poh Kin,

We refer to our numerous emails related to the above third party claims since 18 December 2018.

Until to date we have yet to receive any respond from you.

As requested by our client, please revert with your reply on your insured liability within 7 days from the date of this email.

Thanks

Best Regards,

Raymond

Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>

Facebook: <http://www.facebook.com/bhhsg>