

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SGG 3956C
TP/LONPAC

M/S : LONPAC INSURANCE BERHAD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

TEL: 62507388

FAX: 62963767

ATTN: Motor Claim Department

WS Ref: TP/LONPAC/YS

Claim Type: Third Party

Accident Date: 11/12/2018

TP Veh Reg No: SJW2677U

Estimate No: ES1891406/YISHUN

Date: 13 Dec 2018

Policy No: 5100405753

Veh Reg No: SGG3956C

Make/Model: TOYOTA WISH 1.8 A

Chassis No: ZNE100307939

Engine No: 1ZZ2579443

Reg. Date: 10/05/2006

Estimate Repair Cost to Vehicle No :SGG3956C

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	497.6000	1 PC	497.60	✓
2 REAR BUMPER RH SIDE RETAINER	55.6000	1 PC	55.60	✓
3 REAR BUMPER CLIP	3.5000	6 PC	21.00	✓
4 REAR TAILGATE	1,272.400	1 PC	1,272.40	✓
5 TAILGATE INNER LOCK	398.1000	1 PC	398.10	?
6 TAILGATE INNER RUBBER	322.3000	1 PC	322.30	50% ✓
7 TAILGATE LOGO	59.1000	1 PC	59.10	✓
8 TAILGATE MOULDING	419.8000	1 PC	419.80	✓
9 REAR PANEL OUTER	519.3000	1 PC	519.30	?
			3,565.20	
		Less 25%	891.30	2,673.90
Special Net				
10 REAR WINDSCREEN GLASS SEALANT	40.0000	1 PC	40.00	✓
11 REVERSE SENSOR	200.0000	1 PC	200.00	✓
			240.00	240.00
Labour				
12 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.0000	1 LA	100.00	✓
13 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, TAILGATE, LOCK ASSY; TO CUTTING, WELDING & RENEW REAR PANEL; KNOCKING & REPAIR REAR RH FENDER & REALIGN THE SAME	700.0000	1 LA	700.00	600 ✓
14 PUTTY & RESPRAY PAINTING ON REAR PANEL, REAR BUMPER, REAR RH FENDER, TAILGATE	750.0000	1 LA	750.00	650 ✓
15 RUSTPROOFING	60.0000	1 LA	60.00	✓
			1,610.00	1,610.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$ 4,523.90

Add GST @ 7% 316.67

Total Amount Payable S\$ 4,840.57

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE