Surguer	-	REF: CSI/C	NB180221163/BS	Dez	Special Instruction:	
	Rilly Vac	ASS	SIGNMENT (Offi	ce)	Цз: 4 8000	00
	i): Billy Lee	of CNB		-2018	Third Parties:	
Estimated Co	ost:	-Bill to:			Claimant;	
OD/TP Re-in	aspection / Eva	Justical			Surveyor: K1	Λ 1
		SJS 7163Z		CIAZIONA	Workshop: UN	un hu10
at Workshop	m/s	Guan Auto		STY JIO3B		
	811	k 7 Sin Ming Ind :	Tel:		b and a	
	1	J I I				
Sum Insured:			Excess:			
Make of Veh				18-10-2018		
Client's Record	1)		D.O.A	1-10-010		
200				Н	O.D. Endorsement/Date	:
Date/Time:		Person Contacted:	Vehi	icle IN/OUT		
Date/Time:	Co	onfirmed with	Final Fig	days (Rec	15/_%; 0	riginal 12 day
Date/Time:	13/12/18 Su	bmit Final Fig \$5.05	0/- , 8 days (R	ted \$ 2,250/13	37%; Original 1	2days)
Date/Time	Action/Instruc					
	SJS 7163Z					
	STA JUSE	- X	EIVED 1 t DEC	2018		************
	-	REC	EINFRIG	7010		
					1	
					mato	
	Ropain	days 8			1	3 rodal3
		V	TE	ILIM .		TO BLIVE
				hun	, ७,	
Para(1):	Parts found	not replaced (To	a bi-trata		17-12-18	
(2)	- LI LO TOURG	not replaced (To	o highlight R	or UB, LR	t, Etc)	
4						
Para(2):	Comments o	on consistency of d	amages (Parts N	ot Consists	A - NICO	
		- The state of the	amages (Farts IV	ot Consiste	nt: IVC j	
Para(3):	Nett Value					
	Market Val				Fee Charged:	Date:
	Market Van	ie :	Inspected/		Basic & Add	280
	Salvage Val	lue :	Evaluated by:		Transport Photos	
	Nett Value				Others	
			-		Total	280
1) Data m:	(P	1771 to				
1) Date/Tim		File Pass to	2) Date/Time_		File Return to	
<ol> <li>Date/Tim</li> <li>Date/Tim</li> <li>Date/Tim</li> </ol>	ie	File Pass to	2) Date/Time_ 4) Date/Time_		File Return to	•

## Catherine Chong (LKK Auto)

From:

Jun Tian LEE (CNB) < LEE\_Jun\_Tian@cnb.gov.sg>

Sent:

Wednesday, 12 December, 2018 3:03 PM

To:

Olivia Lau (LKKAuto)

Cc:

assignments

Subject:

RE: [CNB]: Assessment of 3rd party vehicle SJS7163Z

### Message Classification: Restricted

Hi Olivia,

Any updates on the assessment?

Regards

### Billy Lee Jun Tian

OC, Precursor Control Unit Operations Division DID: (65) 63251184







Keeping Singapore Drug-Free

Central Narcotics Bureau W cnb.gov.sg FB fb.com/CNB.DrugFreeSG IG Instagram.com/cnb.drugfreesg

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Jun Tian LEE (CNB)

Sent: Thursday, 29 November 2018 4:51 PM

To: 'Olivia Lau (LKKAuto)' <olivialau@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>

Subject: RE: [CNB]: Assessment of 3rd party vehicle SJS7163Z

### Message Classification: Restricted

Hi Olivia,

Appreciate that. So you all will take it up from there when they sent over the documents?

Billy Lee Jun Tian

OC, Precursor Control Unit Operations Division DID: (65) 63251184





HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

Keeping Singapore Drug-Free

Central Narcotics Bureau W cnb.gov.sg FB fb.com/CNB.DrugFreeSG IG Instagram.com/cnb.drugfreesg

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>

Sent: Thursday, 29 November 2018 4:48 PM

To: Jun Tian LEE (CNB) < LEE Jun Tian@cnb.gov.sg>
Cc: assignments < assignments@lkkauto.com>

Subject: RE: [CNB]: Assessment of 3rd party vehicle SJS7163Z

Dear Billy,

An update on this – I spoke to the claimant's workshop Guan Motor representative earlier. They will get the lawyer to forward the claim documents to your email address, and will copy us accordingly.

Thanks.

Best Regards,

Olivia Lau | Admin Manager

**LKK Auto Consultants** 

phone: 6256-3561 | email: <u>olivialau@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | \$(408933) Make good use of Today

From: Jun Tian LEE (CNB) [mailto:LEE Jun Tian@cnb.gov.sg]

Sent: Thursday, 29 November, 2018 11:10 AM
To: Olivia Lau (LKKAuto) < olivialau@lkkauto.com >
Cc: assignments < assignments@lkkauto.com >

Subject: RE: [CNB]: Assessment of 3rd party vehicle SJS7163Z

Message Classification: Restricted

Dear Olivia,

As spoken, I do not have the claim documents i.e. letter of demand, repair bill breakdown, their independent surveyor report etc. Perhaps you can request from Mdm Helen, her contact details are in preceding mail. Thank you.

Regards

### Billy Lee Jun Tian

OC, Precursor Control Unit Operations Division DID: (65) 63251184







Keeping Singapore Drug-Free

Central Narcotics Bureau W cnb.gov.sg FB fb.com/CNB.DrugFreeSG IG Instagram.com/cnb.drugfreesg

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Olivia Lau (LKKAuto) <<u>olivialau@lkkauto.com</u>>
Sent: Wednesday, 28 November 2018 5:13 PM
To: Jun Tian LEE (CNB) <<u>LEE Jun Tian@cnb.gov.sg</u>>
Cc: assignments <assignments@lkkauto.com>

Subject: [CNB]: Assessment of 3rd party vehicle SJS7163Z

Hi Billy,

Police report and video in separate email well received.

We will also require their claim documents i.e. letter of demand, repair bill breakdown, their independent surveyor report etc.

Please give us a call at 6256-3561 again if you need clarification.

Thanks.

Best Regards,

Olivia Lau | Admin Manager

LKK Auto Consultants

phone: 6256-3561 | email: <u>olivialau@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | \$(408933) Make good we of Today

From: Jun Tian LEE (CNB) [mailto:LEE Jun Tian@cnb.gov.sg]

Sent: Wednesday, 28 November, 2018 4:53 PM To: assignments <assignments@lkkauto.com>

Subject: RE: Assessment of 3rd party vehicle SJS7163Z

Message Classification: Restricted

As spoken, I have sent all the required photos and video using my personal email account. Should you need any other documents please feel free to drop me an email. Thank you.

### Regards

### Billy Lee Jun Tian

OC, Precursor Control Unit Operations Division DID: (65) 63251184







Keeping Singapore Drug-Free

Central Narcotics Bureau W cnb.gov.sg FB fb.com/CNB.DrugFreeSG IG Instagram.com/cnb.drugfreesg

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Jun Tian LEE (CNB)

Sent: Wednesday, 28 November 2018 10:53 AM

To: 'assignments@lkkauto.com' <assignments@lkkauto.com>

Cc: Aden POT (CNB) < Aden POT@cnb.gov.sg >; Shirlene YEO (CNB) < Shirlene YEO@cnb.gov.sg >; Muhammad Hafiz

ABDUL HASSAN from.TP (CNB) < Muhammad Hafiz ABDUL HASSAN from.TP@cnb.gov.sg>

Subject: Assessment of 3rd party vehicle SJS7163Z

### Message Classification: Restricted

Dear Sir / Madam,

Please assist to provide us with an assessment on the following vehicle with details as attached and shown below.

- 1. Vehicle Number: SJS7163Z
- 2. Location/address of the vehicle: -
- 3. Contact person: Helen, 90265320
- Please assist to assess particularly the damaged area → front and rear bumper area.
- 5. Should you need video or photos of the accident, Mdm Helen will be able to provide you.
- Once the assessment is done, please provide us with an update. Thank you.

Regards

Billy Lee Jun Tian

OC, Precursor Control Unit Operations Division DID: (65) 63251184





\*\*TRANSFORMATION 2025 \*\*\*\*
One Home, One Team
Building Our Future Together

Keeping Singapore Drug-Free

Central Narcotics Bureau W cnb.gov.sg FB fb.com/CNB.DrugFreeSG IG Instagram.com/cnb.drugfreesg

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



883 North Bridge Road #11-03 Southbank Singapore 198785 T: 6292 5838 F: 6292 5938 (UEN No. 201333127N)

(GST Reg No. 201333127N)

Our Ref

CY.10209A.18.GA(HW).wp(Lh)

Your Ref

**SLA 2103B** 

1 3 DEC 2018

### SINGAPORE POLICE FORCE

BY EMAIL (lee jun tian@cnb.gov.sg)

CRIMINAL INVESTIGATION DEPARTMENT 391 North Bridge Road Police Cantonment Complex Block C Singapore 088762

Dear Sirs

# ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SJS 7163Z & SLA 2103B ON 18.10.2018 @ 07:15HRS ALONG PIE

We are instructed by Yip Zhun Kit Ames to claim damages and losses against you in connection with the above-captioned road traffic accident which our client's vehicle SJS 7163Z was damaged by vehicle SLA 2103B by your insured at the material time.

We are instructed that the said accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

1)	Repair costs	\$ 8,000.00
2)	Loss of Use	\$ 1,500.00
3)	Survey Report Fee	\$ 550.00
	LTA fee	\$ 7.49
5)	Accident report fee	\$ 29.00
6)	Costs & Incidental	\$ 1,000.00
7)	GST on costs & Incidentals	\$ 70.00
.,	COT ON OCCUPANTALE	\$ 11,156.49

A copy each of the following supporting documents is enclosed:-

- Accident report on our client's vehicle
- Survey Report on SJS 7163Z with 32 coloured photographs
- Final repair bill
- 4) LTA Search on SLA 2103B

We had on 19 October 2018 notified your company of the above accident and a pre-repair inspection was carried out by your appointed surveyor.

Please let us know within the next seven (7) days upon receipt of this letter whether you intend to re-inspect our client's vehicle failing which the said vehicle will no longer be available for the same.



883 North Bridge Road #11-03 Southbank Singapore 198785 T: 6292 5838 F: 6292 5938 (UEN No. 201333127N)

(UEN No. 201333127N) (GST Reg No. 201333127N)

Page 2

(CY.10209A.18.GA(HW).wp(Lh)

Please note that you should send to us an acknowledgment of receipt of this letter <u>within fourteen(14) days</u> of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against your insured without further notice to you.

Please note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

Yours faithfully

C. YOGARAJAH LLC

Enc



883 North Bridge Road #11-03 Southbank Singapore 198785 T: 6292 5838 F: 6292 5938 (UEN No. 201333127N) (GST Reg No. 201333127N)

Our Ref

: CY.10209A.18.GA(HW).wp(Lh)

Your Ref

**SLA 2103B** 

4 3 DEC 2018

### SINGAPORE POLICE FORCE

BY EMAIL (lee\_jun\_tian@cnb.gov.sg)

CRIMINAL INVESTIGATION DEPARTMENT 391 North Bridge Road Police Cantonment Complex Block C Singapore 088762

Dear Sirs

ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SJS 7163Z & SLA 2103B ON 18.10.2018 @ 07:15HRS ALONG PIE

We refer to the above matter which we act for Yip Zhun Kit Ames, owner of vehicle SJS 7163Z.

Our client's vehicle was damaged as a result of the negligence of the driver of SLA 2103B. It has come to our knowledge that you were the owner of the said vehicle at the material time of the accident.

As the owner of the said vehicle SLA 2103B, you are required to let us have the following:-

Name, address & NRIC No. of the driver,

2) whether the driver was at the time of the accident driving as your servant or agent

3) whether the driver was an authorised driver and covered by the policy of insurance

Kindly let us know within **seven (7) days** from the date hereof and quote our reference number when you reply.

Yours faithfully

C. YOGARAJAH LLC

MVA218135193 / VAC - Sin Ming ENTRY DATE & TIME: 18/10/2018 11:02 SUBMITTED BY: CHRISTINA ONG Mui Lan

### SINGAPORE ACCIDENT STATEMENT

### · IMPORTANT NOTICE

**EMail Address** 

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to

- repudiate policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

  5. Any false reporting may be referred to the Police for investigation.

  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Carried Township of the Control	ACCIDENT STATEMENT
Date Of Report	18/10/2018 11:02
Date Of Accident	18/10/2018 07:15
Exact Location Of Accident	PIE TOWARDS JURONG TOH TUCK AVENUE EXIT
Country/State of Loss	SINGAPORE
THE RESERVE OF THE PARTY OF THE	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SJS7163Z
Insured/Policyholder	
Name Of Registered Owner	YIP ZHUN KIT AMES
NRIC No	S8807933G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91383284
Alternative Phone No	OTHERS-91383284
Vehicle Particulars	
Manufacturer	TOYOTA
Model	VIOS
Exact Purpose for which vehicle was being used time of accident	at PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	y NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5100738453 (DRIVO CLASSIC)
Cover Note Number	
Driver	
Name of Driver	LIM BOON CHOO
NRIC No	S1651078E
Date Of Birth	08/12/1964
Occupation	INDOOR
Date Of Driving Pass	27/12/1999
Driving Experience	18 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90265320
Fax Number	
Contact Number	OTHERS-90265320
CALAD Address of	

NOEMAIL

Address

BLK 324 #06-295 YISHUN CENTRAL

Postcode

760324

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

PARENT

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

### General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

### Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

3

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: CHIN CHEW FONG

GENDER:

: FEMALE

### Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

### Circumstances of Accident

REFER TO STATEMENT ATTACHED. (ATTENDED BY CHRISTINA)

### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

**SLA2103B** 

Vehicle Make/Model/Colour

HYUNDAI ELANTRA

**Details Of Properties** 

Vehicle Category

PRIVATE CAR

Name of Driver

TAUFIQ ABDUL AZIM BIN MOHAMED AZMAI

NRIC/Passport Number

S9044864A

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SMC6416A

Vehicle Make/Model/Colour

HONDA JAZZ

Details Of Properties

NRIC/Passport Number

Vehicle Category

PRIVATE CAR

Name of Driver

LING CHIN CHIN

Contact Number

S8376865G

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

2

Passenger 1

NAME:

UNKNOWN

GENDER:

: FEMALE

### Sketch Plan Pg. 1

#### SKETCH PLAN

### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the odgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (i) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (i\*) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(i) for complying with requirements under any regulations, laws or court orders.

18 OCT 2018

Policyholder's Signature

Date & Time:

Oriver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

### Sketch Plan #2 Pg. 1

SKETCH PL	AN
1	
· ;	
	A 335 TB 32
	B SANOR
	C Sind 64-16 P
	DOA 129010
DESCRIBE C	19/19/18
COCKIBE C	RCUMSTANCES OF THE ACCIDENT
_0~	18/10/18 @ abut 7.15Am I was string my valuele 3JETH
alm	(0) 5 (
3	The ALL Vehicle C Chand on A CI
4	Sup. Syntalon, & Halt on lynnat !
( 3)	D 2/078
Nu	1 1 1
	various was probable forward and but with which com
CLARATION	
e declare the	foregoing particulars are true in every respect.
	18 00 c
- 1	18 00 1 2018
wholder's Ci	1 (2) A 3
yholder's Signa & Time:	Driver's Signature Population Control of the Contro
2000000	(if driver is not the policyholder)  Date & Time:
	Date & Time: NRIC/FIN No.:



# **KTO** Automobile Assessors

Reg. No: 52941122M

470 Segar Road #09-232 Singapore 670470 Tel: 98505311 Fax: 63107269

\*\*\*\*INVOICE\*\*\*\*

M/S: Yip Zhun Kit Ames

C/O Guan Auto Service.

Blk 7 Sin Ming Industrial Estate Sector C,

#01-82 Singapore 575642.

Invoice No : 18-08049

Invoice Ref : TP/GAS/SJS7163Z/8049

Date : 22 November 2018

DESCRIPTION	Al	MOUNT
For Services Rendered Inspection Report Fees Inclusive Of: Transportation And Photographs Sixty (60) Copies Vehicle No: SJS 7163 Z Make/Model: Toyota Vios E Auto	\$	550.00
Singapore Dollars: Five Hundred Fifty Only	s	550.00

Cheques should be made payable to KTO AUTOMOBILE ASSESSORS. Please indicate our Invoice No. on the reverse of your cheque.

KTO AUTOMOBILE ASSESSORS

Ong Ah Keng (CAE, AMIMI, MSAAA)

Automotive Appraiser

Reg. No: 52941122M

470 Segar Road #09-232 Singapore 670470 Tel: 98505311 Fax: 63107269

### ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S: Yip Zhun Kit Ames

C/O Guan Auto Service.

Blk 7 Sin Ming Industrial Estate Sector C,

#01-82 Singapore 575642.

Date

: 22 November 2018

Our Ref

: TP/GAS/SJS7163Z/8049

#### REFERENCE PARTICULARS

Date of Accident Date of Inspection : 18 October 2018

Type of Inspection : Third Party Claim

: 18 October 2018

Date of Re-Inspn

VEHICLE PARTICULARS

Registration No

: SJS 7163 Z

Make Model

Year

: Toyota

: Vios E Auto

: 2007 (COE Expiry 31 May 2022)

Engine No

: 1NZX553167

Chassis No

: MR053HY9305004059

Odometer

: 107358 km

Colour : White

### CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition

Foot Brake

Hand Brake

: Good

: Serviceable

: Serviceable

General Body Work: Good

: Serviceable

Steering


Lightings

: Serviceable

### TYRE CONDITION (Remaining estimated life of tyre in mm)

	Make	Size	Thread Balance
Front Near side	: Yokohama	195/50R15	6 mm
Front Off Side	: Yokohama	195/50R15	6 mm
Rear Near Side	: Yokohama	195/50R15	6 mm
Rear off Side	: Yokohama	195/50R15	6 mm

### GENERAL DESCRIPTION OF DAMAGES



#### ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was \$8,000.00 nett at lump sum basis. (Subject to GST if applicable)

Under normal circumstances, estimated period required for repairs: Twelve (12) working days.

Enclosed Sixty (60) photographs depicting damage to the vehicle.

Inspection conducted at: Blk 7 #01-82 Sin Ming Industrial Estate Sector C, Singapore 575642.

Name of Workshop: Guan Auto Service.

In accordance to your instruction, we have not authorise repairs and inspection was conducted strictly on a "WITHOUT PREJUDICE BASIS".

### ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

		QTY	ASSESSED		ORIGINAL		REVISED
()	SPARE PARTS	PC/SET	CONDITION		QUOTATION		QUOTATION
1	Front bumper	1	Deformed	\$	598.40	\$	598.40 CUTU
2	Front bumper reinforcement	1	Dented	\$	379.20	\$	379.20 D b ✓
3	Front bumper side support L/R @ \$37.50	2	Damaged	\$	75.00	\$	75.00
4	Front radiator grille	1	Sheared off	\$	359.20	\$	285 359.20 BR/
5	Front radiator grille chrome moulding	1	Grazed	\$	75.20	\$	75.20 CuTV
6	Front support panel	1	Repair	\$	385.50		~
7	Front upper absorber	1	Cracked	\$	195.00	\$	14 195.00
8	Front brace panel	1	Bent	\$	98.50	\$	98.50DDX
9	Front air-con condenser	1	Punctured	\$	933.80	SE	933.80 BT V
0	Front bonnet lock	1	Jammed	\$	41.70	\$	-41.70 NN X
11	Front headlamp L/R @ \$495.60	2	Cracked - RH	TS4-182	991.20	\$ 1	195,60 991.20 CR4V
12	Front radiator assy	1	Serviceable	\$	748.50		~
13	Front radiator fan motor assy	1	Serviceable	\$	483.70		-
14	Rear boot lid	1	Dented	\$	756.60	\$	756.60 R X
15	Rear boot hinges L/R @ \$49.60	2	Serviceable	\$	99.20		~
16	Rear boot lock	1	Jammed	\$	87.90	\$	87.90
17	Rear end panel top garnish	1	Torn	\$	185.64	\$	185.64 CRAV
18	Rear boot license lamp moulding	1	Sheared off	\$	149.50	\$ NO	dose up 149.50 NN X
9	Rear bumper	1	Dislodged	\$	579.00	\$	579.00 DDV
20	Rear bumper bracket L/R @ \$38.70	2	Bent	\$	77.40	\$	77.40 1 20
21	Rear bumper side retainer L/R @ \$84.90	2	Damaged	\$	169.80	\$	169.80
22	Rear bumper reflector lamp L/R @ \$135.70	2	Cracked RH	4-45	271.40	\$	271.40 CRA
23	Rear end panel	1	Dented	\$	597.70	S	597.70 DD
24	Rear spare tyre compartment	1	Repair	\$	855.10		~
25	Rear boot lid weather-strip	1	Torn	\$	162.50	\$	162.50
26	Rear fender splash shield L/R @ \$69.50	2	Tom	\$	139.00	\$	139.00
27	Rear fender inner trim cover L/R @ \$429.50	2	Torn	\$	859.00	\$	859.00 NN
28	Rear tail lamp panel L/R @ \$98.80	2	Repair	\$	197.60	550	~
29	Rear tail lamp L/R @ \$397.50	2	Cracked	\$	795.00	\$	795.00 CRAV
30	Rear spare tyre side foam L/R @ \$210.80	2	Cracked		421.60		dose up 421.60 NN
,,,	real spare tyre side rount Ext. (c) \$210.00	-	Cidento	\$	11,768.84	\$	
			Less 25%	\$	2,942.21	\$	2,249.81
			2000 20 7.0	\$	8,826.63	\$	6,749.43
B)	S/NETT ITEM			•	-,		3. <del>7. 4</del> 3.1 10.00, 5. 3.00 1
31	Front number plate w/casing	1 set	Cut/Bent	\$	50.00	\$	40.00 50.00 BTV
32	Front humper clips	1 set	Necessary	\$	35.00	\$	35.00
33	Front bumper emblem	1	Grazed	\$	38.50	\$	38.50
34	Rear bumper clips	1 set	Necessary	\$	35.00	\$	35.00 NE
35	Rear boot lid "Vios" emblem	1	Necessary	\$	21.80	\$	21.80
36	Rear boot lid "E" emblem	i	Necessary	\$	12.90	\$	12.90
37	Rear boot lid emblem	i	Necessary	\$	38.50	\$	38.50
88	Rear spare tyre cardboard	1	Torn	\$	115.00	\$	1-15.00 NN X
39	Rear number plate with casing	i	Cut/Bent	\$	50.00	\$	50.00 NN X
10	Rear bumper reverse sensor L/R	l set	Malfunction		250.00		250.00 CUT
10	Real builiper reverse sensor L/R	1 SCL	Parts Total:	<u>s</u>	9,473.33	\$	7,396.13

Our Ref : TP/GAS/SJS7163Z/8049

C)	LABOUR CHARGES & MISC				
41	Spray painting on above new & repaired parts including supply of paint materials.	\$	1,200.00	\$	950.00
42	Remove damaged parts, knock out dent, straighten, jack out damaged damaged panel, cutting, welding, panel beating, remove & reinstall	J	1,200.00	J	750.00
	necessary fittings to facilitate repairs, reshape rear spare tyre panel,				800,00
	refit, adjust, replace and realign all relevant parts.	\$	1,500.00	\$	1,200.00
43	Remove & reinstall air-con system, vacuum and refill air-con gas.	\$	150.00	\$	120.00 90
44	Anti-rust proofing on affected panels & re-seal welded portions.	\$	120.00	\$	60.00
45	Check wiring, lighting system, focus headlight, centre locking system				- 0
	for proper function & perform water leak test.	\$	80.00	\$	50.00
46	To transfer rear tail gate mechanism & components. in largue charges	\$	80.00	\$	40.00 NNX
47	To drill holes & reinstall rear bumper reverse sensor.	\$	120.00	\$	60.00 -80.00
48	To straighten & realign rear exhaust silencer pipe to position.	\$	150.00	\$	X MN00.08
49	To remove & reinstall trims garnish, wire, lining & interior upholstery				0.000000
	etc, to enable necessary repairs, check, refit as same. in labour charges	\$	100.00	\$	60.00
	Labour Total:	\$	3,500.00	\$	2,640.00
	Total Parts and Labour	\$	12,973.33	\$	10,036.13
	FINAL LUMP SUM ADJUSTMENT			\$	8,000.00

### POINT OF IMPACT

The impact was confined to the front & rear portion of the vehicle.

The damages appeared to be consistent as per the accident report statement.

Please refer the attached schedule and photographs for details.

### ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

### CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of \$8,000.00 nett, corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Repair days &

Yours faithfully

KTO Automobile Assessors

Ong Ah Keng (CAE, AMIMI, MSAAA)

Automotive Appraiser

### **GUAN AUTO SERVICE**

Blk 7 Sin Ming Industrial Estate Sector C, ##01-82 Singapore 575642

Yip Zhun Kit Ames Blk 324 Yishun Cenral #06-295 Singpore 760324 Date: 23 November 2018

Tax Invoice: SJS7163Z/TP1808049

Vehicle No : SJS 7163 Z

Make/Model: Toyota Vios E Auto

### **PARTICULAR**

Amount S\$

Front & Rear Portion damaged

Parts replacement, Repair, Straighten, Alignment

Labour And spraypainting etc.

Lump-sum repair cost as per surveyor report recommendation -----

\$8,000.00

Singapore Dollars : Eight Thousand Only

Total \$

\$8,000.00 Nett



# **Facsimile**



10 Sin Ming Drive Singapore 575701

Tel: 1800-CALL LTA (1800-2255582) Fax: (65) 6553 5329

To : C. Yogarajah LLC Fax : 6292 5938
Dept : DID : 6292 5838

Attn : Date : 23 October 2018

From : Toh Lay Eng (Search Section) Fax : 6553 5384

Our ref : VR&L/V43.009.001/ SLA2103B DID : 6553 5414

Your ref : CY.SJS7163Z.18.GA(HW).wp(Lh) No of pages : 1 (including this page)

Dear Sir/Madam

Confirm ownership & insurance details for vehicle No. SLA2103B as at 18 October 2018 @ 07:15 hrs

We received your letter of 18 October 2018.

As the vehicle is a special plate number and ownership details are confidential, LTA will contact the registered owner to contact your law firm quoting your reference number: CY.SJS7163Z.18 GA(HW).wp(Lh).

Please call us on Tel: 6553 5210 if you have any questions.

Yours sincerely

Toh Tay Eng (Ms)
Supervisor, Quota & Registration
VRL Service Operations Division



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: HOMCNBEPO18301125/1

Date: 19th Dec 2018

Our Ref: CS1/CNB18022453/Bsbe2

### M/s Central Narcotics Bureau

Corporate Services Division Blk B Police Cantonment Complex 393 New Bridge Road Singapore 088763

Attn: Billy Lee

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJS 7163Z INSURED VEHICLE: SLA 2103B ACCIDENT DATE: 18/10/2018

We thank you for your instruction on 28/11/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJS 7163Z from M/s KTO Automobile Assessors.
- b) Singapore Accident Statement of Vehicles SJS 7163Z.
- c) Final Repair Bill of SJS 7163Z from M/s Guan Auto Service.
- d) Colour damaged vehicle photographs of SJS 7163Z.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number

: SJS 7163Z

Make & Model

: Toyota Vios E Auto

Year of Registration

: 2007

Chassis Number

: MR053HY9305004059

Engine Capacity

: 1497 cc

- We recommend that the repairs of the entire damage require about <u>8 (Eight)</u> working days to complete.
- We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 7163Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	CUT	598.40	598.40
1	FRONT BUMPER REINFORCEMENT	DENTED	379.20	379.20
2	FRONT BUMPER SIDE SUPPORT L/R @\$37.50	DISTORTED	75.00	75.00
1	FRONT RADIATOR GRILLE	BROKEN	359.20	285.00
1	FRONT RADIATOR GRILLE CHROME MOULDING	CUT	75.20	75.20
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	385.50	-
1	FRONT UPPER ABSORBER	CRACKED	195.00	146.00
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	98.50	-
1	FRONT AIR-CON CONDENSER	BENT	933.80	845.00
1	FRONT BONNET LOCK	NOT NECESSARY	41.70	-
2	FRONT HEADLAMP L/R @\$495.60	O/S CRACKED / N/S NOT NECESSARY	991.20	495.60
1	FRONT RADIATOR ASSY	SERVICEABLE	748.50	-
1	FRONT RADIATOR FAN MOTOR ASSY	SERVICEABLE	483.70	1-
1	REAR BOOT LID	TO REPAIR SEE LABOUR	756.60	C=
2	REAR BOOT HINGES L/R @\$49.60	SERVICEABLE	99.20	5 <b>+</b>
1	REAR BOOT LOCK	JAMMED	87.90	87.90
1	REAR END PANEL TOP GARNISH	CRACKED	185.64	185.64
1	REAR BOOT LICENSE LAMP MOULDING	NOT NECESSARY	149.50	7-
1	REAR BUMPER	DENTED	579.00	579.00
2	REAR BUMPER BRACKET L/R @\$38.70	DENTED	77.40	77.40
2	REAR BUMPER SIDE RETAINER L/R @\$84.90	DISTORTED	169.80	169.80
2	REAR BUMPER REFLECTOR LAMP L/R @\$135.70	O/S CRACKED / N/S NOT NECESSARY	271.40	135.70
1	REAR END PANEL	DENTED	597.70	597.70
1	REAR SPARE TYRE COMPARTMENT	TO REPAIR SEE LABOUR	855.10	-
1	REAR BOOT LID WEATHER-STRIP	TORN	162.50	162.50
2	REAR FENDER SPLASH SHIELD L/R @\$69.50	NOT NECESSARY	139.00	-
2	REAR FENDER INNER TRIM COVER L/R @\$429.50	NOT NECESSARY	859.00	-
2	REAR TAIL LAMP PANEL L/R @\$98.80	TO REPAIR SEE LABOUR	197.60	
2	REAR TAIL LAMP L/R @\$397.50	CRACKED	795.00	795.00

Report Ref No. CS1/CNB18022453/Bsbe2



### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR SPARE TYRE SIDE FOAM L/R @\$210.80	NOT NECESSARY	421.60	-
	LESS 25% DISCOUNT		-2,942.21	-1,422.51
			8,826.63	4,267.53
	SPECIAL NETT ITEMS			
1	SET FRONT NUMBER PLATE W/CASING (SN)	BENT	50.00	40.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	35.00	35.00
1	FRONT BUMPER EMBLEM (SN)	NECESSARY	38.50	38.50
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	35.00	35.00
1	REAR BOOT LID "VIOS" EMBLEM (SN)	NECESSARY	21.80	21.80
1	REAR BOOT LID "E" EMBLEM (SN)	NECESSARY	12.90	12.90
1	REAR BOOT LID EMBLEM (SN)	NECESSARY	38.50	38.50
1	REAR SPARE TYRE CARDBOARD (SN)	NOT NECESSARY	115.00	
1	REAR NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	50.00	
1	SET REAR BUMPER REVERSE SENSOR L/R (SN)	CUT	250.00	200.00
			646.70	421.70
	LABOUR			
	SPRAY PAINTING ON ABOVE NEW & REPAIRED PARTS INCLUDING SUPPLY OF PAINT MATERIALS.		1,200.00	600.00
	REMOVE DAMAGED PARTS, KNOCK OUT DENT, STRAIGHTEN, JACK OUT DAMAGED PANEL, CUTTING, WELDING, PANEL BEATING, REMOVE & REINSTALL NECESSARY FITTINGS TO FACILITATE REPAIRS, RESHAPE REAR SPARE TYRE PANEL, REFIT, ADJUST, REPLACE AND REALIGN ALL RELEVANT PARTS. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL, FRONT BRACE PANEL, REAR BOOT LID, REAR SPARE TYRE COMPARTMENT AND REAR TAIL LAMP PANEL L/R. }		1,500.00	800.00
	TO TRANSFER REAR TAIL GATE MECHANISM & COMPONENTS. }		80.00	
	TO REMOVE & REINSTALL TRIMS GARNISH, WIRE, LINING & INTERIOR UPHOLSTERY, ETC, TO ENABLE NECESSARY REPAIRS, CHECK, REFIT AS SAME. }		100.00	
	REMOVE & REINSTALL AIR-CON SYSTEM, VACUUM AND REFILL AIR-CON GAS.		150.00	90.00
	ANTI-RUST PROOFING ON AFFECTED PANELS & RE- SEAL WELDED PORTIONS.		120.00	50.00
	CHECK WIRING, LIGHTING SYSTEM, FOCUS HEADLIGHT, CENTRE LOCKING SYSTEM FOR PROPER FUNCTION & PERFORM WATER LEAK TEST.		80.00	50.00

Report Ref No. CS1/CNB18022453/Bsbe2



### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DRILL HOLES & REINSTALL REAR BUMPER REVERSE SENSOR.		120.00	60.00
	TO STRAIGHTEN & REALIGN REAR EXHAUST SILENCER PIPE TO POSITION.	NOT NECESSARY	150.00	). <del>-</del>
			3,500.00	1,650.00
	GRAND TOTAL		12,973.33	6,339.23

RECOMMENDED COST OF LUMP SUM REPAIRS	5,050.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS1/CNB18022453/Bsbe2

LIM TEOW GUAN

Asst. Automotive Assessor

HO LEONG CHUAN

**Automotive Assessor** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.