



# GOLDBELL ENGINEERING

Industrial Vehicles.  
20,000 Served. And Counting.

**GOLDBELL ENGINEERING PTE LTD**  
Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676  
Finance: 18 Tuas Avenue 10 Singapore 639142 Tel: 6861 0007 Fax: 6862 3500  
Website: www.goldbell.com.sg  
Co. Reg. No.: 198003963G

## Supplementary Estimate

DATE : 23/01/2019

TO : MS FIRST CAPITAL INSURANCE LIMITED  
ATTN :  
OFFICE / MOBILE : -  
EMAIL ADDRESS : [ENGWOKLONG@GOLDBELL.COM.SG](mailto:ENGWOKLONG@GOLDBELL.COM.SG)

FROM : GOLDBELL ENGINEERING PTE LTD  
ATTN : MR Brian Eng  
OFFICE / MOBILE : 6864-0637 / 9755-7336  
FAX NO. : 6863-0425

VEHICLE NO. : YN3816Z  
MODEL NO. : MITSUBISHI FE83BE0SRDEA  
CHASSIS NO. : FE83BEA21045  
ENGINE NO. : 4M42A91668  
REG. DATE : 29/04/2013

REF. NO. : GBE/SVC/SALES-4755/181214  
D.O.A. : 09/12/2018  
POLICY NO. : SD18V00032/VCZ/R03  
CLAIM TYPE : TD CLAIM - MS FIRST CAPITAL

WORKSHOP : 8 TUAS AVE 18

S/N	PART NO.	DESCRIPTION	QUANTITY	PRICE
1		SIDE GUARD (RH)	1	\$ 450.00 <i>btv</i>
2		REAR DESK RH BODY FLOOR RAIL	1	\$ 900.00 <i>ava</i>
3		REAR DESK DROP SIDE	1	\$ 1,800.00 <i>bt</i>
4		REAR TYRE	2	\$ 500.00 <i>350.</i>
5		FRONT TYRE	2	\$ 650.00 <i>227.50</i>
6		REAR LEAF SPRING	2	\$ 1,500.00 <i>btv</i>
7		RECOVERY TOW OUT	1	\$ 330.00 <i>200.</i>
8		CHANGE TYRE & TOWING	1	\$ 160.00 <i>90</i>

SUB-TOTAL : \$ 5,800.00  
LESS % : \$ - *5517.50*  
BALANCE : \$ 5,800.00

GRAND TOTAL : \$ 5,800.00

PREPARED BY : Brian Eng  
DATE / TIME : \_\_\_\_\_  
SURVEYOR : \_\_\_\_\_  
MOBILE NO. : \_\_\_\_\_  
OFFICE FAX NO. : \_\_\_\_\_  
EMAIL ADDRESS : \_\_\_\_\_  
EXCESS AMOUNT : \_\_\_\_\_  
REPAIR TYPE : PART-BY-PART / LUMP SUM  
AUTHORISATION : AUTHORISED / NOT AUTHORISED  
RE-SURVEY : BEFORE PAINT / AFTER PAINT  
NO. OF DAYS : \_\_\_\_\_  
REMARKS : \_\_\_\_\_

*Part = ... 7.*  
*S/N = ...*  
*labour = ...*  
*Supp = ...*  
*T = ...*  
*repair limit 15k*

