

ASS. REC. BY:

REF CS3/AXA18004045/Bt6-1.

Special Instruction:

Surveyor

MA

ASSIGNMENT (Office)

From (Person):

Gayatri

of

AXA

Date/Time

13/12/2018

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 8761H

Insured:

Public liability

at Workshop m/s

Buk Heng Motor

Tel:

9788 8579

of

5032 # 01-291 Amk Ind. Park 2

Policy No

Claim No:

C0471569

Sum Insured

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/02/2018

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement

Date/Time:

9:34am 23/12/18

Person Contacted

Kalvin

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (X) Estimate

SKW 8761H - V

lump sum \$11450/- (Red: 5050; FF%) , 4 days.

26/12-

File pass to typist

RECEIVED 26 DEC 2018

150

TGLim

24/12/18

AXA

SKW8761H.

11/01/2015

Bak Heng

HONDA VEZEL


1496

White

32593.

RU11105652

215/55R17



TOYO YOKO DUN

23/12/08 21/3/2018

Roof top

PRELIMINARY

☐ Prelim Report
☐ Final Report

Days Of Repair

Resurvey NO. 07/01

Add Fee

100

Catherine Chong (LKK Auto)

From: RAJAM AYER Gayatri <gayatri@axa.com.sg>
Sent: Thursday, 13 December, 2018 10:27 AM
To: Admin-D (LKKAuto)
Cc: assignments
Subject: RE: NEW MATTER - REQUEST FOR SURVEY - AXA REF: C0471569 VEHICLE NO. SKW8761H
Attachments: Lawyer - Carton No3019561038 -b04141- Scanned on 16112018.pdf; LKK INSPECTION REPORT.pdf

Dear Catherine,

We refer to the above matter and previous emails.

We have received the attached claim submission from the lawyer which includes a survey report from Carlink consultancy .

Could you advise if the following in order:

1. Were the repairs at \$6,500.00 is reasonable?
2. Time taken for repair: 7 days x \$80 = \$560.00

I have also attached your inspection report for easy reference.

Thanks & Regards

Gayatri
Senior Specialist - Property & Casualty Claims
AXA Insurance Pte Ltd
8 Shenton Way, #24-01 AXA Tower, Singapore 068811
gayatri@axa.com.sg
DID: (65) 6880-4841 Fax: (65) 6880-4570
Website: www.axa.com.sg



Please consider the environment before printing this message.
This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited.
If you are not the intended recipient of the message, please notify the sender immediately.

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: 16 October 2018 09:44 AM
To: RAJAM AYER Gayatri <gayatri@axa.com.sg>
Cc: assignments <assignments@lkkauto.com>
Subject: RE: NEW MATTER - REQUEST FOR SURVEY - AXA REF: C0471569 VEHICLE NO. SKW8761H

Dear Sir / Madam,

Thank you for your email.

Please be informed that at the time of inspection the repairer did not present their estimation to the damaged vehicle.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: RAJAM AYER Gayatri [<mailto:gayatri@axa.com.sg>]

Sent: Monday, 15 October, 2018 6:29 PM

To: Nivitha (LKK Auto) <admin-d@lkkauto.com>

Subject: RE: NEW MATTER - REQUEST FOR SURVEY - AXA REF: C0471569 VEHICLE NO. SKW8761H

Dear Nivitha,

We refer to the above matter.

Donny is no longer with us. Hence, please advise if there are any other documents other than your attached pre-repair inspection record? For example, final report, repair estimate etc.

Thanks & Regards

Gayatri

Senior Specialist - Property & Casualty Claims

AXA Insurance Pte Ltd

8 Shenton Way, #24-01 AXA Tower, Singapore 068811

gayatri@axa.com.sg

DID: (65) 6880-4841 Fax: (65) 6880-4570

Website: www.axa.com.sg



redefining / insurance

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorised disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.



Please consider the environment before printing this email

From: POON Donny

Sent: 02 March 2018 10:58 AM

To: 'Nivitha (LKK Auto)' <admin-d@lkkauto.com>

Subject: RE: RE: NEW MATTER - REQUEST FOR SURVEY - AXA REF: C0471569 VEHICLE NO. SKW8761H

Dear Nivitha,

Third party is claiming against our Insured which is a security guard company and they have activated their Public Liability policy with us.

There is no GIA report submitted to us so far. We shall extend a copy to you once available.

To assist your side to survey the vehicle, we attached the summary of the incident for your review.

Regards,

Donny Poon | Specialist, SIU & SITF

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg

Email: donny.poon@axa.com.sg

DID: (65) 6417 3166



redefining / insurance

Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Nivitha (LKK Auto) [<mailto:admin-d@lkkauto.com>]

Sent: Friday, March 02, 2018 10:40 AM

To: POON Donny <donny.poon@axa.com.sg>

Subject: RE: RE: NEW MATTER - REQUEST FOR SURVEY - AXA REF: C0471569 VEHICLE NO. SKW8761H

Dear Poon,

Kindly provide both parties GIA report.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: POON Donny [<mailto:donny.poon@axa.com.sg>]

Sent: Thursday, 1 March 2018 4:23 PM

To: assignments@lkkauto.com

Subject: FW: RE: NEW MATTER - REQUEST FOR SURVEY - AXA REF: C0471569 VEHICLE NO. SKW8761H

Dear Sir/Mdm,

This is a new assignment.

Kindly be informed that the vehicle is now at Bak Heng Motor Repairing, 5032 AMK Industrial Park 2 #01-291 Singapore 569535. Please contact Kelvin @ 97888579 for arrangement of survey.

Please survey the vehicle strictly on a without prejudice basis and do not authorize repair.

Should you need any clarification, please contact me at 6417 3166. Thank you.

Regards,

Donny Poon | Specialist, SIU & SITF

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg

Email: donny.poon@axa.com.sg



redefining / insurance

Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors Commissioner For Oaths Notary Public
UEN NO : 201523418E
(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16
MANHATTAN HOUSE
SINGAPORE 169876
TEL : (65) 6532 2455
FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: lhling@tcmg.com.sg

Our Ref : LLH/ing/1197/0518/BHM

Your Ref : Barrier

60120232

15 MAY 2018

M/S Reachfield Security & Safety Management PL (For your attention: without enclosures)
10 Anson Road
Singapore 079903

M/S AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way #27-01
AXA Tower
Singapore 068811

Attn: Motor Claims Department

Dear Sirs,

ACCIDENT INVOLVING SKW 8761 H AND BARRIER ON 23 FEBRUARY 2018 AT THE GATE OF SENGKANG GREEN PRIMARY SCHOOL

We are instructed by **Ang Swee Hong**, to claim damages against the management of Reachfield Security & Safety Pte Ltd or your insured, in connection with the accident that happened on 23 of February 2018, at about 15:35 hours at the gate of Sengkang Green Primary School, involving our client's motor vehicle no. **SKW 8761 H** and the gate barrier that prematurely lowered and hit onto our client's car.

We are instructed that the accident was caused by the management's negligence in managing the exit barrier. As a result of the accident, our client's motor vehicle was damaged and our client had been put to loss and expenses, particulars of which are as follows:

1 Costs of Repair	\$ 6,500.00
2 Loss of Use (\$80 x 7 days)	\$ 560.00
3 Loss of Use (Pre-repair)(\$ 80 x 2 days)	\$ 160.00
4 Survey Report Fee	\$ 720.00
5 Disbursement (at this stage)	\$ 93.00
6 Legal Cost (at this stage)	\$ 700.00
	<u>\$ 8,733.00</u>

DIRECTOR: LING LEONG HUI

CONSULTANTS: TOMMY CHOO TUCK SOON
POOTS LAURENCE JAMES



BY PDX NO. 8176

PDX Intercompany Exchange Pte Ltd



010808426371
FROM TOMMY CHOO, MARK GO LLC
PDX Box No. 8141

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors Commissioner For Oaths Notary Public

UEN NO : 201523418E

(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16
MANHATTAN HOUSE
SINGAPORE 169876
TEL : (65) 6532 2455
FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: lhling@tcmg.com.sg

Our Ref : LLH/ing/1197/0518/BHM

Your Ref : Barrier



15 MAY 2018

M/S Reachfield Security & Safety Management PL (For your attention: without enclosures)
10 Anson Road
Singapore 079903

By Certificate of Posting

M/S AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way #27-01

AXA Tower

Singapore 068811

BY PDX NO. 8176

PDX Intercompany Exchange Pte Ltd



010808426371

FROM TOMMY CHOO, MARK GO LLC
PDX Box No. 8141

Attn: Motor Claims Department

Dear Sirs,

ACCIDENT INVOLVING SKW 8761 H AND BARRIER ON 23 FEBRUARY 2018 AT THE GATE OF SENGKANG GREEN PRIMARY SCHOOL

We are instructed by **Ang Swee Hong**, to claim damages against the management of Reachfield Security & Safety Pte Ltd or your insured, in connection with the accident that happened on 23 of February 2018, at about 15:35 hours at the gate of Sengkang Green Primary School, involving our client's motor vehicle no. **SKW 8761 H** and the gate barrier that prematurely lowered and hit onto our client's car.

We are instructed that the accident was caused by the management's negligence in managing the exit barrier. As a result of the accident, our client's motor vehicle was damaged and our client had been put to loss and expenses, particulars of which are as follows:

1 Costs of Repair	\$ 6,500.00
2 Loss of Use (\$80 x 7 days)	\$ 560.00
3 Loss of Use (Pre-repair)(\$ 80 x 2 days)	\$ 160.00
4 Survey Report Fee	\$ 720.00
5 Disbursement (at this stage)	\$ 93.00
6 Legal Cost (at this stage)	\$ 700.00
	<u>\$ 8,733.00</u>

DIRECTOR : LING LEONG HUI

CONSULTANTS : TOMMY CHOO TUCK SOON
POOTS LAURENCE JAMES

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors Commissioner For Oaths Notary Public
UEN NO : 201523418E
(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16
MANHATTAN HOUSE
SINGAPORE 169876
TEL : (65) 6532 2455
FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)
Email: lhling@tcmg.com.sg

A copy each of the following supporting documents is enclosed:

1. Copy of accident report;
2. Copy of Certificate of Insurance;
3. Copy of survey report and invoice and repair bill;
4. Colour photographs pertaining to our client's motor vehicle for your perusal.

We had on 27 of February 2018 notified your management about the accident and the pre-repair inspection was conducted by M/s AXA INS (S) Pte Ltd.

Please note that if you are insured and you wish to claim from your insurance policy, you should immediately pass this letter to your insurer

Please note that you should send us an acknowledgment of receipt of this letter within fourteen (14) days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against your insured without further notice to you or your insured.

Please note that if you have a counterclaim against our client arising out of the accident, you are also required to send us a letter giving full particulars of the counterclaim together with the relevant documents within 8 weeks of your receipt of this letter.

Yours faithfully,



Encs.

cc. client

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/02/2018 17:06
Date Of Accident	23/02/2018 15:35
Exact Location Of Accident	SENGKANG GREEN PRI SCH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW8761H
Insured/Policyholder	
Name Of Registered Owner	ANG SWEE HONG
NRIC No	S8213501D
Email Address	DCHUA1359@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81395372
Alternative Phone No	OTHERS-91825732
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL-1.5 S (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00345828/01
Cover Note Number	19/11/2017 - 18/11/2018
Driver	
Name of Driver	ANG SWEE HONG
NRIC No	S8213501D
Date Of Birth	01/05/1982
Occupation	INDOOR
Date Of Driving Pass	19/01/2005
Driving Experience	13 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-81395372
Fax Number	
Contact Number	OTHERS-91825732
Email Address	DCHUA1359@GMAIL.COM

Address BLK 493B SENGKANG WEST AVE
 #07-315
 Postcode 782438
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle
 Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLIDED INTO PROPERTY
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? NO
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO THE SKETCH PLAN BY DRIVER


Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

Sketch Plan Pg. 2

Date of accident: 22/07/18 Time: 3:35pm Location: Sengkang Green Pri Sch
 My Vehicle A: SKW 8761H Vehicle B: _____ Vehicle C: _____

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Green

When I drove into Sengkang Primary School, the security guard closed down the barrier when I was half way driven into the school. The barrier hit the left body frame leaving 2 dents and scratches on the 2 top roof racks.

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop:

Email address:

& myself:

Email address: PCUWA1354@gmail.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



AH LIM MOTOR COMPANY


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

X 
 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Person's Signature
 Name:
 NRIC/FIN No.:

direct
asia
insurance

Contact us at
Hotline: (65) 6522 2888
E-mail: CustomerService@DirectAsia.com

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) (Singapore) (the "Act")
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 (Singapore)
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1989 (Malaysia)


This document forms part of your contract with us and should be read together with your Policy Schedule and your Policy Details. Do let us know if any of the details shown here need to be amended or updated.

Certificate No.	: MT/00345828/01
Type of Coverage / Driver Plan	: Car Comprehensive (Value Plus Plan)
1) Vehicle Registration No.	: SKW8761H
Chassis No.	: RU11105652
2) Name of Policy Holder	: Ang, Swee Hong
3) Effective Date / Time of Commencement of Insurance for the Purpose of the Act	: 19/11/2017 00:00
4) Date/Time of Expiry of Insurance	: 18/11/2018 23:59
5) Persons or Classes of Persons Entitled to Drive	
(a) The Insured	
(b) Any named person under the policy who is driving on the Insured's order or with his permission.	
(c) Any authorised person, provided such person is aged 30 and above and holds a valid driving licence of 2 years or more, who is driving on the Insured's order or with his permission	
The person driving must have a valid driving licence to drive in Singapore and must not be under suspension or disqualification from driving.	
6) Limitations as to use	
Use only for private purposes, in accordance with the declared car usage stated on your Policy Schedule. The policy does not cover use for hire or reward, custom, driving test, racing, pace-making, reliability trials, speed tests, the carriage of goods for payment or for any purpose in connection with the motor trade business.	
Limitations rendered inoperative by Section 8 of the Act and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under this heading.	
Sum Insured	: Market Value
Own Damage Excess	: S\$ 1,000.00 (before any applicable GST)
Windscreen Excess	: S\$ 100.00 (before any applicable GST)
Choice of workshop	: My Workshop/ My Authorised Distributor Workshop
Finance company / Hire Purchase	: UOB
Main driver	: Ang, Swee Hong
Named driver	: None
Important Note: This policy does not cover drivers below the age of 30 and drivers who hold a valid driving licence of less than 2 years with the exception of the named drivers above.	

I/we hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and the Road Transport Act, 1987 (Malaysia).

Issued on: 24/10/2017

Direct Asia Insurance (Singapore) Pte. Ltd.


Edip Okur
Chief Underwriting Officer

Direct Asia Insurance (Singapore) Pte Ltd
88 South Bridge Road Singapore 056716
www.DirectAsia.com

Company Registration: 2006224105

木興連嗎呷汽車修理公司
BAK HENG MOTOR REPAIRING CO.,

Block 5032, Ang Mo Kio Industrial Park II, #01-291, Singapore 2056.

TEL: 4816829, 4816820

Reg. No: 23566000X

INVOICE NO. BH/TCMG/08/18

Date: 10th May 2018

Ang Swee Hong
C/O Blk 5032 Ang Mo Kio Ind Park 2
#01-291
Singapore 569535

COST OF REPAIRS FOR VEHICLE NO. SKW 8761 H

Lump sum costs of repairs : S\$6,500.00

Singapore Dollars : Six Thousand Five Hundred Only.

Yours faithfully



.....
M/s Bak Heng Motor Repairing Co.

CARLINK CONSULTANCY

60 Hillside Drive, Singapore 549009
Fax: 62874788 Tel: 62856178


INVOICE

Ang Swee Hong
C/o Blk 5032 Ang Mo Kio Industrial Park 2
#01-291
Singapore 569535

Invoice No: CL 11948 TP
Our Ref: CL 11948 SKW 8761 H
Date: 10th May 2018

S/N	DESCRIPTION	QTY	UNIT PRICE (\$)	AMOUNT (\$)
1	<u>Vehicle No: SKW 8761 H</u> Charges for accident vehicle inspection and appraisal report, photographs, transportation & misc*** (photographs - 120 copies)			\$720.00
			Total:	\$720.00

We thank you for the opportunity to serve you and assure you of our best at all times


PATRICK
Automotive Engineer Assessor
MIMI, MIRTE, LCGI, I ENG, LAE, CGLI ETC.

Note: Payment by cheque should be crossed and made payable to "CARLINK CONSULTANCY"

CARLINK CONSULTANCY


60 Hillside Drive
Singapore 549009

Tel : 62856178

Fax : 62874788

ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT

Our Ref: CL 11948 SKW 8761 H

1 REFERENCE			
Date of request	: 2nd March 2018		
Requested by	: Ang Swee Hong C/o Blk 5032 Ang Mo Kio Industrial Park 2, #01-291, Se 569535		
Type of claim	: Third party		
Workshop	: M/S Bak Heng Motor Repairing Co Blk 5032 Ang Mo Kio Industrial Park 2, #01-291 Singapore 569535		
Date of survey	: 2nd March 2018		
Accident date	: 23rd February 2018		
2 DETAILS OF VEHICLE			
Registration No.	: SKW 8761 H		
Make & Model	: Honda Vezel 1.5 S (A)		
Date of registration	: 19th November 2015		
Engine No.	: L15B4025655		
Chassis No.	: RU11105652		
Speedometer reading	: 032593 Km		
Transmission	: Automatic		
Colour	: White		
3 STATIC CHECK			
Steering	: see annex(es)	Paintwork	: Good
Footbrake	: see annex(es)	Modification	: Nil
Handbrake	: see annex(es)	General condition	: Good
4 TYRE CONDITION			
	<u>Nearside/Make</u>	<u>Offside/Make</u>	<u>Size</u>
Front tyre	: 6mm/Dunlop	6mm/Dunlop	: 215/55 R17
Rear tyre	: 6mm/Dunlop	6mm/Dunlop	: 215/55 R17
5 POINT OF IMPACT			
See Annex(es) and Motor Accident Reports			
6 REMARK			
This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.			

Annex A : Assesment / Adjustment on Spare Parts

SKW 8761 H						
Item	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)
List Items						
1	Front windscreen pillar outer panel LH	Repair	1	\$763.60	100%	\$0.00
2	Front pillar inner trim garnish LH	Distorted/cut	1	\$181.00	20%	\$144.80
3	Front pillar inner trim garnish clips LH	Necessary	4	\$7.20	20%	\$5.76
4	Roof lining inner clips	Necessary	14	\$21.00	20%	\$16.80
5	Aluminium alloy roof side rail LH (Air freight)	Grazed/dented	1	\$2,350.00	20%	\$1,880.00
6	Aluminium alloy roof side rail RH (Air freight)	Grazed/dented	1	\$2,350.00	20%	\$1,880.00
7	Aluminium alloy roof side rail front rubber moulding LH	Grazed/necessary	1	\$85.00	20%	\$68.00
8	Aluminium alloy roof side rail front rubber moulding RH	Necessary	1	\$85.00	20%	\$68.00
9	Aluminium alloy roof side rail rear rubber moulding LH	Necessary	1	\$121.00	20%	\$96.80
10	Aluminium alloy roof side rail rear rubber moulding RH	Necessary	1	\$121.00	20%	\$96.80
11	Aluminium alloy roof side rail screw cover LH	Dented/bent/ necessary	4	\$32.00	20%	\$25.60
12	Aluminium alloy roof side rail screw cover RH	Grazed/dented	4	\$32.00	20%	\$25.60
13	Front windscreen moulding	Necessary	1	\$74.60	20%	\$59.68
S/Nett						
14	Front windscreen gum	Necessary	1	\$60.00		\$60.00
Total for Spare Parts :				\$6,283.40		\$4,427.84

Annex B : Adjustment on Labour and Spray Painting

SKW 8761 H

Item	Job Description	Workshop Est. (\$)	Adjusted Cost (\$)
1	To apply anti rust coat	\$150.00	\$120.00 60.00 X
2	To remove/refix roof inner lining and front pillar inner trim LH to assist in repair	\$350.00	\$200.00 80.00
3	To spray roof panel, front windscreen pillar outer panel & etc	\$1,600.00	\$1,250.00 400.00
4	To apply paint protection sealant	\$400.00	\$300.00 - NN X
5	To renew damaged parts, repair, align roof panel, front LH pillar outer panel & etc	\$1,600.00	\$1,200.00 500.00
6	To remove & refix front windscreen glass	\$150.00	\$120.00 - NN X
TOTAL FOR LABOUR & SPRAY PAINTING :		\$4,250.00	\$3,190.00

Summary

	Workshop Est. (\$)	Adjusted Cost (\$)
TOTAL FOR SPARE PARTS :	\$6,283.40	\$4,427.84
TOTAL FOR LABOUR & SPRAY PAINTING :	\$4,250.00	\$3,190.00
TOTAL REPAIR COSTS :	\$10,533.40	\$7,617.84

4 days

TCM

24/12/18

CARLINK CONSULTANCY

SKW 8761 H

Annex C: Recommendation

We have inspected thoroughly the actual damages found on the vehicle and our assessment is appended in the Annex(es) attached. The condition and age of the vehicle was considered before we reached our recommendation as to whether the parts need replacement or repair.

M/S Bak Heng Motor Repairing Co estimated repair cost is **S\$10,533.40** and we have adjusted it to **S\$7,617.84** on a part by part basis. However, taking into consideration the age of the vehicle and the availability of used/recondition components. We, therefore recommend a contract lump sum repair cost.


The repairer have agreed to undertake the repairs on a contract lump sum of **S\$6,500.00**, according to acceptable quality and standard. (Repairer discretion to repair parts, to replace with old parts or to replace with OEM or genuine parts).

The entire repair of the damaged vehicle should be completed within a reasonable period of **7** working days.

We have advised the repairer that the inspection was conducted strictly on a **WITHOUT PREJUDICE** basis and we have not given any instruction and authorisation to proceed with the repair of the vehicle.

We are reverting the matter to you for your discretion and enclosed is our invoice for service rendered.

Yours faithfully,
CARLINK CONSULTANCY


PATRICK NG
Automotive Engineer Assessor
MIMI, MIRTE, LCGI, I ENG, LAE, CGLI FTC.



Your Ref: C0471569

Date: 02nd Jan 2019

Our Ref: CS3/AXA18004045/Btbe2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn : Gayatri

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKW 8761H
INSURED VEHICLE: PUBLIC LIABILITY
ACCIDENT DATE: 23/02/2018**

We thank you for your instruction on 13/12/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of from M/s Carlink Consultancy.
- b) Singapore Accident Statement of Vehicles SKW 8761H.
- c) Final Repair Bill of SKW 8761H from Bak Heng Motor Repairing Co.
- d) Colour damaged vehicle photographs of SKW 8761H.

Pre-Repair Inspection Date : 02/03/2018 at M/s Bak Heng Motor Repairing Co, Block 5032 Ang Mo Kio Industrial Park II, #01-291, Singapore 569535.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKW 8761J
Make & Model	: Honda Vezel 1.5S A
Year of Registration	: 2015
Chassis Number	: RU11105652
Engine Capacity	: 1496 cc

2. We recommend that the repairs of the entire damage require about 4(Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 8761H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT WINDSCREEN PILLAR OUTER PANEL LH	TO REPAIR SEE LABOUR	763.60	-
1	FRONT PILLAR INNER TRIM GARNISH LH	NOT NECESSARY	181.00	-
4	FRONT PILLAR INNER TRIM GARNISH CLIPS LH	NOT NECESSARY	7.20	-
14	ROOF LINING INNER CLIPS	NECESSARY	21.00	21.00
1	ALUMINIUM ALLOY ROOF SIDE RAIL LH (AIR FREIGHT)	GRAZED / DENTED	2,350.00	500.00
1	ALUMINIUM ALLOY ROOF SIDE RAIL RH (AIR FREIGHT)	GRAZED / DENTED	2,350.00	500.00
1	ALUMINIUM ALLOY ROOF SIDE RAIL FRONT RUBBER MOULDING LH	NOT NECESSARY	85.00	-
1	ALUMINIUM ALLOY ROOF SIDE RAIL FRONT RUBBER MOULDING RH	NOT NECESSARY	85.00	-
1	ALUMINIUM ALLOY ROOF SIDE RAIL REAR RUBBER MOULDING LH	NOT NECESSARY	121.00	-
1	ALUMINIUM ALLOY ROOF SIDE RAIL REAR RUBBER MOULDING RH	NOT NECESSARY	121.00	-
4	ALUMINIUM ALLOY ROOF SIDE RAIL SCREW COVER LH	BENT	32.00	32.00
4	ALUMINIUM ALLOY ROOF SIDE RAIL SCREW COVER RH	BENT	32.00	32.00
1	FRONT WINDSCREEN MOULDING	NOT NECESSARY	74.60	-
	LESS 20% DISCOUNT		-	-217.00
			6,223.40	868.00
<u>SPECIAL NETT ITEMS</u>				
1	FRONT WINDSCREEN GUM (SN)	NOT NECESSARY	60.00	-
			60.00	-
<u>LABOUR</u>				
	TO APPLY ANTI RUST COAT.	NOT NECESSARY	150.00	-
	TO REMOVE / REFIX ROOF LINER LINING AND FRONT PILLAR INNER TRIM LH TO ASSIST IN REPAIR.		350.00	80.00
	TO SPRAY ROOF PANEL, FRONT WINDSCREEN PILLAR OUTER PANEL & ETC.		1,600.00	400.00
	TO APPLY PAINT PROTECTION SEALANT.	NOT NECESSARY	400.00	-
	TO RENEW DAMAGED PARTS, REPAIR, ALIGN ROOF PANEL, FRONT LH PILLAR OUTER PANEL & ECT. INCLUSIVE OF THE REPAIR OF FRONT WINDSCREEN PILLAR OUTER PANEL LH.		1,600.00	500.00

Report Ref No. CS3/AXA18004045/Btbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIX FRONT WINDSCREEN GLASS.	NOT NECESSARY	150.00	-
			4,250.00	980.00
GRAND TOTAL			10,533.40	1,848.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,450.00

Report Ref No. CS3/AXA18004045/Btbe2-1

LIM TEOW GUAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.