

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 5006 TAMPINES ST 93 #01-204
SINGAPORE 528840
TEL :67853933 FAX:67883933
R.O.C No. 200104141D GST Reg No. 20-0104141-D

TO : S1149057C
TEO HENG LAM
NO 5A JALAN ANGIN LAUT

SINGAPORE 489178
TEL : FAX :
PH : 96390042
ATTN :

ESTIMATE BILL

Number : EBK0000260
Date : 24/12/2018
Case No : ADK0000332
Vehicle No : SLX9986C
Chassis:
Year of Mfr
Policy No
Model : HONDA SHUTTLE

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	RR INNER CORNER PANEL LH RH	2.0	190.00	20	304.00
	<i>Self</i> Labour 1 Sub Total				304.00
SINGAPORE DOLLARS : THREE HUNDRED TWENTY-FIVE AND CENTS TWENTY-EIGHT ONLY			Less Excess		0.00
			SUBTOTAL		304.00
			GST 7.00%		21.28
			TOTAL		325.28

Date of accident : 12/12/2018 07:20 PM. Place : NEW UPPER CHANGI RD TOWARDS CITY

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE