

Surveyor Mr. Jim

ASSIGNMENT (Office)

From (Person) Joel Goh

of EQI

Date/Time 14/12/18 @ 5:11pm

Estimated Cost

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

QBD 7545D

Insured:

at Workshop m/a

Wee the Auto

Tel:

6558 0019

of

19 Kim Chuan Terrace

Policy No:

Claim No:

DM18H003355-JT

Sum Insured:

Excess:

\$500.00 (No waiver)

Make of Veh:

(Client's Record)

D.O.A. 04/12/18

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:06am @ 14/12/18

Person Contacted:

Mr. Kiat

Vehicle ☒ IN ☐ OUT

| Date/Time | Action/Instruction (✓) Estimate                                                                                |
|-----------|----------------------------------------------------------------------------------------------------------------|
| 18/12/18  | QBD 7545D - NA/EQI18021892/KA<br>revised PA & requested authorise repair to Joel<br>via email.<br>@ 11:24 a.m. |
| 19/12/18  | authorise repair approved by Janet Tan via email.                                                              |
| 19/12/18  | @ 11:31 a.m. revert authorise repair to Chua (Gopur) via email.                                                |

REF: EQI

## ASSIGNMENT

From: Date: 17/12/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBD 7545D  
at Workshop no: Wee Hoe Auto  
of: 19 Km chuen Terrace

Insured: E

Policy No:

Claims No:

Sum Insured:

Excess: \$500.00  
(No waiver)

(Client's Record)

Make of Veh:

OE

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 5 days Res: Yes or No

Lump Sum % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GBD 7545D Yr Reg: 23/4/2015

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN ANCEL VAN N1350 2485

Colour: WHITE A/C Insured / Std / NI / NA

Sp. Reading: 443249 T/Radio: Insured / Std / NI / NA

Eng/No: YD25362805 A

C/No: JNIM2E2620004197

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R 15L SPR 106/104R

R: 195 R 15L 3PR 106/104R

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A: 4/12/18

D.O.I: 17/12/18

Survey held at: Wee Hoe Auto

Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MV 113,000/-

PV 247,522/-

NV 18,963/-

Pls see my remarks.

07/05/19 Confirmed HS \$ 11,650.00 @ 5 days with LTG  
( \$ 9,096.79 Red - 44% )

RECEIVED 07 MAY 2019

Date/Time, File Pass by:

07/05/19

b) Typ: 4

Date/Time, File Return to:

2)

Report Format:

Lump Sum / L.B.I: (\$ 11,650/- HS)

☐: Prel. Report☒: Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Insp (\$☐ Weekend (\$

Survey Fee:

Transportation:

) S + RS: \$

1 Photo

1 Other

TOTAL

300

300

TGLM  
18/12

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                                    |
|-------------------------------------|------------------------------------|
| <b>Vehicle Owner Particulars</b>    |                                    |
| Owner ID Type:                      | Company                            |
| Owner ID:                           | 9524D                              |
| <b>Vehicle Details</b>              |                                    |
| Vehicle No.:                        | GBD7545D                           |
| Vehicle to be Exported:             | No                                 |
| Intended Deregistration Date:       | 18 Dec 2018                        |
| Vehicle Make:                       | NISSAN                             |
| Vehicle Model:                      | NV350 PANEL VAN 2.5 5MT 5DR EURO V |
| Primary Colour:                     | White                              |
| Manufacturing Year:                 | 2014                               |
| Engine No.:                         | YD25362805A                        |
| Chassis No.:                        | JN1MC2E26Z0004197                  |
| Maximum Power Output:               | -                                  |
| Open Market Value:                  | \$23,612.00                        |
| Original Registration Date:         | 23 Apr 2015                        |
| First Registration Date:            | 23 Apr 2015                        |
| Transfer Count:                     | 0                                  |
| Actual ARF Paid:                    | \$1,181.00                         |
| <b>Intended PARF Rebate Details</b> |                                    |
| PARF Eligibility:                   | No                                 |
| PARF Eligibility Expiry Date:       | -                                  |
| PARF Rebate Amount:                 | \$0.00                             |
| <b>Intended COE Rebate Details</b>  |                                    |
| COE Expiry Date:                    | 22 Apr 2025                        |
| COE Category:                       | C - Goods Vehicle & Bus            |
| COE Period(Years):                  | 10                                 |
| PQP Paid:                           | \$38,510.00                        |
| COE Rebate Amount:                  | \$24,432.00                        |
| <b>Total Rebate Amount:</b>         | <b>\$24,432.00</b>                 |

The information contained herein is correct as at 18 Dec 2018

OK

Dep 2018/12

100 42K - 43K

13/12/18



Posted: 15-Nov-2018

Tags: 2015 Nissan NV350, 2015 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan

**Nissan NV350 2.5A**

-

N.A

10-Dec-2015

2,488 cc

-

Van

**SOLD****Fuel Type:** Diesel

100% Loan Available, 1 Owner, Warranty By Tan Chong Till December 2018, High Trade In.

Faster Auto Trading

Posted: 03-Nov-2018

Tags: 2015 Nissan NV350, 2015 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan

**Nissan NV350 2.5M**

\$46,800

\$6,930 /yr

17-Sep-2015

2,488 cc

146,300 km

Van

**Available****Fuel Type:** Diesel

Lowest Price In The Market. No Further Discounts. Serious Buyers Are Welcome!

Think One Automobile &amp; Trading

Posted: 25-Oct-2018

Tags: 2015 Nissan NV350, 2015 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan

**Nissan NV350 2.5M**

\$44,800

\$7,040 /yr

28-Apr-2015

2,488 cc

106,345 km

Van

**Available****Fuel Type:** Diesel

Excellent Condition! Euro 5 Engine! Inspection &amp; Road Tax Free! Full Loan Can Be Arrange, Monthly At \$822 Only Lowest Price In The Market. No Further Discount. Serious Buyer Are Welcome!

Think One Automobile &amp; Trading

Posted: 25-Oct-2018

Tags: 2015 Nissan NV350, 2015 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan

**That's a fine looking car interior**

Customise your ride. Replace your leather seats, door panels, steering wheels and more with quality trims of your choice. List of the best workshops available. Each with merchant information, ranking and reviews to help you make the best decision.

Find out more!

**Nissan NV350 2.5M**

-

N.A

26-Jun-2015

2,488 cc

-

Van

**SOLD****Fuel Type:** Diesel

Selling At An Extremely Cheap Pricing. Genuine Lowest Mileage With The Best Condition. 1 Owner Only. Nice Bidded Plate. No Repairs Needed. Easy Financing Up To 100% Loan. High Trade In Value. One Of T...

Car (S) Pte Ltd

Posted: 22-Oct-2018

Tags: 2015 Nissan NV350, 2015 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan

**Nissan NV350 2.5M**

-

N.A

27-Apr-2015

2,488 cc

-

Van

**SOLD****Fuel Type:** Diesel

Low Mileage, 1 Owner, Well Maintain By Owner, Look As Good As New. Don't Miss It, Call Now For Appointment!

ABWIN (1994) Pte Ltd

Posted: 17-Oct-2018

Tags: 2015 Nissan NV350, 2015 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan

**Nissan NV350 2.5M**

-

N.A

10-Mar-2015

2,488 cc

-

Van

**SOLD****Fuel Type:** Diesel

1 Owner Only, Super Good Condition, No Need Repair, Regular Servicing Done, Warranty Provided, Price Negotiable, 100% Loan With Lowest Interest Rate Available, Super High Trade In, Call Now!

ABWIN Bus Pte Ltd

Posted: 11-Oct-2018

Tags: 2015 Nissan NV350, 2015 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan

**Nissan NV350 2.5A**

-

N.A

20-Oct-2015

2,488 cc

-

Bus

**SOLO****Fuel Type:** Diesel

1 Owner, Latest Nissan NV350 12 Seater Microbus. Low Mileage Done. Still Under Agent Warranty. Original Condition Like New. Very Well Maintained And Regular Servicing Just Done. Call Us Now For Viewin...

Posted: 11-Oct-2018

Tags: 2015 Nissan NV350, 2015 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan

**Nissan NV350 2.5M**

-

N.A

24-Jul-2015

2,488 cc

-

Van

**SOLD****Fuel Type:** Diesel

Please Call To Arrange For Viewing, Thanks.

Posted: 04-Oct-2018

Tags: 2015 Nissan NV350, 2015 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan

Compare [ 1 ]

**Nissan NV350 2.5M**

-

N.A

10-Sep-2015

2,488 cc

-

Van

**SOLD****Fuel Type:** Diesel

Select used cars to Compare or Add to Alert

Shortlist [ 1 ]

Add to Shortlist


Compare Now

Clear All




Nissan NV350 2.5M


28-Apr-2015



To compare cars, select from the search results.



To compare cars, select from the search results.



To compare cars, select from the search results.

## Shirley Hiew (LKK Auto)

---

**From:** daryl tan <daryltan@gmail.com>  
**Sent:** Tuesday, 7 May 2019 12:02 PM  
**To:** Shirley Hiew (LKK Auto)  
**Cc:** SUR  
**Subject:** Re: GBD 7545D OD (EQI)

Yes, confirmed.

On Tue, 7 May 2019, 11:48 Shirley Hiew (LKK Auto), <[ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com)> wrote:

Dear Daryl,

Please confirm final fig \$11,650.00 (lump sum) @ 5 days of repairs before excess \$ 500/- & GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** daryl tan [mailto:[daryltan@gmail.com](mailto:daryltan@gmail.com)]  
**Sent:** Thursday, 18 April 2019 2:17 PM  
**To:** Shirley Hiew (LKK Auto) <[ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** Re: GBD 7545D OD (EQI)

We have submitted all documents to your surveyor. We also tried to contact your office but couldn't reach you. Please contact us at 68580019 for any further questions.

Also, the repairs have been completed.

Regards

Wee hoe auto

On Thu, 18 Apr 2019, 14:03 Shirley Hiew (LKK Auto), <[ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com)> wrote:

Dear Mr. Kiat/Mr. Chuan,

Please finalize with us if vehicle has been repaired.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]

**Sent:** Wednesday, 19 December 2018 11:31 AM

**To:** 'daryl tan' <[daryltankc@gmail.com](mailto:daryltankc@gmail.com)>

**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Subject:** RE: GBD 7545D OD (EQI)

Dear Chuan,

As instructed by our client, please proceed at repair cost not exceeding \$15,000.00 (inclusive supplementary) to repair the insured vehicle **GBD 7545D (Excess \$ 500/-)** on lump Sum basis.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Wednesday, 19 December 2018 11:24 AM  
**To:** 'Janet Tan'  
**Cc:** SUR; Admin-D (LKKAuto); assignments  
**Subject:** RE: our ref: DM18HO03355/JT: OD SURVEY FOR GBD7545D (DM18HO03355-JT)

Dear Janet,

Repairer agreed to undertake the repair cost not exceeding \$ 15,000.00 on lump sum basis.

We have authorise repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Janet Tan [mailto:[janet.tan@eqinsurance.com.sg](mailto:janet.tan@eqinsurance.com.sg)]  
**Sent:** Wednesday, 19 December 2018 10:44 AM  
**To:** ShirleyHiew@lkkauto.com  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Admin-D (LKKAuto <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Subject:** our ref: DM18HO03355/JT: OD SURVEY FOR GBD7545D (DM18HO03355-JT)

Dear Shirley

Please proceed to authorise repairs up to \$15,000.00

Regards,

**Janet Tan**

Senior Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190

[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)

 A Member of Citystate

*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify t*

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Tuesday, 18 December 2018 5:57 PM  
**To:** 'Joel Goh'  
**Cc:** 'Janet Tan'; SUR; Admin-D (LKKAuto); assignments  
**Subject:** RE: OD SURVEY FOR GBD7545D (DM18HO03355-JT)  
**Attachments:** GBD 7545D - Preli Advise.pdf

Dear Joel,

Enclosed preliminary revised of vehicle GBD 7545D  
Date of survey: 17/12/2018  
Number of days : 5 days

We have Not authorise repair. Kindly let us have your approval please.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]  
**Sent:** Monday, 17 December 2018 9:10 AM  
**To:** 'Joel Goh' <joel.goh@eqinsurance.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** 'Janet Tan' <janet.tan@eqinsurance.com.sg>; SUR <sur@lkkauto.com>  
**Subject:** RE: OD SURVEY FOR GBD7545D (DM18HO03355-JT)

Dear Sir/Mdm,

Thank you for the assignment.



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Joel Goh [mailto:joel.goh@eqinsurance.com.sg]  
**Sent:** Friday, 14 December 2018 5:11 PM  
**To:** assignments <assignments@lkkauto.com>  
**Cc:** Janet Tan <janet.tan@eqinsurance.com.sg>  
**Subject:** OD SURVEY FOR GBD7545D (DM18HO03355-JT)

Dear LKK

## Nivitha (LKK Auto)

---

**From:** Joel Goh <joel.goh@eqinsurance.com.sg>  
**Sent:** Friday, 14 December 2018 5:11 PM  
**To:** assignments  
**Cc:** Janet Tan  
**Subject:** OD SURVEY FOR GBD7545D (DM18HO03355-JT)  
**Attachments:** 14122018170859-0001.pdf; GBD7545D.PDF

Dear LKK

Please assist to attend to this OD survey.

Excess: \$500.00 (No waiver)

Best Regards,

**Joel Goh**  
Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)

 A Member of Citystate

*Privileged/Confidential Information may be contained in this message. If you are not the intended recipient, please notify the sender.*

19 KIM CHUAN TERRACE  
SINGAPORE 537041

RE: LETTER OF AUTHORIZATION AND AGREEMENT.

TO REPAIR AND CLAIM AS OWN DAMAGE \ THIRD PARTY.

DEAR SIR/MDM,

Million Supplies P/L OWNER/DRIVER OF VEHICLE NO: GRD 7545D

HEREBY AUTHORIZED WEE HOE AUTO SERVICE TO REPAIR MY VEHICLE AND MAKE  
A CLAIM TO ( OTHER PARTY INSURANCE COMPANY ) MY INSURANCE POLICY NO:

DMCPHQ18-001560 AS OWN DAMAGE ~~THIRD PARTY~~ CLAIM. I AM AWARE  
OF THIS CLAIM MIGHT AFFECT MY NCD ON RENEWAL OF MY POLICY. I ALSO AGREE TO  
PAY THE REPAIR COST OF MY SIDE VEHICLE TO THE ABOVE WORKSHOP IF THE  
INSURANCE COMPANY REJECTS OR DISAGREE TO PAY FOR WHATEVER REASONS.

THANK YOU FOR YOUR KIND ATTENTION AND NECESSARY ARRANGEMENT.

YOURS FAITHFULLY



NAME: Leow Hock Seng  
NRIC: SB139424E  
DATE: 13/12/18

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Wednesday, 19 December 2018 11:31 AM  
**To:** 'daryl tan'  
**Cc:** SUR  
**Subject:** RE: GBD 7545D OD (EQI)

Dear Chuan,

As instructed by our client, please proceed at repair cost not exceeding \$15,000.00 (inclusive supplementary) to repair the insured vehicle **GBD 7545D (Excess \$ 500/-)** on lump Sum basis.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** daryl tan [mailto:[daryltan@lkkauto.com](mailto:daryltan@lkkauto.com)]  
**Sent:** Wednesday, 19 December 2018 11:18 AM  
**To:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Subject:** Re: GBD 7545D OD (EQI)

Dear Shirley,

We will proceed with repairs based on lump sum not exceeding \$15000.00

Regards  
Chuan

On Wed, 19 Dec 2018, 11:13 Shirley Hiew (LKK Auto) <[ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com)> wrote:

Dear Mr. Kiat/Mr. Chuan,

As spoken, kindly check the repair cost limit whether you are able to repair the vehicle not exceeding \$ 15,000.00 on lump sum basis.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DM18HO03355-JT

Date: 18 December 2018

Our Ref: CS/EQ118022565/Bsd3

The Motor Claims Department  
EQ INSURANCE COMPANY LTD

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. GBD 7545D**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 17/12/2018 at the premises of M/s Wee Hoe Auto Service and have the following to report:-

|                          |                       |
|--------------------------|-----------------------|
| Workshop Estimate Amount | : <u>SS 20,746.79</u> |
| Revised Estimate Amount  | : <u>SS 11,397.75</u> |
| "Check" Items Amount     | : <u>SS 5,726.52</u>  |
| Total                    | : <u>SS 17,124.27</u> |
| Market Value             | : <u>SS 43,000.00</u> |
| LTA Reimbursement Value  | : <u>SS 24,432.00</u> |
| Nett Value               | : <u>SS 18,568.00</u> |

**Description of Damage:**

The vehicle sustained damages at the front portion.



**Comments/ Present Status:**

Damages Consistent.

Repair cost economical, we have not authorise repair

Repair days: 5 Days

Yours faithfully,  
Lim Teow Guan  
Automotive Assessor

Multi-Party Road Accident Claims Service (M-PAICS)  
 SINGAPORE POLICE (SPP) 05/12/2015 12:58  
 SUPPORTED BY: Consensus by GoLink.com

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any late reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and this copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available to interested parties.

## ACCIDENT STATEMENT

Date Of Report 05/12/2015 12:58  
 Date Of Accident 04/12/2015 17:15  
 Exact Location Of Accident UPPER THOMSON ROAD  
 Country/State of Loss SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number GBD7545D  
 Insured/Policyholder  
 Name Of Registered Owner MILLION SUPPLIES PTE LTD  
 Co Reg No 2013 015240  
 Email Address NOEMAIL  
 Mobile Phone No (LOCAL) +65-83990850  
 Alternative Phone No OFFICE-83990850

## Vehicle Particulars

Manufacturer NISSAN  
 Model

Exact Purpose for which vehicle was being used at time of accident

Are you insuring under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category COMMERCIAL VEHICLE

## Insurance Company

Name of Insurance Company EQ INSURANCE COMPANY LTD

Type Of Coverage COMPREHENSIVE

First Policy NO

Policy Number DMCPHQ15-001560

Cover Note Number

Driver

Name of Driver

NRIC No LEOH HOCK SENG ( LIAO FUSHENG )

Date Of Birth 28/11/1981

Occupation OUTDOOR

Date Of Driving Pass 20/08/2010

Driving Experience 8 YEARS AND 3 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-83990850

Fax Number

Contact Number OTHERS-83990850

E-Mail Address NOEMAIL

64969032

Address BLK 405 ANG MO KIO AVENUE 10  
#07-670  
Postcode 560405  
Was driver an employee of the Insured's Company? YES  
If No, Relationship of the Driver with the Insured  
Vehicle Registration Number of Driver's Own Vehicle  
Insurance Company of Driver's Own Vehicle

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
Weather Conditions RAINING  
Road Surface WET

**Other Information**

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting for my accident claims assistance. NO  
Number of Passengers (including Driver) 2  
Damage to

NAME: NIL  
GENDER: MALE

**Details of Police Action**

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

**Circumstances of Accident**

PLS REFER TO THE ATTACHED STATEMENT.

**Attachment(s)**

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? YES  
Remarks/ Reasons REVERT  
Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number GBC3373P  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category COMMERCIAL VEHICLE  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
9. I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

5/12/2018

Upper Thomson Road

SKETCH PLAN

Traffic  
LightA - GBD 7545D  
B - GBC 3373P

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

veh. A was driving along upper thomson. when approaching the traffic light junction, veh B suddenly ~~brake~~ Brake after the stop line and cause me NO choice but to jam brake but ~~that~~ veh B jam brake too. Sudden I could not brake in time leaving me no choice and knock into veh B.

I got out of the ~~veh~~ our van and ask why he suddenly jam brake, he say he only balance 12 point ~~that~~ why he suddenly jam brake, my delivery assistance also heard it. We had made a Police "Notice of reporting" officers also state that it is not necessary to be my fault as that junction has a traffic camera therefore I would like to request for the investigators to view the camera footage. Veh B driver also in a hurry to rush after asking us or telling us to claim insurance. As I keep asking him why he sudden Emergency brake on a rainy day suddenly would cause danger to other road user. then he say he had 12 points and this is a camera at the junction therefore he E-Brake to prevent him self to cross the line and ask us to claim insurance.

## DECLARATION

We declare the foregoing particulars are true in every respect.

Full name: \_\_\_\_\_  
Date & Time: \_\_\_\_\_Driver's Signature  
(if driver is not the motorist)  
Date & Time: \_\_\_\_\_Reporting Centre Personnel's Signature  
NRIC/FIN No.: \_\_\_\_\_

5/12/2018

Annex D

## NOTICE OF REPORTING

This is to confirm that Leow Hock Seng, NRIC: S8139424E has reported to the Police a non-injury traffic accident which occurred along Upper Thomson Road traffic junction near the Shell and SPC petrol station.  
On 04/12/2018 between 1720pm involving the following vehicles:

- 1) GBD7545D (Complainant's vehicle)
- 2) GBC3373P (Other party)

2 If this accident was reported to the Police within 24 hours of its occurrence, then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Rank/Name of Issuing Officer: Sgt Lim Brandon

Date: 05/12/2018 Time: 1220hrs

S/D Ref: 05

Police Post/Unit: Aljunied NPP / Tanglin Police Division

Original - to be issued to informant

Duplicate - to be submitted to Traffic Police

INVESTIGATOR


WU 002

EQ Insurance Company Limited

5 Malind Road #17-03 Tower Block MND Complex Singapore 085110

Tel: 65 6229 3433 | Fax: 65 6224 3000 | www.eqinsurance.com.sg

Reg No: 1378-10-00-M



## CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES 1959 (FEDERATION OF MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP.189 OF THE REVISED EDITION)

(REPUBLIC OF SINGAPORE)

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES 1956 EDITION (REPUBLIC OF SINGAPORE)

OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

## COMMERCIAL VEHICLE PRIVATE (SCH I)

Comprehensive

Certificate No.: DMCPhQ18-001560

## 1. Index Mark and Registration Number of Vehicles

08D7545D

Form: LCVP1

Excess:

Section 1:

YELD:

WindScreen

Additional

S\$500.00

S\$3,000.00

All Claims

S\$100.00

## 2. Name of Policyholder

MILLION SUPPLIES PTE LTD

## 3. Effective Date of the Commencement of Insurance for the purpose of the Act

23/04/2018

## 4. Date of Expiry of Insurance

23/04/2019

## 5. Person or Classes of persons entitled to drive\*

Goods Carrying - (MZ300) Authorised Driver. Any of the following:-

(a) The Policyholder

(b) Any other person who is driving on the Policyholder's order or with his permission.

\* Provided that the person driving is permitted in accordance with the licensing or other laws or regulation to drive the Motor Vehicle or has been permitted and is not disqualified by order of Court of Law or by reason of any enactment, enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act has not been cancelled at the time of accident loss or damage.

## 6. Limitation as to Use\*

1) Use in connection with the Insured's business.

2) Use for the carriage of passengers (other than for hire or reward) in connection with the Insured's business.

3) Use for social domestic and pleasure purposes.

THE POLICY DOES NOT COVER:

1) Use for hire or reward or for racing pace-making reliability trial or speed testing.

2) Use whilst drawing a greater number of trailers in all than is permitted by Law.

3) Use for the carriage of passengers for hire or reward.

4) Liability arising from or in connection with the carriage of hazardous materials, high explosives, inflammable liquid or gases including LPG in cylinders.

\*Limitations rendered inoperative by Section 8 of the Motor vehicles (Third-Party Risks and Compensation)

Act (Chapter 189) and Section 63 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or and Amendment, Act or Acts passed in substitution thereof.

(Re Purchase):

ABWIN PTE LTD  
6 KATIBUN ST. #03-01  
RUBY WAREHOUSE  
601-33 SINGAPORE 417841

Tel: 6842 3332 FAX: 6842 3301 (ADMIN OFFICE)

A000342/Abwin Pte Ltd

Date of Issue: 15/03/2018 17:40



Authorised Signatory  
EQ Insurance Company Limited

## Note

Young, Elderly &/or Inexperience Driver (YEIDR) refers to any person authorized to drive who is below 26 years old or above 70 years old and/or the holder of a qualified driving licence of less than 2 years duration.

1. A Member of Company

# Wee Hoe Auto Service

19, Kim Chuan Terrace, Singapore 537041

Tel: 9668 4774 Fax: 6858 6470

Vehicle No. : GBD7545D  
Make/Model : Nissan NV350  
Year : 2015  
Chassis No. : JN1MC2E26Z0004197

DATE : 14/12/2018

## ESTIMATE COST OF REPAIRS TO VEHICLE GBD7545D.

### PARTS LIST

|    |       |                                       |                                         |         |        |             |               |       |
|----|-------|---------------------------------------|-----------------------------------------|---------|--------|-------------|---------------|-------|
| 1  | 1 pc  | Frt windscreen                        |                                         |         | \$     | ✓ 1,025.60  | BR ✓          |       |
| 2  | 1 pc  | Frt windscreen moulding               |                                         |         | \$     | ✓ 62.70     | NEC ✓         |       |
| 3  | 1 pc  | Frt wiper garnish                     |                                         |         | \$     | ✓ 184.50    | BR ✓          |       |
| 4  | 1 pc  | Wiper blade RH                        |                                         |         | \$     | 48.00 72.50 | CUT ✓         |       |
| 5  | 1 pc  | Wiper arm RH                          |                                         |         | \$     | 146.10      | NNX           |       |
| 6  | 1 pc  | Wiper blade LH                        |                                         |         | \$     | 48.00 72.00 | CUT ✓         |       |
| 7  | 1 pc  | Wiper arm LH                          |                                         |         | \$     | 165.80      | NNX           |       |
| 8  | 1 pc  | Frt wiper linkage - photo             | DSCN 6848                               | 317.20  | \$     | ✓ 137.20    | BT ✓          |       |
| 9  | 1 pc  | Frt wiper motor                       | DSCN 6847                               |         | \$     | ✓ 431.60    | SC ✓          |       |
| 10 | 1 pc  | Frt panel                             |                                         |         | \$     | ✓ 1,096.90  | DD ✓          |       |
| 11 | 1 pc  | Frt panel inner member                | DSCN 5996, 5997, 5998, 6003, 6004, 6005 |         | \$     | ✓ 206.50    | DD ✓          |       |
| 12 | 2 pcs | Frt corner panel R/L LH - DIS, RH - N |                                         | \$      | 387.20 | \$          | ✓ 774.40      | DD ✓  |
| 13 | 2 pcs | Headlamp R/L                          |                                         | \$      | 348.80 | \$          | ✓ 697.60      | BR ✓  |
| 14 | 1 pc  | Frt grille assy                       |                                         |         |        | \$          | ✓ 486.10      | BR ✓  |
| 15 | 1 pc  | Frt grille emblem (Logo)              |                                         |         |        | \$          | ✓ 73.00       | NEC ✓ |
| 16 | 6 pcs | Frt grille clip                       |                                         | \$      | 3.20   | \$          | ✓ 19.20       | NEC   |
| 17 | 1 pc  | Frt bumper                            |                                         |         |        | \$          | ✓ 652.40      | DD ✓  |
| 18 | 8 pcs | Frt bumper clip                       |                                         | \$      | 3.20   | \$          | ✓ 25.60       | NEC   |
| 19 | 2 pcs | Frt bumper retainer R/L               |                                         | \$      | 32.80  | \$          | ✓ 65.60       | NEC   |
| 20 | 1 pc  | Frt bumper tow cover                  |                                         |         |        | \$          | ✓ 32.60       | NNX   |
| 21 | 2 pcs | Frt bumper fog lamp R/L               | DSCN 5982                               | \$      | 311.80 | \$          | 311.80 623.60 | BR ✓  |
| 22 | 2 pcs | Frt bumper fog lamp grille R/L        | DSCN 5983                               | \$      | 107.80 | \$          | 107.80 215.60 | BR ✓  |
| 23 | 2 pcs | Frt bumper bracket R/L                | DSCN 5991                               | \$      | 104.70 | \$          | 104.70 209.40 | BR ✓  |
| 24 | 1 pc  | Frt bumper reinforcement              | DSCN 6092                               |         |        | \$          | 630.00        | NNX   |
| 25 | 1 pc  | A/c blower assy                       | DSCN 6846, 6347                         |         |        | \$          | 680.40        | DD ✓  |
| 26 | 1 pc  | A/c cooling coil assy                 | DSCN 5996, 5997, 5998                   |         |        | \$          | 2,181.50      | DD ✓  |
| 27 | 1 pc  | A/c suction pipe                      |                                         |         |        | \$          | ✓ 176.00      | BT ✓  |
| 28 | 1 pc  | A/c discharge pipe                    |                                         |         |        | \$          | ✓ 176.00      | BT ✓  |
| 29 | 1 pc  | A/c liquid pipe                       |                                         |         |        | \$          | ✓ 108.60      | BT ✓  |
| 30 | 1 pc  | A/c receiver drier                    | DSCN 5998, 5999, 6050, -6054            |         |        | \$          | ✓ 140.30      | BT ✓  |
| 31 | 1 pc  | Air inlet duct                        |                                         |         |        | \$          | ✓ 132.40      | BR ✓  |
| 32 | 1 pc  | Frt door pillar LH - photo            | DSCN 5993, -5995, 5999, 5990, 6026      |         |        | \$          | ✓ 958.20      | BT ✓  |
| 33 | 1 pc  | Frt door LH                           | 6037                                    |         |        | \$          | 1,232.90      | BR ✓  |
| 34 | 2 pcs | Frt door hinge LH                     |                                         | \$      | 49.00  | \$          | ✓ 98.00       | BT ✓  |
| 35 | 1 pc  | Frt windscreen moulding               |                                         |         |        | \$          | 83.20         | RPTX  |
| 36 | 1 pc  | Frt wiper garnish                     | NNX                                     |         |        | \$          | 712.70        | NNX   |
| 37 | 1 pc  | Frt step garnish LH - photo           | NNX                                     |         |        | \$          | 180.60        | NNX   |
| 38 | 1 pc  | Frt door rear pillar LH               |                                         |         |        | \$          | 913.20        | NNX   |
| 39 | 1 pc  | Dashboard - photo                     | DSCN 6015 - 6023                        | 1324.68 | \$     | ✓ 1,457.20  | DIS ✓         |       |
| 40 | 1 pc  | Dashboard frame                       | DSCN 6015                               |         |        | \$          | 795.30        | BT ✓  |
| 41 | 1 pc  | Dashboard console cover LH - photo    | DSCN 6018 - 6024                        |         |        | \$          | ✓ 375.10      | DIS   |

Total Nett Parts: \$ 18,123.10  
Less 10% \$ 1,812.31  
\$ 16,310.79

# Wee Hoe Auto Service

19, Kim Chuan Terrace, Singapore 537041

Tel: 9668 4774 Fax: 6858 6470

- |   |      |                              |
|---|------|------------------------------|
| 1 | 1 pc | Frt windscreen sealant       |
| 2 | 1 pc | Frt windscreen solar film    |
| 3 | 1 pc | Frt windscreen I.U. bracket  |
| 4 | 1 pc | Frt panel                    |
| 5 | 1 pc | Frt door pillar LH           |
| 6 | 1 pc | Frt door sticker (Co.Reg) LH |

|     |    |         |     |
|-----|----|---------|-----|
| S/N | \$ | ✓ 50.00 | ACC |
| S/N | \$ | 250.00  | NNA |
| S/N | \$ | ✓ 26.00 | NEC |
| S/N | \$ | 50.00   | NNX |
| S/N | \$ | 50.00   | NNX |
| S/N | \$ | ✓ 20.00 | NEC |

**Total Parts:** \$ 16,756.79

## Labour:

- |   |                                                                                                        |             |        |
|---|--------------------------------------------------------------------------------------------------------|-------------|--------|
| 1 | To check electrical system, repair wire harness and focus headlamp.                                    | \$ 40.00    | ✓      |
| 2 | To remove, replace and reinstall front windscreen.                                                     | \$ 140.00   | ✓      |
| 3 | To remove, replace and reinstall dashboard.                                                            | \$ 350.00   | ✓      |
| 4 | To remove, replace and reinstall a/c blower and a/c evaporator.<br>(Include vacuum & recharge a/c gas) | \$ 140.00   | ✓      |
| 5 | To remove & reinstall interior trims, garnishes, seats, etc. for necessary repairs.                    | \$ 150.00   | ✓      |
| 6 | To transfer LHF door component parts to new door.                                                      | \$ 100.00   | ✓      |
| 7 | To straighten, repair, realign on affected area and replace damaged parts.                             | \$ 1,500.00 | ✓      |
| 8 | To conduct chassis alignments.                                                                         | \$ 350.00   | NNX    |
| 9 | To spray painting on affected area.                                                                    | \$ 1,200.00 | 800.00 |

**Total labour:** \$ 3,990.00

**Total Estimated:** \$ 20,746.79

Excess \$ 500.00

Not Authorised

*[Signature]*  
18/12/18

L/S claim

Repair days 3

TOTUM  
LIR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                     |          |                                                                  |                             |            |
|-----------------------------------------------------------------------------------------------------------------------|----------|------------------------------------------------------------------|-----------------------------|------------|
| EQ INSURANCE COMPANY LTD                                                                                              |          |                                                                  | Ref : CS/EQI18022565/Bsd3e2 |            |
| 5 MAXWELL ROAD<br>#17-00 TOWER BLOCK<br>MND COMPLEXSINGAPORE 069110                                                   |          |                                                                  | Date : 21-05-2019           |            |
|                                                                                                                       |          |                                                                  | Code : EQI                  |            |
| <b>1. Policy Particulars :- OWN DAMAGE</b>                                                                            |          |                                                                  |                             |            |
| Insured Veh.                                                                                                          |          | Veh. Inspected                                                   |                             | GBD 7545D  |
| Policy No. DMCPHQ18-001560                                                                                            |          | Coverage (\$)                                                    |                             | 0.00       |
| Claim No. DM18HO03355-JT                                                                                              |          | Excess (\$)                                                      |                             | 500.00     |
| Assign From JOEL GOH                                                                                                  |          | Assign Date                                                      |                             | 14/12/2018 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                         |          |                                                                  |                             |            |
| Make & Model NISSAN NV350 PANEL VAN                                                                                   |          | c.c                                                              |                             | 2488       |
| Engine No. HIDDEN                                                                                                     |          | Year of Reg.                                                     |                             | 2015       |
| Chassis No. JN1MC2E26Z0004197                                                                                         |          | Colour                                                           |                             | WHITE      |
| Odometer 143949                                                                                                       |          | Steering                                                         |                             | IN ORDER   |
| Brakes IN ORDER                                                                                                       |          | Modification                                                     |                             | NIL        |
| General POOR                                                                                                          |          |                                                                  |                             |            |
| <b>3. Conditions of Tyres</b>                                                                                         |          |                                                                  |                             |            |
|                                                                                                                       | Size     | Make                                                             | Balance                     |            |
| R/H Front Tyre                                                                                                        | 195 R15C | BRIDGESTONE                                                      | 6 mm                        |            |
| L/H Front Tyre                                                                                                        | 195 R15C | BRIDGESTONE                                                      | 6 mm                        |            |
| R/H Rear Tyre                                                                                                         | 195 R15C | BRIDGESTONE                                                      | 6 mm                        |            |
| L/H Rear Tyre                                                                                                         | 195 R15C | BRIDGESTONE                                                      | 6 mm                        |            |
| <b>4. Description of Damages</b>                                                                                      |          |                                                                  |                             |            |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.<br>DAMAGES SEE DETAILS.                                           |          |                                                                  |                             |            |
| <b>5. General Information</b>                                                                                         |          |                                                                  |                             |            |
| Accident Date 04/12/2018                                                                                              |          | Inspection Date 17/12/2018                                       |                             |            |
| Survey held at                                                                                                        |          | WEE HOE AUTO SERVICE<br>19 KIM CHUAN TERRACE<br>SINGAPORE 537041 |                             |            |
| <b>5a. Remarks</b>                                                                                                    |          |                                                                  |                             |            |
| A)THE MARKET VALUE IS S\$43,000.00(EST. AVERAGE)<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS. |          |                                                                  |                             |            |
| <b>5b. Estimate Days of Repair</b>                                                                                    |          |                                                                  |                             |            |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                   |          | 5 Working Days                                                   |                             |            |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 7545D

| Qty | Description of Parts                     | Condition                         | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------------|-----------------------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>       |                                   |                           |                   |
| 1   | FRT WINDSCREEN                           | BROKEN                            | 1,025.60                  | 1,025.60          |
| 1   | FRT WINDSCREEN MOULDING                  | NECESSARY                         | 62.70                     | 62.70             |
| 1   | FRT WIPER GARNISH                        | BROKEN                            | 184.50                    | 184.50            |
| 1   | WIPER BLADE RH                           | CUT                               | 72.50                     | 40.00             |
| 1   | WIPER ARM RH                             | NOT NECESSARY                     | 146.10                    | -                 |
| 1   | WIPER BLADE LH                           | CUT                               | 72.00                     | 40.00             |
| 1   | WIPER ARM LH                             | NOT NECESSARY                     | 165.80                    | -                 |
| 1   | FRT WIPER LINKAGE                        | BENT                              | 317.20                    | 317.20            |
| 1   | FRT WIPER MOTOR                          | SHORT CIRCUIT                     | 431.60                    | 431.60            |
| 1   | FRT PANEL                                | DENTED                            | 1,096.90                  | 1,096.90          |
| 1   | FRT PANEL INNER MEMBER                   | DENTED                            | 206.50                    | 206.50            |
| 2   | FRT CORNER PANEL R/L @\$387.20           | N/S DISTORTED / O/S NOT NECESSARY | 774.40                    | 387.20            |
| 2   | HEADLAMP R/L @\$348.80                   | BROKEN                            | 697.60                    | 697.60            |
| 1   | FRT GRILLE ASSY                          | BROKEN                            | 486.10                    | 486.10            |
| 1   | FRT GRILLE EMBLEM (LOGO)                 | NECESSARY                         | 73.00                     | 73.00             |
| 6   | FRT GRILLE CLIP @\$3.20                  | NECESSARY                         | 19.20                     | 19.20             |
| 1   | FRT BUMPER                               | DENTED                            | 652.40                    | 652.40            |
| 8   | FRT BUMPER CLIP @\$3.20                  | NECESSARY                         | 25.60                     | 25.60             |
| 2   | FRT BUMPER RETAINER R/L @\$32.80         | NECESSARY                         | 65.60                     | 65.60             |
| 1   | FRT BUMPER TOW COVER                     | NOT NECESSARY                     | 32.60                     | -                 |
| 2   | FRT BUMPER FOG LAMP R/L @\$311.80        | N/S BROKEN                        | 623.60                    | 311.80            |
| 2   | FRT BUMPER FOG LAMP GRILLE R/L @\$107.80 | N/S BROKEN                        | 215.60                    | 107.80            |
| 2   | FRT BUMPER BRACKET R/L @\$104.70         | N/S BROKEN                        | 209.40                    | 104.70            |
| 1   | FRT BUMPER REINFORCEMENT                 | NOT NECESSARY                     | 630.00                    | -                 |
| 1   | A/C BLOWER ASSY                          | DENTED                            | 680.40                    | 680.40            |
| 1   | A/C COOLING COIL ASSY                    | DENTED                            | 2,181.50                  | 2,181.50          |
| 1   | A/C SUCTION PIPE                         | BENT                              | 176.00                    | 176.00            |
| 1   | A/C DISCHARGE PIPE                       | BENT                              | 176.00                    | 176.00            |
| 1   | A/C LIQUID PIPE                          | BENT                              | 108.60                    | 108.60            |

Report Ref No. CS/EQ18022565/Bsd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                                                                                 | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------------------------------------------------------------------------|----------------------|---------------------------|-------------------|
| 1   | A/C RECEIVER DRIER                                                                                   | BENT                 | 140.30                    | 140.30            |
| 1   | AIR INLET DUCT                                                                                       | BROKEN               | 132.40                    | 132.40            |
| 1   | FRT DOOR PILLAR LH                                                                                   | BENT                 | 958.20                    | 958.20            |
| 1   | FRT DOOR LH                                                                                          | TO REPAIR SEE LABOUR | 1,232.90                  | -                 |
| 2   | FRT DOOR HINGE LH @\$49.00                                                                           | BENT                 | 98.00                     | 98.00             |
| 1   | FRT WINDSCREEN MOULDING                                                                              | REPEATED             | 83.20                     | -                 |
| 1   | FRT WIPER GARNISH                                                                                    | NOT NECESSARY        | 147.70                    | -                 |
| 1   | FRT STEP GARNISH LH                                                                                  | NOT NECESSARY        | 180.60                    | -                 |
| 1   | FRT DOOR REAR PILLAR LH                                                                              | TO REPAIR SEE LABOUR | 913.20                    | -                 |
| 1   | DASHBOARD                                                                                            | DISTORTED            | 1,457.20                  | 1,324.68          |
| 1   | DASHBOARD FRAME                                                                                      | BENT                 | 795.30                    | 795.30            |
| 1   | DASHBOARD CONSOLE COVER LH                                                                           | DISTORTED            | 375.10                    | 375.10            |
|     | LESS 10% DISCOUNT                                                                                    |                      | -1,812.31                 | -1,348.25         |
|     |                                                                                                      |                      | 16,310.79                 | 12,134.23         |
|     | <b><u>SPECIAL NETT ITEMS</u></b>                                                                     |                      |                           |                   |
| 1   | FRT WINDSCREEN SEALANT (SN)                                                                          | NECESSARY            | 50.00                     | 50.00             |
| 1   | FRT WINDSCREEN SOLAR FILM (SN)                                                                       | NOT NECESSARY        | 250.00                    | -                 |
| 1   | FRT WINDSCREEN I.U. BRACKET (SN)                                                                     | NECESSARY            | 26.00                     | 26.00             |
| 1   | FRT PANEL (SN)                                                                                       | NOT NECESSARY        | 50.00                     | -                 |
| 1   | FRT DOOR PILLAR LH (SN)                                                                              | NOT NECESSARY        | 50.00                     | -                 |
| 1   | FRT DOOR STICKER (CO.REG) LH (SN)                                                                    | NECESSARY            | 20.00                     | 20.00             |
|     |                                                                                                      |                      | 446.00                    | 96.00             |
|     | <b><u>LABOUR</u></b>                                                                                 |                      |                           |                   |
|     | TO CHECK ELECTRICAL SYSTEM, REPAIR WIRE HARNESS AND FOCUS HEADLAMP.                                  |                      | 60.00                     | 40.00             |
|     | TO REMOVE, REPLACE AND REINSTALL FRONT WINDSCREEN.                                                   |                      | 140.00                    | 100.00            |
|     | TO REMOVE, REPLACE AND REINSTALL DASHBOARD.                                                          |                      | 350.00                    | 200.00            |
|     | TO REMOVE, REPLACE AND REINSTALL A/C BLOWER AND A/C EVAPORATOR. (INCLUDE VACUUM & RECHARGE A/C GAS). |                      | 140.00                    | 120.00            |
|     | TO REMOVE & REINSTALL INTERIOR TRIMS, GARNISHES, SEATS, ETC. FOR NECESSARY REPAIRS.                  | NOT NECESSARY        | 150.00                    | -                 |

Report Ref No. CS/EQ118022565/Bsd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty         | Description of Parts                                                                                                                             | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-------------|--------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|             | TO TRANSFER LHF DOOR COMPONENT PARTS TO NEW DOOR.                                                                                                | NOT NECESSARY | 100.00                    | -                 |
|             | TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR LH AND FRT DOOR REAR PILLAR LH. |               | 1,500.00                  | 1,100.00          |
|             | TO CONDUCT CHASSIS ALIGNMENTS.                                                                                                                   | NOT NECESSARY | 350.00                    | -                 |
|             | TO SPRAY PAINTING ON AFFECTED AREA.                                                                                                              |               | 1,200.00                  | 800.00            |
|             |                                                                                                                                                  |               | 3,990.00                  | 2,360.00          |
| GRAND TOTAL |                                                                                                                                                  |               | 20,746.79                 | 14,590.23         |

|                                                                      |  |  |           |
|----------------------------------------------------------------------|--|--|-----------|
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) |  |  | 11,650.00 |
| LESS EXCESS                                                          |  |  | -500.00   |
| NETT LIABILITY                                                       |  |  | 11,150.00 |

Report Ref No. CS/EQ118022565/Bsd3e2

LIM TEOW GUAN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.