

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

Due 27/12

→ 4/1/2018

2pm
Survey only

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

15 DEC 2018

Estimate No. : b1 49452	Page No. : 1 of 5
Date Estimated : 15/12/2018	
Prepared By : Chua Kee Sin	

- ESTIMATE REPAIR FOR - Jonas Chua Ghee Seng 1 Sian Tuan Avenue Singapore 588267	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLL2008K	0R99827	20/01/2017	X3 sDrive20	0

DESCRIPTION	VALUE
Replacing rear bumper panel and attachments, rework bootlid, etc to knock out dents caused by the accident	1770. 2,550.00
Spray rear bumper, bootlid	1805 2,006.00
To check electrical wiring systems and lightings at the rear section for proper function.	150. 177.00
Sundries	? 150.00
Total Labour 1:	4,883.00

DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER CARRIER ECE	1	756.50	X 756.50
RR LH BUMPER MIDDLE MOUNTING	1	137.75	X 137.75
RR RH BUMPER MIDDLE MOUNTING	1	137.75	? 137.75
RR BUMPER LH MOUNT	1	192.15	X 192.15
RR BUMPER RH MOUNT	1	192.15	? 192.15
TRIM PANEL BUMPER RR BOTTOM (M)	1	258.00	? 258.00
RR BUMPER TRIM BUMPER PRIMED PDC (	1	1,625.30	de 1,625.30
REAR RH REFLECTOR	1	36.10	cnq 36.10
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	nei 20.20
BUMPER PDC SENSOR (SCHWARZ)	1	236.85	? 236.85
Total Parts :			3,592.75

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 49452
Date Estimated : 15/12/2018
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLL2008K	0R99827	20/01/2017	X3 sDrive20	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date&Time 4/1/19 Excess S\$ _____
Surveyor's Name Tan Jiah Sign [Signature]
Surveyor's Tel 97447770 Authorised Yes / No _____
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____
Surveyor's E-mail tanjiah@lkkauto.com
No. of Working Days Recommend 4 - 5 days

Labour 1	:	4,883.00
Parts	:	3,592.75
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	593.30
Grand Total	:	9,069.05

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **