

CL

CC 4/Asm 180

22596, Aga3sr

LKK:
IDAC:

88708

ASSIGNMENT

Surveyor:

Adrain

DOI:

18/12/18

Date / Time:

17/12/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SCV 68124

Name of Insured:

TAN Lam Koc

Insured Tel No.:

HP:

91800220

Excess Sec II :SS

D.O.A.:

14/12/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

500 33224



INSRS:

WSP:

Tel:

Liability:

RMKS:

Premium



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

18/12
8/1500 33224 X;
SCV 68124 - CVI / VACU 500 780 / G. 100. -

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

26/7/19

OI no. not in use.
Send WOI to 169 Stirling road #09-1153 S(140169)
Stated M SC.

20-12-18

EM LIABILITY CLEAR

24/1/19

24/1/19

16/1/19

7/1/19

- REC WOR to TP (pending LOD)
- LOD in CTS self mandate.
- Pending mandate approval.
- Settle @ \$8891.92 at per TP LOD. DV in
File pass MK to close.

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: Adrain -

Repair Cost:

P/P

SS 7934.50

(4 days)

Reduction: 94.50% 65

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

CMAST

SS

8489.92

Loss of Rental (LOR):

SS

400.00

(4 days)

x \$100

Loss of Use (LOU):

SS

-

(\$

x

days)

Loss of Income (LOI):

SS

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

8891.92

Global Sum SS:

Email

Call

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

SS

8891.92

Name 1:

Premium Automotiles Pte Ltd

Payee 2: (Strike if N.A.)

SS

-

Name 2:

Payee 3: (Strike if N.A.)

SS

-

Name 3:

COPY SENT
21/1/19

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

TP

\$350.

REF:

ASM (AXA)

22596/ACI a3

ASSIGNMENT

From:

Date:

18/12/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SOD 3322H

at Workshop n/s

Premium

of

55 Ubi Rd 1

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

9km

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04888. days

Res.: Yes or No

Lum Sum:

1-1-1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SOD 3322H

Yr Regn: 2014 Oct

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi Q5

C.C. 1984

Colour:

Black.

A/C: Insured / Std / NI / NA

Sp. Reading

84295

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAU2Z8R7EA080296

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

235/55R19.

R:

235/55R19.

BS / DUN / EXNOVA / GY / FS / LIZA ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

ob

mm

R/Bal.

ob

mm

L/Bal.

ob

mm

L/Bal.

ob

mm

D.O.A.

D.O.I.

18/12/18

Survey held at

Premium.

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TPAXA.

$$P/P = 47934.50 - (Red = \$14,509.50 / 65\%)$$

MV: 1051K

PV: 83.4K

Nett: 21.6K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1428/2018/PH
Date : 17-Dec-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle : SCV 6812 H

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Hi Adrian

4 dasys - ok - jb - 29 January 19

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr. Choy Pow Chai
Address : 54 Chuan Garden
Singapore 558567
Telephone : HP +65 96700019
Type of Claim : Third party Claims
Policy No. : 2100391231-04
Vehicle No : **SDD 3322 H**
Model Code : Audi Q5 2.0 TFSI Qu
Model / Year : Oct-14
Engine No : CNC 042541
Chassis No : WAUZZZ8R7EA090296
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Dec-18
Place of Accident : M'sia custom towards Singapore custom

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDD 3322 H .

S/n	Nature of Jobs	Estimated Charges			
1	To remove and reinstall rear parking aid.Check function.	S/N	\$ 280.00	\$	280.00
2	To remove and reinstall rear lid's convenience lock system,wire harness for tail lights and rear wiper system.	S/N	\$ 480.00		
3	To renew rear windscreen.	S/N	\$ 480.00		
4	To dismantle and renew rear bumper and rear lid.Inspect end panelling for further damages.Re-organize crash management components.Reinstall all parts removed.		\$ 2,100.00	\$	700.00
5	To respray rear bumper,rear lower spoiler,rear lid and rear hinges.		\$ 2,500.00	\$	2,100.00
6	To remove and renew rhs rear exhaustr silencer and centre exhaust silencer.To align to position. (Repair and align)		\$ 480.00	\$	280.00
7	<i>Added labour - see attached</i>		\$ 1,200.00	\$	950.00
8	To carry out diagnostic check	S/N	\$ 192.00	\$	192.00
	TOTAL LABOUR CHARGES	:	\$ 6,320.00	\$	4,502.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDD 3322 H .

S/N	Parts Description	<u>Damaged Parts & Prices</u>			
		S/Nett			
1	REAR BUMPER	\$	1,430.00	\$	1,430.00
2	REAR BUMPER FIXING PARTS	\$	143.00		
3	REAR BUMPER TAIL LIGHT - RH	\$	265.00	\$	262.50
4	REAR BUMPER GUIDE SECTION - LH/RH	2 \$	92.00		
5	REAR BUMPER GROMMET	2 \$	20.00		
6	REAR BUMPER SPOILER	\$	749.00	\$	749.00
7	REAR REINFORCEMENT	\$	571.00	\$	571.00
8	REAR REINFORCEMENT BRACKET - LH/RH	2 \$	368.00		
9	REAR BUMPER SENSOR	\$	211.00		
10	REAR BUMPER SENSOR	\$	196.00		
11	REAR LID	\$	3,844.00		
12	REAR LID ATTACHMENT PARTS	\$	106.00		
13	REAR LID HINGE	2 \$	400.00		
14	REAR LID STRUT	2 \$	209.00		
15	GASKET FOR FLAP	\$	176.00		
16	SEAL -UPPER	\$	63.00		
17	STRIKER PLATE WITH MOTOR FOR POWER LATCH	\$	802.00		
18	REAR LID LOCK	\$	157.00		
19	PUSH BUTTON FOR ELECTRIC LID LOCK ACTUATOR	\$	159.00		
20	SEAL FOR PUSH BUTTON	\$	14.00		
SUB TOTAL SPARE PARTS		:	\$ 9,975.00	\$	3,012.50

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDD 3322 H.

S/N	Parts Description	<u>Damaged Parts & Prices</u>		
		S/Nett		
		c/f	\$	3,012.50
21	REAR LID STOP BUFFER	2 \$	48.00	
22	GUARD PLATE - INNER	\$	54.00	
23	LOCKING CLIP	2 \$	41.00	
24	1 SET FIXING PARTS FOR SPOILER	\$	147.00	
25	PACKING ADHESIVE	\$	15.00	\$ 14.50
26	Q5' EMBLEM	\$	83.00	\$ 82.70
27	2.0T' EMBLEM	\$	83.00	\$ 82.70
28	QUATRR0' EMBLEM	\$	83.00	\$ 82.70
29	AUDI LOGO	\$	108.00	\$ 107.50
30	REAR WINDSCREEN	\$	1,020.00	
31	PRIMER	2 \$	38.00	
32	REAR SILENCER - RH	\$	883.00	
33	DUAL CLIP	\$	47.00	
34	BRACKET - LH / RH REAR	2 \$	100.00	\$ 49.90
35	CENTRE SILENCER	\$	875.00	
36	DUAL CLIP	\$	52.00	
37	DUAL CLIP	2 \$	93.00	
38	BRACKET - LH / RH FRONT	2 \$	78.00	
39	TRIM FOR REAR CROSS PANEL - PLASTIC/STAINLESS STEEL	\$	301.00	
40	SUNDRIES	\$	800.00	
TOTAL SPARE PARTS		:	\$ 14,924.00	\$ 3,432.50
TOTAL LABOUR CHARGES		:	\$ 6,320.00	\$ 4,502.00
GRAND TOTAL		:	\$ 21,244.00	\$ 7,934.50

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AXA Insurance Singapore Pte Ltd 8 Shenton Way #27-01 AXA Tower Singapore 068811 Attn: Motor Claims Dept Tel: 6880 4602 - Fax: 6880 4838		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/1428/2018/PH 20-Dec-18 Allan Wu ONE SDD 3322 H Audi Q5 2.0 TFSI Qu
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
		-	
<u>LABORS</u>			
1	To repair and respray rear end panel.	\$ 1,200.00	\$ 950.00
TOTAL		\$ 1,200.00	\$ 950.00

For Premium Automobiles Pte Ltd

AXA RATE 1. Repair \$350/- @ 1/2 day
2. Painting \$600/-

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

Estimate No. PA/TP/1428/2018/PH
Date 20-Dec-18
Service Advisor Allan Wu
Pages ONE
Regn No SDD 3322 H
Model No Audi Q5 2.0 TFSI Qu

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Parts

LABORS

1	To repair and respray rear end panel.	\$ 1,200.00
TOTAL		\$ 1,200.00

For Premium Automobiles Pte Ltd

Adrian Lj

Authorised Signature

950 /
Repair : 350 (half day)
Painting : 600.
950 fl/s.

\$22,444

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1428/2018/PH
Date : 17-Dec-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle : SCV 6812 H

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr. Choy Pow Chai
Address : 54 Chuan Garden
Singapore 558567
Telephone : HP +65 96700019
Type of Claim : Third party Claims
Policy No. : 2100391231-04
Vehicle No : **SDD 3322 H**
Model Code : Audi Q5 2.0 TFSI Qu
Model / Year : Oct-14
Engine No : CNC 042541
Chassis No : WAUZZZ8R7EA090296
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Dec-18
Place of Accident : M'sia custom towards Singapore custom

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDD 3322 H .

S/n	Nature of Jobs	Estimated Charges
1	To remove and reinstall rear parking aid.Check function.	S/N \$ 280.00 ✓ /
2	To remove and reinstall rear lid's convenience lock system,wire harness for tail lights and rear wiper system.	S/N \$ 480.00 X
3	To renew rear windscreen.	S/N \$ 480.00 X
4	To dismantle and renew rear bumper and rear lid.Inspect end panelling for further damages.Re-organize crash management components.Reinstall all parts removed.	\$ 2,100.00 700 ✓
5	To respray rear bumper,rear lower spoiler,rear lid and rear hinges.	\$ 2,500.00 2100 ✓
6	To remove and renew rhs rear exhaustr silencer and centre exhaust silencer.To align to position.	\$ 480.00 280 ✓
7	To carry out diagnostic check	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		\$ 6,320.00 6412

0

1 KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDD 3322 H.

S/N	Parts Description	Damaged Parts & Prices S/Nett	
1	REAR BUMPER <i>Rehanded</i>	\$	1,430.00 ✓/
2	REAR BUMPER FIXING PARTS <i>new</i>	\$	143.00 +
3	REAR BUMPER TAIL LIGHT - RH <i>cracked</i>	\$	265.00 ✓ 262.50 ✓
4	REAR BUMPER GUIDE SECTION - LH/RH <i>new</i>	2 \$	92.00 x.
5	REAR BUMPER GROMMET <i>new</i>	2 \$	20.00 +.
6	REAR BUMPER SPOILER <i>Rehanded</i>	\$	749.00 ✓/
7	REAR REINFORCEMENT <i>Bent.</i>	\$	571.00 ✓/
8	REAR REINFORCEMENT BRACKET - LH/RH <i>new</i>	2 \$	368.00 x.
9	REAR BUMPER SENSOR <i>new</i>	\$	211.00 +.
10	REAR BUMPER SENSOR <i>new</i>	\$	196.00 +.
11	REAR LID <i>Repair</i>	\$	3,844.00 x.
12	REAR LID ATTACHMENT PARTS <i>new</i>	\$	106.00 +
13	REAR LID HINGE	2 \$	400.00 +
14	REAR LID STRUT	2 \$	209.00 +
15	GASKET FOR FLAP	\$	176.00 +.
16	SEAL -UPPER <i>new</i>	\$	63.00 +
17	STRIKER PLATE WITH MOTOR FOR POWER LATCH <i>new</i>	\$	802.00 x
18	REAR LID LOCK <i>new</i>	\$	157.00 x
19	PUSH BUTTON FOR ELECTRIC LID LOCK ACTUATOR <i>new</i>	\$	159.00 x.
20	SEAL FOR PUSH BUTTON <i>new</i>	\$	14.00 x.
SUB TOTAL SPARE PARTS		:	\$ 9,975.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDD 3322 H.

S/N	Parts Description	Damaged Parts & Prices S/Nett	
-----	-------------------	----------------------------------	--

21	REAR LID STOP BUFFER	2	\$ 48.00 x
22	GUARD PLATE - INNER	\$	54.00 x
23	LOCKING CLIP	2	\$ 41.00 x
24	1 SET FIXING PARTS FOR SPOILER	\$	147.00 x.
25	PACKING ADHESIVE	\$	15.00 - 14.50 /
26	Q5' EMBLEM	\$	83.00 - 82.70
27	2.0T' EMBLEM	\$	83.00 - 82.70 /
28	QUATRRRO' EMBLEM	\$	83.00 - 82.70 /
29	AUDI LOGO	\$	108.00 - 107.50 /
30	REAR WINDSCREEN	\$	1,020.00 x
31	PRIMER	2	\$ 38.00 x.
32	REAR SILENCER - RH	\$	883.00 x.
33	DUAL CLIP	\$	47.00 x
34	BRACKET - LH / RH REAR	2	\$ 100.00 x. 48.90.
35	CENTRE SILENCER	\$	875.00 +
36	DUAL CLIP	\$	52.00 x
37	DUAL CLIP	2	\$ 93.00 x
38	BRACKET - LH / RH FRONT	2	\$ 78.00 x
39	TRIM FOR REAR CROSS PANEL - PLASTIC/STAINLESS STEEL	\$	301.00 x.
40	SUNDRIES	\$	800.00 x.

TOTAL SPARE PARTS : \$ 14,924.00

TOTAL LABOUR CHARGES : \$ 6,320.00 6592

GRAND TOTAL : \$ 21,244.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

21436
226360

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 18/12/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0290Z
Vehicle Details	
Vehicle No.:	SDD3322H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Dec 2018
Vehicle Make:	AUDI
Vehicle Model:	Q5 2.0 TFSI QUATTRO (EU6)
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	CNC042541
Chassis No.:	WAUZZZ8R7EA090296
Maximum Power Output:	165.0 kW (221 bhp)
Open Market Value:	\$44,917.00
Original Registration Date:	31 Oct 2014
First Registration Date:	31 Oct 2014
Transfer Count:	0
Actual ARF Paid:	\$54,884.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Oct 2024
PARF Rebate Amount:	\$41,163.00
Intended COE Rebate Details	
COE Expiry Date:	30 Oct 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$72,201.00
COE Rebate Amount:	\$42,233.00
Total Rebate Amount:	\$83,396.00

The information contained herein is correct as at 18 Dec 2018

OK

Guiding their next step

Republic Polytechnic

Get to know more about
guide your child to their c

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad | Advertiser Login | Ways of Selling

Near Showroom Condition Renault Kadjar 1.2L Petrol.

Very Low Mileage, Immaculate Condition, Lowest Depreciation In Market.
Direct Owner: StarAd

StarAd

HIN LUNG AUTO
Ho Bee Group

One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

30 years
of car sale

Browse by Category

Save Search

Print

Sort by Date Posted

20 results/page

4 vehicles

Search Audi Q5

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

Audi Q5

Any

Any

2014

Any

Any

Any

Available



Audi SQ5 3.0 TFSI Quattro

\$143,800

\$20,140 /yr

27-Mar-2014

2,995 cc

39,800 km

SUV

Available

Rare Audi SQ5 Agent Unit. Low Mileage, Agent Serviced. Superb V6 Engine Packs 348BHP In This Pocket Rocket! The SQ5 Will Set You Apart As You Cruise Down The Urban Jungle! Now Within Reach At Half The...

Posted: 26-Nov-2018 Tags: 2014 Audi SQ5, 2014 audi sq5, Audi SQ5, audi sq5, Audi, SQ5, sq5, Used Audi



Audi Q5 2.0A TFSI Quattro

\$102,888

\$13,810 /yr

10-Jun-2014

1,984 cc

107,000 km

SUV

Available

Downpayment \$10K Only! From \$1,500/Month. 1 Owner Unit, Fully Serviced & Maintained By Agent. Drive With Peace Of Mind, Originally Parts Used Only. Diligently Taken Care Of, 100% Accident Free, Non Ab...

Cars 88 Pte Ltd

Posted: 13-Dec-2018 Tags: 2014 Audi Q5, 2014 audi q5, Audi Q5, audi q5, Audi, Q5, q5, Used Audi



Audi Q5 2.0A TFSI Quattro

\$112,800

\$15,190 /yr

31-Jul-2014

1,984 cc

64,800 km

SUV

Available

1 Owner, Low Mileage Car. Superb Condition. Road Tax Till 31/01/2019! Comes With Servicing Records/Receipts. No Repair Needed. Full Leather Interior, 3m Solar Film! Lowest Depre With Such Great Condit...

Think One Automobile & Trading

Posted: 12-Nov-2018 Tags: 2014 Audi Q5, 2014 audi q5, Audi Q5, audi q5, Audi, Q5, q5, Used Audi



Audi Q5 2.0A TFSI Quattro

\$106,988

\$14,100 /yr

25-Sep-2014

1,984 cc

48,291 km

SUV

Available

Don't Miss, Show Room Condition, Honest Dealing, High Loan With Low Down Payment Drive Away, Low Mileage Done, No Hidden Cost, Call For Viewing.

Posted: 01-Dec-2018 Tags: 2014 Audi Q5, 2014 audi q5, Audi Q5, audi q5, Audi, Q5, q5, Used Audi

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Audi Q5, Audi Q5 Singapore, used Audi Q5 Singapore, used Audi Q5, used vehicles Singapore or even buy used Audi Q5 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

Download on the
App StoreGET IT ON
Google play
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

SHORTLISTED

HISTORY

Compare



AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#07-16
AIG Building
Singapore 079120
Co.Reg.No.201009404M

Policy/Reference No. 2100391231-04

01 Oct 2018

Mr. CHOY POW CHAI @CHOY SOOH CHAY
54 CHUAN GARDEN
SINGAPORE 558567

Dear Mr. CHOY POW CHAI @CHOY SOOH CHAY

Your Policy Has Been Renewed

We are pleased to inform you that your AUTOPLAN PRIVATE VEHICLE has been renewed and details of your policy are below:

Policy number : 2100391231-04
Effective date : 31 Oct 2018
Expiry date : 30 Oct 2019

It is important that you review the enclosed policy documents to verify that all the information in these documents is accurate. If you wish to update us on any changes, please contact us.

For More Information

If you require more information about your policy, please contact our customer service representatives Monday through Friday between 9am to 5pm at +65 6419 3000. Alternatively, you can send us an email at www.aig.com.sg.

Thank you for your support. We look forward to serving you in all your general insurance needs.

Yours sincerely

Bucha Manik
Head of Individual Personal Insurance

PS: You can now enjoy round-the-clock access to selected AIG products and services with our easy-to-use Apple or Android smartphone app. Purchase new policies, renew your policies, access claims support or receive emergency assistance for motor and travel, anytime, 24-hours a day. Your AIG Mobile App can be downloaded for free at iTunes or Google Play.

Product underwritten by AIG Asia Pacific Insurance Pte. Ltd. Copyright © 2016 AIG Asia Pacific Insurance Pte. Ltd.

Premium Automobiles

AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811
Attn: Motor Claims Dept
Your ref: SCV 6812 H

Norah Khai
6768 9828
6841 1183
Body Repair

PA/TP/1428/2018/JE
11-Jan-19
1

From
Telephone +65-
Telefax +65-
Our department
Your Claims Ref
Our Ref
Date
Total pages

RE : CLAIM-OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q5 2.0 TFSI Qu
Vehicle Chassis No : WAUZZZ8R7EA090296
Vehicle Regn No. : SDD 3322 H
Vehicle Mileage : 85621KM
Vehicle Owner : Mr. Choy Pow Chai
Certificate No : 2100391231-04
Liability : Direct Settlement by Vic Alpeh of LKK via email
Dated 14/12/2018 with LOU/LOR
Accident Date : 14 December, 2018
Location : M'sia Custom Towards Singapore Custom
Repair Cost : S\$ 8,489.92
WIP No. : 36194
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd

Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner/Insured Signature 

Time

Date



AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#07-16
AIG Building
Singapore 079120
Co.Reg.No.201009404M

Policy/Reference No. 2100391231-04

01 Oct 2018

Mr. CHOY POW CHAI @CHOY SOOH CHAY
54 CHUAN GARDEN
SINGAPORE 558567

Dear Mr. CHOY POW CHAI @CHOY SOOH CHAY

Your Policy Has Been Renewed

We are pleased to inform you that your AUTOPLAN PRIVATE VEHICLE has been renewed and details of your policy are below:

Policy number : 2100391231-04
Effective date : 31 Oct 2018
Expiry date : 30 Oct 2019

It is important that you review the enclosed policy documents to verify that all the information in these documents is accurate. If you wish to update us on any changes, please contact us.

For More Information

If you require more information about your policy, please contact our customer service representatives Monday through Friday between 9am to 5pm at +65 6419 3000. Alternatively, you can send us an email at www.aig.com.sg.

Thank you for your support. We look forward to serving you in all your general insurance needs.

Yours sincerely

Bucha Manik
Head of Individual Personal Insurance

PS: You can now enjoy round-the-clock access to selected AIG products and services with our easy-to-use Apple or Android smartphone app. Purchase new policies, renew your policies, access claims support or receive emergency assistance for motor and travel, anytime, 24-hours a day. Your AIG Mobile App can be downloaded for free at iTunes or Google Play.

Product underwritten by AIG Asia Pacific Insurance Pte. Ltd. Copyright © 2016 AIG Asia Pacific Insurance Pte. Ltd.



Service Request Details

Claim

S8M016QF

Reference

None 

Loss Date

14 December 2018

Request Date

17 December 2018

Due Date

24 December 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

17.12.2018 @ 10:30am
Phuc veh not in
18.12.2018

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SDD3322H

Make

TPVD

Service Address

...

Primary Contact/Insured

TAN LAM KOK
BLK 169 STIRLING ROAD, #09-1153, 140169, Singapore
91800220

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



Re:<MANDATE IA> - S8M016QF {ACCIDENT INVOLVING SCV 6812H (OI) & SDD 3322H (TP) ON 14/12/2018}

Type

🔍 Question

Message

Hi, the marked estimates and supplementary does not add up. Kindly advise: 1) any further document. 2) why is there no attempt on Agent discount since TPV is >3yrs. 3) The labour for respray already given \$2100 in the first marking, why is there more supplementary for the respray. Thanks

Reply

check to Adrian
on Question 2.
Ans: Agent is all base on p/p basis.
doesn't matter to car age.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 16/9/2019

Survey Details:

Date of loss	14-Dec-18
Date of appointment	17-Dec-18
Date of survey	18-Dec-18
Location of survey	PREMIUM AUTOMOBILES PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SDD3322H
Make and Model	AUDI Q5 2.0 TFSI QUATTRO (EU6)
Date of registration	31-Oct-14
Parf Rebate	
Market Value	\$ 105,000.00
Parf Rebate	\$ 83,415.00
Nett Loss	\$ 21,585.00

Repair details:

Initial Estimate	21,244.00
------------------	-----------

Proposed/Revised repair cost:

Parts	\$ 3,432.50
Check items (estimate)	\$ -
Labour	\$ 4,502.00
Total	\$ 7,934.50
Lump Sum(if applicable)	\$ -

Number of days for repair	4 days
---------------------------	--------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)		100%	
Proposed repair cost	\$	8,489.92	W/GST
Loss of use	\$	-	
Loss of rental	\$	400.00	4days x \$100
Loss of income	\$	-	
LTA search fees	\$	2.00	
Others		-	
Proposed Total		8891.92	



<MANDATE IA> - S8M016QF {ACCIDENT INVOLVING SCV 6812H (OI) & SDD 3322H (TP) ON 14/12/2018}

Type

🔔 Question

Message

LIABILITY: 100% BOLA S27 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$8,891.92(CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL / INSTRUCTION. THANKS - CECILIA

Reply

Cecilia Chong (LKK Auto)

From: Mei Kwan (LKKAuto)
Sent: Friday, 25 October 2019 4:12 PM
To: Cecilia Chong (LKK Auto)
Subject: FW: New message for service request 88208, vehicle number SDD3322H

25/10/19 1:45 PM *** MessageHi, Kindly check for 5-10% parts discount on LS COR basis. Thanks - KHONG Lynn

-----Original Message-----

From: lynn.khong@axa.com.sg <lynn.khong@axa.com.sg>
Sent: Friday, 25 October, 2019 1:46 PM
To: admin-d@lkkauto.com
Subject: New message for service request 88208, vehicle number SDD3322H

AXA Insurance has sent you a message for claim number S8M016QF.

Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

File pass Advam to
adjust cor amt as per
AXA instructⁿ. X.

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Thursday, 7 November 2019 2:55 PM
To: Claims
Subject: RE: LOD - ACCIDENT INVOLVING SDD 3322 H AND YOUR INSURED SCV6812H DATED ON 14/12/2018 *** LKK REF : CC4/ASM18022596/Aga3

Without Prejudice

Dear Nadia,

We are pleased to offer total amount of \$8,891.92 (all-in) as per your LOD.

DV already received.

Thus, we shall proceed to submit and close off the case from our end.

Thanks

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."


Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Claims [<mailto:claims@premiumauto.com.sg>]
Sent: Monday, 4 November 2019 10:09 AM
To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: LOD - ACCIDENT INVOLVING SDD 3322 H AND YOUR INSURED SCV6812H DATED ON 14/12/2018 *** LKK REF : CC4/ASM18022596/Aga3

Dear Cecilia,

Following up, has there been any updates from your principal?

Kindly advise.

Thank you.

Best Regards
Nadia Hani



Re:<MANDATE IA> - S8M016QF {ACCIDENT
INVOLVING SCV 6812H (OI) & SDD 3322H (TP) ON
14/12/2018}

Type

🔔 Question

Message

Hi CCL, proceed. Thanks

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SCV 6812H (Insd veh)	Model:	AUDI Q5
	SDD 3322H (TP veh)		
Date of Accident:	14/12/2018		

Global Sum Settlement	: ☐ Yes	: ☒ No	
Repair Estimate	: \$		24,220.52
Final Repair Cost	: \$		8,489.92
Loss of Use	: \$		days at \$0.00 per day
Rental (if any)	: \$		400.00 4 days
LTA / GIA Search Fee	: \$		2.00

Others:	: \$	
---------	------	--

	: \$	
Final Settlement Sum	: \$	8,891.92

Is Third Party Workshop GIA Registered?	[X] YES	[] NO	(Kindly indicate below)
---	-----------	--------	-------------------------

A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
	_____27_____
BOLA Liability: _____100_____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	

Remarks	
---------	---

Payment Instruction: Payee's Breakdown		
1)	PREMIUM AUTOMOBILES PTE LTD	: \$ 8,891.92

NUR SHAQILAH BTE ABDOL
WAHAB

19/11/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18022596/Aga3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: CYNTHIA LOH

Date : 19-11-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SCV 6812H	Veh. Inspected	SDD 3322H
Policy No.	GA312674/1	Coverage (\$)	0.00
Claim No.	S8M016QF	Excess (\$)	0.00
Assign From	CYNTHIA LOH	Assign Date	17/12/2018

2. Vehicle Particulars & Condition

Make & Model	AUDI Q5	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WAUZZZ8R7EA090296	Colour	BLACK
Odometer	84295	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/55 R19	MICHELIN	6 mm
L/H Front Tyre	235/55 R19	MICHELIN	6 mm
R/H Rear Tyre	235/55 R19	MICHELIN	6 mm
L/H Rear Tyre	235/55 R19	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	14/12/2018	Inspection Date	18/12/2018
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDD 3322H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (SN) (CONSISTENT)	DEFORMED	1,430.00	1,430.00
1	REAR BUMPER FIXING PARTS (SN) (CONSISTENT)	NOT NECESSARY	143.00	-
1	REAR BUMPER TAIL LIGHT - RH (SN) (CONSISTENT)	CRACKED	265.00	262.50
2	REAR BUMPER GUIDE SECTION - LH/RH (SN) (CONSISTENT)	NOT NECESSARY	92.00	-
2	REAR BUMPER GROMMET (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	REAR BUMPER SPOILER (SN) (CONSISTENT)	DEFORMED	749.00	749.00
1	REAR REINFORCEMENT (SN) (CONSISTENT)	BENT	571.00	571.00
2	REAR REINFORCEMENT BRACKET - LH/RH (SN) (CONSISTENT)	NOT NECESSARY	368.00	-
1	REAR BUMPER SENSOR (SN) (CONSISTENT)	NOT NECESSARY	211.00	-
1	REAR BUMPER SENSOR (SN) (CONSISTENT)	NOT NECESSARY	196.00	-
1	REAR LID (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	3,844.00	-
1	REAR LID ATTACHMENT PARTS (SN) (CONSISTENT)	NOT NECESSARY	106.00	-
2	REAR LID HINGE (SN) (CONSISTENT)	NOT NECESSARY	400.00	-
2	REAR LID STRUT (SN) (CONSISTENT)	NOT NECESSARY	209.00	-
1	GASKET FOR FLAP (SN) (CONSISTENT)	NOT NECESSARY	176.00	-
1	SEAL - UPPER (SN) (CONSISTENT)	NOT NECESSARY	63.00	-
1	STRIKER PLATE WITH MOTOR FOR POWER LATCH (SN) (CONSISTENT)	NOT NECESSARY	802.00	-
1	REAR LID LOCK (SN) (CONSISTENT)	NOT NECESSARY	157.00	-
1	PUSH BUTTON FOR ELECTRIC LID LOCK ACTUATOR (SN) (CONSISTENT)	NOT NECESSARY	159.00	-
1	SEAL FOR PUSH BUTTON (SN) (CONSISTENT)	NOT NECESSARY	14.00	-
2	REAR LID STOP BUFFER (SN) (CONSISTENT)	NOT NECESSARY	48.00	-
1	GUARD PLATE - INNER (SN) (CONSISTENT)	NOT NECESSARY	54.00	-
2	LOCKING CLIP (SN) (CONSISTENT)	NOT NECESSARY	41.00	-
1	SET FIXING PARTS FOR SPOILER (SN) (CONSISTENT)	NOT NECESSARY	147.00	-
1	PACKING ADHESIVE (SN) (CONSISTENT)	NECESSARY	15.00	14.50
1	Q5' EMBLEM (SN) (CONSISTENT)	NECESSARY	83.00	82.70
1	2.0T' EMBLEM (SN) (CONSISTENT)	NECESSARY	83.00	82.70

Report Ref No. CC4/ASM18022596/Aga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	QUATRRRO' EMBLEM (SN) (CONSISTENT)	NECESSARY	83.00	82.70
1	AUDI LOGO (SN) (CONSISTENT)	NECESSARY	108.00	107.50
1	REAR WINDSCREEN (SN) (CONSISTENT)	NOT NECESSARY	1,020.00	-
2	PRIMER (SN) (CONSISTENT)	NOT NECESSARY	38.00	-
1	REAR SILENCER - RH (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	883.00	-
1	DUAL CLIP (SN) (CONSISTENT)	NOT NECESSARY	47.00	-
2	BRACKET - LH / RH REAR (SN) (CONSISTENT)	DAMAGED 1PC ONLY	100.00	49.90
1	CENTRE SILENCER (SN) (CONSISTENT)	NOT NECESSARY	875.00	-
1	DUAL CLIP (SN) (CONSISTENT)	NOT NECESSARY	52.00	-
2	DUAL CLIP (SN) (CONSISTENT)	NOT NECESSARY	93.00	-
2	BRACKET - LH / RH FRONT (SN) (CONSISTENT)	NOT NECESSARY	78.00	-
1	TRIM FOR REAR CROSS PANEL - PLASTIC / STAINLESS STEEL (SN) (CONSISTENT)	NOT NECESSARY	301.00	-
1	SUNDRIES (SN) (CONSISTENT)	NOT NECESSARY	800.00	-
			14,924.00	3,432.50
	LABOUR			
	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION.		280.00	280.00
	TO REMOVE AND REINSTALL REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER SYSTEM.	NOT NECESSARY	480.00	-
	TO RENEW REAR WINDSCREEN.	NOT NECESSARY	480.00	-
	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. INSPECT END PANELLING FOR FURTHER DAMAGES. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. INCLUSIVE OF THE REPAIR OF REAR LID AND REAR SILENCER - RH.		2,100.00	700.00
	TO RESPRAY REAR BUMPER, REAR LOWER SPOILER, REAR LID AND REAR HINGES.		2,500.00	2,100.00
	TO REMOVE AND RENEW RHS REAR EXHAUST SILENCER AND CENTRE EXHAUST SILENCER. TO ALIGN TO POSITION.		480.00	280.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPAIR AND RESPRAY REAR END PANEL. (ADDITIONAL)		1,200.00	950.00
			7,712.00	4,502.00
	GRAND TOTAL		22,636.00	7,934.50
RECOMMENDED COST OF REPAIRS				7,934.50

Report Ref No. CC4/ASM18022596/Aga3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.