



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18022605/Jga3s2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 27-04-2020



ATTN: PETER WANG

Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 624U	Veh. Inspected	GBF 3213C
Policy No.	GA308937	Coverage (\$)	0.00
Claim No.	S8M016J9	Excess (\$)	0.00
Assign From	PETER WANG	Assign Date	17/12/2018

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KDY2318022737	Colour	WHITE
Odometer	36812	Steering	JAMMED
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/75 R15	BRIDGESTONE	7 mm
L/H Front Tyre	175/75 R15	BRIDGESTONE	7 mm
R/H Rear Tyre	175/75 R15	BRIDGESTONE	7 mm
L/H Rear Tyre	175/75 R15	BRIDGESTONE	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.
---

### 5. General Information

Accident Date	12/12/2018	Inspection Date	17/12/2018
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	14 Working Days
-------------------------------------	-----------------