



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 31/10/2019

### Survey Details:

Date of loss	16-Nov-18
Date of appointment	18-Dec-18
Date of survey	18-Dec-18
Location of survey	YEW TEE AUTOMOBILE TECH PL

### Vehicle Details:

Claim Type:	Third party
Vehicle number	FD 7P
Make and Model	HARLEY DAVIDSON FXSTSB
Date of registration	19/1/1995
Excess	
Market Value	\$15,000
Parf Rebate	\$1,306
Nett Loss	\$13,694

### Repair details:

Initial Estimate	\$ 18,279.30
------------------	--------------

### Proposed/Revised repair cost:

Parts	\$ 10,189.00
Check items (estimate)	NIL
Labour	\$ 950.00
<b>Total</b>	<b>\$ 11,139.00</b>
<b>Lump Sum(if applicable)</b>	<b>\$ 8,500.00</b>

Number of days for repair	5
---------------------------	---



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

*OID made right turn and collided with third party who was riding straight.*

**Mandate:**

Liability(TP)		100%
Proposed repair cost (w/GST)	\$	9,095.00
Loss of use	\$	210.00 (7days x \$30)
Loss of rental		NIL
Loss of income		NIL
LTA search fees	\$	7.45
Others		NIL
<b>Proposed Total</b>	<b>\$</b>	<b>9,312.45</b>