

INS. CASE OWNER:

CC 4, ALG 180

22776, T1pa34

LKK:
IDAC:

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:
WSP:
Tel:
Liability:
RMKS:

Southern motor



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

2/1/19
CH1

128988P - 7 M/M/18 1801604/34 ; 105 28/11/18
1801604/34 - 105 28/11/18

2/4/19

Pending amended LOR from TP
offer \$3564.00 to TP. Pending confirmation.
TP return call saying he already receive
the DV on march that is email to him
by HT. Original DV and other documents already
put out by registered mail on 29/3/19.
(Pending DV return)

9/4/19
10/4/19

DV in - Pending final Repair Bill
MIS INV IN File pass to HT to check.
File pass to Admin to close.

STAGE	DATE / PIC	
Non-Reporting ltr (1st):		
Non-Reporting ltr (2nd):		
Non-Reporting ltr (Final):		
Notification ltr (if non-pickup):		
Call OI:	2/1/19	
After call ltr to OI:		
Documentation Check List:	Handler	Typist
Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
After call ltr to OI:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Authorisation To Act:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Release Voucher:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Final Repair Bill:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Car Rental Invoice:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Towing Invoice	<input checked="" type="checkbox"/>	<input type="checkbox"/>
LTA / GIA :	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Medical Bill:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PIR:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Mandate/Reject Instruction:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
LOD	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Payment Breakdown Form:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Post-Repair Photos:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Others:	<input checked="" type="checkbox"/>	<input type="checkbox"/>

PRELIMINARY ADVICE		Date/Time:	Sent By:	Confirm with:	Confirm by:
Repair Cost:	\$5	(days)	Reduction:	%	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT		Date/Time: 2/4/19 4pm	Confirm with: LHM	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>	
Final Liability:	% 100	(Agreed / Assessed)	BOLA S/N No. 23	If NO or B 28, Ass. Lia:	
Repair Cost:	\$5 2624.00				
Loss of Rental (LOR):	\$5 -	(days)			
Loss of Use (LOU):	\$5 140	(3.35 x 4 days)			
Loss of Income (LOI):	\$5 -	(3 x days)			
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]			
GIA/LTA Search	\$5 -				
Medical:	\$5 -				
Disbursement:	\$5 -	(e.g. Tow/ Independent)			
Legal Cost	\$5 -				
Total:	\$5 2564.00	Global Sum \$5:			
FINAL PAYMENT		Date/Time:	Confirm with:	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>	
Payee 1:	\$5 3564.00	Name 1:	Southern motor		
Payee 2: (Strike if N.A.)	\$5	Name 2:			
Payee 3: (Strike if N.A.)	\$5	Name 3:			

1) Claim status: Normal/Reject/Private Settle
2) Report Format:
3) Survey fee: \$320.00

CH 10/4/19

☐ Weekend (\$)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	S613A
Vehicle Details	
Vehicle No.:	FZ8988P
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Jan 2019
Vehicle Make:	B.M.W.
Vehicle Model:	C650 GT
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	652EA70039652
Chassis No.:	WB10C0501GZ567000
Maximum Power Output:	-
Open Market Value:	\$12,609.00
Original Registration Date:	14 Jul 2016
First Registration Date:	14 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$1,892.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jul 2026
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,012.00
COE Rebate Amount:	\$4,491.00
Total Rebate Amount:	\$4,491.00

The information contained herein is correct as at 23 Jan 2019

MV: \$10K

OK



南方摩哆
SOUTHERN MOTOR

Block 1006, Bukit Merah Lane 2, #01-10
Singapore 159762 Tel: 62730369 Fax: 62746614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters & Insurance Agent

Date: 17th December 2018
Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Raffles Way #07-16
AIG Building
Singapore 078120

Dear Sirs

Re: Cost of repair to BMW C650G7 - F20788P

1 pc of Mirror LH	RM 483.00	✓
" Mirror bracket LH	140.00	✓
" Front fairing LH	260.00	✓
" Centre fairing LH	420.00	✓
" Lower cowling	640.00	✓
" Side box	340.00	✓
" Civi Windscreen	240.00	✓
" BMW Name plate	65.00	✓
" Footrest plate	340.00	X 111
Fit. LH indicator - 9/88.19 mis	4,040.00	4121.24
Less 10%	404.00	
	3,636.00	3709.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary claims must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Yours faithfully,
SOUTHERN MOTOR

Nett

250:

Labour

350.00
4,026.10

3959.12

Tanpin 97495749 4/3/3200
-WP

20/12/18 @ 2pm

Receiving after repair.
surellha auto.wm
4 days

Tel 64193000
Fax 64153727

Performance Motors Limited



A member of the Sime Darby Group
Co Reg No: 197401159M GST Reg No M2-0020061-X

101, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales)
63190111 (AfterSales)
Fax: 64747770

100, Raffles Avenue Road
East Coast Centre
Singapore 438180
Tel: 63190088 (AfterSales)
Fax: 63449772

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190028 (AfterSales)
63190033 / 332 (Motorrad)
Fax: 64786401 (AfterSales)
64786424 (Motorrad)

PARTS TAX INVOICE

Account No. : 20000

Customer Name : Cash Sales - Parts

Invoice No. : 489958 / PAB

Invoice Date : 17/01/2019 10:48:36

Page : 1 of 1

Partsman : S97267

Depot : Q5

Reference : SOUTHERN MOTOR

Handwritten initials: S/P

S/N	Part Number	Description	Issued Qty	BkOrd Qty	Sell. Price	Net Price
RN:813388 \$718.24 AH HUAT HP:62730369						
1	51168396595	LH RR VIEW MIRROR	1	0	483.06	483.06
2	63128556876	FRT RH LED TURN INDICATOR	1	0	188.19	188.19

Parts Total	:	S\$	671.25
Handling / T.T. Charges	:	S\$	0.00
Invoice Total Amount Exclude GST	:	S\$	671.25
GST @ 7.00%	:	S\$	46.99
Invoice Total Amount Include GST	:	S\$	718.24
Amount Payable Include GST	:	S\$	718.24

This is a computer generated invoice. No signature is required

- Note :
- 1) ALL AMOUNTS ARE IN SINGAPORE DOLLARS
 - 2) GOODS SOLD ARE NOT RETURNABLE
 - 3) FOR CREDIT PURCHASES
 - INTEREST CHARGE 1% PER MONTH OR PART THEREOF WILL BE DEBITED ON
 - ANY OUTSTANDING AMOUNT EXCEEDING SPECIFIED CREDIT PERIOD



南方摩哆
SOUTHERN MOTOR

Block 1006, Bukit Merah Lane 2, #01-10
Singapore 159762 Tel: 62730369 Fax: 62746614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters & Insurance Agent

Date: 17th December 2018
Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Raffles Way #07-16
AIG Building
Singapore 078120

Dear Sirs

Re: Cost of repair to BMW C650GT - FZ 8988P

1 pc of Mirror LH	S\$	210.00 mis
" Mirror bracket LH		140.00 bro
" Front fairing LH		260.00 mt
" Centre fairing LH		480.00 mt
" Rear cowling		640.00 mt
" Side box		345.00 mt
" Givi Windscreen		280.00 mt
" BMW Name plate		65.00 mt
" Footrest plate		345.00 X
		<hr/> 4045.00

Less 10%

404.50

3676.10

Nett

250

Labour

310.00

340.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey (before/after spray painting)
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Yours faithfully,
SOUTHERN MOTOR

Tanpin 97495744
-WP-

20/12/18 @ 2pm

Repairing after repair
surellha auto.wm
4 days

Tel 64193000

Fax 64153727



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG18022776/T1pa3

27 DEC 2018

JOAQUIM FLORIST & GIFTS PTE LTD
9 KAKI BUKIT ROAD 2
#03-06 GORDON WAREHOUSE BUILDING
SINGAPORE 417842

Dear Sir/Madam,

**ACCIDENT INVOLVING GBF 5131S & FZ 8988P ALONG/AT BLK 82
STRATHMORE AVE LOADING/UNLOADING BAY ON 28/11/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from FZ 8988P against your motor insurance policy.

Based on the accident report and accident scenario, liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG
Case Handler
DID: 6742 3197
FAX: 6741 4108
Email: chewht@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, TAN KENG SIONG (CHEN QINGXIANG) ("the third party claimant")
of Blk 12 Strathmore Ave #04-153 Singapore 141012 (address),
owner of F2 D988P (vehicle no.) hereby authorize
Southern Motor
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. F2 D988P that was
damaged pursuant to the accident which occurred on 22-11-2018 ²⁵⁻⁰¹⁻²⁰ (date) along
Strathmore Ave public carpark No 093 Lot 23 (location)
involving vehicle no/s G 87 5131 S ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 22nd day of March (month) 20 19 (year)


Signed by "the third party claimant"



SOUTHERN MOTOR
Blk 1006, Bukit Merah Lane 2
#01-10 Singapore 159752
Tel: 62730369 Fax: 62746614

Signed by "the workshop"

WITHOUT PREJUDICE to:

(a) Insurer's Subrogated Claim and/or

(b) Any Personal Injury Claims

[Note: This Notice supersedes any
inconsistencies found in this
Discharge Voucher]

RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

We/I, Southern Motor ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK AUTO CONSULTANT PTE LTD ("name of surveyor") with respect to the amount claimed for SS 3424-00 (repair costs), SS 140-00 (loss of use/rental) SS - (search fees) for vehicle no. 720988P that was damaged pursuant to the accident which occurred on 28-11-2018 (date) along Strathmore Ave public carpark NO 292 Lot 23 (location) involving vehicle no/s GRF 51318

This is pursuant to the inspection conducted on 30-12-2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TAN KENG SENG (CHEN QINGXIN) ("third party claimant") of vehicle no. 720988P to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to 720988P (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.



Dated this 11 day of April (month) 20 19 (year)

Signed by AIG appointed surveyor



SOUTHERN MOTOR
Blk 1006, Bukit Merah Lane 2
#01-10 Singapore 159762

Chopped & Signed by the workshop

WITHOUT PREJUDICE to:
(a) Insurer's Subrogated Claim and/or
(b) Any Personal Injury Claims
[Note: This Notice supersedes any
inconsistencies found in this
Discharge Voucher]

Hsiao Tony



SOUTHERN MOTOR

Blk 1006, Bukit Merah Lane 2 #01-10 Singapore 159762

Tel: 62730369 Fax: 62746614 CO/GST Reg No: 23414700L

TAX INVOICE NO : INV28201
Invoice Date : 28th March 2019
Payment Terms : CASH
Vehicle No. : FZ8988P - BMW C650GT
Mechanic : CASH

AIG ASIA PACIFIC INSURANCE PTE LTD - AA002
78 SHENTON WAY #07-16 AIG BUILDING Singapore 079120

Tel: 64193000 Fax: 64153727

S/No	DESCRIPTION	QTY	U/PRICE	Amount
1	7% GST ON COST OF LUMP SUM REPAIR	1	\$224.00	\$224.00
2	COST OF LUMP SUM REPAIR	1	\$3,200.00	\$3,200.00
3	LOSS OF USE FOR 4 DAYS AT \$35.00 PER DAY	1	\$140.00	\$140.00

TOTAL : \$3,564.00

BALANCE : \$3,564.00

Goods Sold Are Not Returnable. Deposit Paid Are Not Refundable. All cheques should be made payable to "SOUTHERN MOTOR".
Interest Rate of ____% per month will be imposed on overdue Accounts. Thank you.

Received by

Issued by



...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Nov 2018 Edit Reg		19 Dec 2018 00:00 Edit Adj Rpt	\$43,200.00 Edit Estimates	\$43,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	JOAQUIM FLORIST & GIFTS PTE LTD, Co. Reg. No.: 199303010R								
Main Claimant:	TAN KENG SIONG (CHEN QINGXIANG), ID: S7935613A								
Vehicle Reg. No.:	FZ8988P	Date of Loss:	28/11/2018 08:00 - :59 [28 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9014808086SG	Policy/Cover Note No.:	1800121495 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBF5131S	Policy No. (Claimant):	5102093279						
		Excess:							
Repairer:	Southern Motor (HQ) BLK 1006 BUKIT MERAH LANE 2, #01-10, 159762 Bukit Merah - Tel: 62730369								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 31/12/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FZ8988P (9014808086SG)
[GBF5131S]
TP
TAN KENG SIONG (CHEN QINGXIANG)
Nov 28 2018 8:00AM
[JOAQUIM FLORIST & GIFTS PTE LTD]
Southern Motor

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser			View		
Letters/Correspondences															1 per page			<input checked="" type="checkbox"/>					
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail			Print						
1	(Draft)		Third Party Express Settlement – Payment Breakdown														Edit						
Photos/Images															3 per page			<input checked="" type="checkbox"/>					
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail			Print						
1	21/12/18 17:00		General View														Load JPG						
2	21/12/18 17:00		General View														Load JPG						
3	21/12/18 17:00		General View														Load JPG						
4	21/12/18 17:00		General View														Load JPG						
5	21/12/18 17:00		General View														Load JPG						
6	21/12/18 17:00		General View														Load JPG						
7	21/12/18 17:00		General View														Load JPG						
8	21/12/18 17:00		General View														Load JPG						
9	21/12/18 17:00		General View														Load JPG						
10	21/12/18 17:00		General View														Load JPG						
11	21/12/18 17:00		General View														Load JPG						
12	21/12/18 17:00		General View														Load JPG						
13	21/12/18 17:00		General View														Load JPG						
14	21/12/18 17:00		General View														Load JPG						
15	21/12/18 17:00		General View														Load JPG						
16	21/12/18 17:00		General View														Load JPG						
17	21/12/18 17:00		General View														Load JPG						
18	21/12/18 17:00		General View														Load JPG						
19	21/12/18 17:00		General View														Load JPG						
20	21/12/18 17:00		General View														Load JPG						
21	21/12/18 17:00		General View														Load JPG						
22	21/12/18 17:00		General View														Load JPG						
23	21/12/18 17:00		General View														Load JPG						
24	21/12/18 17:00		General View														Load JPG						
Documentation															1 per page			<input checked="" type="checkbox"/>					
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail			Print						
1	19/12/18 16:57		ACKNOWLEDGEMENT EMAIL TO AIG DD 19.12.2018														Load PDF						
2	19/12/18 16:57		EMAIL FROM AIG DD 19.12.2018														Load PDF						
3	19/12/18 16:57		NOTIFICATION FROM WORKSHOP														Load PDF						
4	19/12/18 16:57		TP ESTIMATE + TP GIA REPORT														Load PDF						
5	23/12/18 17:12		TP ESTIMATE - MARKED														Load PDF						
6	24/04/19 16:12		WORKSHOP INVOICE														Load PDF						
7	24/04/19 16:12		AUTHORISATION TO ACT FORM														Load PDF						
8	24/04/19 16:12		Release Voucher														Load PDF						
9	24/04/19 16:12		LETTER TO OI														Load PDF						

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	20/12/18 08:24	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBF5131S (Insd veh)	Model:	BMW C650GT 647CC
	FZ8988P (TP veh)		
Date of Accident:	28/11/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	4,714.01
Final Repair Cost	:	\$	3,424.00
Loss of Use	:	\$	140.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,564.00

4.00 days at \$35.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Southern Motor	:	\$ 3,564.00
2)		:	\$

JOANNE LEE KHANG MIN

24 Apr
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18022776/T1PA3Q2

Date: 24/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800121495
Claimant Vehicle FZ8988P **Insured Vehicle No :** GBF5131S
No :
 Date of Loss: 28/11/2018 Nature of Claim: TP Claim No: 9014808086SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FZ8988P**
 Make & Model: BMW C650GT, 647cc Engine No: 652EA70039652
 Reg. Date: 14/07/2016 (Man. Year: 2016) Chassis No: WB10C0501GZ567000
 Colour: Black Odometer: 0 km
 Engine Capacity: 647 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70 R15 Rear Tyre Size: 160/60 R15
 Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,055.62	3,709.12	346.50	8.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	350.00	250.00	100.00	28.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,405.62	3,959.12	446.50	10.13
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	4,405.62	3,200.00	1,205.62	27.37
+ GST 7.00/7.00% (S\$)	308.39	224.00	84.39	27.36
Nett Amount (S\$)	4,714.01	3,424.00	1,290.01	27.37
+ Loss of Use (4.0 x S\$35.00/day) (S\$)		140.00		
Nett Liability (S\$)		3,564.00		

INSPECTION

Date of Assignment: 19/12/2018
 Date Inspected: 20/12/2018 Inspected At: Southern Motor (HQ)
 BLK 1006 BUKIT MERAH LANE 2, #01-10
 Singapore 159762
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MIRROR LH	Missing	483.06 FL	*483.06 FL
2	1		*MIRROR BRACKET LH	Broken	140.00 FL	*140.00 FL
3	1		*FRONT FAIRING LH	Cut	860.00 FL	*860.00 FL
4	1		*CENTRE FAIRING LH	Cut	480.00 FL	*480.00 FL
5	1		*LOWER COWLING	Cut	640.00 FL	*640.00 FL
6	1		*SIDE BOX	Cut	385.00 FL	*385.00 FL
7	1		*GIVI WINDSCREEN	Cut	880.00 FL	*880.00 FL
8	1		*BMW NAME PLATE	Cut	65.00 FL	*65.00 FL
9	1		*FOOTREST PLATE	Not Necessary	385.00 FL	*- FL
10	1		*FRT LH LED INDICATOR	Missing	188.19 FL	*188.19 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,506.25	4,121.25
- List Item Discount on L Items 10.00/10.00% (S\$)	450.63	412.13
Total Parts (S\$)	4,055.62	3,709.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	350.00	250.00
Gross Labour Cost (\$\$)			350.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >