

ASS. REC. BY:

REF:

CS/ICS18022783/Utho2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Janice Goh

of

ICS

Date/Time:

19.12.2018 435pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKD 8670L

Insured:

at Workshop m/s

Progressive

Tel:

of

Blk 302A Ubi Rd 1 # 01-15

Policy No:

MPC18P00028600

Claim No:

DMPC1800469H/JG

Sum Insured:

Excess:

\$ 500.00

Make of Vch:

D.O.A.

16/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

20.12.2018

H.O.D. Endorsement:

Date/Time: 19.12.2018 5pm

Person Contacted:

Soo

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKD 8670L - CS/ICS18022783/Kid
20/12-	Report via merimen. preli advise.
24/12 @ 12:37pm	authorise repair by Janice goh
24/12- 1:37pm	email to soo leang kiat authorise repair excess 500-

REF: ICS

CS/IC818022783/Uth

ASSIGNMENT

From:

Date: 20/12/2018

Estimated Cost:

① TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKD 8670L

at Workshop no:

Progressive

of

Blk 3022A, ubi Rd 1 # 01-45

Insured:

Policy No:

Claims No:

Sum Insured:

Excess: \$500.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection

Bal. or Market Value:

33k.

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

7 days
1.31 %

Res: Yes or No

Lum Sum:

3 Val: Yes or No

CA / REV / REP. / 24 HRS

6168F

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKD 8670L

To Reg:

1/12

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Hyundai Elantra

E.C. 1591

Colour:

Silver

A/C

Insured / Std / NI / NA

Sp. Reading:

T/Radio: Insured / Std / NI / NA

Eng/No:

ChNo:

KMHDH 41CM C440830

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R/Bal:

R/Bal:

L/Bal:

L/Bal:

D.O.A:

D.O.A:

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

not 943

m. light case 27A 23848 3yrs. lnh day

5/3/19 confirmed fine of \$5813.45 with Ray
(Red: 4125-35! 4106)

RECEIVED 06 MAR 2019

Date/Time, File Pass to?

5/3 Typist



Prel. Report



Final Report

Date/Time, File Return to?

23

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS: \$

) Photos

) Others

) :

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Weekend (\$

Report Format:

Lump Sum / B.I. (\$

00
5813:45

250

10

260

...CLAIM SUBFOLDER...(New Assignment)

Midnight Accident

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Dec 2018 16:16 Sendback Est	19 Dec 2018 16:27 S\$9,235.30	19 Dec 2018 16:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	ONG YONG WAH, ID: S7326168F, Tel: +6582333645, Email: ongorg@gmail.com								
Vehicle Reg. No.:	SKD8670L	Date of Loss:	16/12/2018 03:00 - :59 [83 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / DMPC1800469H/JG	Policy/Cover Note No.:	MPC18A00028600 (Comprehensive)						
		Excess:	S\$500.00						
Repairer:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46, 408716 Ubi - Tel: 67415336								
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Janice Goh - 6303 0182]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/12/2018]								
Driver/Custodian:	ONG YONG WAH (45 / Male), NRIC: S7326168F, Tel: +6582333645								
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
						Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 24 December 2018 1:37 PM
To: Soo Leong Keat
Cc: 'claims@procarcare.com.sg'; SUR
Subject: SKD 8670L / OD / ECICS

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKD 8670L (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

6168F

Vehicle Details

Vehicle No.:

SKD8670L

Vehicle to be Exported:

No

Intended Deregistration Date:

17 Dec 2018

Vehicle Make:

HYUNDAI

Vehicle Model:

ELANTRA 1.6 AT ABS D/AB 2WD 4DR

Primary Colour:

Silver

Manufacturing Year:

2011

Engine No.:

G4FGBU448542

Chassis No.:

KMMDH41CMCU410830

Maximum Power Output:

95.6 kW (128 bhp)

Open Market Value:

\$14,579.00

Original Registration Date:

14 Jan 2012

First Registration Date:

14 Jan 2012

Transfer Count:

0

Actual ARF Paid:

\$14,579.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

13 Jan 2022

PARF Rebate Amount:

\$9,476.00

Intended COE Rebate Details

COE Expiry Date:

13 Jan 2022

COE Category:

A - Car (1600cc & below)

COE Period(Years):

10

QP Paid:

\$46,889.00

COE Rebate Amount:

\$14,407.00

Total Rebate Amount:

\$23,883.00

The information contained herein is correct as at 17 Dec 2018

OK

N.V. Abt #36k.

View Received Message

This mail is associated with :

SKD8670L (DMPC1800469H/JG)

OD

Dec 16 2018 3:00AM

[ONG YONG WAH]

Progressive Car Care Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From ECICS Limited (HQ) (ECICS), sent on 24/12/2018 12:37 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$6322.10) - SKD8670L - Claim Handler: Janice Goh

Approved:6322.10.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Janice Goh

Date: 20 Dec 2018

Preliminary Advice

Vehicle No	: SKD8670L	Accident Date	: 16/12/2018
Make	: HYUNDAI ELANTRA	Policy No.	: MPC18A00028600
Assignment Date	: 19/12/2018	Excess	: S\$500.00
Date of Inspection	: 20/12/2018	Est. Duration of Repair	: 7.00
Inspection At	: PROGRESSIVE CAR CARE PTE LTD (HQ) BLK 3022A UBI ROAD 1, #01-45/46 SINGAPORE 408716		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,235.30
Revised Amount	:S\$	5,195.70
Check Items (Estimated)	:S\$	1,126.40
Total	:S\$	6,322.10

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	33,000.00
COE / PARF Rebate	:S\$	23,883.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,117.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	17/12/2018 11:25
Date Of Accident	16/12/2018 03:40
Exact Location Of Accident	ALONG TAMPINES AVENUE 10
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKD8670L
Insured/Policyholder	
Name Of Registered Owner	ONG YONG WAH
NRIC No	S7326168F
Email Address	ONGORG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-82333645
Alternative Phone No	OTHERS-82333645
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	ELANTRA-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC18A00028600
Cover Note Number	
Driver	
Name of Driver	ONG YONG WAH
NRIC No	S7326168F
Date Of Birth	22/07/1973
Occupation	INDOOR
Date Of Driving Pass	19/03/1996
Driving Experience	22 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82333645
Fax Number	
Contact Number	OTHERS-82333645
Email Address	ONGORG@GMAIL.COM

Address	BLK 245 COMPASSVALE ROAD #03-660
Postcode	540245
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORDED BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA2967X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the G.I.A Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the claim as well as on the external cover of envelopes/my postages) and/or
 - (v) complying with applicable laws (including, as relating, handling and/or dealing with my rights/obligations of the "Insurers").
- (b) all insurers and/or insured vehicle(s) having a right to be involved and the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) to mark of the above purposes;
- (c) the Personal Information may/are collected by any of the Insurers and/or GIA and may/are disclosed to any of the Insurers (including my lawyers/law firms), which may be done outside of Singapore, the land or seas of the above purposes;
- (d) the Personal Information will also be collected and used to compile claims history for the personal fraud prevention, investigation and management, in present and all future claims;
- (e) the information collected under (a) above may be shared/disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, settling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
SRC/RN No.:

17/12/18.

Sketch Plan #2

SKETCH PLAN

Vehicle
A - 5KD8670
B - 5HA2967X

Legend

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 16 Dec 2018 @ 0230hrs, I was traveling along Tampines Ave 10 to reach TPE to head home after a hard day work. My mind went off for few seconds and when ^{Vehicle} appeared I already very near the stationary ^{Vehicle} in front of me (as stated in the Figure above). I had no reaction time to stop so resulting in this accident. The damage incurred are the impact that caused damages to my ~~Report~~ vehicle front. (Photos sent to workshop)

DECLARATION

I/We declare the foregoing particulars are true in every respect.
Please be advised that your insurer may have a fourteen (14) days time limit whereby the claim against your policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

17/12/18.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Singapore NRIC

Owner ID:

6168F

Vehicle Details

Vehicle No.:

SKD8670L

Vehicle to be Exported:

No

Intended Deregistration Date:

17 Dec 2018

Vehicle Make:

HYUNDAI

Vehicle Model:

ELANTRA 1.6 AT ABS D/AB 2WD 4DR

Primary Colour:

Silver

Manufacturing Year:

2011

Engine No.:

G4FGBU448542

Chassis No.:

KMHDH41CMCU410830

Maximum Power Output:

95.6 kW (128 bhp)

Open Market Value:

\$14,579.00

Original Registration Date:

14 Jan 2012

First Registration Date:

14 Jan 2012

Transfer Count:

0

Actual ARF Paid:

\$14,579.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

13 Jan 2022

PARF Rebate Amount:

\$9,476.00

Intended COE Rebate Details

COE Expiry Date:

13 Jan 2022

COE Category:

A - Car (1600cc & below)

COE Period(Years):

10

QP Paid:

\$46,889.00

COE Rebate Amount:

\$14,407.00

Total Rebate Amount:**\$23,883.00**

The information contained herein is correct as at 17 Dec 2018

OK

N.Y. Abt #36K.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6168F
Vehicle Details	
Vehicle No.:	SKD8670L
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Dec 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	G4FGBU448542
Chassis No.:	KMHDH41CMCU410830
Maximum Power Output:	95.6 kW (128 bhp)
Open Market Value:	\$14,579.00
Original Registration Date:	14 Jan 2012
First Registration Date:	14 Jan 2012
Transfer Count:	0
Actual ARF Paid:	\$14,579.00 7289
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jan 2022
PARF Rebate Amount:	\$9,476.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jan 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$46,889.00
COE Rebate Amount:	\$14,369.00
Total Rebate Amount:	\$23,845.00

The information contained herein is correct as at 20 Dec 2018

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

SELL YOUR CAR YOURSELF

Get listed until it's sold + we will handle all the paperwork!



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

18 Mths Old BMW X3 SDrive20i, 1 Owner, 13000Kmi



Fully PML Maintained, PML 3 Years/200,000km Warranty, 5 Years Free Servicing!
Auto Zoom Enterprise StarAd

- Free VICOM evaluation
- Free grooming and 6 month
- In-house workshop ensures
- Member of SVTA and hire p
- 100% deposit refund for un

YONG LEE SEN

[Browse by Category](#)
[Sort by Date Posted](#)

14 vehicles

[Advanced Search](#)

Make Model Price Depreciation Reg Date Eng Cap Mileage V

Search Selection

Hyundai Elantra

Any

Any

2012

Any

Any



Hyundai Elantra 1.6A Elite

\$34,800

\$8,980 /yr

12-Jan-2012

1,591 cc

59,000 km

1 Owner With Original Regular Maintained Condition, Decent Fuel Consumption, Spacious And Stylish With Full Spec Family Ideal Sedan, Comfort Handling, Price Negotiable, Trade In Welcome.

Laxis

Posted: 19-Dec-2018

Tags: 2012 Hyundai Elantra, 2012 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS

\$33,800

\$8,700 /yr

14-Mar-2012

1,591 cc

92,000 km

Well Maintained By 1 Owner Only! Spacious And Fuel Efficient With Low Monthly Repayment! Lowest Price In The Market Yet Still Negot Viewing! Trade In Available! Flexible Bank/In-House Loan A...

Benefit Auto Enterprise Pte Ltd

Posted: 19-Dec-2018

Tags: 2012 Hyundai Elantra, 2012 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A Elite

\$38,800

\$9,070 /yr

14-Jun-2012

1,591 cc

66,000 km

Elite Model, Careful Lady Owner, Low Mileage, Good Condition, Spacious Interior And Boot, Flexible Loan Available, Trade In Welcome.

Posted: 18-Dec-2018

Tags: 2012 Hyundai Elantra, 2012 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A Elite

\$43,088

\$10,310 /yr

13-Jun-2012

1,591 cc

97,000 km

Road Tax Just Renew For 6 Months On 12th Dec 2018! Elite Model. 1 Owner, Low Mileage Done, Full Agent Maintained! Excellent Condi 100% Accident Free! Trade-In Available At High Value! Ba...

Posted: 16-Dec-2018

Tags: 2012 Hyundai Elantra, 2012 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



In a Nutshell: Effect of VES on cars

With the new Vehicular Emissions Scheme kicking in, here's a breakdown of how it affects the banding and pricing of some popular car r Singapore.

[Read this article](#)



Hyundai Elantra 1.6A Elite

\$35,800

\$8,700 /yr

10-Apr-2012

1,591 cc

127,527 km

White Elantra 1.6A, Elite Model! Road Tax Till Apr 19. Low Mileage Clockd Of 18800km Annually. Excellent Condition, Confirm f needed. Expat Owner. 100% Accident Free. Call Now!

Credit Pte Ltd



PROGRESSIVE
CAR CARE PTE LTD

Progressive Car Care Pte Ltd

(Co. Reg. No. 201006949C)

Blk 3022A Ubi Road 1 #01-45/46 S408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD 1218-6810
Policy No:	MPC18A00028600	Date of Loss:	16/12/2018
Vehicle Reg. No.:	SKD8670L	Driveable?	
Driver Age/Info:	45 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ONG YONG WAH	Contact No:	+6582333645
Driver:	ONG YONG WAH		
Make/Model:	HYUNDAI ELANTRA, 1.6 (A)	Vehicle Reg. Date:	14/01/2012
Vehicle Colour:	SILVER	Chassis No:	KMHDH41CMCU410830
Engine No:	G4FGBU448542		
Odometer:	263578 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	REFER TO ATTACHED STATEMENT RECORDED BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336		
Remarks:	VEHICLE IN WORKSHOP		
Present Location:	PROGRESSIVE CAR CARE PTE LTD (HQ)		

Not Attached
2 days
4/5
Take photo other up
7 days

COST OF CLAIMS

	Amount
Parts	5,470.30
Miscellaneous Items	115.00
Labour	2,450.00
Paintwork Labour	1,200.00
Towing	0.00
Gross Total (S\$)	9,235.30
+ GST 7.00% (S\$)	646.47
Nett Amount (S\$)	9,881.77

This claim is handled by: SOO LEONG KEAT

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Let's make the claimant's finance notify
the Receiver of the following:

- To be notified when the car is being
- To be notified when the car is being
- To be notified when the car is being
- To be notified when the car is being
- To be notified when the car is being
- To be notified when the car is being
- To be notified when the car is being
- To be notified when the car is being

Acknowledged by Receiver

Signature:

Date:

9839.30

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 19 Dec 2018)

Parts: 143

HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Progressive Car Care Pte Ltd/SKD8670L/19/12/2018 16:27

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*ENGINE MOUNTING - LH	11	0.00	*60.00 F
2	1	NA	*ENGINE MOUNTING - RH	11	0.00	*105.00 F
3	1	NA	*ENGINE MOUNTING - REAR	11	0.00	*75.00 F
4	1	NA	*ENGINE MOUNTING BRACKET - LH - NO STK	11	0.00	*F
5	1	NA	*FUSE BOX COVER - TOP	11	0.00	*15.00 F
6	1	NA	*FUSE BOX COVER - CENTRE	11	0.00	*F
7	1	NA	*FUSE BOX COVER - LOWER	11	0.00	*F
8	1	NA	*FRONT ABSORBER - LH	11	0.00	*150.00 F
9	1	NA	*FRONT ABSORBER TOP MOUNTING - LH	11	0.00	*35.00 F
10	1	NA	*FRONT LOWER ARM W/BALL JOINT - LH	11	0.00	*125.00 F
11	1	NA	*FRONT KNUCKLE ARM - LH	11	0.00	*185.00 F
12	1	NA	*FRONT KNUCKLE ARM BEARING - LH	11	0.00	*42.00 F
13	1	NA	*FRONT STAY LINK - LH	11	0.00	*32.00 F
14	1	NA	*STEERING CROSSMEMBER	11	0.00	*385.00 F
15	1	NA	*INTAKE MANIFOLD		0.00	*480.00 F
16	1	NA	*AIR CLEANER BOX ASSY	300	0.00	*75.00 F
17	1	NA	*BATTERY LOWER TRY	11	0.00	*30.00 F
18	1	NA	*FRONT NUMBER PLATE GARNISH	11	0.00	*F
19	1	NA	*GRILLE ASSY W/LOGO	11	0.00	*76.00 F
20	10	NA	*GRILLE CLIPS	11	0.00	*15.00 F
21	1	NA	*GRILLE TOP GARNISH	11	0.00	*F
22	1	NA	*FRONT BUMPER	11	0.00	*195.00 F
23	10	NA	*FRONT BUMPER CLIPS	11	0.00	*15.00 F
24	1	NA	*FRONT BUMPER SIDE HOLDER - LH	11	0.00	*8.00 F
25	1	NA	*FRONT BUMPER SIDE HOLDER - RH	11	0.00	*8.00 F
26	1	NA	*FRONT BUMPER FOAM	11	0.00	*45.00 F
27	1	NA	*FRONT BUMPER REINFORCEMENT	11	0.00	*165.00 F
28	1	NA	*FRONT BUMPER REINFORCEMENT BRACKET - LH	11	0.00	*12.00 F
29	1	NA	*FRONT BUMPER REINFORCEMENT BRACKET - RH	11	0.00	*12.00 F
30	1	NA	*FRONT BUMPER LOWER CENTRE GRILLE W/CHROME MOULDING	11	0.00	*70.00 F
31	1	NA	*FRONT BUMPER FOG LAMP - RH	11	0.00	*95.00 F
32	1	NA	*FRONT BUMPER FOG LAMP - LH	11	0.00	*95.00 F
33	1	NA	*FRONT BUMPER TOW COVER - RH	11	0.00	*5.00 F
34	1	NA	*SUPPORT PANEL ASSY	11	0.00	*220.00 F
35	1	NA	*SUPPORT PANEL TOP GARNISH	11	0.00	*F
36	1	NA	*HORN - RH	11	0.00	*42.00 F
37	1	NA	*HORN - LH	11	0.00	*42.00 F
38	1	NA	*HEADLAMP ASSY - LH	11	0.00	*265.00 F
39	1	NA	*HEADLAMP ASSY - RH	11	0.00	*265.00 F
40	1	NA	*HEADLAMP LOWER RETAINER - LH	11	0.00	*8.00 F
41	1	NA	*HEADLAMP LOWER RETAINER - RH	11	0.00	*8.00 F
42	1	NA	*FRONT FENDER - LH	11	0.00	*135.00 F
43	1	NA	*FRONT FENDER COWLING - LH	11	0.00	*25.00 F
44	10	NA	*FRONT FENDER COWLING CLIPS - LH	11	0.00	*15.00 F
45	1	NA	*BONNET	11	0.00	*365.00 F
46	1	NA	*BONNET HINGE - LH	11	0.00	*22.00 F
47	1	NA	*BONNET HINGE - RH	11	0.00	*22.00 F
48	1	NA	*BONNET LOCK	11	0.00	*25.00 F
49	1	NA	*BONNET RUBBER - CENTRE	11	0.00	*12.00 F
50	1	NA	*BONNET RUBBER - LH	11	0.00	*6.00 F
51	1	NA	*BONNET RUBBER - RH	11	0.00	*8.00 F
52	1	NA	*RADIATOR	11	0.00	*195.00 F
53	2	NA	*RADIATOR TOP HOSE	11	0.00	*44.00 F
54	1	NA	*RADIATOR BOTTOM HOSE	11	0.00	*22.00 F
55	1	NA	*RADIATOR SPARE TANK W/FAN MOTOR & FAN BLADE & COWLING	11	0.00	*495.00 F
56	1	NA	*CONDENSER	11	0.00	*F
57	1	NA	*CONDENSER FAN MOTOR	11	0.00	*F
58	1	NA	*CONDENSER FAN BLADE	11	0.00	*F
59	1	NA	*CONDENSER FAN COWLING	11	0.00	*F
60	1	NA	*AIRCON CONDENSER SIDE GARNISH - LH	11	0.00	*12.00 F
61	1	NA	*AIRCON CONDENSER SIDE GARNISH - RH	11	0.00	*12.00 F

Progressive Car Care Pte Ltd/SKD8670L/19/12/2018 16:27. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
62	1	NA	*AIRCON DISCHARGE PIPE	11	0.00	0.00
63	1	NA	*AIRCON LIQUID TUBE	11	0.00	0.00
64	1	NA	*WIPER TANK	11	0.00	0.00
65	1	NA	*WIPER TANK MOTOR	11	0.00	0.00
66	1	NA	*AIR CLEANER END HOSE	11	0.00	0.00
F=Franchise part.						
1 def windscreen \$450 cracked 402 -						Sub Total (\$\$)
1 ref " " moulding \$20 per 40						+ Margin on L,N Items 10.00% (\$\$)
						Total Parts (\$\$)

Progressive Car Care Pte Ltd/SKD8670L/19/12/2018 16:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

P-3389.50
102
3728.45
115.00
1970.00
5813.45

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	COOLANT	20.00 ✓
2	1	FRONT NUMBER PLATE W/CASING	35.00 ✓
3	2	SEALANT	40.00 ✓
4	1	SPONGE TAPE	20.00 ✓
Sub Total (S\$)			115.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New 900	1,200.00
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS; LHF WHEELHOUSE; CHASSIS; CUT/WELD SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New 700	1,400.00
3	TO CHECK WIRING	New ✓	20.00
4	TO RESET CHECK LIGHT	New ✓	80.00
5	TO REMOVE; REPLACE CONDENSER AND REFILL GAS	New ✓	100.00
6	TO REMOVE; REPLACE FRONT WINDSCREEN	New ✓	120.00
7	TO 4 WHEEL ALIGNMENT	New ✓	70.00
8	TO REMOVE; REPLACE UNDERCARRIAGE	New 12X	300.00
9	TO LIFT UP ENGINE	New 12X	80.00
10	TO REMOVE; REPLACE ENGINE MOUNTINGS & CHECK	New 12X	300.00
Gross Labour Cost (S\$)			3,650.00

Progressive Car Care Pte Ltd/SKD8670L/19/12/2018 16:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK T repair bench, draw planner and the support dolly system to provide accurate re-alignment and speedy repairs.



PROGRESSIVE
CAR CARE PTE LTD

Progressive
(Co. Reg.
Blk 3022A Ubi Road 1 #C
T: +65 6741 5336 |
E: claims@p
W: www.p

(SUPPLEMENTARY)

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD 1218-6810
Policy No:	MPC18A00028600	Date of Loss:	16/12/2018
Vehicle Reg. No.:	SKD8670L	Driveable?	
Driver Age/Info:	45 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ONG YONG WAH	Contact No:	+6582333645
Driver:	ONG YONG WAH		
Make/Model:	HYUNDAI ELANTRA, 1.6 (A)	Vehicle Reg. Date:	14/01/2012
Vehicle Colour:	SILVER	Chassis No:	KMHDH41CMCU410830
Engine No:	G4FGBU448542		
Odometer:	263578 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		

Description of Accident/Loss: REFER TO ATTACHED
STATEMENT RECORDED BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336
Present Location: PROGRESSIVE CAR CARE PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	572.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	572.00
+ GST 7.00% (S\$)	40.04
Nett Amount (S\$)	612.04
+ Previous Estimates (S\$)	9,881.77
Claim Total (S\$)	10,493.81

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Jan 2019)

Parts: 143 HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Progressive Car Care Pte Ltd/SKD8670L/19/01/2019 12:37

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT W/SCREEN <i>CN</i>	0.00	0.00	*400.00 F ✓
2	1		*FRT W/SCREEN MOULDING <i>REL</i>	0.00	0.00	*40.00 F ✓
3	1		*RADIATOR JOINT <i>CN</i>	0.00	0.00	*35.00 F ✓
4	1		*AIR CLEANER END HOSE * <i>CN</i>	0.00	0.00	*45.00 F ✓
IN EST , BUT NO PRICE						
Sub Total (S\$)						520.00
+ Margin on L,N Items 10.00% (S\$)						52.00
Total Parts (S\$)						572.00

F=Franchise part.

Progressive Car Care Pte Ltd/SKD8670L/19/01/2019 12:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Jan 2019)

Parts: 143 HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Progressive Car Care Pte Ltd/SKD8670L/29/01/2019 16:55

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*WIPER GARNISH	0.00	0.00	*105.00 F
2	1		*FRT BUMPER SIDE BRACKET, TOP - LH	0.00	0.00	*15.00 F

F=Franchise part.

Sub Total (S\$) 120.00

+ Margin on L,N Items 10.00% (S\$) 12.00

Total Parts (S\$) 132.00

Progressive Car Care Pte Ltd/SKD8670L/29/01/2019 16:55. Not valid without Reference section.
Generated using Merimen e-Claims IEAS



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9200



Dept Direct: 6300 9010



Dept Direct: 6417 9794



Dept Direct: 6300 9010



Dept Direct: 6417 9795



Dept Direct: 6300 9011



Dept Direct: 6417 9796



Dept Direct: 6300 9012



Dept Direct: 6417 9797



Dept Direct: 6417 9798



Dept Direct: 6417 9799



Dept Direct: 6417 9800

Wiper blade: NWS (Nippon Wiper blade), Siliper (Made in Korea),
Ferch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN: WENDY

TAX INVOICE : AR201901-00423
DATE : 02/01/2019
CUSTOMER ID : PRO005
VEH REG. NO. : SKJ8670L
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

001X 8-6810

SQ STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1. WHY ELANTRA*11 SEN	86111-3X150 FRF W/S GLASS W/SENSOR	CC	1	400.00	400.00
2. ELANTRA 11"		CC6-D-6R			
3. MID.HY ELANTRA*11	86131-3X000 FRF W/S MLD	CC	1	40.00	40.00
4. ELANTRA 1.6 11"		CC6-A-1E			

SUB-TOTAL : 440.00
ADD GST 7.00 % : 30.80
TOTAL AMOUNT SGD : 470.80

[P] 02/01/2019 1:59:37PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on Overdue Account(s).

[E] 02/01/2019 1:22:05PM

JAE Auto Pte. Ltd.

Sales Executive: YIP

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



特 立 机 器 贸 易

MEGA POWER ENGINEERING & TRADING

Automobile Air Conditioning System Is Our Business

Head Office: 30 Genting Road Singapore 349405 Tel: 6542 3388 Fax: 6542 3373
Email: mega1000@singnet.com.sg Business Reg No: 40889100W

TAX INVOICE

GST Reg# : M8-8002998-3
Invoice No. : INV 10091031
Invoice Date : 29-Dec-2018
Terms : 30 DAYS
PO No :
Vehicle No : SKD8670L 0b1x18-6810
Chassis No :
Staff : MS NEO

Bill To: PRO002

PROGRESSIVE CAR CARE PTE LTD
BLK 3022A UBI ROAD 1
#01-45/46
SINGAPORE 408716
Attn: Account Dept

Ship To: KG1

PROGRESSIVE CAR CARE PTE LTD
BLK 3022A UBI ROAD 1
#01-45/46
Attn: WENDY
Tel: 82585595

Remarks:

MUST KEY IN ORDER PERSON'S
NAME & VEHICLE NO.

S/NC	DESCRIPTION	MOQ	BIN	WH	QTY	PRICE	SP	TOTAL(SGD)
PO Number :		DO Number :						
1	CD-01155 HY ELANTRA Y11 HCC COND W/DESI		KB2-C04	KB	1	320.00		320.00
2	RM-08130 HY ELANTRA Y11 RAD FAN ASSY		KB1-C10	KB	1	350.00		350.00

Rate: 1 SGD: 1.000000 SGD

Note: Goods sold are not returnable.

All Brand New compressor sold are without warranty.

Late payment is subject to 2% interest per month.

SUB-TOTAL 670.00 SGD
DISC 0.00% (-) SGD
GST 7% 46.90 SGD
AMOUNT 716.90 SGD

This is a computer-generated document.

No signature is required.

Printed on:29/12/2018 13:27:53

CUSTOMER COPY

Customer Signature & Stamp



Blk 5025, Ang Mo Kio Ind Park 2 #01-55/57 S(509528) Tel: 6482 3389 Fax: 6481 1107

No 13 Kaki Bukit Rd 4 #01-27 Bartley Biz Centre S(417807) Tel: 8355 3389 Fax: 8355 3329

No 5 Soon Lee St #01-25 Pioneer Park S(527907) Tel: 6252 3389 Fax: 6275 3389

No 21 Toh Guan Rd East #01-33 Toh Guan Centre S(609009) Tel: 67603389 Fax: 6316 2484



LOCAL
Page 1 of 1



松義汽車機件私人有限公司 SONG YI AUTO PARTS PTE LTD

Block 637 Veerasamy Road #01-119 Singapore 200637
Tel: 6297 3700 Fax: 6297 3839 Email: songyi@singnet.com.sg

07178-6810

TAX INVOICE

REG NO: 200922088G
GST NO: 200922088G

PROGRESSIVE CAR CARE PTE LTD
BLK 3022A, UBI ROAD 1,
#01-45/#01-46
SINGAPORE 408716

Invoice No: SAL18-087284 /
Date: 28/12/2018 11:16
Account No: P019
Sales person: SKM
Order By:
Vehicle No: SKD8670L
P/O No: CU410830

Page 1 of 1

No.	Part No.	Description	Location	Qty	Price	Amount
1	86350-3X000	GRILLE-RADIATOR ###	WH	1	70.00	70.00
2	86595-2T500	CLIP-BUMPER	C21-20	5	1.50	7.50
3	86511-3X020	BUMPER COVER-FRONT ###	WH	1	195.00	195.00
4	86595-2T500	CLIP-BUMPER	C21-20	10	1.50	15.00
5	86513-3X000	BRACKET-FRT BUMPER SIDE LH ###	U-11	1	8.00	8.00
6	86514-3X000	BRACKET-FRT BUMPER SIDE RH ###	U-11	1	8.00	8.00
7	86520-3X100	SPONGE-FRT BUMPER ###	WH	1	45.00	45.00
8	86530-3X200	REINFROMENT-BUMPER (FRT) ###	WH	1	105.00	105.00
9	86553-3X000	BRACKET-FRT BUMPER LH ###	Box 157	1	12.00	12.00
10	86554-3X000	BRACKET-FRT BUMPER RH ###	Box 157	1	12.00	12.00
11	86588-3X000	COVER-TOWING FRT BUMPER	Box 103	1	5.00	5.00
12	64101-3X003	PANEL-RAD SUPPORT ###	WH	1	220.00	220.00
13	92101-3X090	HEAD LAMP ASSY-LH ###	WH	1	265.00	265.00
14	92102-3X090	HEAD LAMP ASSY-RH ###	WH	1	265.00	265.00

Sub Total: 1,232.50

Add GST @ 7%: 86.28

Grand Total: 1,318.78

Issued By

Goods sold returned are to be in full packaging
original condition within SEVEN working days

Received By

Received the above mentioned goods in order and good condition





松義汽車機件私人有限公司 SONG YI AUTO PARTS PTE LTD

Block 637 Veerasamy Road #01-119 Singapore 200637
Tel: 6297 3700 Fax: 6297 3839 Email: songyi@singnet.com.sg

001X8-6810

TAX INVOICE

REG NO: 200022086G
GST NO: 200022086G

PROGRESSIVE CAR CARE PTE LTD
BLK 3022A, UBI ROAD 1,
#01-45/#01-46
SINGAPORE 408716

Invoice No: SAL18-087297
Date: 29/12/2018 08:58
Account No: P019
Sales person: SKM
Order By:
Vehicle No: SKD8670L
P/O No: CU410830

						Page 1 of 1
No.	Part No.	Description	Location	Qty	Price	Amount
1	29134-3X000	GARNISH-RAD SIDE RH	WH	1	12.00	12.00
2	29136-3X000	GARNISH-RAD SIDE LH ^^^	WH	1	12.00	12.00
3	86517-3X000	BRACKET-FRT BUMPER UPR LH ####	Box 71	1	15.00	15.00
4	86560-3X000	GRILLE-FRT BUMPER CTR ####	WH	1	70.00	70.00
Sub Total:						109.00
Add GST @7%:						7.63
Grand Total:						116.63

Issued By

Received By

Goods sold returned are to be in full packaging
original condition within SEVEN working days

Received the above mentioned goods in order and good condition





松義汽車機件私人有限公司
SONG YI AUTO PARTS PTE LTD

Block 637 Veerasamy Road #01-119 Singapore 200637
Tel: 6297 3700 Fax: 6297 3839 Email: songyi@singnet.com.sg

001718-6810

TAX INVOICE

REG NO: 200022000G
GST NO: 200022000G

PROGRESSIVE CAR CARE PTE LTD
BLK 3022A, UBI ROAD 1,
#01-45/#01-46
SINGAPORE 408716



Invoice No: SAL19-087325
Date: 02/01/2019 09:21
Account No: P019
Sales person: SKM
Order By:
Vehicle No: SKD8670L
P/O No: CU410830

						Page 1 of 1
No.	Part No.	Description	Location	Qty	Price	Amount
1	25329-1P100	NECK-RADIATOR	Box 23	1	35.00	35.00
					Sub Total:	35.00
					Add GST @ 7%:	2.45
					Grand Total:	37.45

Issued By

Goods sold returned are to be in full packaging
original condition within SEVEN working days.

Received By

Received the above mentioned goods in order and good condition





松義汽車機件私人有限公司
SONG YI AUTO PARTS PTE LTD

Block 637 Veerasamy Road #01-119 Singapore 200637
Tel: 6297 3700 Fax: 6297 3539 Email: songyi@singnet.com.sg

061718-6810

TAX INVOICE

REG NO: 200922086G
GST NO: 200922086G

PROGRESSIVE CAR CARE PTE LTD
BLK 3022A, UBI ROAD 1,
#01-45/#01-46
SINGAPORE 408716

Invoice No: SAL19-087353
Date: 03/01/2019 13:29
Account No: P019
Sales person: SKM
Order By:
Vehicle No: SKD8670L
P/O No:

Page 1 of 1

No.	Part No.	Description	Location	Qty	Price	Amount
1	01071-3X000	CAD BATTERY (1) SLP (MODIFY)	Box 16	1	25.00	25.00
2	18210-3X020	AIR DUCT	WH	1	45.00	45.00
3	18212-3X000	SHIELD AIR INTAKE SLP (MODIFY)	Box 18	1	8.00	8.00
Sub Total:						78.00
Add GST @ 7%:						5.46
Grand Total:						83.46

Issued By

Received By

Goods sold returned are to be in full packaging
original condition within SEVEN working days

Received the above mentioned goods in order and good condition





松義汽車機件私人有限公司
SONG YI AUTO PARTS PTE LTD

Block 637 Veerasamy Road #01-119 Singapore 200637
Tel: 6297 3700 Fax: 6297 3839 Email: songyi@singnet.com.sg

061718-6810

TAX INVOICE

REG NO: 200022086G
GST NO: 200022086G

PROGRESSIVE CAR CARE PTE LTD
BLK 3022A, UBI ROAD 1,
#01-45/#01-46
SINGAPORE 408716

Goods Delivery To:

Invoice No: SAL19-087330
Date: 02/01/2019 10:52
Account No: P019
Sales person: SKM
Order By:
Vehicle No: SKD8670L
P/O No:



Page 1 of 1

No.	Part No.	Description	Location	Qty	Price	Amount
1	86811-3X000	LINING-FRT FENDER L/S LH #0000	WH	1	25.00	25.00
Sub Total:						25.00
Add GST @7%:						1.75
Grand Total:						26.75


Issued By


Received By

3389.50

Goods sold returned are to be in full packaging
original condition within SEVEN working days

Received the above mentioned goods in order and good condition





松義汽車機件私人有限公司

SONG YI AUTO PARTS PTE LTD

Block 637 Veerasamy Road #01-119 Singapore 200637
Tel: 6297 3700 Fax: 6297 3839 Email: songyi@singnet.com.sg

001218-6810

TAX INVOICE

REG NO: 200922086C
GST NO: 200922086C

PROGRESSIVE CAR CARE PTE LTD
BLK 3022A, UBI ROAD 1,
#01-45/#01-46
SINGAPORE 408716

Invoice No: SAL18-087294 ✓
Date: 28/12/2018 16:55
Account No: P019
Sales person: SKM
Order By:
Vehicle No: SKD8670L
P/O No: CU410830



Page 1 of 1

No.	Part No.	Description	Location	Qty	Price	Amount
1	91950-3X720	COVER-FUSE BOX	W-25 Top	1	15.00	15.00 — ✓
2	25411-3X100	HOSE-RADIATOR (UPR)	P-8	1	18.00	18.00 — ✓
2	25411-3X150	HOSE-RADIATOR (UPR)	P-11	1	22.00	22.00 — ✓
4	86150-3X600	GARNISH-WIPER PANEL	WH	1	105.00	105.00 — ✓
5	86153-3X000	GARNISH WIPER PANEL SIDE LH	Box 35	1	8.00	8.00 — ✓
6	37150-3X000	TRAY-BATTERY	R-5	1	30.00	30.00 — ✓
7	28110-3X000	AIR CLEANER ASSY ###	WH	1	75.00	75.00 — ✓
8	66400-3X002	BONNET ###	WH	1	365.00	365.00 — ✓
9	79110-3X000	HINGE-BONNET LH ###	E-1	1	22.00	22.00 — ✓
10	79120-3X000	HINGE-BONNET RH ###	E-1	1	22.00	22.00 — ✓
11	81130-3X900	LOCK-BONNET ###	O/S-1	1	25.00	25.00 — ✓
12	86435-3X000	RUBBER-BONNET (FRT)	GG Box 1	1	12.00	12.00 — ✓
13	86450-3X000	STOPPER-BONNET	Box 102	2	4.00	8.00 — ✓
14	25310-3X151	RADIATOR A/T (GENUINE) ### ^^^	WH	1	195.00	195.00 — ✓

Sub Total: 922.00

Add GST @7%: 64.54

Grand Total: 986.54

Issued By

Goods sold returned are to be in full packaging
original condition within SEVEN working days

Received By

Received the above mentioned goods in order and good condition



906
3446.50
711

...CLAIM SUBFOLDER...(Pending for Survey Report)

Midnight Accident

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Dec 2018 16:16 Sendback Est	19 Dec 2018 16:27 S\$9,235.30	19 Dec 2018 16:35 Edit Adj Rpt	S\$5,813.45 Edit Estimates	S\$5,813.45 View Rpt		Pending for Survey Report Cancel Case
Supp #1	19 Jan 2019 12:28	19 Jan 2019 12:37 S\$572.00	19 Jan 2019 12:37			(Combined)	Combined with Main Uncombine Suppl.
Supp #2	29 Jan 2019 16:54	29 Jan 2019 16:55 S\$132.00	29 Jan 2019 16:55			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: ONG YONG WAH , ID: S7326168F, Tel: +6582333645, Email: ongorg@gmail.com									
Vehicle Reg. No.: SKD8670L		Date of Loss: 16/12/2018 03:00 - :59	[83 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type: OD / DMPC1800469H/JG		Policy/Cover Note No.: MPC18A00028600 (Comprehensive)	Excess: S\$500.00						
Repairer: Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46, 408716 Ubi - Tel: 67415336									
Handling Insurer: ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Janice Goh - 6303 0182]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 31/12/2018]									
Driver/Custodian: ONG YONG WAH (45 / Male) , NRIC: S7326168F, Tel: +6582333645 Email: ongorg@gmail.com									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• ECICS (24/12/2018): Alert - Adj Mandate Approved (S\$6322.10) - SKD8670L - Claim Handler: Janice Goh									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKD8670L (DMPC1800469H/JG)

OD

Dec 16 2018 3:00AM

[ONG YONG WAH]

Progressive Car Care Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Assessment Reports

1 per page ☒

No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	19/12/18 16:27	Repairer Estimates	 Load HTM	☐
2	19/01/19 12:37	Repairer Estimates Suppl. #1	 Load HTM	☐
3	29/01/19 16:55	Repairer Estimates Suppl. #2	 Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/12/18 14:41	Adjuster Immediate Advice	 Load HTM	☐

Photos/Images

3 per page ☒

No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	19/12/18 16:22	1	 Load JPG	☒
2	19/12/18 16:22	2	 Load JPG	☒
3	19/12/18 16:22	3	 Load JPG	☒
4	19/12/18 16:22	4	 Load JPG	☒
5	19/12/18 16:22	5	 Load JPG	☒
6	19/12/18 16:22	6	 Load JPG	☒
7	19/12/18 16:22	7	 Load JPG	☒
8	19/12/18 16:22	8	 Load JPG	☒
9	19/12/18 16:22	9	 Load JPG	☒
10	19/12/18 16:22	10	 Load JPG	☒
11	19/12/18 16:22	11	 Load JPG	☒
12	19/12/18 16:22	12	 Load JPG	☒
13	19/12/18 16:22	13	 Load JPG	☒
14	19/12/18 16:22	14	 Load JPG	☒
15	19/12/18 16:22	15	 Load JPG	☒
16	19/12/18 16:22	16	 Load JPG	☒
17	19/12/18 16:22	17	 Load JPG	☒
18	19/12/18 16:22	18	 Load JPG	☒
19	19/12/18 16:22	19	 Load JPG	☒
20	19/12/18 16:22	20	 Load JPG	☒
21	19/12/18 16:22	21	 Load JPG	☒
22	19/12/18 16:22	22	 Load JPG	☒
23	19/12/18 16:22	23	 Load JPG	☒
24	19/12/18 16:22	24	 Load JPG	☒
25	19/12/18 16:22	25	 Load JPG	☒
26	19/12/18 16:22	26	 Load JPG	☒
27	19/12/18 16:22	27	 Load JPG	☒
28	19/12/18 16:22	28	 Load JPG	☒
29	19/12/18 16:22	29	 Load JPG	☒
30	19/12/18 16:22	30	 Load JPG	☒
31	19/12/18 16:22	31	 Load JPG	☒
32	19/12/18 16:22	32	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
33	19/12/18 16:22	33	 Load JPG	☒
34	19/12/18 16:22	34	 Load JPG	☒
35	19/12/18 16:22	35	 Load JPG	☒
36	19/12/18 16:22	36	 Load JPG	☒
37	19/12/18 16:22	37	 Load JPG	☒
38	19/12/18 16:22	38	 Load JPG	☒
39	19/12/18 16:22	39	 Load JPG	☒
40	19/12/18 16:22	40	 Load JPG	☒
41	19/12/18 16:22	41	 Load JPG	☒
42	19/12/18 16:22	42	 Load JPG	☒
43	19/12/18 16:22	43	 Load JPG	☒
44	19/12/18 16:22	44	 Load JPG	☒
45	19/12/18 16:22	45	 Load JPG	☒
46	19/12/18 16:22	46	 Load JPG	☒
47	19/12/18 16:22	47	 Load JPG	☒
48	19/12/18 16:22	48	 Load JPG	☒
49	19/12/18 16:22	49	 Load JPG	☒
50	19/12/18 16:22	50	 Load JPG	☒
51	19/12/18 16:22	51	 Load JPG	☒
52	19/12/18 16:22	52	 Load JPG	☒
53	19/12/18 16:22	53	 Load JPG	☒
54	19/12/18 16:22	54	 Load JPG	☒
55	19/12/18 16:22	55	 Load JPG	☒
56	19/12/18 16:22	56	 Load JPG	☒
57	19/12/18 16:22	57	 Load JPG	☒
58	19/12/18 16:22	58	 Load JPG	☒
59	19/12/18 16:22	59	 Load JPG	☒
60	19/12/18 16:22	60	 Load JPG	☒
61	19/12/18 16:22	61	 Load JPG	☒
62	19/12/18 16:22	62	 Load JPG	☒
63	19/12/18 16:22	63	 Load JPG	☒
64	19/12/18 16:22	64	 Load JPG	☒
65	19/12/18 16:22	65	 Load JPG	☒
66	19/12/18 16:22	66	 Load JPG	☒
67	19/12/18 16:22	67	 Load JPG	☒
68	19/12/18 16:22	68	 Load JPG	☒
69	19/12/18 16:22	69	 Load JPG	☒
70	19/12/18 16:22	70	 Load JPG	☒
71	19/12/18 16:22	71	 Load JPG	☒
72	19/12/18 16:22	72	 Load JPG	☒
73	19/12/18 16:22	73	 Load JPG	☒
74	19/12/18 16:22	74	 Load JPG	☒
75	19/12/18 16:22	75	 Load JPG	☒
76	19/12/18 16:22	76	 Load JPG	☒
77	19/12/18 16:22	77	 Load JPG	☒
78	19/12/18 16:22	78	 Load JPG	☒
79	19/12/18 16:22	79	 Load JPG	☒
80	19/12/18 16:22	80	 Load JPG	☒
81	19/12/18 16:22	81	 Load JPG	☒
82	19/12/18 16:22	82	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
83	19/12/18 16:22	83		☒
84	19/12/18 16:22	84		☒
85	19/12/18 16:22	85		☒
86	19/12/18 16:22	86		☒
87	19/12/18 16:22	87		☒
88	19/12/18 16:22	88		☒
89	19/12/18 16:22	89		☒
90	19/12/18 16:22	90		☒
91	19/12/18 16:22	91		☒
92	19/12/18 16:22	92		☒
93	19/12/18 16:22	93		☒
94	19/12/18 16:22	94		☒
95	19/12/18 16:22	95		☒
96	19/12/18 16:22	96		☒
97	19/12/18 16:22	97		☒
98	19/12/18 16:22	98		☒
99	19/12/18 16:22	99		☒
100	19/12/18 16:22	100		☒
101	19/12/18 16:22	101		☒
102	19/12/18 16:22	102		☒
103	19/12/18 16:22	103		☒
104	19/12/18 16:22	104		☒
105	19/12/18 16:22	105		☒
106	19/12/18 16:22	106		☒
107	19/12/18 16:22	107		☒
108	19/12/18 16:22	108		☒
109	19/12/18 16:22	109		☒
110	19/12/18 16:22	110		☒
111	19/12/18 16:22	111		☒
112	19/12/18 16:22	112		☒
113	19/12/18 16:22	113		☒
114	19/12/18 16:22	114		☒
115	19/12/18 16:22	115		☒
116	19/12/18 16:22	116		☒
117	19/12/18 16:22	117		☒
118	19/12/18 16:22	118		☒
119	19/12/18 16:22	119		☒
120	19/12/18 16:22	120		☒
121	19/12/18 16:22	121		☒
122	19/12/18 16:22	122		☒
123	19/12/18 16:22	123		☒
124	19/12/18 16:22	124		☒
125	19/12/18 16:22	125		☒
126	19/12/18 16:22	126		☒
127	19/12/18 16:22	127		☒
128	19/12/18 16:22	128		☒
129	19/12/18 16:22	129		☒
130	19/12/18 16:22	130		☒
131	19/12/18 16:22	131		☒
132	19/12/18 16:22	132		☒

Assessment Reports			1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
133	19/12/18 16:22	133	 Load JPG	☒
134	19/12/18 16:22	134	 Load JPG	☒
135	19/12/18 16:22	135	 Load JPG	☒
136	19/12/18 16:22	136	 Load JPG	☒
137	19/12/18 16:22	137	 Load JPG	☒
138	19/12/18 16:22	138	 Load JPG	☒
139	19/12/18 16:22	139	 Load JPG	☒
140	19/12/18 16:22	140	 Load JPG	☒
141	19/12/18 16:22	141	 Load JPG	☒
142	19/12/18 16:22	142	 Load JPG	☒
143	19/12/18 16:22	143	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/12/18 08:34	General View	 Load JPG	☒
2	24/12/18 08:34	General View	 Load JPG	☒
3	24/12/18 08:34	General View	 Load JPG	☒
4	24/12/18 08:34	General View	 Load JPG	☒
5	24/12/18 08:34	General View	 Load JPG	☒
6	24/12/18 08:34	General View	 Load JPG	☒
7	24/12/18 08:34	General View	 Load JPG	☒
8	24/12/18 08:34	General View	 Load JPG	☒
9	24/12/18 08:34	General View	 Load JPG	☒
10	24/12/18 08:34	General View	 Load JPG	☒
11	24/12/18 08:34	General View	 Load JPG	☒
12	24/12/18 08:34	General View	 Load JPG	☒
13	24/12/18 08:34	General View	 Load JPG	☒
14	24/12/18 08:34	General View	 Load JPG	☒
15	24/12/18 08:34	General View	 Load JPG	☒
16	24/12/18 08:34	General View	 Load JPG	☒
17	24/12/18 08:34	General View	 Load JPG	☒
18	24/12/18 08:34	General View	 Load JPG	☒
19	24/12/18 08:34	General View	 Load JPG	☒
20	24/12/18 08:34	General View	 Load JPG	☒
21	24/12/18 08:34	General View	 Load JPG	☒
22	24/12/18 08:34	General View	 Load JPG	☒
23	24/12/18 08:34	General View	 Load JPG	☒
24	24/12/18 08:34	General View	 Load JPG	☒
25	24/12/18 08:34	General View	 Load JPG	☒
26	24/12/18 08:34	General View	 Load JPG	☒
27	24/12/18 08:34	General View	 Load JPG	☒
28	24/12/18 08:34	General View	 Load JPG	☒
29	24/12/18 08:34	General View	 Load JPG	☒
30	24/12/18 08:34	General View	 Load JPG	☒
31	24/12/18 08:34	General View	 Load JPG	☒
32	24/12/18 08:34	General View	 Load JPG	☒
33	24/12/18 08:34	General View	 Load JPG	☒
34	24/12/18 08:34	General View	 Load JPG	☒
35	24/12/18 08:34	General View	 Load JPG	☒
36	24/12/18 08:34	General View	 Load JPG	☒
37	24/12/18 08:34	General View	 Load JPG	☒
38	24/12/18 08:34	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
39	24/12/18 08:34	General View	 Load JPG	☒
40	24/12/18 08:34	General View	 Load JPG	☒
41	24/12/18 08:34	General View	 Load JPG	☒
42	24/12/18 08:34	General View	 Load JPG	☒
43	24/12/18 08:34	General View	 Load JPG	☒
44	24/12/18 08:34	General View	 Load JPG	☒
45	24/12/18 08:34	General View	 Load JPG	☒
46	24/12/18 08:34	General View	 Load JPG	☒
47	24/12/18 08:34	General View	 Load JPG	☒
48	24/12/18 08:34	General View	 Load JPG	☒
49	24/12/18 08:34	General View	 Load JPG	☒
50	24/12/18 08:34	General View	 Load JPG	☒
51	24/12/18 08:34	General View	 Load JPG	☒
52	24/12/18 08:34	General View	 Load JPG	☒
53	24/12/18 08:34	General View	 Load JPG	☒
54	24/12/18 08:34	General View	 Load JPG	☒
55	24/12/18 08:34	General View	 Load JPG	☒
56	24/12/18 08:34	General View	 Load JPG	☒
57	24/12/18 08:34	General View	 Load JPG	☒
58	24/12/18 08:34	General View	 Load JPG	☒
59	24/12/18 08:34	General View	 Load JPG	☒
60	24/12/18 08:34	General View	 Load JPG	☒
61	24/12/18 08:34	General View	 Load JPG	☒
62	24/12/18 08:34	General View	 Load JPG	☒
63	24/12/18 08:34	General View	 Load JPG	☒
64	24/12/18 08:34	General View	 Load JPG	☒
65	24/12/18 08:34	General View	 Load JPG	☒
66	24/12/18 08:34	General View	 Load JPG	☒
67	24/12/18 08:34	General View	 Load JPG	☒
68	24/12/18 08:34	General View	 Load JPG	☒
69	24/12/18 08:34	General View	 Load JPG	☒
70	24/12/18 08:34	General View	 Load JPG	☒
71	24/12/18 08:34	General View	 Load JPG	☒
72	24/12/18 08:34	General View	 Load JPG	☒
73	24/12/18 08:34	General View	 Load JPG	☒
74	24/12/18 08:34	General View	 Load JPG	☒
75	24/12/18 08:34	General View	 Load JPG	☒
76	24/12/18 08:34	General View	 Load JPG	☒
77	24/12/18 08:34	General View	 Load JPG	☒
78	24/12/18 08:34	General View	 Load JPG	☒
79	24/12/18 08:34	General View	 Load JPG	☒
80	24/12/18 08:34	General View	 Load JPG	☒
81	24/12/18 08:34	General View	 Load JPG	☒
82	24/12/18 08:34	General View	 Load JPG	☒
83	24/12/18 08:34	General View	 Load JPG	☒
84	24/12/18 08:34	General View	 Load JPG	☒
85	24/12/18 08:34	General View	 Load JPG	☒
86	24/12/18 08:34	General View	 Load JPG	☒
87	24/12/18 08:34	General View	 Load JPG	☒
88	24/12/18 08:34	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
89	24/12/18 08:34	General View	 Load JPG	☒
90	24/12/18 08:34	General View	 Load JPG	☒
91	24/12/18 08:34	General View	 Load JPG	☒
92	24/12/18 08:34	General View	 Load JPG	☒
93	24/12/18 08:34	General View	 Load JPG	☒
94	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
95	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
96	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
97	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
98	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
99	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
100	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
101	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
102	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
103	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
104	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
105	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
106	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
107	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
108	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
109	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
110	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
111	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
112	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
113	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
114	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
115	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
116	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
117	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
118	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
119	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
120	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
121	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
122	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
123	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
124	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
125	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
126	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
127	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
128	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
129	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
130	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
131	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
132	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
133	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
134	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
135	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
136	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
137	02/01/19 17:44	Reinspection Photo	 Load JPG	☒
138	02/01/19 17:44	Reinspection Photo	 Load JPG	☒

Assessment Reports				1 per page	☒
No.	Finalized On	Progressive Car Care Pte Ltd (HQ)		Thumbnail	Print
139	02/01/19 17:44	Reinspection Photo		Load JPG	☒
140	02/01/19 17:44	Reinspection Photo		Load JPG	☒
141	02/01/19 17:44	Reinspection Photo		Load JPG	☒
142	02/01/19 17:44	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No.	Finalized On	Progressive Car Care Pte Ltd (HQ)		Thumbnail	Print
1	19/12/18 16:17	E-filed GIA report		Load PDF	
2	19/12/18 16:17	Driver's Driving License & NRIC		Load TIF	
3	19/12/18 16:17	Certificate of Insurance		Load TIF	
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/03/19 10:49	Parts Invoice		Load PDF	
2	07/03/19 10:52	Supplementary		Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No.	Finalized On	Progressive Car Care Pte Ltd (HQ)		Thumbnail	Print
1	17/12/18 12:59	Accident Statement		Load HTM	
Photos/Images				3 per page	☒
No.	Finalized On	Progressive Car Care Pte Ltd (HQ)		Thumbnail	Print
1	17/12/18 11:36	Accident Photo		Load JPG	☒
2	17/12/18 11:36	Accident Photo		Load JPG	☒
3	17/12/18 11:36	Accident Photo		Load JPG	☒
4	17/12/18 11:36	Accident Photo		Load JPG	☒
5	17/12/18 11:36	Accident Photo		Load JPG	☒
6	17/12/18 11:36	Accident Photo		Load JPG	☒
7	17/12/18 11:36	Accident Photo		Load JPG	☒
8	17/12/18 11:36	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No.	Finalized On	Progressive Car Care Pte Ltd (HQ)		Thumbnail	Print
1	17/12/18 12:58	Sketch Plan		Load JPG	☒
2	17/12/18 12:58	Sketch Plan #2		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One
Singapore 038987

Our File No: CS/ICS18022783/UTBE2

Date: 07/03/2019

REFERENCE

Insured/Claimant: ONG YONG WAH Policy No: MPC18A00028600
Date of Loss: 16/12/2018 Nature of Claim: OD Claim No: DMPC1800469H/JG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKD8670L**
Make & Model: HYUNDAI ELANTRA, 1.6 (A) Engine No: G4FGBU448542
Reg. Date: 14/01/2012 (Man. Year: 2011) Chassis No: KMHDH41CMCU410830
Colour: Silver Odometer: 0 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$33,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,174.30	3,728.45	2,445.85	39.61
Miscellaneous Items	115.00	115.00	0.00	0.00
Labour	2,450.00	1,070.00	1,380.00	56.33
Paintwork Labour	1,200.00	900.00	300.00	25.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,939.30	5,813.45	4,125.85	41.51
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	9,939.30	5,313.45	4,625.85	46.54
+ GST 7.00/7.00% (S\$)	695.75	371.94	323.81	46.54
Nett Amount (S\$)	10,635.05	5,685.39	4,949.66	46.54

INSPECTION

Date of Assignment: 19/12/2018 Present Location: Progressive Car Care Pte Ltd (HQ)
Date Inspected: 20/12/2018 Inspected At: Progressive Car Care Pte Ltd (HQ)
Blk 3022A Ubi Road 1, #01-45/46
Singapore 408716
Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Mar 2019)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKD8670L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*ENGINE MOUNTING - LH (WCP)	Not Necessary	60.00 F	*- F
2	1	NA	*ENGINE MOUNTING - RH (WCP)	Not Necessary	105.00 F	*- F
3	1	NA	*ENGINE MOUNTING - REAR (WCP)	Not Necessary	75.00 F	*- F
4	1	NA	*ENGINE MOUNTING BRACKET - LH - NO STK (NPA)	Not Necessary	0.00 F	*- F
5	1	NA	*FUSE BOX COVER - TOP (WCP)	Cracked	15.00 F	*15.00 F
6	1	NA	*FUSE BOX COVER - CENTRE (NPA)	Repair	0.00 F	*- F
7	1	NA	*FUSE BOX COVER - LOWER (NPA)	Repair	0.00 F	*- F
8	1	NA	*FRONT ABSORBER - LH (WCP)	Not Necessary	150.00 F	*- F
9	1	NA	*FRONT ABSORBER TOP MOUNTING - LH (WCP)	Not Necessary	35.00 F	*- F
10	1	NA	*FRONT LOWER ARM W/BALL JOINT - LH (WCP)	Not Necessary	125.00 F	*- F
11	1	NA	*FRONT KNUCKLE ARM - LH (WCP)	Not Necessary	185.00 F	*- F
12	1	NA	*FRONT KNUCKLE ARM BEARING - LH (WCP)	Not Necessary	42.00 F	*- F
13	1	NA	*FRONT STAY LINK - LH (WCP)	Not Necessary	32.00 F	*- F
14	1	NA	*STEERING CROSSMEMBER (WCP)	Not Necessary	385.00 F	*- F
15	1	NA	*INTAKE MANIFOLD (WCP)	Not Necessary	480.00 F	*- F
16	1	NA	*AIR CLEANER BOX ASSY (WCP)	Broken	75.00 F	*75.00 F
17	1	NA	*BATTERY LOWER TRY (WCP)	Cracked	30.00 F	*30.00 F
18	1	NA	*FRONT NUMBER PLATE GARNISH (NPA)	Not Necessary	0.00 F	*- F
19	1	NA	*GRILLE ASSY W/LOGO (WCP)	Broken	76.00 F	*70.00 F
20	1	NA	*GRILLE CLIPS (10PCS)(WCP)	Necessary-5pcs only	15.00 F	*7.50 F
21	1	NA	*GRILLE TOP GARNISH (NPA)	Not Necessary	0.00 F	*- F
22	1	NA	*FRONT BUMPER (WCP)	Distorted	195.00 F	*195.00 F
23	10	NA	*FRONT BUMPER CLIPS (WCP)	Necessary	15.00 F	*15.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
24	1	NA	*FRONT BUMPER SIDE HOLDER - LH (WCP)	Not Necessary	8.00 F	*- F
25	1	NA	*FRONT BUMPER SIDE HOLDER- RH (WCP)	Not Necessary	8.00 F	*- F
26	1	NA	*FRONT BUMPER FOAM (WCP)	Not fitted	45.00 F	*- F
27	1	NA	*FRONT BUMPER REINFORCEMENT (WCP)	Bent	165.00 F	*105.00 F
28	1	NA	*FRONT BUMPER REINFORCEMENT BRACKET - LH (WCP)	Bent	12.00 F	*12.00 F
29	1	NA	*FRONT BUMPER REINFORCEMENT BRACKET - RH (WCP)	Bent	12.00 F	*12.00 F
30	1	NA	*FRONT BUMPER LOWER CENTRE GRILLE W/CHROME MOULDING (WCP)	Necessary	70.00 F	*70.00 F
31	1	NA	*FRONT BUMPER FOG LAMP - RH (WCP)	Not fitted	95.00 F	*- F
32	1	NA	*FRONT BUMPER FOG LAMP - LH (WCP)	Not fitted	95.00 F	*- F
33	1	NA	*FRONT BUMPER TOW COVER - RH (WCP)	Necessary	5.00 F	*5.00 F
34	1	NA	*SUPPORT PANEL ASSY (WCP)	Bent	220.00 F	*220.00 F
35	1	NA	*SUPPORT PANEL TOP GARNISH (NPA)	Not fitted	0.00 F	*- F
36	1	NA	*HORN - RH (WCP)	Not Necessary	42.00 F	*- F
37	1	NA	*HORN - LH (WCP)	Not Necessary	42.00 F	*- F
38	1	NA	*HEADLAMP ASSY - LH (WCP)	Broken	265.00 F	*265.00 F
39	1	NA	*HEADLAMP ASSY - RH (WCP)	Holder Cracked	265.00 F	*265.00 F
40	1	NA	*HEADLAMP LOWER RETAINER - LH (WCP)	Not Necessary	8.00 F	*- F
41	1	NA	*HEADLAMP LOWER RETAINER - RH (WCP)	Not Necessary	8.00 F	*- F
42	1	NA	*FRONT FENDER - LH (WCP)	Repair	135.00 F	*- F
43	1	NA	*FRONT FENDER COWLING - LH (WCP)	Torn	25.00 F	*25.00 F
44	10	NA	*FRONT FENDER COWLING CLIPS - LH (WCP)	Not Necessary	15.00 F	*- F
45	1	NA	*BONNET (WCP)	Buckled	365.00 F	*365.00 F
46	1	NA	*BONNET HINGE - LH (WCP)	Bent	22.00 F	*22.00 F
47	1	NA	*BONNET HINGE - RH (WCP)	Bent	22.00 F	*22.00 F
48	1	NA	*BONNET LOCK (WCP)	Twisted	25.00 F	*25.00 F
49	1	NA	*BONNET RUBBER - CENTRE (WCP)	Necessary	12.00 F	*12.00 F
50	1	NA	*BONNET RUBBER - LH (WCP)	Not Necessary	8.00 F	*- F
51	1	NA	*BONNET RUBBER - RH (WCP)	Not Necessary	8.00 F	*- F
52	1	NA	*RADIATOR (WCP)	Bent / Twisted	195.00 F	*195.00 F
53	2	NA	*RADIATOR TOP HOSE (WCP)	Torn	44.00 F	*40.00 F
54	1	NA	*RADIATOR BOTTOM HOSE (WCP)	Not Necessary	22.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	1	NA	*RADIATOR SPARE TANK W/FAN MOTOR & FAN BLADE & COWLING (WCP)	Cracked / Jammed	195.00 F	*350.00 F
56	1	NA	*CONDENSER (WCP)	Bent / Punctured	0.00 F	*320.00 F
57	1	NA	*CONDENSER FAN MOTOR (NPA)	No such part	0.00 F	*- F
58	1	NA	*CONDENSER FAN BLADE (NPA)	No such part	0.00 F	*- F
59	1	NA	*CONDENSER FAN COWLING (NPA)	No such part	0.00 F	*- F
60	1	NA	*AIRCON CONDENSER SIDE GARNISH - LH (WCP)	Torn	12.00 F	*12.00 F
61	1	NA	*AIRCON CONDENSER SIDE GARNISH - RH (WCP)	Not Necessary	12.00 F	*- F
62	1	NA	*AIRCON DISCHARGE PIPE (WCP)	Not Necessary	180.00 F	*- F
63	1	NA	*AIRCON LIQUID TUBE (WCP)	Not Necessary	165.00 F	*- F
64	1	NA	*WIPER TANK (WCP)	Not Necessary	25.00 F	*- F
65	1	NA	*WIPER TANK MOTOR (WCP)	Not Necessary	30.00 F	*- F
66	1	NA	*AIR CLEANER END HOSE (NPA)	Not Necessary	0.00 F	*- F

Supplementary #1

67	1		*FRT W/SCREEN (WCP)	Cracked	400.00 F	*400.00 F
68	1		*FRT W/SCREEN MOULDING (WCP)	Necessary	40.00 F	*40.00 F
69	1		*RADIATOR JOINT (WCP)	Cracked	35.00 F	*35.00 F
70	1		*AIR CLEANER END HOSE * (WCP)	Cracked	45.00 F	*45.00 F

Supplementary #2

71	1		*WIPER GARNISH (WCP)	Torn	105.00 F	*105.00 F
72	1		*FRT BUMPER SIDE BRACKET, TOP - LH (WCP)	Cracked	15.00 F	*15.00 F

F=Franchise part.

Sub Total (\$\$)	5,613.00	3,389.50
+ Margin on L,N Items 10.00/10.00% (\$\$)	561.30	338.95
Total Parts (\$\$)	6,174.30	3,728.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	COOLANT (NECESSARY)	20.00	20.00
2	1	FRONT NUMBER PLATE W/CASING (MISSING)	35.00	35.00
3	2	SEALANT (NECESSARY)	40.00	40.00
4	1	SPONGE TAPE (NECESSARY)	20.00	20.00
Sub Total (S\$)			115.00	115.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,200.00	900.00
Labour Items				
2	TO KNOCK OUT DENTS; LHF WHEELHOUSE; CHASSIS; CUT/WELD SUPPORT PANEL;REMOVE; REPLACE ACCIDENT PARTS	New	1,400.00	700.00
3	TO CHECK WIRING	New	20.00	20.00
4	TO RESET CHECK LIGHT	New	60.00	60.00
5	TO REMOVE; REPLACE CONDENSER AND REFILL GAS	New	100.00	100.00
6	TO REMOVE; REPLACE FRONT WINDSCREEN	New	120.00	120.00
7	TO 4 WHEEL ALIGNMENT	New	70.00	70.00
8	TO REMOVE; REPLACE UNDERCARRIAGE	New	300.00	0.00
9	TO LIFT UP ENGINE	New	80.00	0.00
10	TO REMOVE; REPLACE ENGINE MOUNTINGS & CHECK	New	300.00	0.00
Gross Labour Cost (S\$)			3,650.00	1,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >