

KARZ WORKS PTE LTD

53 UBI AVENUE 1 #01-23, PAYA UBI INDUSTRIAL PARK

SINGAPORE 408934

(TEL) 6 8 4 4 5 9 3 4 (FAX) 6 8 4 4 2 4 7 4 - (E-MAIL) KARZWORKSSG@GMAIL.COM

M/s India International Insurance Pte Ltd

64 Cecil Street #04-02

IOB Building

Singapore 049711

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3RD PARTY CLAIM ESTIMATION

Vehicle number	SLN3317B
Make / Model	VOLKSWAGEN GOLF
Chassis number	WVWZZZ1KZ8W093143
Accident date	18-12-18
Reference	KM1812-24

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	FRONT BUMPER NH	1444.26 X
1	FRONT BUMPER RETAINER NH	161.20 X
1	FRONT RH DOOR PANEL deg	1609.40 X
1	FRONT RH FENDER Hnl	655.70 X
1	FRONT RH WING MIRROR broken	860.00 ✓
1	FRONT RH WING MIRROR COVER broken	201.30 ✓
1	FRONT RH QUARTER GLASS Hnl	335.18 X
		5267.04
Less 10%		1819.40
Subtotal		3447.64
Balance C/F		3447.64
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
Balance B/F		3447.64
1 SET	BUMPER CLIP Hnl	50.00 X
Subtotal		50.00
Balance C/F		3497.64
LABOUR AND MISCELLANEOUS CHARGES		
Balance B/F		3497.64
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 30/-
5	PANEL BEATING ON AFFECTED AREAS	600.00 400/-
6	SPRAY PAINTING ON AFFECTED AREAS	600.00 400/-
7	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30/-
20/12/2018 @ 1400hrs Not Attached 2/Sum 2 days		
Subtotal		1410.00
Grand total		4907.64