



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving 1 2014 AUDI A4 1.8 TURBO (SKR1942A)

Date of Loss 17 December 2018

Time of Loss 19.05

Loss Description SKR1942A (INSD) C/W SGE1440Y (TP)

Comment

Workshop Details

Total Rebate Amount 62604

Nett Loss Amount \$13,396.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion * 48



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Vehicle & Driver Details

Vehicle Registration#	SKR1942A	Purchase Date	dd/mm/yyyy
Registration State	SINGAPORE	Registration Date *	23/01/2015
Mileage	76179	Age of Vehicle	3

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2014	2014
Make	AUDI	AUDI
Model	A4 1.8 TURBO	A4 1.8 TFSI MU (E

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	NG POH KIM	
Date of Birth	29 January 1957	dd/mm/yyyy
Age	61	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No	WAUZZZ8K6FA062977	WAUZZZ8K6FA062977
Engine No	CJE092266	CJE092266
Engine Capacity		1798
Sum Insured	0	0
Market Value	0	76000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	32	
Driver License #		
License Type		
License Issue Date		dd/mm/yyyy 
License Expiration Date		dd/mm/yyyy 
Address	19 SENNETT LANE, 466910, Singapore	
Address type	Residential	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Female	
Marital status	Married	
Identification #	S1278773A	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

26/12/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

600

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

225/55R16

Front left side

MICHELIN6mm

Front right side

MICHELIN6mm

Rear Tyre Size

225/55R16

Rear left side

MICHELIN6mm

Rear right side

MICHELIN6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details				Vehicle & Driver Details		Vehicle Condition		Taxes & Ratio		Parts & Labour		Miscellaneous		Summary		Parts	
Add		Approve		Deny		Submit All											
	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE	
		1	1			BONNET (WCP) (10%)			Buckled	990				990	Reviewing		
		2	1			FRONT BUMPER COVER (WCP) (10%)			Damaged	935				935	Reviewing		
		3	10			FRT BUMPER CLAMP KIT (WCP) (10%)			Necessary	3.3				33	Reviewing		
		4	1			FRT BUMPER FILLING SPONGE (WCP) (10%)			Damaged	71.5				71.5	Reviewing		
		5	1			FRT BUMPER SUPPORT (WCP) (10%)			Bent	473				473	Reviewing		
		6	1			FRT CENTRE AIR GUIDE (WCP) (10%)			Damaged	88				88	Reviewing		
		7	1			FRT LOCK CARRIER			Repair	0	0	0	0	0	Deny		
		8	1			GRILLE (WCP) (10%)			Cracked	572				572	Reviewing		
		9	1			H/LAMP WASHER VALVE (WCP) (10%)			Cracked	110				110	Reviewing		
		10	1			R/F AIR GUIDE GRILLE (WCP) (10%)			Missing	71.5				71.5	Reviewing		
		11	1			R/F FOG LAMP (WCP) (10%)			Cracked	148.5				148.5	Reviewing		

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		12	1			R/F OUT BUMPER BRKT (WCP) (10%)			Bent	24.2				24,2	Reviewing	
		13	1			R/F WHEELHOUSE COVER			Serviceable	0	0	0	0	0	Deny	
		14	1			R/F WING (WCP) (10%)			Buckled	434.5				434,5	Reviewing	
		15	1			R/HEADLAMP MOUNTING (WCP) (10%)			Cracked	93.5				93,5	Reviewing	
		16	1			R/HEADLAMP MOUNTING (WCP) (10%)			Cracked	93.5				93,5	Reviewing	
		17	1			R/W-HOUSE SHIELD MTG			Serviceable	0	0	0	0	0	Deny	
		18	10			R/WING CLAMP KIT (WCP) (10%)			Necessary	2.2				22	Reviewing	
		19	1			RIGHT HEADLAMP ASSY (WCP) (10%)			Broken	968				968	Reviewing	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		PANEL / MECHANICAL	418.5	0	0	Reviewing		
		2		PAINTWORK	306	0	0	Reviewing		
		3		CORR PROT INTERNAL 3 WU	13.5	0	0	Reviewing		
		4		PAINT / MATERIAL COSTS	205.16	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR : 4 DAYS	Reviewing			
		2	FRT CLOSSING PART (WCP) (10%)	Reviewing	198	BENT (SUPPLEMENTARY)	
		3	R/F BUMPER BRACKET (WCP) (10%)	Reviewing	176	BENT (SUPPLEMENTARY)	
		4	AIRCON COOLANT	Deny	0	NOT NECESSARY	
		5	RADIATOR COOLANT	Deny	0	NOT NECESSARY	

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount

\$5,845.36

Claim Amount

\$5,845.36

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$5,128.20	\$5,128.20
Labour	\$943.16	\$943.16
Miscellaneous	\$374.00	\$374.00
Excess	-\$600.00	-\$600.00

Submit for Review