

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: IRENE JAMES HENRY

Date: 07 Jan 2019

Preliminary Advice

Vehicle No	: SLM4258L	Accident Date	: 20/12/2018
Make	: NISSAN SYLPHY	Policy No.	: D18MTPV01005886
Assignment Date	: 21/12/2018	Excess	: S\$0.00
Date of Inspection	: 04/01/2019	Est. Duration of Repair	: 5.00
Inspection At	: AUTOLUTION INDUSTRIAL PTE LTD (UBI) 19 UBI ROAD 4 SINGAPORE 408623		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,060.38
Revised Amount	:S\$	2,492.38
Check Items (Estimated)	:S\$	1,170.00
Total	:S\$	3,662.38

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	53,070.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,930.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :