

TRANS-CAB AUTO SERVICES PTE LTD

Francis

Not Noted
21 Sep @ 2300h

SHD 5444D -

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHD 5444D - Francis
JTDGJ20W305002260+
TOYOTA
WISH 2.0 BI-FUEL
19.09.2014
AXA

PART			LIST	
1	1	Front Bumper	\$	B ₁ 585.36 ✓
2	1	Front Bumper Retainer LH	\$	D ₁₁ 74.50 ✓
3	1	Front Bumper Retainer RH	\$	R 74.50 X
4	1	Front Bumper Lower Absorber	\$	S ₁ 130.00 X
5	1	Front Bumper Reinforcement	\$	R 318.11 X
6	1	Front Fender LH	\$	B ₁ 837.60 ✓
7	1	Front Fender Liner LH	\$	D ₁₁ 369.14 ✓
8	1	Front Fender Indicator lamp LH	\$	S ₁ 95.80 X
9	1	Front Headlamp LH	\$	C ₁₂₁ 672.00 ✓
TOTAL			\$	3,157.01
25%			\$	789.25
			\$	2,367.76

Special Nett

1Set	Bumper Fastener Clip	\$	A ₁ 50.00 ✓
1	CNG Sticker	\$	A ₁ 30.00 ✓
1 Set	Front Fender Liner Clip LH	\$	A ₁ 30.00 ✓
TOTAL		\$	110.00
TOTAL PARTS		\$	2,477.76

To Rust-Proofing Of The Affected Areas.	\$	220.00	30%
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The same	\$	1,400.00	40%
Putty And Spray Painting Of The Affected Portion.	\$	1,350.00	40%

TRANS-CAB AUTO SERVICES PTE LTD**Francis**

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 5444D -To check steering geometry and computer
wheel alignment\$ *NR* 220.00 *X*

To Check Electrical Lighting Concerned.

\$ 120.00 *2d***TOTAL** \$ 3,310.00**Over All Total** \$ 5,787.76**REPAIR DAYS***5 DAYS*
*2 day***LKK Auto Consultants** hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: