

ASS. REC. BY:

REF:

CS/FCI18022982/Uvd3

n2

Special Instruction:

Surveyor

Mat: 38

ASSIGNMENT (Office)

From (Person):

81/12/18

of

FCI

Date/Time:

11:15am 24/12/18

Estimated Cost:

Bill to:

OD (IT) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJA 8579X

Insured:

8HB 3232Y

at Workshop m/s

ZOOM Autowerks

Tel:

94507900

of

130 Bedok Reservoir Rd # 08-1339

Policy No:

Claim No:

D18008998MPSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

11:18am 24/12/18

Person Contacted:

Elin

Vehicle IN/OUT

Date/Time

Action/Instruction (✓)

Estimate Insp: 15 kaki Bukit Rd 4 #01-53

SJA 8579X - NA/INC1802294/24

DOA: 21/12/18

8HB 3232Y - NA/INC1802294/24

DOA: 21/12/18

26/12/18

Informed FCI pending workshop est by email

4/1/19

Email preli revised to FCI

ASSIGNMENT

Front: _____ Date: _____

Estimated Cost: _____

OD (TP / WS / TP RES / OD RES / EVA / INV / MV)

To Inspect Vehicle No: SJA 8579Xat Workshop m/s: Zoom Autoswales

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 24800

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 8 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

quality estimate 3 yrs 11 mths. net \$74434/1/19 2/5 \$6000 car fund with E/in (Red 646.48, 52/0)MV: \$24,500 (EST) LTA: \$17,057 NV: \$7443

RECEIVED 04 JAN 2019

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

u/i - typistReport Format: CWSLump Sum / I.B.I. (\$) 6000Days Of Repair: 8Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

2x15-30170+305050+50108+5408

463



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18008998MFSH

Our ref: CS/FC118022982/Uvd3

DATE: 4/1/2019

The Motor Claims Department
M/s: MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. SJA 8579X


We thank for your instruction on 29/12/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 24/12/2018 at the premises of M/s ZOOM AUTOWERKS PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$12,462.48
Revised Estimate Amount	: S\$6,000.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	21-12-2018	Our Ref No. D18008998MFSH
Accident Date	21-12-2018	Claim Type. Third Party
Insured Vehicle	SHB3232Y	Third Party Vehicle. SJA8579X
Survey Location	130 BEDOK RESERVOIR ROAD#08-1339	
Contact Person.	ELIN CAI	
Contact No.	94507920/ 94507920	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ZOOM AUTOWERKS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.



PRI Header Details

Claim No	D18008998MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & ZOOM AU
Workshop Name	ZOOM AUTOWERKS PTE LTD (Contact Person : ELIN CAI)	Survey Location & Contact Details	130 BEDOK RESERVOIR ROAD#08-1339 Mobile: 94507920 , Phone: 94507920 , Fax: 0 EmailId: ZOOMAUTOWERKS@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB3232Y	TP Vehicle No	SJA8579X
PRI Recieved Date	21-12-2018 10:44:22 PM	Surveyor Appointed Date	24-12-2018 11:15:02 AM	Surveyor Accept Date	24-12-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	24-12-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Date	Job Remarks	Action
------	-------------	--------

FINAL SUMMARY

Surveyor Final Adjusted Amount	Surveyor Fees	Remarks	

Submit Assessment

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 4 January 2019 11:10 AM
To: 'CWS Motor Claims'
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008998MFSH/1, SJA 8579X
Attachments: SJA 8579X PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SJA 8579X
Date of survey: 24/12/2018
Number of days : 8 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 26 December 2018 8:53 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008998MFSH/1, SJA 8579X

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SJA 8579X on 24/12/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 24 December 2018 11:22 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008998MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Monday, 24 December 2018 11:15 AM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D18008998MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.

www.avg.com

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 26 December 2018 8:53 AM
To: 'CWS Motor Claims'
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008998MFSH/1, SJA 8579X

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SJA 8579X on 24/12/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 24 December 2018 11:22 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008998MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 24 December 2018 11:15 AM
To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008998MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



altis

Price Range

Depreciation

> 10 year(s)

Vehicle Type

Home » Used Cars » Prime Motor & Leasing » Toyota Corolla Altis 1.6A (COE till 12/2021)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Toyota Corolla Altis 1.6A (COE till 12/2021)

Overview

Financial

Accessories

Similar

Research

Photos

Map



PRIME MOTOR & LEASING



(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)
 • PRIME CAR RENTAL & TAXI SERVICES PTE LTD • SECTION CREDIT & MOTOR LEASING PTE LTD • BEST PETROL AND DIESEL SUPPLY PTE LTD •

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$20,500	
Depreciation	\$6,900 /yr	?
Reg Date	15-Dec-2006 (2yrs 11mths 18days COE left)	
Manufactured	2006	?
Mileage	-	
Transmission	Auto	
Engine Cap	1,598 cc	
Road Tax	\$890 /yr	?
Power	81.0 kW (108 bhp) View specs of the Toyota Corolla Altis (2000-2007)	
Curb Weight	1,115 kg	?
Features	SRS Airbags, ABS, Reliable And Fuel Efficient 1.6L VVTI Engine, Climate Control Aircon, Multi Function Steering.	
Accessories	Leather Seats, Sports Rims, Audio System.	
Description	Elegant Toyota Altis, Low Fuel Consumption, Low Maintenance Cost, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-house Loan Packages Available.	
COE	\$25,636	?
OMV	\$15,498	?
ARF	\$17,048	?
Dereg Value	\$15,227 as of today (change)	?
No. of Owners	2	?
Type of Veh	Mid-Sized Sedan	



Location Map

Seller Information

Company	Prime » deale » 105 v availabl
Address	31 Wes Search
Location	West O
Office No	67782
Contact Person(s)	Danny Roy

Car Tyres



Compare



altis

Price Range

Depreciation

> 10 year(s)

Vehicle Type



Home » Used Cars » Heng Wei Motors Pte Ltd » Toyota Corolla Altis 1.6A (COE till 04/2022)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



Toyota Corolla Altis 1.6A (COE till 04/2022)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$21,800**Depreciation** \$6,520 /yr**Reg Date** 02-May-2007
(3yrs 4mths 4days COE left)**Manufactured** 2007**Mileage** 148,000 km (12.7k /yr)**Transmission** Auto**Engine Cap** 1,598 cc**Road Tax** \$816 /yr**Power** 81.0 kW (108 bhp)
View specs of the Toyota Corolla Altis (2000-2007)**Curb Weight** 1,115 kg**Features** Toyota 16V DOHC Vvti Engine, Smooth Auto ECT Transmission, Dual SRS Airbags, ABS, Digital Climate Control Aircon, Etc.**Accessories** All Original, Sports Rims, Leather Seats, Toyota Audio System C/w Woofer, Retractable Side Mirrors, Solar Film, Reverse Sensor, Steering Control.**Description** 2 Owners, Best Excellent Altis In Town! All Major Parts Including New Paint, Suspension, Fan Belt, Compressor, Etc Are Changed During COE Renewal. Trade-in/Bank/In-house Loan Available. View Now, Thanks!**COE** \$25,115**OMV** \$14,924**ARF** \$16,417**Dereg Value** \$16,803 as of today (change)**No. of Owners** 2**Type of Veh** Mid-Sized Sedan**Category** COE Car**Availability** Available

Seller Information

Company Heng
» dealer
» 5 veh

Address 15 Corr
Search

Location Commc

Contact Person(s) Mr Ong
Tony

Useful Services

Afraid of len
this car eval

Vehicle E

Compare

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2017 M/Benz CLA180 @ \$108,800 Only! 1.98% Int Rate!



R18 Facelift Model, 1.98% Int.
 Rate, Maintained By C&C.
 Almost New Car Condition
 Auto Zoom Enterprise StarAd

Aut
 An Inspiration

click here to view
 our **PRISTINE**
 at

Browse by Category

« Back (1 2 3 4 5 6) Next »

Sort by Date Posted

115 vehicles

altis

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	altis	Any	Any	> 10 year(s) old	Any	Any	
	Toyota Corolla Altis 1.6A (New 5-yr COE)	\$39,888	\$7,970 /yr	15-Dec-2008	1,598 cc	160,000 km	
Vehicle Well Maintained! Original Paintwork And Interior! Reliable Engine! No Major Repairs Needed! Low Depreciation! No Obligations! Bank Loans Available! Kindly Contact Our Sales Advisor ...							
Posted: 30-Nov-2018		Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota					
	Toyota Corolla Altis 1.6A (COE till 10/2020)	\$15,998	\$8,750 /yr	24-Oct-2005	1,598 cc	-	
Be Our Next Lucky Client To Own This Quality Pre-Owned Vehicle At Most Reasonable And Affordable Price. Rock Solid Altis! Fuel Consu 14km/L. Very High Paper Value! Minimum Controlled Lost! ST...							
Posted: 29-Nov-2018		Tags: 2005 Toyota Corolla, 2005 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota					
	Toyota Corolla Altis 1.6A (New 5-yr COE)	\$29,800	\$5,960 /yr	10-Sep-2008	1,598 cc	126,000 km	
\$2K Down Payment On Top Of Asking Price. 100% Flexible Loan Options Available! Lowest Price With Lowest Depreciation At \$6K Per Y Go, No Gimmicks! We Only Put Up The Good Condition Unit ...							
Posted: 29-Nov-2018		Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota					
	Toyota Corolla Altis 1.6A Elegance (OPC) (COE till 04/2028)	\$47,900	\$5,130 /yr	29-Apr-2008	1,598 cc	75,000 km	
1 Owner Only, Low Mileage For A 10 Years Old Car. Recently Just Serviced. Superb Car For Daily Usage. Super Reliable Toyota Corolla A Immaculate Condition Inside Out. Consignment Unit. Selling Wi...							
Prem Roy Motoring							
Posted: 26-Nov-2018		Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota					

**GET YOUR
 COE
 RENEWAL
 LOAN**

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in tow approval in 2 days without effort! Enquire today.

Compare

ita Corolla Altis 1.6A (COE \$29,888 \$6,300 /yr 24-Sep-2008 1,598 cc 123,352 km

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3468E
Vehicle Details	
Vehicle No.:	SJA8579X
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	3ZZ4697564
Chassis No.:	MR053ZEC107155259
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$14,757.00
Original Registration Date:	26 Dec 2007
First Registration Date:	26 Dec 2007
Transfer Count:	2
Actual ARF Paid:	\$16,233.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Dec 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$21,349.00
COE Rebate Amount:	\$17,057.00
Total Rebate Amount:	\$17,057.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Dec 2018

OK



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

02 January 2019

D.O.A : 21 December 2018

OWNER : CHEW PENG SAN

REG NO. : SJA 8579 X

MAKE/MODEL : TOYOTA ALTIS

Not Allowed
2/5 6000/-
24/1/18

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Rear windscreen moulding	\$ 11 89.50 X
1	Rear boot lid	\$ But/Buc 733.80 ✓
2	Rear boot hinges	\$ 2 133.80 X
2	Rear boot lamps	\$ one 379.30 ✓
1	Rear boot lock	\$ Turf 126.70 ✓
1	Rear boot lock catch	\$ 11 66.90 X
1	Rear boot logo	\$ 11 38.50 X
1	Rear boot "COROLLA" emblem	\$ 11 47.40 ✓
1	Rear boot "ALTIS" emblem	\$ 11 38.60 ✓
1	Rear boot "1.6" emblem	\$ 11 32.40 ✓
1	Rear boot "E" emblem	\$ 11 31.50 ✓
1	Rear boot "VVT-I" emblem	\$ 11 36.50 ✓
1	Rear boot outer chrome moulding	\$ 11 158.50 X
1	Rear boot number plate garnish	\$ 11 165.90 X
2	Rear boot number plate lamps	\$ 11 84.40 X
2	Rear taillamps	\$ one 721.90 ✓
2	Rear taillamp panels	\$ But/Buc 897.90 ✓
2	Rear apron panels	\$ But 179.90 ✓
1	Rear end panel	\$ But/Buc 777.30 ✓
1	Rear end panel inner garnish	\$ Turf 89.80 ✓
1	Rear bumper	\$ 11 486.60 ✓
2	Rear bumper brackets	\$ 11 117.00 IPC
2	Rear bumper side retainers	\$ But 73.80 ✓
1	Rear floor panel	\$ rumped/buc 647.20 ✓
1	Rear floor board	\$ Turf 186.90 ✓
1	Rear exhaust silencer	\$ 11 589.70 X
2	Rear exhaust mountings	\$ 11 58.40 X
2	Rear fenders	\$ 2 1,575.20 X
2	Rear fender air gates	\$ 11 175.00 X
2	Rear fender inner shields	\$ 11 111.20 X
2	Rear fender inner trims	\$ 11 579.80 IPC
		\$ 9,431.30
	Less 25%	\$ 2,357.83
		\$ 7,073.48

Less 25%

5678.7
25%
4259.02

SPECIAL NETT ITEMS

1	Rear windscreen sealant	\$ 11	80.00	X
4	Rear apron panel reverts	\$ rec	34.00	✓
1	Rear bumper clip (1 set)	\$ rec	45.00	✓
1	Rear reverse sensor (1 set)	\$ shock	350.00	200
		\$	509.00	
			279	

S/N LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	30
2	To remove and refit inner garnishes.	\$	150.00	80
3	To remove and refit rear reverse sensor.	\$	150.00	50
4	To transfer boot lid mechanism and wiring assembly.	\$	120.00	60
5	To remove and refit rear windscreen glass.	\$ 11	180.00	X
6	To remove, refit and replace exhaust silencer and mountings.	\$	150.00	60
7	To apply undercoating.	\$	250.00	100
8	Panel beating.	\$	2,000.00	1400
9	To re-spray painting on the affected areas.	\$	1,800.00	1200
		\$	4,880.00	
			2980	

GRAND TOTAL :**\$ 12,462.48**

Let Auto Consultants hence notify the Repairs of the following:

- To survey before/after spray painting
- To survey damaged part(s) during resurvey
- Repairs must be subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

P-4259.02
S-2279.00
10km-2980.00
75-18.02
6014.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18022982/Uvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-01-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3232Y	Veh. Inspected	SJA 8579X	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18008998MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	24/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	MR053ZEC107155259	Colour	GREY	
Odometer	229631	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	BFGOODRICH	6 mm	
L/H Front Tyre	195/65 R15	BFGOODRICH	6 mm	
R/H Rear Tyre	195/65 R15	BFGOODRICH	6 mm	
L/H Rear Tyre	195/65 R15	BFGOODRICH	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/12/2018	Inspection Date	24/12/2018	
Survey held at	15 KAKI BUKIT ROAD 4# 01-53			
Repairer	ZOOM AUTOWERKS PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJA 8579X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	89.50	-
1	REAR BOOT LID	BENT / BUCKLED	733.80	733.80
2	REAR BOOT HINGES	TO REPAIR SEE LABOUR	133.80	-
2	REAR BOOT LAMPS	CRACKED	379.30	379.30
1	REAR BOOT LOCK	TWISTED	126.70	126.70
1	REAR BOOT LOCK CATCH	NOT NECESSARY	66.90	-
1	REAR BOOT LOGO	NOT NECESSARY	38.50	-
1	REAR BOOT "COROLLA" EMBLEM	NECESSARY	47.40	47.40
1	REAR BOOT "ALTIS" EMBLEM	NECESSARY	38.60	38.60
1	REAR BOOT "1.6" EMBLEM	NECESSARY	32.40	32.40
1	REAR BOOT "E" EMBLEM	NECESSARY	31.50	31.50
1	REAR BOOT "VVT-I" EMBLEM	NECESSARY	36.50	36.50
1	REAR BOOT OUTER CHROME MOULDING	NOT NECESSARY	158.50	-
1	REAR BOOT NUMBER PLATE GARNISH	NOT NECESSARY	165.90	-
2	REAR BOOT NUMBER PLATE LAMPS	NOT NECESSARY	84.40	-
2	REAR TAILLAMPS	CRACKED	721.90	721.90
2	REAR TAILLAMP PANELS	DENTED / BUCKLED	897.90	897.90
2	REAR APRON PANELS	BENT	179.90	179.90
1	REAR END PANEL	BADLY DENTED	777.30	620.10
1	REAR END PANEL INNER GARNISH	TWISTED	89.80	89.80
1	REAR BUMPER	DISTORTED	486.60	486.60
2	REAR BUMPER BRACKETS	N/S BENT	117.00	58.50
2	REAR BUMPER SIDE RETAINERS	BENT	73.80	73.80
1	REAR FLOOR PANEL	CRUMPLED / BUCKLED	647.20	647.20
1	REAR FLOOR BOARD	TORN	186.90	186.90
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	589.70	-
2	REAR EXHAUST MOUNTINGS	NOT NECESSARY	58.40	-
2	REAR FENDERS	TO REPAIR SEE LABOUR	1,575.20	-

Report Ref No. CS/FCI18022982/Uvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER AIR GATES	NOT NECESSARY	175.00	-
2	REAR FENDER INNER SHIELDS	NOT NECESSARY	111.20	-
2	REAR FENDER INNER TRIMS	N/S TORN	579.80	289.90
	LESS 25% DISCOUNT		-2,357.82	-1,419.67
			7,073.48	4,259.03
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
4	REAR APRON PANEL REVERTS (SN)	NECESSARY	34.00	34.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	45.00	45.00
1	SET REAR REVERSE SENSOR (SN)	SHORTED	350.00	200.00
			509.00	279.00
	<u>LABOUR</u>			
	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING.		80.00	30.00
	TO REMOVE AND REFIT INNER GARNISHES.		150.00	80.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR.		150.00	50.00
	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY.		120.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	180.00	-
	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS.		150.00	60.00
	TO APPLY UNDERCOATING.		250.00	100.00
	PANEL BEATING,INCLUSIVE OF THE REPAIR OF REAR BOOT HINGES,REAR EXHAUST SILENCER AND REAR FENDERS.		2,000.00	1,400.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.		1,800.00	1,200.00
			4,880.00	2,980.00
	GRAND TOTAL		12,462.48	7,518.03

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,000.00
---	--	--	-----------------

Report Ref No. CS/FCI18022982/Uvd3n2

MARKET VALUE: \$24,500.00 (EST)-LTA REIMBURSEMENT VALUE: \$17,057.00=NETT VALUE: \$7,443.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.