

LKK Auto

SMRT AUTOMOTIVE SERVICES PTE LTD

60 Woodlands Industrial Park E4 Singapore 757705

Tel: 65 6866 2652 Fax: 65 6368 7421 www.smrt.com.sq

ate: 24.2.19

Our Ref .: TAx / 11 / 18 / 2075 / 57

Dear Sirs.

ON 20.12.18 ALONG HENDESON Rd function Bukit Menh Central

LETTER OF CLAIM

Your insured's negligent driving has caused the above accident. As a result, my client has suffered the following losses:-

1.	Cost of Repair	:2	\$	2	394-13
2	Loss of Rental for 6/14 days @ S\$ 11.35 /day	10	\$		758.36
3.	Loss of Income for 63 4 days @ S\$ 60.00 /day	5	\$		405.00
4.	Police Report/ SAS Report/ LTA Search Fee	9	\$		7.00
5.	Survey Fee	3	\$	20	7.00
6.	Others		_		
	Total Claims	3	\$	3 5	64 49

We enclose the following documents:-

Х	Repair Invoice	X	Vehicle laid-up report
Х	Police Report / SAS Report	X	LTA Search result
Х	Letter of Authorisation		Others 1
	Investigation results	1	
Х	Proof of Loss of Use/Rental/Income	2	

We look forward to your confirmation to settle our claims within 15 days from the date of this letter. Payment by cheque shall be crossed and made payable to **SMRT TAXIS PTE LTD**.

Yours sincerely,

SMRT AUTOMOTIVE SERVICES PTE LTD

Selena Tan

For Manager, Claims Claims Department Direct line: 6866 2653

Email address: tanselena@smrt.com.sg

AUTHORIZATION TO ACT

INDUSTRIAL PARK E4 (S) 757705 (address), owner of SHB 5158R (vehicle no.) hereby authorize SMRT AUTOMOTIVE SERVICES PTE LTD ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no SHB 5158R that was damaged pursuant to the accident which occurred on 20/12/2018 (date) along HENDERSON ROAD JUNCTION BUKIT MERAH CENTRAL (location) involving vehicle no/s SLA 446A ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of SMRT TAXIS PTE LTD.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 9th (day) of December (month) 2019 (year)

Signed by "the third party claimant" (with chop if applicable) Signed by "the workshop" (with chop)

DISCHARGE VOUCHER

Without Prejudice Save As to Costs

Your Reference :

TAX/12/18/2079/ST

Our Reference :

VC012276

I/We, SMRT TAXIS PTE LTD do hereby acknowledge the sum of Singapore Dollars: THREE THOUSAND THREE HUNDRED SEVENTY FIVE AND CENTS TWENTY THREE ONLY (S\$3,375.23) being full discharge and satisfaction of all claims against QBE Insurance (Singapore) Pte Ltd and their Insured, 'CHUA CHEE YONG', over damage to my/our vehicle SHB 5158R from an accident involving SLA 446A at/along HENDERSON ROAD JUNCTION BUKIT MERAH CENTRAL, which occurred on 20/12/2018 at about 07:30hours.

Further, I/we hereby acknowledge and accept that the above said sum paid to me is 'strictly on a without admission of liability basis' and I/we hereby discharge and release the said QBE Insurance (Singapore) Pte Ltd and their Insured 'CHUA CHEE YONG', from all claims, demands or action of damages as a result of the said accident.

Also, I/we hereby agree to indemnify and keep indemnified the said QBE Insurance (Singapore) Pte Ltd against all and any claims whatsoever made or to be made by any person or persons on my/our behalf in respect of the said accident.

Dated this (day) of (month)	December (year) 2019
Signature Selena Tan Claimant's Name	Witness's Signature Witness's Name
198905369K	SXXXX362I FIN/NRIC No.
Address	Address
60 Woodlands Industrial Park E4 Singapore 757705 Tel: 55 6482 3888 Fax: 65 6368 7421	Please return to: General Claims Department QBE Insurance (Singapore) Pte Ltd 1 Raffles Quay #29-10 South Tower Singapore 048583 Fax: 6534 5356

Company stamp if applicable



Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4

SINGAPORE 757705



SMRT Automotive Services Pte Ltd 251 North Bridge Road Singapore 179102 Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7 CRN : 199004280Z Invoice No. : IV190100474 Date : 25.01.2019 Vehicle No. : SHB5158R

Your Ref No. : TAX/12/18/2079

Our Ref No. : 24099327 Terms : 30 Days

Description		Qty Unit			1	(Discount)			Amount
			Cost	- 8	_	Amount		_	
Parts									
SENSOR REVERSE	1.00	\$	180.00	0.00		\$	0.00	\$	180.00
REAR BUMPER REINFORCEMENT	1.00	\$	318.80	(25.00)	\$	79.70	\$	239.10
COVER, RR BUMPER ASSY	1.00	S	423.90	(25.00	1	\$	105.97	\$	317.93
CLIPS PIECE, FRT & RR BUMPER	10.00	\$	1,50	(25.00)	\$	3.75	\$	11.25
PAD, RR BUMPER, RH & LH , 1	2.00	ş	3.80	(25.00	3	\$	1.90	S	5.70
PAD, RR BUMPER, RH & LH , 2	2.00	\$	3.80	(25.00	3	\$	1.90	S	5.70
PAD, RR BUMPER, RH & LH , 3	2.00	\$	3.80	(25.00	1	\$	1.90	5	5.70
SEAL, RR BUMPER ARM, RH & LH	2.00	\$	11.00	(25.00	7	\$	5.50	ş	16.50
SEAL, RR BUMPER , RH	0.00	\$	85.20	0.00		\$	0.00	S	0.00
FILLER, RR BUMPER , RH	1.00	\$	119.90	[100.0	01	\$	119.90	S	0.00
SENSOR REVERSE	0.00	\$	180.00	0.00		ş	0.00	S	0.00
PIXEL STICKER	2.00	\$	60.00	0.00		\$	0.00	S	120.00
RETAINER, RR BUMPER, RH	0.00	\$	112.70	0.00		S	0.00	ş	0.00
STOPPER, RR BUMPER, RH & LH	1.00	\$	4.30	(25.00	2	\$	1.07	Ş	3.2
REAR BUMPER GROMMET SCREW	1.00	\$	2.20	(25.00)	\$	0.55	\$	1.6
REAR BUMPER REINFORCEMENT	0.00	\$	318.80	0.00		\$	0.00	\$	0.0
GUARD, RR BUMPER, LOWER	1.00	\$	558.30	(25.00	3	\$	139,57	\$	418.7
COVER, GUARD RR BUMPER LOWER	1.00	s	14.80	(25.00	1	5	3.70	\$	11.1
PAD, RR BUMPER, CTR	3.00	\$	2.20	(25.00	3	\$	1.65	\$	4.9
CLIP , FLOOR UNDER COVER , NO.1	0.00	Ś	2.60	0.00		\$	0.00	\$	0.0
CLIP , FLOOR UNDER COVER , NO.2	0.00	S	3.20	0.00		\$	0.00	\$	0.0
COVER, REAR FLOOR UNDER , RH	0.00	S	169.50	0.00		s	0.00	\$	0.0
COVER, REAR FLOOR UNDER CENTER	0.00	5	222.60	0.00		S	0.00	\$	0.0
TAIL GATE PANEL SUB-ASSY, BACK DOOR	0.00	Ş	929.60	0.00		s	0.00	\$	0.0
TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1.00	5	891.20	(100.0	0)	5	891.20	\$	0.0

Authorised Signature

for SMRT Automotive Services Pte Ltd



Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4

SINGAPORE 757705

SMRT Automotive Services Pte Ltd 251 North Bridge Boad Singapore 179102 Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7 CRN : 199004280Z Invoice No. : IV190100474 Date : 25.01.2019 Vehicle No. : SHB5158R

Your Ref No. : TAX/12/18/2079

Our Ref No. : 24099327 Terms : 30 Days

Description	Qty Uni			Add	1	(Di	scount)		Amount
			Cost	8		Ar	mount		
EMBLEM SUB-ASSY REAR	1.00	S	46.30	(25.00)	\$	11.57	\$	34.73
NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	1.00	3	52.30	(25.00)	\$	13.07	9	39.23
NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1.00	\$	52.30	(25.00	E	S	13.07	05	39.23
NUMBER PLATE FRAME	0.00	\$	25.00	0.00		\$	0.00	\$	0.00
SMRT LOGO	1.00	S	7.80	0.00		s	0.00	Ş	7.80
STICKER DECAL 6555 8888	1.00	S	21.60	0.00		\$	0.00	S	21.60
TAIL GATE WEATHERSTRIP, BACK DOOR	0.00	\$	360.70	0.00		\$	0.00	S	0.00
END PANEL SUBASSY, BODY LOWER BACK	0.00	Ş	629.80	0.00		ş	0.00	\$	0.00
ADHESIVE: DIRECT GLAZING	0.00	S	37.00	0.00	_	\$	0.00	s	0.00
					Su	b-To	tal	\$	1484.13
Labour									
TO REPAIR REAR END PANEL	1.00	\$	100.00	0.00		\$	0.00	ş	100.00
TO REPAIR RH REAR PORTION		\$	300.00	0.00		\$	0.00	S	300.00
Others									
TO RESPRAY REAR PANEL	1.00	Ş	100.00	0.00		\$	0.00	Ş	100.00
TO REPSRAY REAR BUMPER	1.00	\$	200.00	0.00		\$	0.00	\$	200.00
TO RESPRAY FILLER RR BUMPER RH	1.00	\$	50.00	0.00		ş	0.00	Ş	50.00
TO RESPRAY BUMPER BEAM	0.00	\$	180.00	0.00		\$	0.00	\$	0.00
TO RESPRAY TAIL GATE	0.00	ş	378.00	0.00		\$	0.00	S	0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	1.00	\$	100.00	0.00		\$	0.00	Ś	100.00
TO RESPRAY REAR PANEL	0.00	Ş	180.00	0.00		\$	0.00	ş	0.00
TO CHECK WIRING AND SYSTEM FUNCTION	1.00	\$	20.00	0.00		\$	0.00	\$	20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	1.00	ş	20.00	0.00		\$	0.00	9	20.00

Authorised Signature

for SMRT Automotive Services Pte Ltd



Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4

SINGAPORE 757705

SMRT Automotive Services Pte Ltd 251 North Bridge Road Singapore 179102 Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7 CRN : 1990042802 Invoice No. : IV190100474 Date : 25.01.2019 Vehicle No. : SHB5158R

Your Ref No. : TAX/12/18/2079

Our Ref No. : 24099327 Terms : 30 Days

Description	Qty	Unit	Add	1	(Dis	count)		Amount
		Cost	1	Amount				
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	0.00	\$ 120.00	0.00		\$	0.00	\$	0.00
TO REMOVE AND REFIT WIRE HARDESS	1.00	\$ 20.00	0.00		S	0.00	3	20.00
TO REPLACE SUNDRY PARTS	0.00	\$ 100.00	0.00		S	0.00	\$	0.00
TO WASH AND VACUUM	0.00	\$ 60.00	0.00		\$	0.00	ş	0.00
			GRA	ND	TOTA	L	\$	2,394.1

Remark :

Make/Model : PRIUS4 Accident Date : 19.12.2018

N.B. Payment by cheque should be crossed and made payable to 'SMRT Automotive Services Pts Ltd'. No receipt will be issued unless requested.

Authorised Signature

for SMRT Automotive Services Pte Ltd



SMRT Taxis Pte Ltd

MEMORANDUM

To:

Claims Dept

Our Ref: TAX/12/18/2079/ST

From: SMRT Taxis Pte Ltd

Date:

15.1.2019

ACCIDENT INVOLVING SHB5158R & SLA446A ON 20.12.2018 ALONG HENDERSON ROAD JUNCTION BUKIT MERAH CENTRAL

This is to certify that Mr. Teo Kok Seng of IC No. S0010937A is the registered hirer of the above taxi no. SHB5158R.

This is also to confirm that the daily rental rate for SHB5158R is \$112.35.

Please proceed to recover any rental loss from the third party as a result of the above accident.

Thank you.

Yours sincerely SMRT TAXIS PTE LTD

for Manager



Laid Up Report

Accident Start Date: 20/12/2018

Accident End Date : 20/01/2019

Date Generated: 29/01/2019

User Name : TanSelena

Date and Time (Repair Completed)	26/12/2018 3:36 PM
Date and Time (Accident Repair)	20/12/2018 9:00 AM
Job Card Number	24099327
Vehicle Model	PRIUSA
Vehicle Make	TOYOTA
Company Type	SMRT Taxis Pie Lid
Vehicle Registration Number	SHB5158R
Case Reference Number	TAX/12/18/2079

32 12 - 169 33 12 - 1669 34 12 - 1663 25.12 - 1day 20 12 - 1dey N. 13 - 1 dy

Enquire Transaction History

Transaction History Details

Log Date/Time:

20 Dec 2018 / 16:44:01

Asset Type: Asset ID:

User ID:

Vehicle

Transaction Type:

SLA446A

18.32 Insurance Enquiry (GIRO Payment) Channel:

ESASBAHO - BALQISH BINTE ABDUL

HALIL

External Agency

Business Transaction Reference No.:

Transaction Amount:

20181220164401874666

Search Date / Time:

20 Dec 2018 07:32:00

Insurance Company:

QBE INSURANCE (SINGAPORE) PTE LTD

Information displayed is correct as at the log date and time.

Enquire Related Logs

Back to List

Jia Le (LKK Auto)

From:

Jenny Toh <jenny.toh@qbe.com>

Sent:

Monday, 9 December 2019 10:33 AM

To:

Jia Le (LKK Auto)

Cc:

claims-singapore

Subject:

[VC012276] Direct Settlement - Accident Involving SLA446A (OI: QBE - TBA) AND

SHB5158R (TP: LKK REF - CC3/QBE18023000/Jda3) on 20/12/2018

Attachments:

LKKInspection.pdf; LKKAdjustment1.pdf; SURVEY PHOTO.pdf; RESURVEY

PHOTO.pdf; LOD.pdf

Hi Jia le

Kindly proceed with settlement.

regards

Jenny Toh

Senior Assistant

Claims / Asia

1 Raffles Quay, #29-10 South Tower, Singapore 048583

+65 6224 6633 | +65 6477 1225

Website

LinkedIn

Twitter



From: Jia Le (LKK Auto) < JiaLe@lkkauto.com>

Sent: Monday, 9 December 2019 9:46 AM

To: Jenny Toh <jenny.toh@qbe.com>; Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving SLA446A (OI: QBE - TBA) AND SHB5158R (TP: LKK REF -

CC3/QBE18023000/Jda3) on 20/12/2018

Your ref: TBA

Our ref: CC3/QBE18023000/Jda3

Dear Sirs/Madam,

ACCIDENT INVOLVING SLA 446A(OI) & SHB 5158R(TP) ON 20/12/2018

We refer to the above matter.

It is a head-to-rear collision. Liability is not in our driver's favour.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer Third Party repairer "SMRT AUTOMOTIVE SERVICES PTE LTD" at \$3,375.23(all-in).

The summary is as follows: -

		Amount Claimed		mount Revised
1. Cost of Repair (w/GST)		9,387.80	\$	2,394.13
2. Loss of Rental (6.75days x \$112.35)	\$	758.36	\$	674.10 (6days x \$112.35)
3. Loss of Income (6.75 x \$60)	\$	405.00	\$	300.00 (6days x \$50)
4. LTA/ GIA Search Fee	\$	7.00	\$	7.00
Total	al \$1	10,558.16	\$	3,375.23

^{**04} days recommendation for repair + 1Sun +1PRS = 6days.

Enclosed here with all the relevant documents for your perusal.

For your approval/instruction please.

Best Regards,

Chan Jia Le | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: <u>Jiale@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Goh Siew Geok [mailto:janice.goh@gbe.com]

Sent: Tuesday, 8 October 2019 10:02 AM

To: Mei Kwan (LKKAuto)

Cc: Jia Le (LKK Auto); Admin A; Jenny Toh

Subject: RE: Direct Settlement - Accident Involving SLA446A (OI: QBE - TBA) AND SHB5158R (TP: LKK REF -

CC3/Q8E18023000/Jda3) on 20/12/2018

Hi Mei Kwan

As requested, please refer to the attachment.

Thank you.

Executive, Claims Claims | Asia

1 Raffles Quay, #29-10 South Tower, Singapore 048583 +65 6477 1243





From: Mei Kwan (LKKAuto) < Meikwan@lkkauto.com>

Sent: Tuesday, 8 October 2019 9:53 AM

To: Jenny Toh <jenny.toh@qbe.com>; Janice Goh Siew Geok <janice.goh@qbe.com>

Cc: Jia Le (LKK Auto) < JiaLe@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving SLA446A (OI: QBE - TBA) AND SHB5158R (TP: LKK REF -

CC3/QBE18023000/Jda3) on 20/12/2018

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

Sent: Monday, 24 December, 2018 3:18 PM

To: 'Jenny Toh' <jenny.toh@gbe.com>

Cc: KKLau <kklau@lkkauto.com>; Poh Kin (LKKAuto) <pohkin@lkkauto.com>; Vic (LKKAuto)

<vicalpeh@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: Direct Settlement - Accident Involving SLA446A (OI: QBE - TBA) AND SHB5158R (TP: LKK REF -

CC3/QBE18023000/Jha3) on 20/12/2018

WITHOUT PREJUDICE

Dear Jenny,

We refer to the above matter.

We have received a new assignment from M/s SMRT Automotive Services Pte Ltd - Woodlands.and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary Advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE: The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.