



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D

GST REG. NO.: 19-9501140-D

TAY MEE LING
C/O FALCON-AIR AUTO SERVICES PTE LTD
NO. 8 PANDAN LOOP

Attention : Motor Claim Department

Contact : 97204037

Estimate : ES003357

Date : 24/12/2018

Vehicle Num. : SJE7741D

Make/Model : NISSAN LATIO

Chassis/Eng# :

Accident Date : 20/12/2018

Claim No. :

Reference : TP CLAIM - TMIS vs AXA

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		TO REPAIR RH FRONT FENDER, FRONT BUMPER		350.00
		SPRAY PAINTING ON RH FRONT FENDER, FRONT BUMPER,		550.00
		RH FRONT WHEEL HUB CAP		
		Labour Total S\$:		900.00

E. & O.E.

Total S\$: 900.00

for FALCON AIR AUTO SERVICES PTE LTD

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ■ No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg