

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

24-Dec-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6033 E

1 pc	Bootlid emblem ✓ ✓	\$	27.00
1 pc	Bootlid CRDi ✓ ✓	\$	29.00
1 pc	Boot lid rubber weatherstrip X	\$	96.00
1 pc	End panel X	\$	250.00
1 pc	End panel garnish X	\$	74.00
1 pc	Rear bumper ✓	\$	696.00
1 pc	Rear bumper lower cover X <i>repair</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 X	\$	58.00
1 pc	Rear bumper inner sponge X	\$	114.00
1 pc	Rear bumper reinforcement X	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 X	\$	106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 X	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 X	\$	36.00
2 pcs	Rear bumper reflector o/s & n/s @ \$23.00 X	\$	46.00
		\$	2,381.00
		Less 10%	\$ 238.10
		\$	2,142.90

S/NETT

1 set	Rear bumper clips ✓	\$	48.00
1 set	End panel inner garnish clips X	\$	30.00
1 set	Bootlid lower garnish clips X	\$	60.00
1 set	Bootlid stickers ✓	\$	100.00
1 set	Reverse sensor ✓	\$	280.00 200
1 pc	Rear bumper top protector X	\$	80.00

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6033 E

Sundry	\$	50.00 20
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 X
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, Including knock-out, straighten, repair, reshape and adjust of the bootlid, bootlid lower garnish, etc.	\$	900.00 300
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel	\$	900.00 540
To apply rustproofing on the repaired and replaced panels.	\$	150.00 X
	\$	<u>5,040.90</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kalvin UKE
M 26/12/18 1005 hrs
3 Days
4/5
Alfa Repair p.ltd.