



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER: India International Insurance Pte Ltd (HQ)
UNKNOWN

Singapore

Claimant Insurer: HL Assurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	18/12/2018
Vehicle Reg. No.:	SKU3139Z	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	ONG JUNXIONG (WANG JUNXIONG)		
Make/Model:	MAZDA 3, 1.5 4 DOOR SEDAN SP (A)	Vehicle Reg. Date:	16/07/2015
Vehicle Colour:	GREY	Chassis No:	JM6BM42A8G0313058
Engine No:	P520295499		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %	Nett Item Discount:	10.00 %
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	-		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	2,364.80
Miscellaneous Items	10.00
Labour	1,280.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,654.80
+ GST 7.00% (S\$)	255.84
Nett Amount (S\$)	3,910.64

This claim is handled by: JACELYN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 24 Dec 2018)

Parts: 143 **MAZDA 3 1.5 4 DOOR SEDAN SP (A)** (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Mova Automotive Pte Ltd/SKU3139Z/24/12/2018 16:34

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*HEADLAMP LH	20.00	0.00	*795.00 FL
2	1		*HEADLAMP LOWER BRACKET LH	20.00	0.00	*25.00 FL
3	1		*FRONT BUMPER	20.00	0.00	*945.00 FL
4	1		*FRONT BUMPER SIDE RETAINER LH	20.00	0.00	*25.00 FL
5	10		*FRONT BUMPER CLIPS	20.00	0.00	*50.00 FL
6	1		*FRONT FOGLAMP GARNISH LH	20.00	0.00	*55.00 FL
7	1		*FRONT FENDER LH	20.00	0.00	*368.00 FL
8	1		*FRONT FENDER COWLING LH	20.00	0.00	*98.00 FL
9	10		*FRONT FENDER COWLING CLIPS	20.00	0.00	*50.00 FL
10	1		*FRONT WHEEL BEARING LH	20.00	0.00	*545.00 FL
11	1		*FRONT WHEEL LH - REPAIR	20.00	0.00	-

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,956.00
- List Item Discount on L Items (\$\$)	591.20
Total Parts (\$\$)	2,364.80

Mova Automotive Pte Ltd/SKU3139Z/24/12/2018 16:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO INSPECT FRONT LIGHTING MECHANISM	New	50.00
2	TO REPAIR FRONT WHEEL LH	New	100.00
3	TO REPLACE UNDERCARRIAGE DAMAGED ITEMS	New	100.00
4	TO REMOVE & REPLACE DAMAGED ITEMS, REALIGN CONNECTION	New	400.00
5	TO SPRAY PAINT ON REPAIRED AREAS	New	500.00
6	TO CHECK WHEEL ALIGNMENT	New	80.00
7	TO CONDUCT TYRE BALANCING	New	50.00
Gross Labour Cost (S\$)			1,280.00

Mova Automotive Pte Ltd/SKU3139Z/24/12/2018 16:34. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >