

ASS. REC. BY:

REF

OS/MSG18023148/Uq03n2

Special Instruction

Surveyor
Menimen

Marcus
Pauline Tham

ASSIGNMENT (Office)

of MSG

Date/Time 27/12/15 @ 10:15am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GX 8826S

Insured:

YN1866S

at Workshop m/s

Liu's Brother

Tel:

67411730

of

1 Kaki Bukit Ave 6 #01-01

Policy No:

2899 2363 MLC

Claim No:

580004

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/07/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10:20am @ 27/12/18

Person Contacted:

Susun

Vehicle

(IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	GX 8826S - CS / RT16016870 / Uq03n2
	YN1866S - X
31/12/18 @ 11:20am	Informed Pauline Tham, we are pending estimate from repairer.
27/12/18 @ 2:07pm	Revised to Pauline Tham via Menimen.

ASS. REC. BY: *MAJUS*

REF:

MSIG /
ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: *6488265*at Workshop m/s *1st BN*

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *146.*

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *4* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *6488265*Yr Regn: *9.05*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *CM*Make: *Nissan cabstar* c.c. *3153*Colour: *white* A/C: Insured / Std / NI / NASp. Reading: *646577* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *JN1SF4F2320860154*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: *Inorder* / Jammed / Leaked / Burnt orBrake: *Inorder* / Jammed / Leaked / Burnt orModi: *Nil* / S/Rim / STD A/Rim orTyre Size: F: *195-215*R: *155-212*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. *6* mm R/Bal. *6/6* mmL/Bal. *6* mm L/Bal. *6/6* mmD.O.A. *18/7/18* D.O.I. *28/12/18*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear
The U/C / Chassis frame / Body Structure affected due to collision.Date / Time Action / Instruction *CR 12-9-2020**2 prs. wh. 21A 8514**22/2/19 confd +/5 \$1600 with sus. (red B3552-60, 69%)*

RECEIVED 25 FEB 2019

Date/Time, File Pass to?

1) *2/2/19* ☐ : Preli. Report
☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: *4*Resurvey No. of Trip: *1*

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) *S + RS* *SI*☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)

TOTAL

Report Format: *MT2 TP*Lump Sum / I.B.I. (\$) *1600*

150
10
160

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 22 Feb 2019

Preliminary Advice

Insured Vehicle No	: YN1866S		
TP Vehicle No	: GY8826S	Accident Date	: 18/07/2018
Make	: NISSAN CABSTAR	Assignment Date	: 27/12/2018
Date of Inspection	: 28/12/2018	Est. Duration of Repair	: 4.00
Inspection At	: LIU'S BROTHER AUTO WORKSHOP (HQ) 1 KAKI BUKIT AVE 6 #01-01, AUTO BAY@KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,152.60
Revised Amount	:S\$	2,060.25
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,060.25
 Lump Sum Repair	 :S\$	 1,600.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis. KINDLY ASSIST TO AMEND THE MAKE & MODEL OF GY 8826S TO NISSAN CABSTAR (3153cc) INSTEAD OF NISSAN CABSTAR 3.0.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Dec 2018		27 Dec 2018 10:15 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	FROSTS FOOD & BEVERAGE (PTE) LTD, Co. Reg. No.: 198302507K		
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N		
Vehicle Reg. No.:	GY8826S	Date of Loss:	18/07/2018 00:00 - :59 [154 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 580004	Policy/Cover Note No.:	28992363MKC Coverage: 01/08/2017 - 31/07/2018
Vehicle Reg. No. (Insured):	YN1866S	Policy No. (Claimant):	
		Excess:	
Repairer:	LIU'S BROTHER AUTO WORKSHOP (HQ) 1 Kaki Bukit Ave 6 #01-01, Auto Bay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6741-1730/1731		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/12/2018]		
Adj Asg. Remarks:	on WP. OI NON REPORTING. LIABILITY UNCLEAR. TP agree with SJE - assign Marcus Chua of LKK Auto Consultants Pte Ltd		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Monday, 31 December 2018 11:20 AM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE GY 8826S (YOUR REF: 580004)

This mail is associated with :

***GY8826S (580004)**

[YN1866S]

TP

GOLDBELL LEASING PTE LTD

Jul 18 2018 12:00AM

[FROSTS FOOD & BEVERAGE (PTE) LTD]

LIU'S BROTHER AUTO WORKSHOP

Dear Pauline,

Please be informed that we have inspected the vehicle GY 8826S on 28/12/2018.

We are pending estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

NESCAFE Dolce Gusto - Limited-Time Festive Promo

Enjoy more than \$100 savings this season of gifting. Exclusive Machine + Capsules Promo! dolce-gusto.com.sg/perfectcoffee/perfectgift

OPEN

Nissan Cabstar

Price Range

Depreciation

> 10 year(

Vehicle Type



Submit

Advanced Search

Home » Used Cars » M.Y Commercial Pte Ltd » Nissan Cabstar (COE till 11/2020)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Leasing



YOUR PREFERRED CAR LEASING
OPTION IN SINGAPORE



6769 7117 8720 5000 8720 8000



SAVE UP TO
50%*

SHOP NOW

*T&Cs apply.



COFFEE IS NOT JUST BLACK

Compare

Nissan Cabstar (COE till 11/2020)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price **\$15,800**

Depreciation \$8,260 /yr

Reg Date 26-Nov-2005
(1yr 10mths 28days COE left)

Lifespan 25-Nov-2025

Manufactured 2005

Mileage -

Transmission Manual

Engine Cap 3,153 cc

Curb Weight 1,500 kg

Fuel type Diesel

Features -

Accessories -

Description PQP Paid \$22,924. High Scrap Value! Well Maintenance By Previous Owner, Price Still Can Negotiable, High Loan With Lowest Interest Rate Available, Call Our Friendly Salesperson To View Now.

COE \$22,924

OMV \$20,070

ARF \$1,004

Dereg Value \$8,768 as of today (change)

No. of Owners 2

Type of Veh Truck

Category COE Car

Availability Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 21-Nov-2018 | Last Updated on: 23-Nov-2018

Tags: Nissan Cabstar, nissan cabstar, 2005 Nissan Cabstar, 2005 nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan

Upfront Payment

» more Financial info

Transfer Fee \$25

Down Payment \$1,580 (change)

Maximum 90% Loan

1st Instalment \$700

Total Upfront Payment \$2,305 (excluding insurance)



Seller Information

Company

M.Y Commercial Pte Ltd

» dealer's pricelist

» 6 vehs sold | 6 vehs available

Address

7030 Ang Mo Kio Avenue 5 #02-16

Search cars nearby this location

Location

Northstar @ AMK

Office No

69093877

Contact Person(s)

Kenny Tan

91853232

Nick Ong

81684411

Useful Services



Afraid of lemons? Request to have
this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car.
Get a free Car Valuation.

Free Valuation

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Owner ID:

Company

1196N

Vehicle Details

Vehicle No.:

GY8826S

Vehicle to be Exported:

No

Intended Deregistration Date:

24 Dec 2018

Vehicle Make:

NISSAN

Vehicle Model:

CABSTAR

Primary Colour:

White

Manufacturing Year:

2005

Engine No.:

QD32212058

Chassis No.:

JN1SF4F23Z0860154

Maximum Power Output:

-

Open Market Value:

\$19,711.00

Original Registration Date:

13 Sep 2005

First Registration Date:

13 Sep 2005

Transfer Count:

1

Actual ARF Paid:

\$986.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

12 Sep 2020

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

5

PQP Paid:

\$24,768.00

COE Rebate Amount:

\$8,514.00

Total Rebate Amount:**\$8,514.00****Message**

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 24 Dec 2018

OK

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Feb 2019)	
Parts:	N/A	NISSAN CABSTAR 3.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GY8826S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE LOCK LATCH	Not Necessary	47.40 FS	*- FS
2	2		*REAR TAIL LAMP (CRACKED)	Not Consistent With The Impact	494.40 FS	*- FS
3	1		*REAR TAILGATE NISSAN STICKER	Not Necessary	128.60 FS	*- FS
4	1		*REAR TAILGATE (\$1688.20)(50%)	Bent	1,886.40 FS	*844.10 FS
5	1		*REAR TAILGATE LOWER MEMBER (50%)	Bent	552.30 FS	*276.15 FS
6	1		*REAR TAILGATE LOWER L BRACKET	Repair	115.50 FS	*- FS
7	1		*REAR REVERSE BUZZER (BROKEN)	Not Consistent With The Impact	280.00 FS	*- FS
8	1		*REAR NUMBER PLATE METAL	Not Necessary	28.00 FS	*- FS
9	1		*REAR TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
10	1		*REAR TAILGATE 13 PAX STICKER	Necessary	15.00 FS	*10.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 3,562.60 1,140.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	20.00
2	REMOVE AND REFIX REAR TAILGATE COMPONENTS & MECHANISM	New	80.00	0.00
3	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS	New	680.00	550.00
4	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	700.00	300.00
5	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	50.00
Gross Labour Cost (\$\$)			1,590.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J. Tel: 6741-1730 / 731. Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GY8826S180718

Estimate

Customer		Date:	24-12-18
Name:	MSIG Insurance (Singapore) Pte Ltd	Vehicle No:	GY8826S
Address:	Motor Claims Department	Model/Make:	Nissan Cabstar
	4 Shenton Way #21-01		
	SGX Centre 2		Singapore 068807

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate <i>1688.20</i>	\$ 1,886.40	<i>SN 105.2</i> <i>844.10</i>
2	" Tailgate Lower Member <i>Best</i>	\$ 552.30	<i>SN 5.2</i> <i>276.15</i>
3	" Tailgate Lock Latch <i>11</i>	\$ 47.40	<i>SN X</i>
4	" Tail Lamp 02 pcs (@ \$5247.20 N) <i>n/c C100</i>	\$ 494.40	<i>SN X</i>
5	" Tailgate Lower "L" Bracket <i>R</i>	\$ 115.50	<i>SN X</i>
6	" Reverse Buzzer <i>11 320</i>	\$ 280.00	<i>SN X</i>
7	" Number Plate "Metal" <i>11</i>	\$ 28.00	<i>SN X</i>
8	" Tailgate "Nissan" Sticker <i>(102)</i> <i>11</i>	\$ 128.60	<i>SN X</i>
9	" Tailgate "70 KM/H" Sticker <i>11</i>	\$ 15.00	<i>SN 105.2</i>
10	" Tailgate "13 PAX" Sticker <i>11</i>	\$ 15.00	<i>SN 105.2</i>
	To check all wiring & electrical component for proper function	\$ 50.00	<i>20</i>
	Remove and refix rear tailgate components & mechanism	\$ 80.00	<i>11 X</i>
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 680.00	<i>500</i>
	To putty & spray painting & including touch up paint on accident affected	\$ 700.00	<i>300</i>
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 80.00	<i>50</i>

Total Parts & Labour of estimate for damaged vehicle

\$ 5,152.60

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

LIU'S BROTHER AUTO ENGINEERING WORKSHOP'S NOTICE

We hereby notify the customer of the following:

- To the extent of the spray painting
- To the extent of the paint (s) during the repair
- To the extent of the work to be performed
- To the extent of the work to be performed
- To the extent of the work to be performed
- To the extent of the work to be performed
- To the extent of the work to be performed
- To the extent of the work to be performed

Acknowledged by Repairer

Signature:

Date:

Not Attached

Mal

28/12/18

4/5 \$1600

427

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18023148/UQD3N2

Date: 26/02/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28992363MKC
Claimant Vehicle No :	GY8826S	Insured Vehicle No :	YN1866S
Date of Loss:	18/07/2018	Nature of Claim:	TP
		Claim No:	580004

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GY8826S	Engine No:	QD32212058
Make & Model:	NISSAN CABSTAR, 3.0 (M)	Chassis No:	JN1SF4F23Z0860154
Reg. Date:	13/09/2005 (Man. Year: 2005)	Odometer:	646577 km
Colour:	White		
Engine Capacity:	3153 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6/6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,562.60	1,140.25	2,422.35	67.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,590.00	920.00	670.00	42.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,152.60	2,060.25	3,092.35	60.02
Approved Total (Overridden) (\$\$)		1,600.00		
Nett Amount (\$\$)	5,152.60	1,600.00	3,552.60	68.95

INSPECTION

Date of Assignment:	27/12/2018	
Date Inspected:	28/12/2018	Inspected At:
		LIU'S BROTHER AUTO WORKSHOP (HQ)
		1 Kaki Bukit Ave 6 #01-01, Auto Bay@Kaki Bukit
		Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.