#### Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

# (SUPPLEMENTARY)

**INSURER:** 

Present Location:

Sompo Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CL	AIM		
Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D18MTPV01008957	Date of Loss:	24/12/2018
Vehicle Reg. No.:	SLC5928H	Driveable?	NO
Driver Age/Info:	65 / MALE / SELF-EMPLOYED	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAN CHEE YU (CHEN QIYOU)	Contact No:	+6581285384
Driver:	TAN LYE KHENG		
Make/Model:	VOLVO V40, 1.5 T2 (A)	Vehicle Reg. Date:	19/05/2016
Vehicle Colour:	SILVER		
Engine No:	B4154T51497638	Chassis No:	YV1MV28H0G2327274
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	20		
	ON 24/12/2018 AROUND 1.25PM, 11. SUDDENLY VEHICLE B (SLH		
Description of Accident/Loss	BRAKE AND I COULD NOT STOP PORTION OF VEHICLE B (SLH68	ON TIME AND HIT ONT	O REAR LEFT

COST OF CLAIMS		Amount
Parts		872.30
Miscellaneous Items		0.00
Labour		0.00
Paintwork Labour		0.00
Towing		0.00
	Gross Total (S\$)	872.30
	+ GST 7.00% (S\$)	61.06
	Nett Amount (S\$)	933.36
	+ Previous Estimates (S\$)	17,721.88
	Claim Total (S\$)	18,655.24

ACCORD AUTO SERVICES PTE LTD (AMK) TEL: 64819517

Generated using Merimen e-Claims Internet Estimation & Adjusting System

#### REPAIR DETAILS

#### Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 07 Jan 2019)

Parts:

VOLVO V40 1.5 T2 (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Accord Auto Services Pte Ltd/SLC5928H/07/01/2019 15:08

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
 1	1		*Horn (RH)	0.00	0.00 G1	1 *62.00 F - 4 *40.00 F -
2	1		*Front bumper white lamp bracket (RH)	0.00		
3	1		*Air guide cover (top)	0.00	0.00 CM	<b>1</b> *433.00 F ─
4	1		*Aircon bypass hose (compressor to cooling coil)	0.00		*195.00 F
5	1		*Radiator upper hose	0.00		€ *18.00 F -
6	1		*Radiator lower hose	0.00	0.00 R	*45.00 F─
F=Fra	anchise	part.	Sub Total (S\$)			793.00
			+ Margin on L,N Items 10.00% (S\$)			79.30
			Total Parts (S\$)			872.30

Accord Auto Services Pte Ltd/SLC5928H/07/01/2019 15:08. Not valid without Reference section. Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

There are no labour items selected.

Accord Auto Services Pte Ltd/SLC5928H/07/01/2019 15:08. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

### Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

#### (SUPPLEMENTARY)

INSURER:

Sompo Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLA	AIM		
Claim Type: Policy No: Vehicle Reg. No.: Driver Age/Info: TP Injury Involved?	OD (OWN DAMAGE) D18MTPV01008957 SLC5928H 65 / MALE / SELF-EMPLOYED NO	Ref. No: Date of Loss: Driveable? Party At Fault: Third Party Involved?	24/12/2018 NO UNKNOWN YES
Insured/Claimant: Driver:	TAN CHEE YU (CHEN QIYOU) TAN LYE KHENG	Contact No:	+6581285384
Make/Model: Vehicle Colour:	VOLVO V40, 1.5 T2 (A) SILVER	Vehicle Reg. Date:	19/05/2016
Engine No: Odometer:	B4154T51497638 0 KM	Chassis No:	YV1MV28H0G2327274
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	20		
Description of Accident/Loss	ON 24/12/2018 AROUND 1.25PM, 11. SUDDENLY VEHICLE B (SLH6 BRAKE AND I COULD NOT STOP PORTION OF VEHICLE B (SLH687	870G) DROVE IN FRON ON TIME AND HIT ONT	T OF ME JAMMED

Present	Location:

ACCORD AUTO SERVICES PTE LTD (AMK) TEL: 64819517

COST OF CLAIMS		Amount
Parts		57.20
Miscellaneous Items		0.00
Labour		0.00
Paintwork Labour		0.00
Towing		0.00
•	Gross Total (S\$)	57.20
	+ GST 7.00% (S\$)	4.00
	Nett Amount (S\$)	61.20
	+ Previous Estimates (S\$)	18,655.24
•	Claim Total (S\$)	18,716.44

Generated using Merimen e-Claims Internet Estimation & Adjusting System

#### REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 01 Mar 2019)

Parts:

144

VOLVO V40 1.5 T2 (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Validity:

F=Franchise part.

Print Code: Accord Auto Services Pte Ltd/SLC5928H/01/03/2019 09:50 These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

Es	Estimates on Parts		0/ B!	0/ D
No.	Qty Part No.	Particulars	%Disc	%Dep
1	1	*Support panel top garnish (air inlet)	0.00	0.0

CM- \*52.00 FL 52.00 Sub Total (S\$)

Amount

5.20

+ Margin on L,N Items 10.00% (S\$) 57.20 Total Parts (S\$)

Accord Auto Services Pte Ltd/SLC5928H/01/03/2019 09:50. Not valid without Reference section. Generated using Merimen e-Claims IEAS

# Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

There are no labour items selected.

Accord Auto Services Pte Ltd/SLC5928H/01/03/2019 09:50. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >