

15/2/10

INS. CASE OWNER:

CC 3 / III1802

LKK:
VAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner? (YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

21/1/10
DM

GHL6850M

GHL5566M

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

NA

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

SS

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

SS

Loss of Rental (LOR):

SS

days) 103.58

Loss of Use (LOU):

SS

(S x days)

Loss of Income (LOI):

SS

(S x days)

LOR only

LOU only

SS

LOR + LOU

LOR + LOU

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

650.82

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

650.82

Name 1:

PREMIER AUTOMOTIVE SERVICES PTE LTD

Payee 2: (Strike if N.A.)

SS

X

Name 2:

X

Payee 3: (Strike if N.A.)

SS

X

Name 3:

X

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT
21/1/10




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC3/III18023191/K1jb3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 27-12-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKK 5566M	Veh. Inspected	SHC 6850M	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	27/12/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	23/12/2018	Inspection Date	26/12/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

26-Dec-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6850 M

1 pc	Rear bumper	\$	696.00
1 pc	Rear bumper lower cover	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00
1 pc	Rear bumper inner sponge	\$	114.00
1 pc	Rear bumper reinforcement	\$	607.00
2 pcs	Rear bumper n/s & o/s stay @ \$53.00	\$	106.00
2 pcs	Rear bumper reinforcement lower bracket @ 18.00	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00
			\$ 1,859.00
Less 10%			\$ 185.90
			\$ 1,673.10

S/NETT

1 set	Rear bumper clips	\$	48.00
1 set	Reverse sensor	\$	280.00

Sundry

To dismantle / replace reverse sensor to new bumper and reset to the same

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc

To putty and spray painting on rear bumper

To apply rustproofing on the repaired and replaced panels.

\$	50.00 20
\$	120.00 X 3
\$	180.00 X 1
\$	550.00 200
\$	400.00 180
\$	120.00 X 1
\$	3,421.10

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

4/1/19
P/P \$400/200
[Signature]

Kalwa (KK)
26/12/18 (6464)
200
L/S
After Repair photo

LEK Auto Consultants hence notify the Receiver of the following:

- To receive before/after spray painting
- To display damaged part(s) during return
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Supplementary details must be reduced and is subject to final approval from Insurance Company

Acknowledged by Receiver
Signature: _____
Date: _____

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

26-Dec-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6850 M

1 pc	Rear bumper <i>X n/m</i>	\$ 696.00
1 pc	Rear bumper lower cover <i>X</i>	\$ 206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>X</i>	\$ 58.00
1 pc	Rear bumper inner sponge <i>X</i>	\$ 114.00
1 pc	Rear bumper reinforcement <i>X</i>	\$ 607.00
2 pcs	Rear bumper n/s & o/s stay @ \$53.00 <i>X</i>	\$ 106.00
2 pcs	Rear bumper reinforcement lower bracket @ 18.00 <i>X</i>	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>X</i>	\$ 36.00
		<hr/>
		\$ 1,859.00
		Less 10%
		<hr/>
		\$ 1,673.10

S/NETT

1 set	Rear bumper clips <i>X</i>	\$ 48.00
1 set	Reverse sensor <i>X</i>	\$ 280.00
Sundry		
To dismantle / replace reverse sensor to new bumper and reset to the same		\$ 50.00 <i>20</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$ 120.00 <i>X</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc		\$ 180.00 <i>X</i>
To putty and spray painting on rear bumper		\$ 550.00 <i>200</i>
To apply rustproofing on the repaired and replaced panels.		\$ 400.00 <i>180</i>
		<hr/>
		\$ 120.00 <i>X</i>
		<hr/>
		\$ 3,421.10

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalua (KK)
26/12/18 1646h.
26/12
4/3
After Repair photo

Gary Shi

From: Gary Shi
Sent: Wednesday, 13 February, 2019 2:17 PM
To: 'Joy Irene (LKKAUTO)'
Cc: AccReport; Admin A
Subject: RE: LOD / Accident involving SHC6850M & SKK5566M on 23.12.18 (III case)
Attachments: SHC6850M - DV.pdf

WITHOUT PREJUDICE

Dear Joy,

On a without prejudice basis and without admission of liability whatsoever on our client's part and driver of SHC6850M, our client agreed to direct settle the above claims at \$650.82

We enclosed hereby Discharge voucher & ATA for your kind attention, original copies will pass to Mr Calvin.

Kindly let us have your settlement sum of S\$650.82 in our favour – Premier Automotive Services Pte Ltd within 14days from the date hereof.

Please be informed that this settlement excludes any bodily injuries arising out of the above said accident and pertains to property damage only.

Regards

Gary Shi
Senior Executive, Claims
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 069 | DID: 6544 6671 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

From: Joy Irene (LKKAUTO) [mailto:JoyIrene@lkkauto.com]
Sent: Wednesday, 13 February, 2019 11:22 AM
To: Gary Shi
Cc: AccReport; Admin A
Subject: RE: LOD / Accident involving SHC6850M & SKK5566M on 23.12.18 (III case)

WITHOUT PREJUDICE

Dear Gary,

DV and ATA attached for your necessary action.

Thank you.

Print Received Message

This mail is associated with :

***SHC6850M (MPC2018D0000283)**
[SKK5566M]

TP

PREMIER TAXIS PTE LTD
Dec 23 2018 11:00PM
[NEO AIK YOU]
Premier Automotive Services Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 01/02/2019 13:52 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$722.61) - SHC6850M - Claim Handler: Lalitha Krishnan

Approved: 722.61.

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	20 Aug 2015 / 07:43:11	Receipt No.:	AACCK001-AX239-150820-000017
Asset Type:	Vehicle	Transaction Amount:	\$72,061.00
Asset ID:	SHC6850M	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150820074311814337		

Vehicle No.:	SHC6850M
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	20 Aug 2015
Original Registration Date:	20 Aug 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5603645
Engine No.:	D4FDEH313574
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2015
Open Market Value:	\$21,203.00
Minimum PARF Benefit:	\$13,011.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	20 Aug 2015 07:43:11
COE No.:	2015082001003033N
COE Expiry Date:	19 Aug 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$50,236.00
Lifespan Expiry Date:	19 Aug 2023

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5095103893

Cover : Third Party

- | | |
|--|---------------------------|
| 1. Index mark and Registration Number of Vehicle | : SHC6850M |
| Chassis Number | : KNAGM414MF5603645 |
| 2. Name of Policyholder | : PREMIER TAXIS PTE. LTD. |
| 3. Effective Date of Insurance | : 20 Oct 2017 |
| 4. Expiry Date of Insurance | : 31 Jan 2019 |

5. Persons or Classes of Persons entitled to drive*

- (a) The Policyholder.
- (b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use*

- (a) Use as a Taxi.
- (b) Use for social domestic and pleasure purposes.

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third- Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I)	: N/A
EXCESS (SECTION II)	: S\$3,500
INSURE WITH COE	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)
Date of Issue : 16 Oct 2017 17:13 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:



Authorised Officer



Chief Executive

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVE 2 #01-02
SINGAPORE 486443
TEL:65446671 FAX:62141511
CO. REG:200707743D GST REG:200707743D

Our Ref: SHC6850M/GS

WITHOUT PREJUDICE

15th January 2019

(By Email Only)

Attn: The Motor Claims Department
India International Insurance Pte Ltd
64 Cecil Street #04/#05
IOB Building
Singapore 049711

Dear Sir/Madam

ACCIDENT INVOLVING SHC6850M & SKK5566M ALONG UPPER PICKERING STREET INFRONT OF ROYAL PARK HOTEL ON 23.12.18

We have been authorized by Premier Taxis Pte Ltd, the owner of Taxi vehicle number: SHC6850M, to claim against the party/parties responsible for the damages arising from the above-mentioned accident.

Our records show that you are the insurers of vehicle number: SKK5566M at the material time of the accident with the driver of our client's vehicle, Mr Oh Tiong Sing

As a result of the accident caused by your Insured Driver's negligent driving and/or management of your insured's Vehicle Number: SKK5566M, our client's vehicle was damaged and we have been put to loss and damage as follows:

(1) Cost of repair	\$	428.00 (Incl. GST)
(2) Loss of Rental - 2Days @\$103.58per day	\$	207.16
(3) Loss of Income – 2Days @\$100.00per day	\$	200.00
(4) LTA Search Fee	\$	7.45
	\$	<u>842.61</u>

A copy of each of the following supporting documents is enclosed:

- (1) Final Repair Bill, GIA report & sketch plan of SHC6850M
- (2) Driver's I/C and Driving Licence
- (3) Vehicle Registration card, Certificate of Insurance
- (4) Check In/Out Voucher, LTA search

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVE 2 #01-02

SINGAPORE 486443

TEL:65446671 FAX:62141511



CO. REG:200707743D GST REG:200707743D

Our Ref: SHC6850M/GS

We would appreciate if you could look into the subject matter and let us have your favorable offer within 14 days. If you are agreeable to the settlement of the above said claims, please forward us your discharge voucher as for our client's signature and payment made to "Premier Automotive Services Pte Ltd".

Please note that if we do not hear from you within the stipulated 14 days, we will have no alternative but to appoint our solicitor to act on our behalf to commence proceedings against you without further notice to you.

Yours faithfully,



Claims Department – Gary Shi

Email: gary.shi@premiertaxi.com

NB: We encourage all parties to liaise with us via email to expedite all matters

PS: Please quote our reference no when replying

c.c. Client – Premier Taxis Pte Ltd


AUTHORISATION TO ACT

I/We, **PREMIER TAXIS PTE LTD** ("the third party claimant") of **23 CHANGI SOUTH AVENUE 2 #03-02 SINGAPORE 486443** (address), owner of **SHC 6850M** (vehicle no.) hereby authorize **PREMIER AUTOMOTIVE SERVICES PTE LTD** ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. **SHC 6850M** that was damaged pursuant to the accident which occurred on **23/12/2018** (date) along **UPPER PICKERING STREET** (location) involving vehicle no/s **SKK 5566M** ("the accident").


I/We further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of "the workshop".

I/We further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 13 (day) of Feb (month) 2019 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

EXPRESS SETTLEMENT

DISCHARGE VOUCHER

III- Direct Settlement (PODS)

India Ref: MPC2018D0000283

Claimant Ref: SHC 6850M

We/I, PREMIER AUTOMOTIVE SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 428.00 (repair cost), S\$ 215.37 (loss of use/rental), S\$ 7.45 (search fee), vehicle no. SHC 6850M that was damaged pursuant to the accident which occurred on 23.12.2018 (date) at UPPER PICKERING STREET (location) involving vehicle no. SKK 5566M (insured vehicle). This is pursuant to the inspection conducted on 26/12/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner PREMIER TAXIS PTE LTD ("the third party claimant") of vehicle no. SHC 6850M to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SHC 6850M (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 650.82 to PREMIER AUTOMOTIVE SERVICES PTE LTD

Dated this 13 day of February 2019

CLAIMANT:

Signature: _____

Signed by "the workshop" (with chop)

Name: _____

NRIC: _____

Address: _____

Nationality: _____

Occupation: _____

WITNESS:

Signature: _____

Name: _____

NRIC: _____

Address: _____

Nationality: _____

Occupation: _____



Signed by appointed Surveyor

LKK AUTO CONSULTANTS PTE LTD

199607198R

51 UBI AVENUE 1 #01-25

PAYA UBI INDUSTRIAL PARK (S) 408933

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MPC2018D0000283
Claimant Ref: SHC 6850M

We/I, PREMIER AUTOMOTIVE SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 428.00 (repair cost), S\$ 215.37 (loss of use/rental), S\$ 7.45 (search fee), vehicle no. SHC 6850M that was damaged pursuant to the accident which occurred on 23.12.2018 (date) at UPPER PICKERING STREET (location) involving vehicle no. SKK 5566M (insured vehicle). This is pursuant to the inspection conducted on 26/12/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner PREMIER TAXIS PTE LTD ("the third party claimant") of vehicle no. SHC 6850M to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SHC 6850M (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 650.82 to PREMIER AUTOMOTIVE SERVICES PTE LTD

Dated this 13 day of February 20 19

CLAIMANT:

Signature: [Signature]
Signed by "the workshop" (with chop)
Name: Gary Shi
NRIC: S8644864H
Address: 23 Changi South Ave 2
#01-02 S486443
Nationality: Singaporean
Occupation: _____

WITNESS:

Signature: [Signature]
Signed by appointed Surveyor
Name: LKK AUTO CONSULTANTS PTE LTD
NRIC: 199607198R
Address: 51 UBI AVENUE 1 #01-25
PAYA UBI INDUSTRIAL PARK (S) 408933
Nationality: _____
Occupation: _____




PREMIER AUTOMOTIVE SERVICES PTE LTD
OFFICE: 23 Changi South Avenue 2 #01-02 S(486443)
TEL: 65436678 / 65436689 FAX: 62141511
CO. REG NO.: 200707743D GST. REG. NO.: 200707743D

PREMIER TAXIS PTE LTD
23 CHANGI SOUTH AVENUE 2 #03-02
SINGAPORE 486443

TAX INVOICE

DATE 14-Jan-2019
PAGE 1 OF 1

ITEM	Description	QTY	U.PRICE	AMOUNT
	FINAL REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6850 M			\$ 400.00
TOTAL REPAIR COSTS AS RECOMMENDED BY SURVEYOR				\$ 400.00
GST @ 7%				\$ 28.00
GRAND TOTAL				\$ 428.00


for Premier Automotive Services Pte Ltd

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)



14 January 2019

To Whom It May Concern

Dear Sir/Madam

CERTIFICATION LETTER

This letter serves to inform that Oh Tiong Sing of NRIC Number S1007684F is a registered driver of SHC6850M. Oh Tiong Sing is paying daily rental rate of \$103.58 (Inclusive of GST).

Should you require further information, please contact us at 6214 8880.

Thank you.

Yours sincerely

A handwritten signature in black ink, appearing to be 'Kellie Poh', written over a circular stamp.



Kellie Poh

Administration Manager

Prepared By: SY

PREMIER TAXIS PTE LTD
23 Changi South Avenue 2
#03-02
Singapore 486443
Telephone: +65 6214 8880 Fax: +65 6214 0330
www.premiertaxi.com
Co. Reg. No. 20030497511



REPLACEMENT VEH GIVEN YES / NO

VEH NO. _____

JOB NO. _____

CHECK IN / OUT VOUCHER

DRIVER'S NAME RAYMOND YEO MUI CHONG (CREW)	
NRIC S1625466E	HANDPHONE 98630777
TAXI REGN NO. SHC 6850M	MAKE / MODEL K02
DATE IN 26/12/18	TIME IN 1200
DATE OUT 27/12/18	TIME OUT 1509
KILOMETRES IN 204759	FUEL IN E 1/4 1/2 3/4 F
KILOMETRES OUT	FUEL OUT E 1/4 1/2 3/4 F

TAXI METER DOWNLOADED

YES

NO

DATE / TIME TOWED IN TO WORKSHOP

D D M M Y Y H H M M

DATE / TIME CALL TO DRIVER FOR VEHICLE COLLECTION

D D M M Y Y H H M M

I ACKNOWLEDGE AND CONFIRM THAT I HAVE EXAMINED THE ABOVE SAID VEHICLE AND THAT THE SAME IS IN GOOD CONDITION AND TO MY SATISFACTION IN EVERY RESPECT TOGETHER WITH THE ACCESSORIES / ITEMS LIST ABOVE. THIS VOUCHER IS USED IN CONJUNCTION WITH THE TERM RENTAL AGREEMENT.

CHECK IN

Raymond yeo mui chong

DRIVER'S NAME

WR

X

DRIVER'S SIGNATURE / DATE / TIME

CHECKED IN BY
(PREMIER'S AUTHORISED WORKSHOP)

CHECK OUT

Raymond yeo mui chong

DRIVER'S NAME


WR

X

DRIVER'S SIGNATURE / DATE / TIME

CHECKED OUT BY
(PREMIER'S AUTHORISED WORKSHOP)

INDICATE AREA OF DAMAGE HERE:



BODY MARKINGS

- 1 - Light Dent
- 2 - Serious Dent
- 3 - Light Scratch
- 4 - Serious Scratch

- 5 - Damaged
- 6 - Chip
- 7 - Crack
- 8 - Peeling

SERVICE / REPAIRS DONE	DRIVER'S REMARKS
<input type="checkbox"/> SERVICING <input type="checkbox"/> OTHERS: <input type="checkbox"/> T / BELT <input type="checkbox"/> AIRCON SYSTEM <input checked="" type="checkbox"/> ACCIDENT: DATE / TIME of ACCIDENT: <input type="checkbox"/> TURBO 26/12/18 23MS <input type="checkbox"/> BRAKE SYSTEM <input type="checkbox"/> CLUTCH SYSTEM <input type="checkbox"/> BULB <input type="checkbox"/> UNDER CARRIAGE <input type="checkbox"/> CPF <input type="checkbox"/> BATTERY TP / V	-Hire - 04 Tiang Sing - 8672 9306

> Back to OneMotoring



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 26 Dec 2018 / 15:34:25

Receipt Date/Time : 26 Dec 2018 / 15:34:25

Tax Invoice/Receipt

Receipt No. : ITNET-00000-181226-002367

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SKK5566M As at 23 Dec 2018/23:15:00 Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - SKK5566M Enquiry Fee 20181226153330631825	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx0416	Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Direct Settlement

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jan 2019 Edit Reg		26 Dec 2018 00:00 Edit Adj Rpt	\$400.00 Edit Estimates	\$400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by adjuster]						
Insured:	NEO AIK YOU, ID: S1592771B								
Main Claimant:	PREMIER TAXIS PTE LTD, Co. Reg. No.: 200304975H								
Vehicle Reg. No.:	SHC6850M	Date of Loss:	23/12/2018 23:00 - :59 [40 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MPC2018D0000283	Policy/Cover Note No.:	D18MPC0000310						
Vehicle Reg. No. (Insured):	SKK5566M	Policy No. (Claimant):	5095103893						
		Excess:							
Repairer:	Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02, 486443 Changi - Tel: 62148880								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Lalitha Krishnan - 6347 6139]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 08/01/2019]								
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
● III_SG (01/02/2019): Alert - Adj Mandate Approved (S\$722.61) - SHC6850M - Claim Handler: Lalitha Kris...									
ALL ASSOCIATED TASKS									
		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHC6850M (MPC2018D0000283)
[SKK5566M]
TP
PREMIER TAXIS PTE LTD
Dec 23 2018 11:00PM
[NEO AIK YOU]
Premier Automotive Services Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View Use Viewer	
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	27/12/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>			
2	27/12/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>			
3	27/12/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>			
4	27/12/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>			
5	27/12/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>			
6	27/12/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>			
7	27/12/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>			
8	27/12/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>			
9	27/12/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>			
10	27/12/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>			
11	27/12/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>			
12	27/12/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>			
13	27/12/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>			
14	27/12/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>			
15	27/12/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>			
16	27/12/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>			
17	27/12/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>			
18	27/12/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>			
19	27/12/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>			
20	27/12/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>			
21	27/12/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>			
22	04/01/19 13:54	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>			
23	04/01/19 13:54	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>			
24	04/01/19 13:54	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>			
25	04/01/19 13:54	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>			
Documentation							1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	27/12/18 20:45	TP ESTIMATE- MARKED	1	Load PDF				
2	27/12/18 20:45	TP GIA REPORT	1	Load PDF				
3	29/01/19 12:35	WORKSHOP INVOICE	1	Load PDF				
4	29/01/19 12:35	RENTAL RECEIPT	1	Load PDF				
5	29/01/19 12:35	RENTAL MILEAGE	1	Load PDF				
6	29/01/19 12:35	LTA SEARCH	1	Load PDF				
7	29/01/19 12:35	LOD	1	Load PDF				
8	20/02/19 10:55	AUTHORISATION TO ACT FORM	1	Load PDF				
9	20/02/19 10:55	DISCHARGE VOUCHER	1	Load PDF				
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print			
1	28/12/18 08:33	Singapore Accident Statement	1	Load PDF				

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18023191/K1JB3N2

Date: 20/02/2019

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MPC0000310
Claimant Vehicle No :	SHC6850M	Insured Vehicle No :	SKK5566M
Date of Loss:	23/12/2018	Nature of Claim:	TP
		Claim No:	MPC2018D0000283

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC6850M	Engine No:	D4FDEH313574
Make & Model:	KIA OPTIMA, 1.7 D (A)	Chassis No:	KNAGM414MF5603645
Reg. Date:	20/08/2015 (Man. Year: 2015)	Odometer:	204759 km
Colour:	Silver		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65R16	Rear Tyre Size:	205/65R16
Front Left Side:	Maxxis 7 mm	Rear Left Side:	Maxxis 7 mm
Front Right Side:	Maxxis 7 mm	Rear Right Side:	Maxxis 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,051.10	20.00	2,031.10	99.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,370.00	380.00	990.00	72.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	3,421.10	400.00	3,021.10	88.31
+ GST 7.00/7.00% (\$\$)	239.48	28.00	211.48	88.31
Nett Amount (\$\$)	3,660.58	428.00	3,232.58	88.31
+ Loss of Use (1.5 x S\$40.00/day) (\$\$)		60.00		
+ Car Rental (1.5 x S\$103.58/day) (\$\$)		155.37		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		650.82		

INSPECTION

Date of Assignment:	26/12/2018	
Date Inspected:	26/12/2018 Inspected At:	Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02 Singapore 486443

Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 29 Jan 2019)
Parts: 143	KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC6850M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Repair	696.00 FL	*- FL
2	1	*REAR BUMPER LOWER COVER	Serviceable	206.00 FL	*- FL
3	2	*REAR BUMPER SIDE BRACKET O/S & N/S	Serviceable	58.00 FL	*- FL
4	1	*REAR BUMPER INNER SPONGE	Serviceable	114.00 FL	*- FL
5	1	*REAR BUMPER REINFORCEMENT	Serviceable	607.00 FL	*- FL
6	2	*REAR BUMPER N/S & O/S STAY	Serviceable	106.00 FL	*- FL
7	2	*REAR BUMPER REINFORCEMENT LOWER BRACKET	Serviceable	36.00 FL	*- FL
8	2	*REAR BUMPER REINFORCEMENT UPPER BRACKET	Serviceable	36.00 FL	*- FL
9	1	*SET REAR BUMPER CLIPS	Not Necessary	48.00 FS	*- FS
10	1	*SET REVERSE SENSOR	Serviceable	280.00 FS	*- FS
11	1	*SUNDRY	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,237.00	20.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	185.90	0.00
Total Parts (\$\$)	2,051.10	20.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME	New	120.00	0.00
2	TO DISMANTLE/REFIT THE INNER GARNISHES,INNER LININGS,INNER TRIMS,CUSHION SEAT,CARPET,ETC TO FACILITATE REPAIRS	New	180.00	0.00
3	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE SAME,ETC	New	550.00	200.00
4	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER	New	400.00	180.00
5	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	0.00
Gross Labour Cost (S\$)			1,370.00	380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >