

SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMA	TION	Brata was a second	The Clark to the second	
INCIDENT NO. : /20181225/0754		LOCATION OF FIRE:	LOCATION OF FIRE:	
FIRE REPORTED ON : 25 December 2018		Along Choa Chu Kang North 6		
TIME OF CALL: 20:09:24 hrs		Near junction of Choa (Singapore	Near junction of Choa Chu Kang Street 64 Singapore	
STATION COVERAGE : Bukit Batok Fire Station				
2. INCIDENT INFORMA	TION	11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
FIRE INVOLVED: The en	ngine of a Toyota car (SGR5364P).		
METHOD OF EXTINGU fire appliance.	ISHMENT: By SCDF c	rew using 2 compressed	air foam backpacks from a	
PROBABLE CAUSE OF	FIRE: Accidental (Ove	erheating at engine comp	partment)	
DAMAGE SUSTAINED:	As a result of the fire,	the engine, windscreen a	and front parts of the car at, smoke and water damage.	
3. FATALITY/INJURY II			150 40	
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED	
NIL	NIL	NIL	NIL	
REPORT CERTIFIED T	RUE AND CORRECT	BY:		
-				
HUANG WEI KANG for COMMISSIONER				
SINGAPORE CIVIL DE	FENCE FORCE			

This is a computer generated Fire Report. No signature is required.